

Conifer High School		Sampled 4/21/2022	Status
CustomerSampleNumber	Description	Lead Results (ppb)	
73600-C127-S3	Food Service Sink-Food Prep	2.7	
73600-B102H-WBFS	Hallway Water Bottle Filling Station outside of Cafeteria	<0.1*	
73600-B102H-DF	Hallway Drinking Fountain outside of Cafeteria	<0.1*	
73600-2022-B102H-WBFS 2	Hallway Water Bottle Filling Station outside of Cafeteria	<0.1*	
73600-C110-S	Sink in Concession Area	1.3	
73600-D132-DF	Drinking Fountain in Small Gym	<0.1*	
73600-2022-D132-WBFS	Water Bottle Filling Station in Small Gym	<0.1*	
73600-D110-DF	Drinking Fountain in Locker Room D110	4.1	
73600-D116-IM	Ice Machine in Training Room D116	3.5	
73600-D124-DF	Drinking Fountain in Locker Room D124	1.8	
73600-2022-D101-DF	Drinking Fountain in Large Gym	<0.1*	
73600-2022-D101-WBFS	Water Bottle Filling Station in Large Gym	<0.1*	
73600-D128-DF	Drinking Fountain in Locker Room D128	0.7	
73600-D108-DF	Drinking Fountain in Locker Room D108	not in use	
73600-B143-S	Sink in Clinic	2.4	
73600-B112-S	Sink in Teacher's Lounge	1.2	
73600-2022-A140H-WBFS	Water Bottle Filling Station outside of Technology Lab A140	<0.1*	
73600-A130H-WBFS	Water Bottle Filling Station outside of Technology Lab A136	<0.1*	
73600-A130H-DF	Hallway Drinking Fountain outside of Technology Lab A136	<0.1*	
73600-A033-S1	Sink in Kitchen Classroom A033	4.2	
73600-A033-S2	Sink in Kitchen Classroom A033	9.4	Repairs Pending
73600-2022-A037H-DF	Hallway Drinking Fountain across from Kitchen Classroom A033	<0.1*	
73600-2022-A037H-WBFS	Water Bottle Filling Station across from Kitchen Classroom A033	<0.1*	
73600-A228H-DF	Hallway Drinking Fountain across from Work Room A202	<0.1*	
73600-2022-A228H-WBFS	Water Bottle Filling Station across from Work Room A202	<0.1*	
73600-B124-DF	Drinking Fountain in Work Room B124	<0.1*	
73600-2022-B124-WBFS	Water Bottle Filling Station in Work Room B124	<0.1*	
73600-2022-E114-S	Sink	1.5	
73600-2022-E105H-DFL	Hallway Drinking Fountain/Left	<0.1*	
73600-2022-E105H-DFR	Hallway Drinking Fountain/Right	<0.1*	
73600-2022-E105H-WBFS	Water Bottle Filling Station in Hallway	<0.1*	
73600-2022-E101H-DFL	Hallway Drinking Fountain/Left	<0.1*	

73600-2022-E101H-DFR	Hallway Drinking Fountain/Right	<0.1*	
73600-2022-E101H-WBFS	Water Bottle Filling Station in Hallway	<0.1*	
* This results is less than 0.1ppb, which is the lowest level that can be reported by the lab.			