

Dakota Ridge High School		Sampled 4/19/2022	Status
CustomerSampleNumber	Description	Lead Results (ppb)	
73800-ST200H-DFL	Hallway Drinking Fountain across from Library/Left	0.1	
73800-ST200H-DFR	Hallway Drinking Fountain across from Library/Right	<0.1*	
73800-ST200H-WBFS	Hallway Water Bottle Filling Station across from Library	<0.1*	
73800-AR201H-DFR	Hallway Drinking Fountain across from Prep/Work Room AR209/Right	0.4	
73800-2022-AR201H-DFL	Hallway Drinking Fountain across from Prep/Work Room AR209/Left	0.7	
73800-B201H-DFL	Hallway Drinking Fountain outside of Classroom B205/Left	0.2	
73800-B201H-DFR	Hallway Drinking Fountain outside of Classroom B205/Right	0.2	
73800-B244H-DFL	Hallway Drinking Fountain across from ClassroomB239/Left	<0.1*	
73800-B244-WBFS	Water Bottle Filling Station across from Classroom B239	<0.1*	
73800-B244H-DFR	Hallway Drinking Fountain across from ClassroomB239/Right	1.1	
73800-SC109-S	Sink in Concessions	9.1	Repairs Pending
73800-AD103-S	Sink in Clinic	0.5	
73800-AD103-IM	Ice Machine in Clinic	<0.1*	
73800-ST102H-DFL	Hallway Drinking Fountain across from Resource Room SE103/Left	0.2	
73800-ST102H-DFR	Hallway Drinking Fountain across from Resource Room SE103/Right	not in use	
73800-AR115H-DFL	Hallway Drinking Fountain across from Classroom AR134/Left	0.5	
73800-AR115H-DFR	Hallway Drinking Fountain across from Classroom AR134/Right	0.4	
73800-AR123-DF	Drinking Fountain in Vocal Room AR123	0.2	
73800-SC115-S1	Food Service Sink-Food Prep	not in use	
73800-SC115-S6	Food Service Sink-Food Prep	1.8	
73800-SC110-DFL	Drinking Fountain in Cafeteria/Left	0.7	
73800-SC110-DFR	Drinking Fountain in Cafeteria/Right	0.3	
73800-SC106-S	Sink in Teacher's Lounge	<0.1*	
73800-PE116H-DFL	Hallway Drinking Fountain by Weight Room/Left	<0.1*	
73800-PE116-H-WBFS	Water Bottle Filling Station by Weight Room	<0.1*	
73800-PE116H-DFC	Hallway Drinking Fountain by Weight Room/Center	<0.1*	
73800-PE116H-DFR	Hallway Drinking Fountain by Weight Room/Right	<0.1*	
73800-PE113-IM	Ice Machine in Training Room PE113	<0.1*	
73800-HR144H-DFL	Hallway Drinking Fountain across from Classroom HR139/Left	0.3	
73800-HR144H-DFR	Hallway Drinking Fountain across from Classroom HR139/Right	0.6	
73800-HR110-S1	Sink in Kitchen Classroom HR110	0.2	
73800-HR110-S2	Sink in Kitchen Classroom HR110	0.2	

73800-HR110-S3	Sink in Kitchen Classroom HR110	0.3	
73800-HR110-S4	Sink in Kitchen Classroom HR110	0.2	
73800-HR110-S5	Sink in Kitchen Classroom HR110	0.1	
73800-HR110-S6	Sink in Kitchen Classroom HR110	0.2	
73800-HR110-S7	Sink in Kitchen Classroom HR110	0.6	
73800-HR124H-DFL	Hallway Drinking Fountain outside of Planning Room HR124/Left	0.3	
73800-HR124H-DFR	Hallway Drinking Fountain outside of Planning Room HR124/Right	0.4	
73800-SC101-S	Sink in Store	0.6	

* This results is less than 0.1ppb, which is the lowest level that can be reported by the lab.