

D'Evelyn Jr/Sr		Sampled 4/5/2022	Status
CustomerSampleNumber	Description	Lead results (ppb)	
52100-W101-S	Sink in Clinic	0.3	
52100-AUDIH-DFL	Hallway Drinking Fountain on West Side of Auditorium/Left	0.5	
52100-AUDIH-DFR	Hallway Drinking Fountain on West Side of Auditorium/Right	0.3	
52100-NW101H-WBFS	Hallway Water Bottle Filling Station outside of Cafeteria	0.1	
52100-NW101H-DFL	Hallway Drinking Fountain outside of Cafeteria/Left	<0.1*	
52100-NW101H-DFR	Hallway Drinking Fountain outside of Cafeteria/Right	0.2	
52100-NW101A-S7	Food Service Sink-Food Prep	0.5	
52100-NW103-S	Sink in Teacher's Lounge	0.1	
52100-NW103-WC	Water Cooler in Teacher's Lounge	0.1	
52100-2022-G101-WC	Water Cooler	<0.1*	
52100-NW100-IM	Ice Machine in Training Room NW100	<0.1*	
52100-2022-NE108-WBFS	Water bottle filling station weight room NE108	0.2	
52100-NE108-DF	Drinking Fountain in Weight Room NE108	0.2	
52100-NE106-SWB	Sink with Bubbler in Instrument/Band Room NE106	5	Repairs pending
52100-NE106H-DFL	Hallway Drinking Fountain outside of Vocal Room NE106/Left	0.1	
52100-NE106H-DFR	Hallway Drinking Fountain outside of Vocal Room NE106/Right	0.1	
52100-2022-NE106H-WBFS	Water Bottle filling station outside of Vocal Room NE106	0.1	
52100-EAUDIH-DFL	Hallway Drinking Fountain on East Side of Auditorium/Left	<0.1*	
52100-EAUDIH-DFR	Hallway Drinking Fountain on East Side of Auditorium/Right	<0.1*	
52100-C100F-WC	Water Cooler in Counseling Area	<0.1*	
52100-W-2H-DFL	Hallway Drinking Fountain across from Classroom W202/Left	0.1	
52100-W-2H-DFR	Hallway Drinking Fountain across from Classroom W202/Right	0.2	
52100-L200B-WC	Water Cooler in Library Work Room	<0.1*	
52100-E-2H-DFR	Hallway Drinking Fountain across from Classroom E202/Right	<0.1*	
52100-E-2H-DFL	Hallway Drinking Fountain across from Classroom E202/Left	<0.1*	
52100-2022-E-SH-WBFS	Water bottle filling station	<0.1*	

* This results is less than 0.1ppb, which is the lowest level that can be reported by the lab.