

Connections Learning Center - Sampled 10/7/16				Resampled * 4/26/19	
SampleNumber	Description	Lead Result	Unit	Lead Result	Unit
85001-302-DFL	Drinking Fountain in Cafeteria/Left	0.4	ppb	0.3	ppb
85001-302-DFC	Drinking Fountain in Cafeteria/Center	0.3	ppb	0.2	ppb
85001-302-DFR	Drinking Fountain in Cafeteria/Right	0.4	ppb	0.2	ppb
85001-103H-DF	Hallway Drinking Fountain across from Classroom 106 and 102	0.4	ppb	0.2	ppb
85001-101-S	Sink in Classroom 101	0.3	ppb		
85001-113AH-DFL	Hallway Drinking Fountain across from Classroom 110 and 114/Left	0.3	ppb	0.1	ppb
85001-113AH-DFR	Hallway Drinking Fountain across from Classroom 110 and 114/Right	0.3	ppb	0.1	ppb
85001-113AH-WBFS	Hallway Water Bottle Filling Station across from Classroom 110 and 114	<0.1 ** †			
85001-111A-S	Sink in Science Prep Room 111A	0.5	ppb		
85001-109-S1	Sink in Laboratory 109	0.2	ppb		
85001-109-S2	Sink in Laboratory 109	0.3	ppb		
85001-113-S1	Sink in Laboratory 113	0.3	ppb		
85001-219-WC	Water Cooler in Teacher's Lounge	0.2	ppb	<0.1 **	ppb
85001-219-S	Sink in Teacher's Lounge	1.0	ppb	0.6	ppb
85001-211-S	Sink in Clinic	0.3	ppb	0.2	ppb
* Resampling results were from samples collected on 4/26/19 as part of an ongoing rotation of lead testing.					
** This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.					
† This fixture was sampled for the first time on 4/26/19.					