

Governor's Ranch Elementary School		Sampled 4/5/2022	Status
CustomerSampleNumber	Description	Lead results (ppb)	
18200-115-S	Sink in Clinic	0.6	
18200-119-S	Sink in Planning Room near Office	1.5	
18200-137-S	Sink in Teacher's Lounge	0.4	
18200-133H-DF	Hallway Drinking Fountain near Cafeteria	<0.1*	
18200-2022-133H-WBFS	Water bottle filling station near Cafeteria	<0.1*	
18200-C-14X-S	Hallway Sink in C-Pod	0.6	
18200-C-8H-DF	Hallway Drinking Fountain near Classroom C-305	0.4	
18200-C-13H-DF	Hallway Drinking Fountain near Classroom C-301	0.5	
18200-2022-B-13H-WBFS	Water bottle filling station near Classroom C-301	0.5	
18200-B-8H-DF	Hallway Drinking Fountain near Classroom B-205	3.4	
18200-A-13H-DF	Hallway Drinking Fountain near Classroom A-107	0.6	
18200-A-8H-DF	Hallway Drinking Fountain near Classroom A-103	0.3	
18200-126H-DF	Hallway Drinking Fountain near Kindergarten Classroom A-101	0.1	
18200-2022-126H-WBFS	Water bottle filling station near Kindergarten Classroom A-101	<0.1*	
18200-A-101-SWB	Sink with Bubbler in Kindergarten Classroom A-101	0.4	
18200-A-100-SWB	Sink with Bubbler in Kindergarten Classroom A-100	0.3	
18200-REC-104-DF	Drinking Fountain in Temp REC-104	0.3	
18200-RE-027-DF	Drinking Fountain in Temp RE-027	2	
18200-REC-081-DF	Drinking Fountain in Temp REC-081	6.4	Repairs Pending
18200-R1-167-DF	Drinking Fountain in Temp R1-167	not in use	
* This results is less than 0.1ppb, which is the lowest level that can be reported by the lab.			