

Irwin Preschool Sampled - 7/28/16				Resampled** 4/26/19	
SampleNumber	Description	Lead Result	Units	Lead Result	Units
19695-106X-S	Sink in Clinic	13.9	ppb	1.5	ppb
19695-106H-DFL	Main Hallway Drinking Fountain/Left	0.3	ppb	<0.1 *	ppb
19695-106H-DFR	Main Hallway Drinking Fountain/Right	0.5	ppb	<0.1 *	ppb
19695-108-S	Sink in Teacher's Lounge	3.0	ppb	1.4	ppb
19695-108-WC	Water Cooler in Teacher's Lounge	<0.1 * ***	ppb		
19695-107X-S	Sink in Work Room 107X	2.0	ppb		
* This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.					
** Resampling results were from samples collected on 4/26/19 as part of an ongoing rotation of lead testing.					
*** This fixture was sampled for the first time on 4/26/19.					