

Leawood Elementary School		Sampled 4/14/2022	Status
CustomerSampleNumber	Description	Lead Results (ppb)	
23200-E145H-DF	Hallway Drinking Fountain near Main Entrance	23.5	Repairs Pending
23200-E148H-SWB	Hallway Sink with Bubbler near Computer Lab	0.2	
23200-E148AH-SWB1	Hallway Sink with Bubbler near Classroom E164C	0.1	
23200-E148AH-SWB2	Hallway Sink with Bubbler near Classroom E164A	0.1	
23200-E113-S	Food Service Sink-Food Prep	0.4	
23200-179-DF	Drinking Fountain in Cafeteria	0.7	
23200-E159H-SWB	Hallway Sink with Bubbler across from Kitchen	0.1	
23200-E126H-DF	Hallway Drinking Fountain near Music Room	3.8	
23200-194H-DFL	Hallway Drinking Fountain near Classroom 185/Left	<0.1*	
23200-194H-DFR	Hallway Drinking Fountain near Classroom 185/Right	<0.1*	
23200-185-SWB	Sink with Bubbler in Classroom 185	<0.1*	
23200-188-SWB	Sink with Bubbler in Classroom 188	<0.1*	
23200-189-SWB	Sink with Bubbler in Classroom 189	0.2	
23200-190-SWB	Sink with Bubbler in Classroom 190	<0.1*	
23200-191-SWB	Sink with Bubbler in Classroom 191	<0.1*	
23200-192-SWB	Sink with Bubbler in Classroom 192	<0.1*	
23200-193-SWB	Sink with Bubbler in Classroom 193	<0.1*	
23200-E124H-DF	Hallway Drinking Fountain near Gym	<0.1*	
23200-2022-E124H-WBFS	Water Bottle Fillinf Station near Gym	<0.1*	
23200-E126D-S	Sink in Clinic	0.1	
23200-E101-SWB	Sink with Bubbler in Kindergarten Classroom E101	4.5	
23200-E104-SWB	Sink with Bubbler in Kindergarten Classroom E104	1	
* This results is less than 0.1ppb, which is the lowest level that can be reported by the lab.			