

Peak Expeditionary School at Pennington - Sampled 6/9/16				Resampled ** 5/8/18	
SampleNumber	Description	Lead Result	Units	Lead Result	Units
32500-106-S	Sink in Clinic	1.4	ppb	0.5	ppb
32500-105-S	Sink in Workroom	0.2	ppb		
32500-104-S	Sink in Teacher's Lounge	0.5	ppb	0.3	ppb
32500-122-S	Sink in Library Workroom	0.5	ppb		
32500-122H-DFL	Hallway Drinking Fountain/Left	0.3	ppb	<0.1*	ppb
32500-122H-DFR	Hallway Drinking Fountain/Right	0.3	ppb	<0.1*	ppb
32500-146H-DF	Hallway Drinking Fountain by Computer Lab	0.5	ppb	0.6	ppb
32500-147-S	Sink in Music Room	1.8	ppb		
32500-148-S	Sink in Classroom 148	1.8	ppb	0.7	ppb
32500-149-S	Sink in Kindergarten Classroom 149	1.4	ppb	0.3	ppb
32500-151-S	Sink in Kindergarten Classroom 151	0.3	ppb	0.2	ppb
32500-153-S	Sink in Art Room	2.1	ppb	1.3	ppb
32500-154-S	Sink in Classroom 154	1.1	ppb	1.8	ppb
32500-155-S	Sink in Classroom 155	1.2	ppb	0.4	ppb
32500-123-S	Sink in Classroom 123	0.7	ppb	0.2	ppb
32500-124-S	Sink in Classroom 124	1.3	ppb	0.3	ppb
32500-125-S	Sink in Classroom 125	0.6	ppb	0.2	ppb
32500-126-S	Sink in Classroom 126	0.7	ppb	0.1	ppb
32500-127-S	Sink in Classroom 127	0.8	ppb	0.3	ppb
32500-128-S	Sink in Classroom 128	0.4	ppb	0.2	ppb
32500-136-DFL	Cafeteria Drinking Fountain/Left	0.4	ppb	0.3	ppb
32500-136-DFR	Cafeteria Drinking Fountain/Right	0.3	ppb	0.2	ppb
32500-A47-S1	Food Service Sink	1.6	ppb	0.6	ppb
32500-A47-S2	Food Service Sink	2.0	ppb	1.6	ppb
32500-REC-093-DF	Drinking Fountain in Temp REC-093	1.7	ppb	1.3	ppb
* This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.					
** Resampling results were from samples collected on 5/8/18 as part of an ongoing five-year rotation of lead testing.					