

Stott Elementary School - Sampled 7/15/16				Resampled* 8/9/16		Resampled** 5/18/18	
SampleNumber	Description	Lead Result	Units	Lead Result	Units	Lead Result	Units
38200-134-S	Sink in Kindergarten Classroom 134	0.8	ppb				
38200-134-SWB	Sink with Bubbler in Kindergarten Classroom 134	0.8	ppb			0.3	ppb
38200-130-SWB	Sink with Bubbler in Kindergarten Classroom 130	0.9	ppb			0.2	ppb
38200-130-S	Sink in Kindergarten Classroom 130	1.1	ppb				
38200-122-SWB	Sink with Bubbler in Clinic	1.9	ppb			0.9	ppb
38200-122-S	Sink in Clinic	3.2	ppb			0.3	ppb
38200-120H-DFL	Hallway Drinking Fountain across from Gym/Left	0.3	ppb			<0.1***	ppb
38200-120H-DFR	Hallway Drinking Fountain across from Gym/Right	0.8	ppb			<0.1***	ppb
38200-105H-DF	Hallway Drinking Fountain across from Book Room	1.0	ppb			1.0	ppb
38200-100-DF	Drinking Fountain in Cafeteria	0.6	ppb			2.0	ppb
38200-153-S1	Food Service Sink-Food Prep	59.6	ppb	Fixture Removed			
38200-153-S2	Food Service Sink-Food Prep	22.0	ppb	7.0	ppb	5.2	ppb
38200-153-S3	Food Service Sink-Wash/Rinse	15.6	ppb	5.9	ppb		
38200-153-S4	Food Service Sink-Wash/Rinse	17.0	ppb	7.9	ppb		
38200-153-S5	Food Service Sink-Sprayer	3.6	ppb				
38200-153-S6	Food Service Sink-Hand Sink	13.9	ppb				
38200-102-S1	Sink in Work Room 102	7.4	ppb			10.3	ppb
38200-102-S2	Sink in Work Room 102	10.7	ppb			10.3	ppb
38200-192H-S1	Hallway Sink across from Classroom W1	1.8	ppb				
38200-192H-SWB1	Hallway Sink with Bubbler across from Classroom W1	2.3	ppb			1.5	ppb
38200-192H-S2	Hallway Sink across from Classroom W1	3.7	ppb				
38200-192H-SWB2	Hallway Sink with Bubbler across from Classroom W1	1.5	ppb			1.3	ppb
38200-175H-SWB	Hallway Sink with Bubbler across near Classroom N4	1.6	ppb			2.3	ppb
38200-175H-S	Hallway Sink near Classroom N4	5.0	ppb				
38200-165H-S	Hallway Sink across from Classroom S3	2.0	ppb				
38200-165H-SWB	Hallway Sink with Bubbler across from Classroom S3	0.8	ppb			0.9	ppb
38200-S1-S	Sink in Teacher's Lounge	5.9	ppb			2.5	ppb
38200-138H-DF	Hallway Drinking Fountain near Art Room	8.2	ppb			0.5	ppb
38200-120H-WBFS	Hallway Water Bottle Filling Station					<0.1*** †	ppb
38200-139-S1	Art Room Sink	19.6	ppb	12.6	ppb		
38200-139-S2	Art Room Sink	5.3	ppb				
38200-142H-S	Hallway Sink near Library	1.6	ppb				
38200-142H-SWB	Hallway Sink with Bubbler near Library	1.7	ppb			5.2	ppb
* Resampling results after elevated fixtures were removed and replaced.							
** Resampling results were from samples collected on 5/18/18 as part of an ongoing five-year rotation of lead testing.							
*** This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.							
† This fixture was sampled for the first time on 5/18/18.							