

Thomson Elementary School		Sampled 6/26/20 <sup>†</sup>		Resampled 7/10/20 <sup>‡</sup>	
CustomerSampleNumber	Description	Lead Result	Units	Lead Result	Units
43900-004H-DF	Hallway Drinking Fountain near Art Room	8.7	ppb		
43900-001-S	Sink in Kindergarten Classroom 001	3.5	ppb		
43900-001-SWB	Sink with Bubbler in Kindergarten Classroom 001	3.5	ppb		
43900-002-S	Sink in Kindergarten Classroom 002	2.8	ppb		
43900-002-SWB	Sink with Bubbler in Kindergarten Classroom 002	3.6	ppb		
43900-81H-S	Hallway Sink across from Main Office	3.5	ppb		
43900-81H-SWB	Hallway Sink with Bubbler across from the Main Office	3.3	ppb		
43900-060-S	Sink in Clinic	1.3	ppb		
43900-060-SWB	Sink with Bubbler in Clinic	0.9	ppb		
43900-040-S	Sink in Office next to Principal's Office	6.5	ppb		
43900-071H-S2	Hallway Sink across from Kitchen	6.1	ppb		
43900-071H-SWB2	Hallway Sink with Bubbler across from Kitchen	2.8	ppb		
43900-071H-S1	Hallway Sink across from Kitchen	2.3	ppb		
43900-071H-SWB1	Hallway Sink with Bubbler across from Kitchen	2.4	ppb		
43900-004-S1	Art Room Sink	0.9*	ppb		
43900-004-S2	Art Room Sink	1.1*	ppb		
43900-74-S	Sink in Library Work Room	5.7*	ppb		
43900-009-S	Sink in Classroom 009	0.4	ppb		
43900-010H-S	Hallway Sink across from Classroom 010	2.9	ppb		
43900-010H-SWB	Hallway Sink with Bubbler across from Classroom 010	3.7	ppb		
43900-011-S	Sink in Classroom 011	15.5	ppb	1.6	ppb
43900-013-S	Sink in Classroom 013	0.6	ppb		
43900-014H-S	Sink in Hallway across from Classroom 014	2.1	ppb		
43900-014H-SWB	Hallway Sink with Bubbler across from Classroom 014	3.6	ppb		
43900-015-S	Sink in Classroom 015	0.3	ppb		
43900-017-S	Sink in Classroom 017	10.6	ppb		
43900-031-S1	Food Service Sink-Food Prep	Fixture Removed			
43900-031-S2	Food Service Sink-Food Prep	7.0	ppb		
43900-031-S3	Food Service Sink-Wash/Rinse	9.7*	ppb		
43900-031-S4	Food Service Sink-Wash/Rinse	8.1***	ppb		
43900-031-S5	Food Service Sink- Sprayer	12.6***	ppb		
43900-031-S6	Food Service Sink- Hand Sink	8.0***	ppb		
43900-030-S	Sink in Cafeteria	0.4	ppb		
43900-030-SWB	Sink with Bubbler in Cafeteria	1.7	ppb		
43900-108-S	Sink in Teacher's Lounge	4.0	ppb		
43900-021-S	Sink in Classroom 021	4.2	ppb		
43900-021-SWB	Sink with Bubbler in Classroom 021	0.2	ppb		
43900-023-S	Sink in Classroom 023	0.3	ppb		
43900-023-SWB	Sink with Bubbler in Classroom 023	<0.1**	ppb		
43900-120H-DF	Hallway Drinking Fountain across from Rooms 024 and 026	0.3	ppb		
43900-025-S	Sink in Classroom 025	9.0	ppb		
43900-025-SWB	Sink with Bubbler in Classroom 025	0.2	ppb		
43900-027-S	Sink in Classroom 027	10.6	ppb		
43900-027-SWB	Sink with Bubbler in Classroom 027	<0.1**	ppb		
43900-028-S	Sink in Classroom 028	0.3	ppb		
43900-028-SWB	Sink with Bubbler in Classroom 028	0.2	ppb		
43900-026-S	Sink in Classroom 026	0.8	ppb		
43900-026-SWB	Sink with Bubbler in Classroom 026	0.2	ppb		
43900-024-S	Sink in Classroom 024	0.4	ppb		
43900-024-SWB	Sink with Bubbler in Classroom 024	0.3	ppb		
43900-022-S	Sink in Classroom 022	2.6	ppb		
43900-022-SWB	Sink with Bubbler in Classroom 022	0.3	ppb		
43900-020-SWB	Sink with Bubbler in Classroom 020	0.2	ppb		
* Sampled on 7/14/16					
** This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.					
*** Resampling results on 8/24/16 after elevelad fixture was removed and replaced.					
‡ Resampling results on 7/10/20 after elevelad fixture was repaired.					
† Sampled as part of Jeffco's ongoing 5 year sampling program.					