

Windy Peak		Sampled 5/24/2022	Status
CustomerSampleNumber	Description	Lead Results (ppb)	
59200-Main Office-S	Sink in Main Office	<0.1*	
59200-Astronomy-DF	Drinking Fountain in Astronomy Bldg	not in use	
59200-Dining Hall-Kitchen-S3	Faucet on Left over 3-Basin Sink in Dining Hall Kitchen	1.9	
59200-Dining Hall-Kitchen-S4	Faucet on Right over 3-Basin Sink in Dining Hall Kitchen	4.7	
59200-2022-Dining Hall-WBFSL	59200-2022-Dining Hall-WBFSL	<0.1*	
59200-2022-Dining Hall-WBFS2	59200-2022-Dining Hall-WBFS2	<0.1*	
59200-Dining Hall-Entrance-DF	Drinking Fountain in Dining Hall Entrance	0.1	
59200-Geology-DF	Drinking Fountain in Geology Classroom in Barn	not in use	
59200-Spigot	Spigot near Clinic	16.1	Repairs pending
59200-Clinic-S	Sink in Clinic	0.8	
59200-Clinic-Bath-S	Sink in Clinic Restroom	0.5	
59200-LMC-DF	Drinking Fountain in Library	not in use	
59200-Clinic-DF	Drinking Fountain in Clinic	not in use	
* This result is less than 0.1ppb, which is the lowest level that can be reported by the lab			