

PASADENA UNIFIED SCHOOL DISTRICT School Support Services Division

Prepared by Eric Sahakian, based on 6/10/19 meeting with Dr. Brian McDonald, PPD Chief Perez, and PPD Commander Clawson.

Planning	• PUSD's Executive Leadership Cabinet meeting with
Preventing future emergencies or minimizing their effects: Summer 2019	Pasadena PD- Chief Perez and Commander Clawson. • Establish meeting to define roles and responsibilities for district/central office safety managers (group of 8-10).
Preparedness Preparing Table Top Activities: Fall 2019	 Includes staff development on emergency preparedness/active shooter for August 7th- All-district PD. Includes a Table Top activity with all PUSD central office safety managers in conjunction with PUSD staff and Law Enforcement agencies
Response Responding to an active shooter emergency scenario: Spring 2020	 Putting response preparedness plans into action at a designated PUSD school site. Seeking full participation by school site staff, volunteer students, PTA, Law Enforcement Agency, and PUSD Emergency Response Team.
	 Response activities reviewed and "best practices" shared out to the PUSD community.

As requested:


Altadena ES, Longfellow ES, and Madison ES Access Report

Altadena ES

Altadena ES buildings were renovated during the last 20 years under DSA A#'s 103837, 113581, & 112958. There are no major additional ADA access requirements for this site at this time.

Building Exit & Access notes:

- 1. 2nd floor emergency exit staircase hand rail and guard rails to existing parking doesn't comply with requirements.
- 2. The double exit gate at far west of the school main entry needs to have PHWR. The existing HWR doesn't comply with ADA and building emergency exit regulations.
- 3. The double gate entry and PHWR at east of the main entry is damaged. To maintain the emergency exit function, district needs to replace the existing HWR & repair the gate properly.
- 4. The only issue with Altadena ES is the lack of adequate parking for staff and/or visitors. As you know, this school has only three (3) standard and one (1) ADA access parking. We might want to use some of the unused upper school yard and create additional



Longfellow ES

Longfellow ES is a combination of three (3) buildings; buildings A, B, and preschool building. **Building A** houses school administration offices, school auditorium, and classrooms. This building was partially remodeled under DSA A#03-103919.

ADA access and code deficiencies:

- 1. Steps at main entry of school from Washington Blvd are missing handrails.
- 2. Three (3) exterior emergency exit staircases from 1st & 2nd floors to ground level are missing guard rails and installed hand rails do not comply with regulations.
- 3. Auditorium stage exterior emergency exit stars railing doesn't comply with regulations.
- 4. Needs major maintenance and HWR adjustment for all exterior exit doors.
- 5. There are two (2) auditorium occupancy sings one states, "maximum occupancy 312 persons" and the 2nd one shows "443 persons for assembly". Need to clarify which occupancy sign is accurate and remove the incorrect sign.
- 6. The installed handmade wooden fire hose cabinets do not comply with NFPA requirements and elevations of the cabinets do not comply with code.
- 7. Most of the installed fire extinguishers elevations do not comply with regulations. In most of the classrooms fire extinguishers are not installed within five (5) feet of door/exit, and in some rooms, they are hidden behind furniture's and not visible as you walk in.
- 8. Classroom 108 double doors swing into the classroom. Fire exit regulation states that classroom doors must swing out and double doors may need panic HWR.
- 9. Only one of the cafeteria double exit doors have panic HWR and the 2nd swing doesn't have any HWR.
- 10. North exterior exit doors from building to lower school yard do not have minimum of 36in landing as required by code.
- 11. West stairs railing from lower play yard to upper yard doesn't comply with access regulations.
- 12. For safety of maintenance crew, the staircase going down to basement mechanical room needs proper handrail.

Building B is a relatively new construction built under DSA A#03-103919 and complies with year 2000 code requirements.

Maintenance deficiencies:

- 1. Room 100 exterior emergency exit door is not functioning and needs maintenance.
- 2. Upper level east deck waterproofing is damaged, and rainwater/moisture is leaking into the electrical room bellow. This has damaged the fire rating assembly of the ceiling drywall.
- 3. Electrical room fire damper installation is missing the angle supports and needs immediate correction.

The preschool building was renovated and complies with requirements of year 2000 code. Maintenance deficiencies:

- 1. The main entry door HWR may need adjustment or replacement.
- 2. The yard gate HWR needs maintenance or replacement and new door closure.
- 3. Room #2 ceiling partially separated, and the light fixture cover is hanging.

Madison ES

Madison ES site is a combination of four (4) buildings

Building A is a two (2) story building, and it holds administration offices, elementary classrooms, kindergarten classrooms, and auditorium.

The original 1930's two (2) story building was remodeled under A#03-103861 based on 2000 code. As a result of the construction, the building restrooms are in compliance with ADA regulations, the 2nd floor access is provided by elevator, the wheelchair lift is providing access to auditorium stage, and all classrooms have ADA sinks with combination of drinking fountain. Building "A" Deficiencies:

- 1. There is no ADA access to school main entry & auditorium building from school address side *E. Ashtabula St.*
- 2. One of the two auditorium exits to *E. Ashtabula St.* is closed off therefore the emergency exit to street based on occupancy load of the auditorium doesn't exist anymore.
- 3. South 1/3rd of auditorium interior floor near exit doors to *E. Ashtabula St.* has been raised 6 inches by a wooden platform, therefore exit access is blocked. Recommendation is to remove wooden platform and open the blocked entry door to have the original required exits to street.
- 4. The hand railings of the east and west interior stairs to 2nd floor do not comply with regulations.
- 5. The 2nd floor east and west exterior emergency exit staircase railings do not comply with regulations.
- 6. We recommend adding ADA automatic door operators at the main double-door building entry from yard.
- 7. Noticed that the 1st floor hallway none-rated double doors which separate kindergarten section of the building from elementary, is held in open position by a chair at all times. In case of an emergency, this will create a hazardous condition. Remove the double doors if this separation is not needed or address the school staff to remove the chair from path of exit/travel.
- 8. ^{1st} floor kindergarten hallway has one direct exit to exterior school yard refuge area, and this exit doesn't have wheelchairs access.
- 9. Kindergarten room #129 has two (2) doors opening to hallway and one is blocked off. This room also has three (3) emergency exits to yard and none of the exits have wheelchair access.
- 10. For safety of maintenance crew, the staircase going down to basement mechanical room needs proper handrail.

Building B: Kitchen and cafeteria lunchroom with small lunch shelter canopy structure located at south of the building.

Lunchroom has five (5) entry/exit doors, and three (3) of them do not comply with code and/or access regulations. The other two (2) exits may need improvement such as safety railing at exterior landing.


Building C: Preschool Childcare Center A#03-113534 certified on 01/06/2015 was a recently built new structure and compiles with ADA requirement of 2010. No action is required at this time.

Building D: classroom building A#03-103861 certified on 09/15/2009 is a relatively new structure and compiles with year 2000 ADA requirements. No action is required at this time.

Comments:

In August of 2011, DSA issued permit A#03-113778 for bus drop off at *Buckeye St.* and two (2) large lunch shelter canopy construction in courtyard between the cafeteria building and D building. This permit was not constructed and was canceled/voided on May of 2016.

With additional students transferring to Madison ES and possibly additional busing, the district may need to think about re-activating the above mentioned permit to have bus access to the existing single car drop off zone and to have lunch shelter for added students.



For Reference: Site Plan of A#03-113778



PUSD CAC Monday October 28th, 2019

JAMES MADISON ELEMENTARY ACCESSIBILITY UPGRADES



ADDRESS SCHOOL ACCESSIBILITY (ADA) UPGRADES

- It is the intent of the California Legislature that the building standards published in the California Building where the general public is concerned requirements to ensure that buildings, structures, and related facilities are accessible to, and functional for, every member of the public, so as to provide equal opportunity to access public accommodations. Standards Code (Title 24) relating to accessibility by people with disabilities shall be used as minimum Access is to be provided to, through, and within the buildings, without loss of function, space, or facility
- The Division of the State Architect (DSA) promulgates California Building Code (CBC) provisions to government buildings and facilities, privately owned public accommodations and commercial facilities, and address accessibility for persons with disabilities. These provisions are applicable to State and local public housing.

ADDRESS SCHOOL ACCESSIBILITY (ADA) UPGRADES

Site Access:

- There is no ADA access to school main entry & auditorium building from school address side E. Ashtabula St. Recommend providing new stair/ramp access with gathering space afront auditorium and main entry
- ADA Path of Travel: The site currently has grade differentials or physical steps at most exterior door locations, access point. Recommend constructing new stair and/or ramp combinations for ADA access at all exterior specifically at Bldg's A + B. The interior courtyard also has a raised step from the concrete walkway down to the interior courtyard that would require an accessible ramp or sloped sidewalk to make an ADA compliant
- Paving at path-of-travel within the campus (A/C & concrete) have been patched repaired with various replace with complaint slopes modernization/maintenance upgrades work and is inconsistent in slope and appearance. Recommend to



ADDRESS SCHOOL ACCESSIBILITY (ADA) UPGRADES

Building A:

- One of the two auditorium exits to E. Ashtabula St. is closed off therefore the emergency exit to street based on occupancy load of the auditorium doesn't exist anymore
- South 1/3 of auditorium interior floor near exit doors to E. Ashtabula St. has been raised 6 inches by a wooden blocked entry door to have the original required exits to street. platform, therefore exit access is blocked. Recommendation is to remove wooden platform and open the
- stairs to 2nd floor do not comply with regulations The hand railings of the east and west interior stairs, interior maintenance stairs and exterior emergency exit
- Recommend adding ADA automatic door operators at the main double-door building entry from yard and building C main double door entry to courtyard
- Recommend to remove double doors between kindergarten corridor and Building A main corridor.
- Provide accessible access to exterior directly from Kindergarten exits



ADDRESS SCHOOL ACCESSIBILITY (ADA) UPGRADES

Building B:

Kitchen and cafeteria lunchroom with small lunch shelter canopy structure located at south of the regulations. The other two (2) exits may need improvement such as safety railing at exterior landing. building. Lunchroom has five (5) entry/exit doors, and three (3) of them do not comply with code and/or access

Building C:


 Preschool Childcare Center A#03-113534 certified on 01/06/2015 was a recently built new structure and compiles with ADA requirement of 2010. No action is required at this time.

Building D:

Classroom building A#03-103861 certified on 09/15/2009 is a relatively new structure and compiles with year 2000 ADA requirements. No action is required at this time



JAMES MADISON ELEMENTARY SCHOOL FACILITIES ASSESSMENT REPORT



MADISON

AVENUE

ADA ACCESSIBILITY UPGRADES

PRIORITY 1 (0-5 YEARS)

JAMES MADISON ELEMENTARY ACCESSIBILITY UPGRADES

EXISTING SITE PLAN SITE PLAN REPLECTS MAJOR PRIORITY ITEMS. REFER TO FOLLOWING PAGE FOR COMPLETE PRIORITIZED SCOPE OF ALL DISCIPLINES




TIMELINE

PLANNING PROCESS



PROJECT DESIGN/CONSTRUCTION PROCESS



Commerce Scale Methy Parise Grape Grap	<blank></blank>		PO	motor -installed			1450000							TOTO TOTO			
Columb C			ito	blower whee								Franklin Flomentary			Closed Work Orders		248427
Control Delivery Control Del			nhled	blower -to or													
The contract of the contract o			or and	/remove mot													
Company Comp			isolated	moor burned													
The control of the co			blower	/found a dua													room.
Control Cont	<blank></blank>						6/2//2019	0/20/2019									smelled in
Control Cont	<blank></blank>	SAF	salvador			11202019	100	ODEDO		Conference Doom	Faculty ounge	Field Elementary	Ibarra, Sabas	_	Closed Work Orders		320588 Rubber bu
The control of the co			John Done			Theman	OF OCISCIE	7/26/2019				Eliot Middle	Drohan, Miceal	Fire Alarm System	Closed Work Orders	_	321241 Fire Alarm
Control Cont				with new on													
Signification and series of the series of th	<blank></blank>	SAF	Micea			6/26/2019	6/27/2019	6/26/2019	<blank> 1</blank>	A 153		Education Center	Dronan, Miceal	Fire Alarm System	Closed AAOLY Cldeis	bector	Trouble
Experimental (III) Registration (III) Regist	<blank></blank>	SAF	re-Ersilia		1 \$42.	9/11/2018	9/12/2018	9/11/2018	<blank></blank>	Lights	rai Ning Lot	Encountry Califai	Conscionation, and				the so. car
Expression (1) Control (1) Con			and and	/straighten o									Constraint	Electrical	Closed Work Orders		
Experimental Modern Mod	Spianks									Office & C3				Series de la constante de la c		7 8	to the porc
Seguente de la Control						10/11/2018	10/11/2018	10/11/2018		Outside by Custodial		Edison Elementary	Hernandez, Nicolas	Heating/Ventilation	Closed Work Orders		313436 AC unit. P
Singhiller, M. 1949. Models Mo	<blank></blank>					11/5/2018	11/6/2018	11/5/2018	<blank> 1</blank>	Alma Fuerte Room		Edison Elementary	McKinney, Larry	Electrical	Closed Work Orders		outlets in c
Same Same May Control Code C			pilet spots	,tighten all t												Can	tightened.
Series Se			and	faculty toiled												olts	loose, 2 by
Signification (In the Control	Oldrin		9	× (Women's Restrooms	1					very	is moving,
Sinching Mark Mark Mark Mark Mark Mark Mark Mark	∠Blank>					11/2/2018	11/2/2018	11/2/2018		Main Bldg. Mens &	Restroom (Staff)	Edison Elementary	Jones, Charles	Plumbing	Closed Work Orders	-	
Company Comp	<blank></blank>	SAF	5			3/7/2019	4/9/2019	3/7/2019			Grounds	Edison Elementary	Cilca, Saillia		Ciceron Ascis Circle		need to be
Elementa della Control			D to see	lamps to LE		1						ndion nionostore	llos		Closed Work Orders	ß	
Company of the Control Contr	<blank></blank>	SAF				4/10/2019	#11/2019									vill be	program w
Singhame and protection of the control of the contr	-		-				174	4/10/2019	<blank></blank>	C 4		Edison Elementary	Martinez, Hugo	_	Closed Work Orders		318407 Room is d
Control Cont	<blank></blank>	SAF	_			5/23/2019	5/23/2019	5/23/2019		Bungalow C Upper		Edison Elementary	Loera, Sam		Closed Work Orders		area adiac
Common Color Control			Tire ok at	reinstalled.												_	odoroo Thoroic o
Sinches Sinches (2004) Clearly (2004																rear	Driver side
Sub-news in Ending Claric New Cours (Cours) (C	<blank></blank>	SAF	bire, and			4/30/2019	5/3/2019	4/30/2019				DSC Garage	Anderson, Glenford		Closed Work Orders		318946 Venicle: 5
Sub-reason			moved	Seat belt re													in.
Contraction Contra			nplete.	replace, co												latch	Belt wont
Submission Sulfry Sulfr	<blank></blank>	SAF	7			4/29/2019	5/15/2019	4/29/2019				Coc Garage	Orderson, Germond		CIONES AND CINE		
Schwere and Service Control Se	<blank></blank>	SAF	Ray		\$0.0	10/7/2019	10/7/2019	10000		100011 200		Fundamental	Anderson Clanford		Closed Work Orders		upper hate
Controlations Golffee Control			wn weeds	and blow d				10770010		Room 29	Classroom	Don Benito		_	Closed Work Orders		324171 Secure th
Controlation of the Controlation of the Controlation of Contro	<blank></blank>	SAF	Gary			6/7/2019	6/10/2019	6/7/2019		6.		District Service Center	villegas, Juan		CIOCOL STORY CIOCOL		possible, I
Contract of Mark Contract Cont	College	9	×							Facilities offices			CH .		Closed Mark Order	hte Cafety	220105 As soon a
Contravers and Series (Contravers) (Contrave	<rlank></rlank>	SAF	1		1 \$38	10/3/2018	11/15/2018	10/3/2018		Outside around		District Service Center	Ulloa, Jaime		Closed Work Orders	just Safety	313217 Please ad
Chicare de Chicare de Chicare (Chicare) Chicare (C			thts wiring and	hallways lig /traced the													unsafe.
Contenova State Contenova St	<blank></blank>				7	100000000000000000000000000000000000000										out	Very dark
Content Mork Order Salety Content Mork Order	2		ılt area			11/29/2018	11/29/2018	11/29/2018		A-bldg Main Hallway	Hallway/Corridor	Cleveland Elementary	Martinez, Hugo		Closed Work Orden		314638 Main hally
Content Note Cont	<blank></blank>	SA	Priete			3/12/2019	3/12/2019	3/12/2019			Electrical Room	Cleveland Elementary	Ulloa, Jaime		Closed Work Orden		31 / /3/ Clean the Electrical
Configuence Safety Control Configuence Safety Control Configuence Safety Control Configuence Safety Control Co	<blank></blank>					11202010										a. a	
Contributions Safety Contribution Safety Contr	Collection		-			70000	27063010	61003672		Stratford Academy		Burbank Elementary	Drohan, Miceal	_	Closed Work Order		321268 Fire Pane
Contribution Safety Condesive Configuration Safety	ARIANKA		-			5/6/2019	5/8/2019	5/6/2019		Statford School		Burbank Elementary	Drohan, Miceal	_	Closed Work Order	_	319127 Fire Dete
Configeration Safety Closed Work Orders Safety Closed Work Orders Cappentry Safety Configeration Safety Closed Work Orders Safety	<blank></blank>					4/19/2019	4/19/2019	4/19/2019				Burbank Elementary	Ulloa, Jaime		Closed Work Order	P_	duct dete
Contine man guille in					4	-				School				-			
Contribution. Self-ly Contribution Self-ly Contribu						4/10/2019	4/10/2019	4/10/2019		Front of Stratord		Burbank Elementary	Martinez, Erik		Closed Work Order		
Contrierrore Safety Closed Work Orders Carpentry Safety Closed Work Orders Carpentry Safety Control Safety Control Safety Control Safety Control Safety Closed Work Orders Carpentry Safety Carpentry Safety Closed Work Orders Carpentry Safety Closed Work Orders Carpentry Safety Carpentry Carpe						3/1/2019	4/11/2019			115	Office	Burbank Elementary	Trapani, Jeremy		Closed Work Order	neck for Safety	317420 Please ch
Confrence Safety Closed Work Orders Carpentry Carpentry Closed Work Orders Carpentry Carpen			_		\$0.	10/9/2018	10/10/2018	10/9/2018	<blank> 1</blank>	Gymnasium & Locke	Gym	Blair HS	Green, Kay		Closed Work Order	her	Extinguis
Conference Safety Closed Work Orders Carpentry Seety Lecroard Conference Room Room Ballety Conference Room Room Ballety Conference Room Room Ballety Conference Room Room Room Room Room Room Room Roo	<blank></blank>				\$0.	10/9/2018	10/24/2018	109/2018						-	Cloud Mark Out		Gym, up
Conference Safety Closed Work Orders Carpentry Seeky, Lecrand Conference Room Abliga 2nd 206 Conference Room Balliday Conference			Ø.	mulch and				1000000			Gym	Blair HS	Drohan, Miceal	_	Closed Work Order		313383 Disable t
Conference Safety Closed Work Orders Carpentry Seeky, Lecrand Carpentry Conference Room A-Bligg 2nd 206 Calpentry Carpentry Carpent			ilding.	sides of bu												t taken	this is no
Conference Safety Closed Work Orders Carpentry Seeky, Lecnard Glank- Room Bales, Mod Carpentry Conference Room A-Blig 2nd 205 Clased Work Orders Carpentry Conference Room A-Blig 2nd 205 Clased Work Orders Carpentry Conference Room A-Blig 2nd 205 Clased Work Orders Pest Control Alladems Elementary Classroom Building A and B Classroom Building			and east	A & b bldg												dents ool if	from sch
Conference Safety Clased Work Orders Carpentry Seely, Leonard Classroom A-Big 2nd 206 Callanko Conference Room A-Big 2nd 206 Callanko Callank			_	plants on												d will	upsetan
Conference Safety Closed Work Orders Carpentry Seek, Leonard Seek Conference Room A-Big 2nd 205 Conference Room Building A and B Caleston Seek Seek Conference Room Building A and B Caleston Seek Seek Seek Seek Seek Seek Seek See					\$0.	8102/1/11	11/3/2010									es ire	mosquito
Conference Safety Clear Work Orders Carpentry Safety Clear Work Orders Carpentry Safety Conference Room A-Big 2nd 206 Canterno Safety Conference Room A-Big 2nd			-		1	1440040	11/2/2010			Building A and B	Classroom	Altadena Elementary	•		Closed Work Orde		314036 Still have
			4			12/10/2018	12/12/2018	121012010									

\$21.18	0.5	1/17/2019	1/17/2019	1/17/2019	ık> 0	Kitchen <blank></blank>		Mair High		_		bleachers need
	12	10/10/2018	10/10/2018	10/10/2018	ik> 0	Football Field <blank></blank>	Athletic Field	Muir High	Green, Ray	Closed Work Orders Construction	Safety Close	
						Canteen		ALC: INC.			Salety	students who daily walk over
	6	9/7/2018	10/16/2018	9/7/2018	39			Muir High	Charles	Closed Work Orders Construction		Alarm.
	2	6/7/2019	6/7/2019	6/7/2019	0	<blank></blank>		Muir High	Miceal			the Library are
	2	6/10/2019	6/11/2019	6/10/2019	7	<blank></blank>	Library	McKinley	Hernandez, Nicolas	Closed Work Orders Heating/Ventilation	Safety Close	320199 PEF students in S
												Safety Hazard
				GIZIZZO IO	~	Fence		McKinley	Green, Ray	Closed Work Orders Construction	Safety	
	2	8/27/2018	8100/2014	4/18/2019 8/27/2018				McKinley	Villegas, Juan	Closed Work Orders Grounds	Safety Close	
1200	۵	1467740										Needs repair. City tree fell on to school property.
	28	1/22/2019	1/23/2019	1/22/2019	7	On Oak Knoll Side <blank></blank>		Secondary McKinley		- 1		floor at the door Fence damaged.
	9	4/10/2019	5/31/2019	4/10/2019	51	A216 <blank></blank>	Classroom	Marshall Fundamental	Trapani, Jeremy	Closed Work Orders Carpentry	Safety Closes	318417 Hello there! The S
		8/28/2019	8/28/2019	8/28/2019	0	A-Bldg Underneath <blank> the Bridge</blank>		Marshall Fundamental Secondary	-	Closed Work Orders Pest Control	Safety Closed	322755 Live Active S WASP Nest URGENT!
		WINZIN.	77272019	7/2/2019	0	Kinder Play Stucture <blank></blank>	Playground	Madison Elementary	-	Closed Work Orders Construction	Safety Closed	320/32 Missing piece on S climbing structure exposing bolts.
		3/12/2019	4/3/2019	3/12/2019		Tk - Kinder Play <blank> structure</blank>	Playground T	Madison Elementary	-	Closed Work Orders Construction	Safety Closed	
		9/13/2018	3/13/2019	9/13/2018		D building <blank></blank>	Restroom (Boys)	Madison Elementary	Seely, Leonard	Closed Work Orders Carpentry	Safety Closed	312555 Urgent Please S
		No.	10/24/2010	10/3/2018		A205 <blank></blank>	Classroom	Madison Elementary		Closed Work Orders Pest Control	Safety Closes	7
1		9/10/2010	8/20/2018	9/18/2018		main building/exterior <blank></blank>		Longfellow Elementary	Loera, Sam	Closed Work Orders Construction	Safety Close	
100	4			77 77 77 77 77 77 77 77 77 77 77 77 77	ð	Siank	Athletic Field	Longfellow Elementary	Ulloa, Jaime	Closed Work Orders Electrical	Safety Closed	310453 Check in with S. Head Custodian Sal. The electrical outlet behind the
	15	7/17/2018	877678	77.77		a i	ZI Z	ongfellow Elementary	Stratis, Mark	Closed Work Orders Plumbing	Safety Closed	п
1	2	5/16/2019	6/7/2019	5/16/2019	3 8		Restroom (Girls) N	_ongfellow Elementary	Luiten, Stephen			Handicap stall one bolt holding
	i	5/16/2019	6/5/2019	5/16/2019			Restroom (Boys) N	Longfellow Elementary	Luiten, Stephen	Closed Work Orders Plumbing	Safety Closed	
	1	5/16/2019	6/3/2019	5/16/2019		Main Bldg Upstairs <blank></blank>	Restroom (Boys) N	Center Longfellow Elementary	Luiten, Stephen	Closed Work Orders Plumbing	Safety Closed	
	-	2/12/2019	2/12/2019	2/12/2019	0	<blank></blank>		ongfellow Childrens	Luiten, Stephen	ed Work Orders Plumbing	Safety Closed	
						NOTE:	Cassing	uniarson Elemenias y	Darra, Sabas	Closed Work Orders Heating) vertuation (Air Conditioning	Salery	31983 HVAC system Standing noise (sounds like a halicoptar) causing observed and the coptary observed and the vents and exposed above
	7	1/10/2019	1/15/2019	2/22/2019	5 3	<blank></blank>		Jackson Elementary	al	+		We conducted a
	1.0	3/28/2019	4/4/2019	3/28/2019	> 7	girls restroom closest <blank> to Cafeteria</blank>	Restroom (Girls) g	Jackson Elementary	Trapani, Jeremy	ed Work Orders Carpentry	Safety Closed	
	77		4/1/7/2019	10/10/2018	183	<blank></blank>		Jackson Elementary	Dunning, Michael	ed Work Orders Key and Lock	Safety Closed	s at
180	S .	10/10/2018	11112010	וטו ווצטוא		D-building/1st fir <blank< td=""><td>Restroom (Boys)</td><td>Hamilton Elementary</td><td>Trapani, Jeremy</td><td>Closed Work Orders Carpentry</td><td>Safety Close</td><td>313575 Have mold in S ceiling needs to be removed 3rd incident of mold</td></blank<>	Restroom (Boys)	Hamilton Elementary	Trapani, Jeremy	Closed Work Orders Carpentry	Safety Close	313575 Have mold in S ceiling needs to be removed 3rd incident of mold
	4	10/17/2018	01022010	81342018		room 108/exit door <blank></blank>		Hamilton Elementary		Closed Work Orders Pest Control	Safety Closed	311183 Have a wasp S nest next to, above door, very
		8/13/2018	0.14.9.004.0									safety issues. Floor lifting at seam
		OLOZIIZI O	7/31/2018	7/27/2018	4	B-1 <blank></blank>	Portables	Hamilton Elementary	Trapani, Jeremy	Closed Work Orders Carpentry	Safety Close	

86	85	84	83	83	81	80	79	õ	79	76	75	74	73		72		70	9	8 8	67	06	8	ğ	2 2	3 6	61	60	59	58	
Clean or replace	Apply seal coat	Trouble call Fire	322477 Place a latch on Safety	PARKING LOT LIGHTS:	315364 NORTH Safety	318547 Mrs. Newhart, Safety the teacher in	316228 Door not Safety securing/latchin	bottom of	pane in the	We have an outlet that isn't	Window stuck open.	the steel 9 1/2"	The Roof Access Room door needs to be fixed. Unable to open		313597 Please remove Safety the safe, take back to lock shop.	Large Bee Hive in the tree, between the old Cafeteria and the A-Bldg.	316261 Fence is wobbly, Safety safety hazard. Please secure. After in order for	outlet in the Resource	7" Gap in railing by ramp.	311679 The bottom of Safety	323767 Principal Mrs. Safety Lewis would like the entire A and B building the adding spiders on an A- Monday.	319809 lower level 319809 lower level branch limb falling off-			314951 We need a foam Safety		318699 Fire Alarm went Safety off:	317778 The Women's Safety faculty restroom		box, concrete lid
		Complete Fire Alarm System			Closed Work Orders Electrical	Closed Work Orders Carpentry	Closed Work Orders Key and Lock			1	Closed Work Orders Carpentry				Closed Work Orders Construction		Closed Work Orders Construction	Ciders			Closed Work Orders Pest Control	Closed Work Orders Grounds	Clased Work Orders Electrical	_	-	1 1	Closed Work Orders Fire Alarm System	Clased Work Orders Plumbing		
Do	-				Ulloa, Jaime ZZ	Trapani, Jeremy ZZ	Westad, Matthew ZZ				Seely, Leonard W		my		Green, Ray W	п λ	Green, Ray W	ngo		emy		Villegas, Juan S	marunez, rugo S				Drohan, Miceal	Farber, Robert M	Stratis, Mark M	bert
Don Benito	District Service Center	Cleveland Elementary	Cleveland Elementary	2222Sierra Madre Elementary	ZZZZ *Do NOT Use*	ZZZZ *Do NOT Use* ZZZZSierra Madre	ZZZZ *Do NOT Use* ZZZZSierra Madre Elamentary	Center	Washington Middle	Washington Middle	Washington Middle	Washington Middle	Washington Elementary		Washington Childrens Center	Accelerated Elementary	Washington Accelerated Elementary	Accelerated Elementary	Washington Accelerated Elementary	Sierra Madre Upper	Sierra Madre Lower	San Rafael Elementary	San Karael Elementary	an Kafael lementary	San Rafael Elementary	Rose City High	Pasadena High	Muir High	Muir High	Muli righ
Classroom			Building					Noteri	Classroom	Classroom			Roof					Office	O.E.	Main Entrance	Hallway/Corridor	Lower Level	Classroom	1st Floor	1st Floor	Grounds		Restroom (Women)		
Room 29		E-300	NOOH 12	Dom 13		1777	A-111, C-123	200		117	Floor)2 to	ğ				Bungalows next to new C-bldg.	Ms. Bevy	Area	Office	All interior Offices, Classrooms, Closets, etc.	lower playground	2 working					PCC building D 1st floor		Canteen, across from
<blank> 0</blank>		<blank> 0</blank>	<blank> 8</blank>		<blank> 0</blank>	<blank> 31</blank>	<blank> 0</blank>	Oldino	CBlank>	<blank> 0</blank>	<blank> 0</blank>	<blank> 23</blank>	<blank> 8</blank>		<blank> 1</blank>	Constitution	<blank> 0</blank>	Coank			-Blank> 14	cBlank> 1	chank	<blank> 1</blank>	<blank> 1</blank>	cBlank> 0	<blank> 0</blank>	<blank> 23</blank>	<blank> 0</blank>	Siank
10/7/2019	9/23/2019	10/17/2019	8/21/2019	8707010	12/20/2018	4/15/2019	1/28/2019	22112013	8/19/2019	9/27/2019	5/28/2019	2/26/2019	3/28/2019		10/17/2018		1/29/2019	4/3/2013	7/12/2018	8/22/2018	9242019	5/28/2019	MANANIA	12/6/2018	12/6/2018	7/27/2018	4/19/2019	3/13/2019	11/7/2018	10/18/2018
10/7/2019	9/24/2019	10/17/2019	8/29/2019	מאמקמם	12/20/2018	5/16/2019	1/28/2019	2202019	8/20/2019	9/27/2019	5/28/2019	3/21/2019	4/3/2019		10/18/2018		1/28/2019	49/2019	7/12/2018	8/22/2018	10/8/2019	5/28/2019	2/2/1/2/19	12/7/2018	127/2018	7/27/2018	4/19/2019	4/5/2019	11/7/2018	10/1//2018
10/7/2019	9/23/2019	10/17/2019	8/21/2019	270700	12/20/2018	4/15/2019	1/28/2019	DENZITZ	8/19/2019	9/27/2019	5/28/2019	2/26/2019	3/26/2019		10/17/2018	5.00	1/29/2019	4/8/2019	7/12/2018	8/22/2018	9/24/2019	5/28/2019	2/20/2019	12/6/2018	12/6/2018	7/27/2018	4/19/2019	3/13/2019	11/7/2018	10/16/2018
m m	\$0.00	\$0.00	\$0.00		1 \$38.42	\$21.23	\$26.81	448.06		3 \$128.34	1.5 \$53.60		2.5 \$58.66		12 \$378.54	90,00	4 \$160.32	\$212.54	6 \$207.65	0.1 \$2.12	\$0.00	7.5 \$199.73	2 \$79.02			2 \$66.22	1 \$38.42	3 \$109.38	\$0.00	\$63.22
Ra	a :	-	replace latch on gate Ni	AND RESET TIMES	WENT TO JOB SITE Lir	fixed falling tiles Ge	door adjusted // arr completed	e we	replaced missing Na	0	()			Safe may possibly be moved to Eliot. MS	Oh hold until further N notice. Mike Durning to speak with CC Director.	tree	-	rge ed	-	ğ	Armed Exterminators Treated health office, Rm 76, hallways in A&B bidgs. for spiders Pesticide posting	-	stall a e also	Cover steam pipes 8 with insulation.		Complete	contractor did put sys. on test /also timer programmed as	nagm on neck		and
			Ninfa Mahabir SAFETY		Lindsay Lewis SAFETY	Georgina Tarry SAFETY	arthur anderson SAFETY	Rachel Zavala SAFETY	Molina	Nancy Laguna Molina SAFETY	Leonard Seely SAFETY	on	Pascual SAFETY		Ninfa Mahabir SAFETY	Mario Castro SAFETY	Castro	Maria Romero SAFETY		Tracy Maybank SAFET	Georgina Tarry SAFETY	Jennifer Delgadillo SAFETY	Jennifer Delgadillo SAFETY			rson	Paul Senebandith SAFETY	Nadia Zendejas SAFETY	Marcela Zamorano SAFETY	Rogelio Macias SAFETY
			TY <blank></blank>		TY <blank></blank>	TY <blank></blank>	TY <blank></blank>	-TY <blank></blank>		:TY <blank></blank>	:TY <blank></blank>	:TY <blank></blank>	ETY <blank></blank>		ETY <blank></blank>	Blank		ETY <blank></blank>			ETY <blank></blank>	ETY <blank></blank>	ETY <blank></blank>	ETY <blank></blank>			ETY <blank></blank>	ETY <blank></blank>	ETY <blank></blank>	ETY <blank></blank>

109	108	107	8	8 8	105	104	103	102	101	100	99	98	97	96	95	94		93	92	91	90	89	88	0
314335	324452	322374	322230	200000	CVENCE	320876	322801	319345	324255	322858	321262	323554	322046	319500	319498	311163		320957	321848	321847	321846	321619	310913	300230
314335 Please trim back Safety	324452 Cut weeds, trim Safety	322374 Armed Exterminators	hole right	324343 One of the plass salety	the walkway, 6	320876 Large crack in	322801 outlet box/wire	319345 HAZARDOUS! exposed wires in wall outlet,			321262 Fire Alarm	4 Yellow Taylor Cart needs to	322046 Good morning,	319500 The central brass stem	319499 The Elkoy faucet is leaking at the	311163 Have black mold Safety near ceiling air	Safety issue.	320957 Custodian's cart Safety brakes are not braking.	321848 Light ballast is	321847 Light switch is hard to turn on.	321846 Light switch	321619 Reset Pull		fence needs to
Safety	Safety	Safety	Carety	Safety	Cafaty	Safety	Safety	Safety	Safety	Safety	Safety	Safety	Safety	Safety	Safety	Safety		Safety	Safety	Safety	Safety	Safety	Safety	Carety
Complete	Complete	Complete	Compress	Complete	Complete	Complete	Complete	Complete	Complete	Complete	Complete	Complete	Complete	Complete	Complete	Complete		Complete	Complete	Complete	Complete	Complete	Complete	Compiese
Grounds	Grounds	Key and Lock	Constitution	Construction	Carpentry	Construction	Electrical	Electrical	Heating/Ventilation /Air Conditioning	Painting	Fire Alarm System	Vehicle Maintenance	Carpentry	Plumbing	Plumbing	Heating/Ventilation /Air Conditioning		Vehicle Maintenance	Electrical	Electrical	Electrical	Electrical	Heating/Ventilation /Air Conditioning	College
Villegas, Juan	•		-	1		-	-	Ulloa, Jaime	Pascual,	-	Drohan, Miceal		-	Luiten, Stephen	-	Pham, Mau		Rodas, Rene	-	-	-	-	Aziz, Kamal	-
Willard Childrens	Willard Childrens	Webster Elementary	Accelerated	Washington	Sierra Madre I Inner	Sierra Madre Lower	San Rafael	Pasadena High	Pasadena High	Pasadena High	McKinley	Marshall Fundamental Secondary	Marshall Fundamental Secondary	Longfellow Elementary	Longfellow Elementary	Hamilton Elementary		Eliot Middle	Eliot Middle	Eliot Middle	Eliot Middle	Eliot Middle	Education Center	Edisoli Eigiligilai y
	Yard	Building	Cimeni Coin	Classroom	Gvm			Office	Mechanical Room	Classroom			Gym			Restroom (Boys)			Classroom	Hallway/Corridor	Restroom (Girls)			Cionida
	Willard CC	L-Shaped I		B114	to Km 111	A-Bldg	room 5	A108					Old Gym	Main B	Main Bldg Te Work Room						(Girls) Main Floor	Pull Sta	Room 102	upper &
<b< td=""><td></td><td>L-Shaped Building by Slank> Playground</td><td>Ġ</td><td>AR O</td><td></td><td>Floor Next</td><td></td><td>â</td><td></td><td></td><td><b< td=""><td><b< td=""><td></td><td>Main Bldg Rm 118 <b< td=""><td>achers</td><td>D-building/1st fir <b< td=""><td></td><td>- AB</td><td></td><td>nd FI Nxt</td><td></td><td>Pull Station A019 <bi< td=""><td></td><td>upper & lower levels</td></bi<></td></b<></td></b<></td></b<></td></b<></td></b<>		L-Shaped Building by Slank> Playground	Ġ	AR O		Floor Next		â			<b< td=""><td><b< td=""><td></td><td>Main Bldg Rm 118 <b< td=""><td>achers</td><td>D-building/1st fir <b< td=""><td></td><td>- AB</td><td></td><td>nd FI Nxt</td><td></td><td>Pull Station A019 <bi< td=""><td></td><td>upper & lower levels</td></bi<></td></b<></td></b<></td></b<></td></b<>	<b< td=""><td></td><td>Main Bldg Rm 118 <b< td=""><td>achers</td><td>D-building/1st fir <b< td=""><td></td><td>- AB</td><td></td><td>nd FI Nxt</td><td></td><td>Pull Station A019 <bi< td=""><td></td><td>upper & lower levels</td></bi<></td></b<></td></b<></td></b<>		Main Bldg Rm 118 <b< td=""><td>achers</td><td>D-building/1st fir <b< td=""><td></td><td>- AB</td><td></td><td>nd FI Nxt</td><td></td><td>Pull Station A019 <bi< td=""><td></td><td>upper & lower levels</td></bi<></td></b<></td></b<>	achers	D-building/1st fir <b< td=""><td></td><td>- AB</td><td></td><td>nd FI Nxt</td><td></td><td>Pull Station A019 <bi< td=""><td></td><td>upper & lower levels</td></bi<></td></b<>		- AB		nd FI Nxt		Pull Station A019 <bi< td=""><td></td><td>upper & lower levels</td></bi<>		upper & lower levels
<blank> 0</blank>	<blank> 7</blank>	ank> 3		<blank></blank>		<blank> 1</blank>	<blank> 5</blank>	<blank> 0</blank>		<blank> 0</blank>	<blank> 5</blank>	<blank> 12</blank>	<blank> 26</blank>	<blank> 22</blank>	<blank> 33</blank>	<blank> 1</blank>		<blank> 3</blank>	<blank> 2</blank>	<blank> 2</blank>	<blank> 1</blank>	<blank> 7</blank>	<blank> 36</blank>	C C
11/14/2018	10/14/2019	8/20/2019	G 100 200	8/10/2019	10/10/2019	7/10/2019	8/29/2019	5/13/2019	10/8/2019	8/30/2019	7/26/2019	9/18/2019	8/14/2019	5/16/2019	5/16/2019	8/13/2018		7/15/2019	8/12/2019	8/12/2019	8/12/2019	8/7/2019	8/6/2018	0,23,2019
11/14/2018	10/21/2019	8/23/2019	5	8/21/2019	10/18/2019	7/11/2019	9/3/2019	5/13/2019	10/14/2019	8/30/2019	7/31/2019	9/30/2019	9/9/2019	6/7/2019	6/18/2019	8/14/2018		7/18/2019	8/14/2019	8/14/2019	8/13/2019	8/14/2019	9/11/2018	GEGEOLO
11/14/2018	10/14/2019	8/20/2019		8/19/2019	10/10/20	7/10/2019	8/29/2019	5/13/2019	10/8/2019	8/30/2019	7/26/2019	9/18/2019	8/14/2019	5/16/2019	5/16/2019	8/13/2018		7/15/2019	8/12/2019	8/12/2019	8/12/2019	8/7/2019	8/6/2018	OI ECOI ECO I CO
8	19				9			N					_	1				Ch.					3.5	
\$0.00	\$0.00	\$0.00		\$0.00	\$0.00	\$0.00	\$0.00	\$86,80	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$38.42	\$0.00	\$38.42		\$170.10	\$0.00	\$0.00	\$0.00	\$0.00	\$ 124.01	40.00
completed	Removed weeds blew down area.		then patch with cold	fill hole with base	COLICIDIO	ground down lifting		area , had to install a blank cover, no cover		remove and replace				Cleaned under and found nothing wrong with stem		Checked the vent/ there's no source of water on here! the	the brakes', they were not working, I removed two tres's. The parking brake cable was missing the roller pin. I put if back together and adjusted the brake.	On 7/16 I went to pick up the Taylor cart at Elliot middle school and checked					check both units in 103 and 104, adjusted and tested, hoth working and to	
, Pascual	Ninfa Mahabir	Naria Coleman	+		Tracy Maybank	ng arthur anderson		all a		1 50	+	David Ramirez	Audrey Green	-		-	- "	salvador flores	L	salvador nores	salvador flores		n Kamal Aziz ed,	\vdash
SAFETY	SAFETY				SAFETY	NAFETY	Б	-	SAFETY	CAFETY	SAFETY	SAFELY	SAFETY					0	OAFETY	OATE I	SAFETY	SAFETY	SAFE	
<blank></blank>	<blank></blank>	Control	ARIANKY	<blank></blank>	<blank></blank>	<blank></blank>	<blank></blank>		<blank></blank>	<blank></blank>	<blank></blank>	Spiank	Spiank	Control of the contro	\Diank\	C C C C C C C C C C C C C C C C C C C		Cell	ABlanks	Blank	\ Blank>	<blank></blank>	Chank	