



School Data

Date School Opened: 1998

2019 – 2020 Projected School Year

Enrollment: 1,532

Standard Classrooms: 82

Portable Classrooms: 0

Classrooms Used for Other Programs: 14

Permanent Building Area: 174,884

Facility Capacity: 1759

Revised October 2, 2019

Jesse Bethel High School


1800 Ascot Parkway

Jesse Bethel High School - Background information

Jesse Bethel High School is one of the newest campuses in Vallejo City Unified School District. The campus is primarily composed of permanent buildings of wood framing and concrete masonry unit construction. There are also number of modular classroom buildings. In 2012 a new modular classroom building was constructed with ten new classrooms. Existing buildings were also renovated to create two additional science labs, an administrative area for the 9th Grade Academy and to remove student lockers from the campus. These renovations were completed in part to accommodate additional students which were transferred to the school when Hogan High School was closed, and its site converted to Hogan Middle School.

Jesse Bethel High School is implementing a Wall to Wall Academies program which establishes a 9th Grade Academy and five thematic College and Career Academies for grades 10-12. The Academies are International Finance, Law, Biomed, Green and Multimedia.

Jesse Bethel High School was originally designed to be a small high school campus and does not have some features typically associated with a comprehensive high school. There is only a small theater that does not have the capability for large productions. Also, Jesse Bethel does not have a competition track and stadium and holds all competition sporting events at Corbus Field on the Vallejo High School campus. This has long been the case in Vallejo, as Hogan High School did the same before the its closure.





Jesse Bethel High School - Existing Conditions Summary

Facilities Assessment Needs

- Finishes in classrooms are worn out. Replace flooring, wall covering and ceiling panels
- Light fixtures in some classrooms are not functioning properly or appropriate for their current use
- Standing seam metal roofs do not have roof gutters which has damaged concrete and are dirty
- Exterior dirty and marred needs to be cleaned and painted
- Walls and base in main gym in need of repair
- Damaged and missing accessories in restrooms.
- Address accessibility issues throughout campus
- Provide code compliant signage throughout campus

Educational Program Needs

- Create individual, small administration spaces for each academy
- Provide lab and presentation spaces as required for each academy
- Small Group Instruction areas in each academy
- Security Fencing at perimeter of the campus

Unique Opportunities

Outdoor spaces are generous and have potential to create identity for campus







Jesse Bethel High School - Master Plan Summary

Master Plan Features

- Provide infrastructure for multi-media presentations in classrooms, student union and theater
- Provide athletic stadium

- Remodel and construct addition at gym -Develop outdoor learning areas
- Renovate interior and exterior finishes

Selected Improvements by Theme

	FACILITIES NEED THEME	IMPROVEMENT
	Campus Safety	Provide site security fencing. Upgrade remaining locks. Fire alarm is out of date. Provide new window blinds.
占	Accessibility	Provide accessible identification signage. Provide code compliant ramps and landings and any other accessibility upgrades as required by code.
	Technology	Provide A/V system in classrooms, auditorium, MPR, and gym. Add wireless internet throughout campus. Upgrade electrical, data, and security infrastructure as required.
四	Science, Technology, Engineering, Mathematics (STEM)	Provide STEM Lab in each academy. Create outdoor learning areas
	Community Schools	Improve utilization of existing Administration spaces to provide meeting areas. New exterior paint. Renovate student restrooms. New classroom furniture.
	Infrastructure	Replace mechanical units with energy efficient models. Replace or repair roofing. Repair concrete damage throughout campus. Repair site utilities as needed. Modernize restrooms.

Jesse Bethel High School - Committee Facilities Improvement Priorities

The Master Plan Committee provided their recommendation on the priority of improvements with in the three categories for use in future decision making. These recommendations will be considered along with other factors when scheduling projects as funding becomes available.

Current Facilities Needs (CFN)

- Address accessibility issues throughout campus
- Provide code compliant signage throughout campus
- Provide site security fencing
- Lack of roof gutters has damaged concrete
- Finishes in classrooms are worn out: replace flooring, wall covering and ceiling panels
- Indoor air quality improvements (due to quarry nearby)
- Ventilation needed in gym, locker room
- Address drainage issues behind bldg. "C"
- Lower terrace is flooding and site drainage
- Provide blinds in classrooms


Educational Program Needs (EPN)


- Classroom AV system
- Teacher work area in each academy
- Improve acoustics in student union building (acoustics are horrible)
- Light fixtures in classrooms old and inefficient
- Currently there are no provisions for multi-media, (AV and lighting in theater), presentations in theater or student union
- Need to create space for five academies: Law, Green, International Finance, Biomed and Multimedia
- Provide flexible spaces in each academy

Future Facilities Needs (FFN)

- Need stadium. At a minimum need bleachers at field
- Need toilet rooms on lower terrace
- Remodel library spaces, "back of house"
- Remodel "C" wing for PE and athletics
- Damaged and missing accessories in restrooms, remodel
- Need power at quad stage
- Need outdoor eating area near student union
- Need water and power at tennis courts
- Need teacher lunchroom
- Remodel band room for more storage and practice rooms
- Exterior dirty and marred, clean and paint
- Need multitude of storage (lockable), need more storage in classrooms
- Walls in main gym damaged, portions of vented base missing
- Create retaining walls to address problematic grade changes










Vallejo City Unified School District Facilities Master Plan



Vallejo City Unified School District Facilities Master Plan









Jesse Bethel High School

Conceptual Enlarged Plan







Jesse Bethel High School

Conceptual Enlarged Plan

JBHS-15





Jesse M. Bethel High School Preliminary Cost Estimate

1800 Ascot Parkway, Vallejo, CA 94591 707/556-5700

Square Footage (Bldg. only): 174,934

Classrooms: 82 # Portables: 0

	CFN	EPN	FFN	Grand Total
Construction Costs	\$ 12,058,867.70	\$ 15,941,926.84	\$ 3,585,250.00	\$ 31,586,044.54
Sub-Total	\$ 12,058,867.70	\$ 15,941,926.84	\$ 3,585,250.00	\$ 31,586,044.54
Design Contingency (0%)	\$ -	\$ -	\$ -	\$ -
Sub-Total	\$ 12,058,867.70	\$ 15,941,926.84	\$ 3,585,250.00	\$ 31,586,044.54
General Contractor OHP (12%)	\$ 1,447,064.12	\$ 1,913,031.22	\$ 430,230.00	\$ 3,790,325.34
General Contractor Insurance (2%)	\$ 241,177.35	\$ 318,838.54	\$ 71,705.00	\$ 631,720.89
Sub-Total	\$ 13,747,109.18	\$ 18,173,796.60	\$ 4,087,185.00	\$ 36,008,090.78
Soft Costs: Change Order Contingency, A/E Fees,				
Inspection, Management Fees, etc. (35%)	\$ 4,811,488.21	\$ 6,360,828.81	\$ 1,430,514.75	\$ 12,602,831.77
Sub-Total	\$ 18,558,597.39	\$ 24,534,625.41	\$ 5,517,699.75	\$ 48,610,922.55
Escalation (18%)	\$ 3,340,547.53	\$ 4,416,232.57	\$ 993,185.96	\$ 8,749,966.06
Grand Total	\$ 21,899,144.92	\$ 28,950,857.98	\$ 6,510,885.71	\$ 57,360,888.61

CODE	DISCIPLINE	LOCATION		DESCRIPTION		PHOTO	ESTIMA TAKE Qty.		COST/ UNIT	TOTAL COST
				SITE ISSUES						
CFN	Site Utilities	Site	Deficiency	Site utilities are nearing the end of their useful life			1	ls	\$ 950,000.00	\$ 950,000.00
			Remedy	Replace underground utility lines						
CFN	Accessibility Issue	Site	Deficiency Remedy	throughout site .		2 06 2	1475	sf	\$ 40.00	\$ 59,000.00
CFN	Accessibility Issue	Site	Deficiency Remedy	cross slope on path of travel exceeds 2% at 46 locations hroughout site. Remove and replace section of walkway that is non compliant. Estimate of 150 sf ea occurrence.		2 06 3	6900	sf	\$ 40.00	\$ 276,000.00
CFN	Accessibility Issue	Site	Deficiency Remedy	Slopes on path of travel > 5% without handrails at 8 locations. Remove and replace ramp with slopes < 5% or provide handrails for ramp as required path of travel.		2 04 1	1200	sf	\$ 40.00	\$ 48,000.00
CFN	Accessibility Issue	Site	Deficiency Remedy	Slopes on path of travel > 8.33% at 3 locations. Remove ramp and construct code compliant ramp	6		450	sf	\$ 40.00	\$ 18,000.00
CFN	Accessibility Issue	Site	Deficiency Remedy	Broken or raised pavement at 1 locations. Remove and replace pavement. Estimate 25 sf ea occurrence	9		25	sf	\$ 40.00	\$ 1,000.00
CFN	Accessibility Issue	Site	Deficiency Remedy	Non compliant accessible Parking signage. Provide code compliant accessible signage.	10		2	ea	\$ 100.00	\$ 200.00
CFN	Accessibility Issue	Site	Deficiency Remedy	Slopes exceed 2% in any direction on accessible parking stall or loading area Repave accessible parking area to provide maximum of 2% cross slope or relocate accessible parking.	11		520	sf	\$ 30.00	\$ 15,600.00
CFN	Accessibility Issue	Site	Deficiency Remedy	Non-compliant ramp. Modify ramp as required - add truncated domes.			260	sf	\$ 30.00	\$ 7,800.00
CFN	Accessibility Issue	Site	Deficiency Remedy	Pavement markings faded. Restripe as part of pavement slurry item			1	ls	\$ 10,000.00	\$ 10,000.00
EPN	Paving & Grading	Site	Deficiency Remedy	Repair and Upgrade Campus Parking Lot	26		1	ls	\$ 150,000.00	\$ 150,000.00

		<u> </u>								
CODE	DISCIPLINE	LOCATION		DESCRIPTION	SITE PLAN KEY	PHOTO	ESTIMA TAKE (COST/ UNIT	TOTAL COST
			Deficiency	Pavement broken or failing.						
EPN	Paving & Grading	Site	Remedy	Remove existing paving and base and replace full paving section.	26		Cost in		ed in Parking Lot cost	\$ -
			Deficiency	Pavement maintenance program necessary.						
FFN	Paving & Grading	Site	Remedy	Anticipate budget to fill cracks, slurry seal surface and repaint as necessary	27		375000	sf	\$ 0.15	\$ 56,250.00
FFN	Plumbing	Site	Deficiency	Inadequate drainage - soil washing onto walkways.	28	2 0 04	Cost in	clude	d in Site Utilities	\$ -
			Remedy	Re-grade and provide storm drain to accept drainage. GENERAL & CAMPUS-WIDE ISSUES						
			Deficiency	Roofing in need of replacement	1	ı				
CFN	Roofing	Campus Buildings	Remedy				1	ls	\$ 1,635,800.00	\$ 1,635,800.00
			Deficiency	eficiency Due to proximity of campus to quarry, there is a concern						
CFN	Mechanical	Campus-wide	Remedy	· 1			1	Is	\$ 2,414,089.20	\$ 2,414,089.20
			Deficiency	Replace HVAC units. Provide efficient filtering system	-	ļ				
CFN	Site	Lower Terrace/Bldg. C	Deficiency Remedy	Drainage and flooding issues at lower terrace and behind building C. Re-grade areas of concern and provide area drains connected to storm drain system			1	ls	\$ 65,000.00	\$ 65,000.00
			Deficiency	Ventilation poor in gym and locker room.						
CFN	Mechanical	Gymnasium	Remedy	Replace HVAC units. Add additional exhaust fans to address ventilation issues.			Cost in		ed in Mechanical costs	\$ -
CFN	Doors	Campus-wide	Deficiency Remedy	Weather-stripping at all exterior doors damaged or missing. Provide new weather-stripping at all exterior doors.			100	ea	\$ 125.00	\$ 12,500.00
			Deficiency	Metal roofs are dirty and growing moss.						
CFN	Roofing	Campus-wide	Remedy			03	Cost in	clude	d in Roofing cost	\$ -
			Deficiency	Site lacks code compliant identification & directional signage	†					
CFN	Accessibility	Campus-wide	Remedy			10	174934	sf	\$ 0.50	\$ 87,467.00
			Deficiency	Site perimeter is not secure.						
CFN	Fencing	Campus-wide	Remedy	medy Provide site perimeter fencing and create one entrance to			(Comp	leted 2018	\$ -
-				campus		L	<u> </u>			

			es needs opieausneet									
DISCIPLINE	LOCATION		DESCRIPTION E		DESCRIPTION SIZE FLANCE OF THE PROPERTY OF THE					COST/ UNIT		TOTAL COST
Electrical/ Fire Alarm	Campus-wide	Deficiency Remedy	Electrical system upgrades/Fire alarm outdated and not up to current code. Repair/replace electrical as necessary. Update fire alarm with			1	ls	\$ 3,017,611.50	\$	3,017,611.50		
		Deficiency	horn/strobe. Acoustics in student union are poor.									
Walls & Ceilings	Student Union	Remedy	Add acoustical treatment to walls, replace ceiling panels with more sound absorbent panels.			2500	sf	\$ 3.40	\$	8,500.00		
Exterior Envelope	Campus-wide	Deficiency Remedy	Exterior of building brick, dirty and marred. Thoroughly clean exterior, paint		02	174934	sf	\$ 1.00	\$	174,934.00		
Doors	Campus-wide	Deficiency	eficiency Exterior metal doors paint is marred, scratched and dirty.		09 11	100	ea	\$ 150.00	\$	15,000.00		
Flooring	Campus-wide	Deficiency				174934	sf	\$ 6.00	\$	1,049,604.00		
		Remedy Deficiency	Replace all VCT and carpet with linoleum/sheet vinyl or carpet									
Plumbing	Campus-wide	,	emedy Replace with stainless			174934	sf	\$ 0.88	\$	153,941.92		
			CLASSROOMS			<u> </u>						
		Deficiency	Vinyl wall covering dirty and damaged.	I		1	T		Г			
Walls	Classrooms	Remedy	Remove all vinyl wall covering and repair gypboard and paint or provide wall covering		04 05 06	174934	sf	\$ 1.00	\$	174,934.00		
Ceiling	Classrooms	Deficiency Remedy	Suspended ceiling panels old, dirty and sagging. Replace all ceiling panels and re-tension grid			174934	sf	\$ 3.50	\$	612,269.00		
Lighting	Classrooms	Deficiency	Light fixtures are old and inefficient.		08	Cost inc	cluded	l in Electrical cost	\$	-		
Windows	Classrooms	Deficiency	Window blinds damaged or missing.		07	174934	sf	\$ 0.88	\$	153,941.92		
Flooring	Classrooms	Deficiency Remedy	Deficiency VCT flooring worn out and damaged.			Cost in	clude	d in Flooring cost	\$	-		
		vinyl										
Restrooms	Campuswide	Deficience				5984	sf	\$ 575.00	\$	3,440,800.00		
Accessibility	Student Restrooms	Deficiency Remedy	eficiency 44" clear pathway obstructed by Lav.			Cost Inc	luded	in Restroom Cost	\$	-		
	Electrical/ Fire Alarm Walls & Ceilings Exterior Envelope Doors Flooring Plumbing Walls Ceiling Lighting Windows Flooring Restrooms	Electrical/Fire Alarm Walls & Ceilings Student Union Exterior Envelope Campus-wide Doors Campus-wide Flooring Campus-wide Campus-wide Campus-wide Campus-wide Classrooms Classrooms Lighting Classrooms Windows Classrooms Flooring Classrooms Classrooms Classrooms Student Classrooms	Electrical/ Fire Alarm Campus-wide Remedy Deficiency Remedy Classrooms Remedy Deficiency Remedy Classrooms Remedy Deficiency Remedy	Electrical/ Fire Alarm Campus-wide Remedy Replace all celling panels old, dirty and sagging. Classrooms Remedy Replace all celling panels old, dirty and sagging. Classrooms Remedy Replace all celling panels old, dirty and sagging. Classrooms Remedy Replace all celling panels old, dirty and sagging. Classrooms Remedy Replace all celling panels old, dirty and sagging. Classrooms Remedy Replace all celling panels old, dirty and sagging. Classrooms Remedy Replace all celling panels old, dirty and sagging. Classrooms Remedy Replace all celling panels old, dirty and sagging. Classrooms Remedy Replace all celling panels old, dirty and sagging. Classrooms Remedy Replace all celling panels old, dirty and sagging. Classrooms Remedy Replace all celling panels old, dirty and sagging. Classrooms Remedy Replace all celling panels old, dirty and sagging. Classrooms Remedy Replace all celling panels old, dirty and sagging. Classrooms Remedy Replace all celling panels old, dirty and sagging. Classrooms Remedy Replace all celling panels old, dirty and sagging. Classrooms Remedy	Electrical/ Fire Alarm Campus-wide Remedy Deficiency Deficiency Remedy Repair/replace electrical as necessary. Update fire alarm with horn/strobe. Deficiency Acoustics in student union are poor. Add acoustical treatment to walls, replace ceiling panels with more sound absorbent panels. Exterior Envelope Campus-wide Remedy Doors Campus-wide Remedy Plooring Campus-wide Remedy Remedy Remedy Deficiency Deficiency Exterior of building brick, dirty and marred. Exterior metal doors paint is marred, scratched and dirty. Paint all doors and frames. Policiency Exterior dinking fountains damaged. Remedy Replace all VCT and carpet with linoleum/sheet vinyl or carpet Deficiency Exterior dinking fountains damaged. Pumbing Campus-wide Remedy Replace with stainless. CLASSROOMS Classrooms Remedy Remedy are place all ceiling panels old, dirty and sagging. Ceiling Classrooms Remedy Classrooms Remedy Replace all ceiling panels and re-tension grid Deficiency Uint fixtures are old and inefficient. Remedy Replace fixtures with more efficient up/down fixtures Policiency Vindows blinds damaged or missing. Classrooms Remedy Replace fixtures with more efficient up/down fixtures Policiency Vindow blinds damaged or missing. Remedy Replace all VCT flooring throughout campus with linoleum/sheet vinyl STUDENT RESTROOMS Full upgrade to all campus restrooms Policiency Accessibility Pumbing Deficiency Superpade celectrical as necessary. Update fire alarm with nor/nor/stude vall covering and repairs and re-tension grid Deficiency Virdoving with out and damaged. Full upgrade of all campus restrooms Pumbing Pumbing Deficiency Virdoving worn out and damaged. Full upgrade to all campus restrooms Pumbing Pumbing Deficiency Accessibility Pumbing Deficiency Defici	Deficiency Deficiency Campus-wide Remedy Deficiency Deficiency Campus-wide Remedy Deficiency Deficiency Deficiency Deficiency Add acoustical treatment to walls, replace celling panels with more sound absorbent panels. Deficiency Defici	Deficiency Campus-wide Remedy Add acoustical treatment to walls, replace ceiling panels with more sound absorbent panels. Deficiency Exterior from the panels with more sound absorbent panels. Deficiency Exterior from the panels with more sound absorbent panels. Deficiency Exterior from the panels with more sound absorbent panels. Deficiency Exterior from the panels with more sound absorbent panels. Deficiency Exterior from the panels with more sound absorbent panels. Deficiency Exterior from the panels with more sound absorbent panels. Deficiency Exterior from the panels with more sound absorbent panels. Deficiency Exterior from the panels with more sound absorbent panels. Deficiency Exterior from the panels with more sound absorbent panels. Deficiency Exterior from the panels with more sound absorbent panels. Deficiency Exterior metal doors paint is marred, scratched and dirty. Osg 11 100 Deficiency Deficiency Exterior from the panels with incleam/sheet whyl or carpet Deficiency Exterior drinking fournams damaged. Throughly clean exterior drinking fournams damaged. Throughly clean exterior drinking fournams damaged. Throughly covering dirty and covering and repair gypboard and paint or provide well covering Calastrooms Remedy Replace all ceiling panels and re-tension grid Throughly wall covering and repair gypboard and paint or provide well covering Deficiency Deficiency Calastrooms Remedy Replace all ceiling panels and re-tension grid Throughly wall covering and repair gypboard and paint or provide well covering Throughly wall covering and repair gypboard and paint or provide wall wall covering Throughly wall covering and repair gypboard and paint or provide wall wall covering Throughly wall covering and repair gypboard and paint or provide wall wall covering Throughly wall covering and repair	Deficiency Fire Alarm Defi	Deficiency Exterior Envelope Campus-wide Remedy Paint all doors and frames Deficiency Exterior of building brick, drify and marred. Deficiency Exterior drifting fountains damaged. Deficiency Exterior drifting fountains damaged. 174934 sf \$ 0.88	Description Description		


CODE	DISCIPLINE	LOCATION		DESCRIPTION		PHOTO	ESTIMA TAKE (C	OST/ UNIT		TOTAL COST
CFN	Accessibility	Theater Lobby	Deficiency Remedy	Restrooms at theater lobby not accessible. No 44" clear path provided. Requires complete modernization.			Cost Included in Restroom Cost		estroom Cost	\$	-	
CFN	Accessibility	Student Restrooms	Deficiency	Damaged or missing toilet accessories. Replace all toilet accessories			Cost Inc	luded	in Re	estroom Cost	\$	-
EPN	Cleaning	Student Restrooms	Deficiency Remedy	Finishes dirty. Thoroughly clean all surfaces, paint ceilings, replace FRP and toilet compartments.			Cost Inc	luded	in R	estroom Cost	\$	-
EPN	Flooring	Gymnasium	Deficiency Remedy	Restrooms at gym lobby base tile damaged, some missing. Replace damaged and missing base tile, allow for 10 tiles each restroom.			Cost Inc	luded	in R	estroom Cost	\$	-
				STAFF RESTROOMS								
FFN	Cleaning	Staff Restrooms	Deficiency Remedy	Routine Maintenance Issue		ance Issue	\$	-				
EDUCATIONAL PROGRAM NEEDS												
EPN	Educational Needs	Campus-wide	Needs	Modernize two science classrooms, 1,400 sf each	T T	ı	2800	sf	\$	650.00	\$	1,820,000.00
EPN	Technology	Campus-wide	Needs	Provide infrastructure to meet district Ed Spec for technology.			174934	sf	\$	3.00	\$	524,802.00
EPN	0,	Campus-wide	Needs	Provide teacher work area in each academy.			800	sf	\$	560.00	\$	448,000.00
EPN		Campus Wide	Needs	Replace Classroom Furniture			80	CR	\$	12,000.00	\$	960,000.00
EPN	Audio/Visual	Campus-wide	Needs	Provide for multi-media presentations in classrooms, student union and theater.			0	ea	\$	3,000.00	\$	-
EPN	General	Band Room, Practice Room	Needs	Band room, practice rooms and support areas. Walls damaged, doors damages Requires complete modernization.		12 13	1	ls	\$	338,000.00	\$	338,000.00
EPN	General	Kitchen	Needs	Kitchen/Food Service Modernization and Upgrade			1	ls	\$	845,000.00	\$	845,000.00
EPN	General	Campus-wide	Needs	Jesse Bethel was designed as mini-high school. Capacity has exceeded original intention. Theater, Cafeteria, Gym, are now undersized for current enrollment.			1	ls	•	8,450,000.00	\$	8,450,000.00
EPN	Walls &Finishes	Gymnasium	Deficiency Remedy	RP walls in gym are damaged. epair damage to walls, replace damaged FRP panel			1	ls	\$	45,000.00	\$	45,000.00
EPN	Flooring	Gymnasium	Deficiency Remedy	Portions of vent floor base are missing in the gym. 1 Is \$ 18,000.00 Replace missing vented base		\$	18,000.00					
EPN	Technology	Campus-wide	Deficiency Remedy	Wireless throughout campus Provide/upgrade wiring to 1gig fiber connection			Per 6		eetin nplet	ng, already ed	\$	-
FFN	General	Lower Terrace	Needs	Provide staff restroom at lower terrace.			400	sf	\$	560.00	\$	224,000.00
V / - II	-'- O'(11-'C		District	Tacilities Master Dlen			1					

CODE	DISCIPLINE	LOCATION		DESCRIPTION		РНОТО	ESTIMA TAKE (COST/ UNIT	TOTAL COST
	_						Qty.	Unit		
FFN	General	General	Needs	Need teacher's lunch room large enough to accommodate entire staff			1	ls	\$ 455,000.00	\$ 455,000.00
FFN	General	Campus-wide	Needs	Provide storage throughout campus			1	ls	\$ 1,300,000.00	\$ 1,300,000.00
FFN	Plumbing/Electrical	Tennis Courts	Needs	Provide water and power to tennis courts.			1	ls	\$ 650,000.00	\$ 650,000.00
FFN	Paving & Grading	Site	Deficiency Remedy	ade changes across campus problematic. ovide retaining walls to create useable level areas			1	ls	\$ 650,000.00	\$ 650,000.00
FFN	General	Site	Needs	Provide outdoor eating area near student union			1	ls	\$ 250,000.00	\$ 250,000.00

CFN Total	\$ 12,058,867.70
EPN Total	\$ 15,941,926.84
FFN Total	\$ 3,585,250.00

IOTAL COSTS (not including escalation) \$ 31,586,044.54

Jesse Bethel High School - Photographs







1

2 5

3








Vallejo City Unified School District Facilities Master Plan


JBHS-233

Jesse Bethel High School - Photographs











Vallejo City Unified School District Facilities Master Plan

JBHS-24

Jesse Bethel High School - Photographs







 13
 14
 15

 16
 17





Vallejo City Unified School District Facilities Master Plan