

Lead Sample Test Results and Actions

CHIEF JOSEPH ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 001		No				
FX 002		No				
FX 003	Bottle filler east hall	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 004		No				
FX 005		No				
FX 006		No				
FX 007	Room 1 sink	Yes	0.002			Re-tested after adding filter 9/20/2022; No further action required
FX 008	Room 2 sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 009	Room 3 sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 010	Room 4 sink	Yes	0.006		Must be fixed, replaced or removed	
FX 011	Room 5 sink	Yes	0.002			Re-tested after adding filter 9/20/2022; No further action required
FX 012	Room 6 sink	Yes	0.002			Re-tested after adding filter 9/20/2022; No further action required
FX 013	Room 7 sink	Yes	0.001			Re-tested after adding filter 9/20/2022; No further action required
FX 014	Room 8 sink	Yes	0.001			Re-tested after adding filter 9/20/2022; No further action required
FX 015	Room 9 sink	Yes	0.001			Re-tested after adding filter 9/20/2022; No further action required
FX 016	Room 10 sink	Yes	0.002			Re-tested after adding filter 9/20/2022; No further action required

Lead Sample Test Results and Actions

CHIEF JOSEPH ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 017	Room 11 sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 018		No				
FX 019		No				
FX 020	Room 12 sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 021	Room 13 sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 022	Room 14 sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 023	Room 15 sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 024	Room 16 sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 025	Room 17 sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 026	Room 18 sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 027	Room 19 sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 028	Room 20 sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 029	Library sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 030		No				
FX 031		No				

Lead Sample Test Results and Actions

CHIEF JOSEPH ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 µg/L less than 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 032	Bottle filler	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 033	Fountain	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 034		No				
FX 035		No				
FX 036	Gym fountain hi	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 037	Gym bottle filler	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 038	Kitchen hand sink	Yes	0.002			Re-tested after adding filter 9/20/2022; No further action required
FX 039	Kitchen dish sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 040	Kitchen hand sink	Yes	0.002			Re-tested after adding filter 9/20/2022; No further action required
FX 041	Kitchen dish sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 042	Kitchen dish sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 043	Kitchen sprayer	Yes	0.006		Must be fixed, replaced or removed	
FX 044	Teachers lounge sink	Yes	0.0009			Re-tested after adding filter 9/20/2022; No further action required
FX 045		No				
FX 046	Room 21	Yes	0.025	Must be immediately removed		
FX 047		No				
FX 048		No				
FX 049	Room 22	Yes	0.027	Must be immediately removed		