

Lead Sample Test Results and Actions

LEWIS AND CLARK ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 000	Office sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 001		No				
FX 002	Aides room sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 003		No				
FX 004	Fountain hi office hall	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 005	Bottle filler office hall	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 006		No				
FX 007		No				
FX 008	Rm 1 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 009	Rm 2 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 010	Rm 3 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 011	Rm 4 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 012	Rm 5 sink	Yes	0.001			Re-tested after adding filter 9/27/2022; No further action required
FX 013	Rm 6 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 014		No				

Lead Sample Test Results and Actions

LEWIS AND CLARK ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 015		No				
FX 016		No				
FX 017		No				
FX 018	Boys hi fountain	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 019	Bottle filler boy's side	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 020		No				
FX 021		No				
FX 022		No				
FX 023		No				
FX 024		No				
FX 025	Girls hi fountain	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 026	Bottle filler girl's side	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 027	Room 7 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 028	Room 8 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 029	Rm 17 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 030	Rm 17 fountain	Yes		Fixture permanently removed		
FX 031	Rm 18 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 032		No				

Lead Sample Test Results and Actions

LEWIS AND CLARK ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.	
FX 033	Fountain hi by gym	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required	
FX 034	Bottle filler by gym	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required	
FX 035		No					
FX 036		No					
FX 037	Rm 9 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required	
FX 038	Rm 9 fountain	Yes	Fixture permanently removed				
FX 039		No					
FX 040	Rm 10 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required	
FX 041	Rm 11 sink	Yes	0.002			Re-tested after adding filter 9/27/2022; No further action required	
FX 042	Rm 11 fountain	Yes	Fixture permanently removed				
FX 043	Rm 12 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required	
FX 044	Rm 12 fountain	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required	
FX 045	Rm 13 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required	
FX 046		No					
FX 047	Rm 14 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required	

Lead Sample Test Results and Actions

LEWIS AND CLARK ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 048	Rm 15 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 049	Rm 15 fountain	Yes		Fixture permanently removed		
FX 050	Rm 16 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 051	Rm 16 fountain	Yes		Fixture permanently removed		
FX 052		No				
FX 053	East hall bottle filler	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 054	Rn 19 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 055	Rm 19 fountain	Yes		Fixture permanently removed		
FX 056	Rm 20 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 057		No				
FX 058	Rm 21 sink	Yes	0.004			Re-tested after adding filter 9/27/2022; No further action required
FX 059		No				
FX 060	Rm 22 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 061	Rm 22 fountain	Yes		Fixture permanently removed		
FX 062	Rm 23 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 063	Rm 23 fountain	Yes		Fixture permanently removed		
FX 064	Rm 24 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required

Lead Sample Test Results and Actions

LEWIS AND CLARK ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 065	Rm 24 fountain	Yes	Fixture permanently removed			
FX 066	Rm 25 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 067		No				
FX 068	Rm 26 sink	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 069	Rm 26 fountain	Yes	Fixture permanently removed			
FX 070		No				
FX 071		No				
FX 072	Kitchen sink	Yes	0.001			Re-tested after adding filter 9/27/2022; No further action required
FX 073	Kitchen sprayer	Yes	0.0009			Re-tested after adding filter 9/27/2022; No further action required
FX 074	Kitchen sprayer	Yes	0.001			No action