

AHERA THREE YEAR RE-INSPECTION LOG



LEA NAME:		Brownsville ISD					
SCHOOL BUILDING NAME:		El Jardin Elementary School					
ADDRESS:		6911 Boca Chica Boulevard					
DATE:		05-01-2023					
HA No.	Material Type / Description	Material Location	Condition	Friability	Category	Classification	Results
101	12" x 12" Floor Tile with mastic Off White / Grey Specks	Throughout School, Library, Gym Office	Good	Non-Friable	5	Miscellaneous	Presumed ACM
102	12" x 12" Floor Tile with mastic Grey Tile	Classroom 206-216 and Hallway	Good	Non-Friable	5	Miscellaneous	Presumed ACM
103	12" x 12" Floor Tile with mastic Multi Color Tile	600 Hallway, Main Offices	Good	Non-Friable	5	Miscellaneous	Presumed ACM
104	12" x 12" Floor Tile with mastic Beige	Cafeteria, Kitchen Office, Storage Room	Good	Non-Friable	5	Miscellaneous	Presumed ACM
105	12" x 12" Floor Tile with mastic Beige / Grey	Classroom 600-612	Good	Non-Friable	5	Miscellaneous	Presumed ACM
106	Wood Floor Wood	Front Hallway and Auditorium	Good	Non-Friable	5	Miscellaneous	Presumed ACM
201	2 x 6 Acoustical Panels Fiberglass	Classrooms 500-502 and Boys and Girls Restroom	Good	Non-Friable	5	Miscellaneous	Presumed ACM
202	2' x 4' Ceiling Tile Off White, Medium Fissure Small Holes	Classrooms 206-216, Coach's Office and Storage	Good	Friable	5	Miscellaneous	Presumed ACM
203	2' x 2' Ceiling Tile Small Fissure, Small Hole	Throughout Classrooms	Good	Friable	5	Miscellaneous	Presumed ACM
301	Chalkboard Mastic Black or Green	Classrooms 103-106 and 500- 502	Good	Non-Friable	5	Miscellaneous	Presumed ACM

AHERA THREE YEAR RE-INSPECTION LOG



302	Stainless Steel Sink Undercoating	Classrooms 213-216, 207,209 and 103-106	Good	Non-Friable	5	Surfacing	Presumed ACM
303	Stage Curtains	Auditorium	Good	Non-Friable	5	Miscellaneous	Presumed ACM
304	Cove Base Grey	Throughout School	Good	Non-Friable	5	Miscellaneous	Presumed ACM
401	HVAC Mastic White	Mechanical Room	Good	Non-Friable	5	Miscellaneous	Presumed ACM
501	Sheet Rock and Joint Compound	Throughout School	Good	Friable	5	Surfacing	Presumed ACM
502	Cinder Block White	Throughout School	Good	Non-Friable	5	Miscellaneous	Presumed ACM

Category:	1 Damaged/significantly damaged thermal insulation, 2 Damaged friable surfacing 3 Significantly damaged friable surfacing 4 Damaged/Significantly damaged friable miscellaneous 5 Potential for damage 6 Potential for significant damage 7 Remaining ACBM
Inspector Name	Eloy Palacios
Signature:	
Date:	5.31.23
Accreditation:	Asbestos Consultant 105727
PREVENTATIVE MEASURES (to keep undamaged from becoming damaged)	
Do not subject material to cutting, drilling, grinding, abrading, or burning. Prevent further damage by protecting from impact or vibration. Minimize entry to area by personnel.	
RESPONSE ACTIONS:	
Follow response action section of the management plan for maintenance activities. Follow response action section of the management plan for renovation and remodeling activities. Follow response action section of the management plan for emergency response procedures.	