

AHERA THREE YEAR RE-INSPECTION LOG



LEA NAME:		Brownsville ISD					
SCHOOL BUILDING NAME:		Egly Elementary School					
ADDRESS:		445 Land-O-Lakes Drive					
DATE:							
HA No.	Material Type / Description	Material Location	Condition	Friability	Category	Classification	Results
101	12" x 12" Floor Tile with mastic White W/Brown Specks	Offices 400	Good	Non-Friable	5	Miscellaneous	Presumed ACM
102	12" x 12" Floor Tile with mastic White W/Brown Specks	Cafeteria, PDC Room, 201-206, 300 Building	Good	Non-Friable	5	Miscellaneous	Presumed ACM
103	Sheet Flooring and Mastic Grey Pebble Design	Kitchen	Good	Non-Friable	5	Miscellaneous	Presumed ACM
104	12" x 12" Floor Tile with mastic White W/Blue Flecks	700 Building	Good	Non-Friable	5	Miscellaneous	Presumed ACM
105	12" x 12" Floor Tile with mastic Red W/Red Streaks	700 Building Designs	Good	Non-Friable	5	Miscellaneous	Presumed ACM
106	12" x 12" Floor Tile with mastic Purple W/Purple Streak	700 Building Designs	Good	Non-Friable	5	Miscellaneous	Presumed ACM
107	12" x 12" Floor Tile with mastic Yellow W/Yellow Streaks	700 Building Designs	Good	Non-Friable	5	Miscellaneous	Presumed ACM
108	12" x 12" Floor Tile with mastic Green W/Green	700 Building Designs	Good	Non-Friable	5	Miscellaneous	Presumed ACM

AHERA THREE YEAR RE-INSPECTION LOG



	Streak						
109	12" x 12" Floor Tile with mastic Lt Blue W/Dk Blue Streaks	700 Building Designs	Good	Non- Friable	5	Miscellaneous	Presumed ACM
110	Carpet Mastic – Multi Color Carpet	Library	Good	Non- Friable	5	Miscellaneous	Presumed ACM
111	12" x 12" Floor Tile with mastic White W/Tan Flecks	1-11,106-109,207- 211,306,400 Building, 500 Building, 600 Building	Good	Non- Friable	5	Miscellaneous	Presumed ACM
112	12" x 12" Floor Tile with mastic White W/Tan Flecks W/Unknown Color	Teachers Work Room	Good	Non- Friable	5	Miscellaneous	Presumed ACM
113	12" x 12" Floor Tile with mastic Beige W/Brown Streaks	Rooms 16-19, 100-105	Good	Non- Friable	5	Miscellaneous	Presumed ACM
201	Ceiling Texture Popcorn Ceiling Texture	Cafeteria, 400 Building, 500 Building, 600 Building	Good	Friable	5	Surfacing	Presumed ACM
202	2' x 4' Ceiling Tile Off White, Medium Fissure Small Holes	Offices	Good	Friable	5	Miscellaneous	Presumed ACM
203	2' x 2' Ceiling Tile Small Fissure, Small Hole	Throughout Building	Good	Friable	5	Miscellaneous	Presumed ACM
301	Chalk board Mastic Black or Green	Classrooms Throughout Buildings	Good	Non- Friable	5	Miscellaneous	Presumed ACM
302	Stainless Steel Sink Undercoating	Teachers Work Room	Good	Non- Friable	5	Surfacing	Presumed ACM
303	Maroon Stage Curtains	Cafeteria	Good	Non- Friable	5	Miscellaneous	Presumed ACM

AHERA THREE YEAR RE-INSPECTION LOG



304	Cove Base - Mastic	Throughout Building	Good	Non-Friable	5	Miscellaneous	Presumed ACM
305	Mirror Mastic	Gang Restroom	Good	Non-Friable	5	Miscellaneous	Presumed ACM
401	HVAC Mastic White	Cafeteria	Good	Non-Friable	5	Miscellaneous	Presumed ACM
501	Sheet Rock and Joint Compound	Throughout School	Good	Friable	5	Surfacing	Presumed ACM

Category:	1 Damaged/significantly damaged thermal insulation, 2 Damaged friable surfacing 3 Significantly damaged friable surfacing 4 Damaged/Significantly damaged friable miscellaneous 5 Potential for damage 6 Potential for significant damage 7 Remaining ACBM
Inspector Name	Eloy Palacios
Signature:	
Date:	5.31.23
Accreditation:	Asbestos Consultant 105727
PREVENTATIVE MEASURES (to keep undamaged from becoming damaged)	
Do not subject material to cutting, drilling, grinding, abrading, or burning. Prevent further damage by protecting from impact or vibration. Minimize entry to area by personnel.	
RESPONSE ACTIONS:	
Follow response action section of the management plan for maintenance activities. Follow response action section of the management plan for renovation and remodeling activities. Follow response action section of the management plan for emergency response procedures.	