

AHERA THREE YEAR RE-INSPECTION LOG



LEA NAME:		Brownsville ISD					
SCHOOL BUILDING NAME:		Burns Elementary School					
ADDRESS:		1974 E. Alton Gloor Boulevard					
DATE:		05-01-2023					
HA No.	Material Type / Description	Material Location	Condition	Friability	Category	Classification	Results
100	12" x 12" Floor Tile with mastic White W/Brown Flecks	Office, Cafeteria, 601-604	Good	Non-Friable	5	Miscellaneous	Presumed ACM
101	12" x 12" Floor Tile with mastic White W/Blue Flecks	Office	Good	Non-Friable	5	Miscellaneous	Presumed ACM
102	12" x 12" Floor Tile with mastic Tan W/White Streaks	Asst Principal, Lounge, Classrooms, Nurse	Good	Non-Friable	5	Miscellaneous	Presumed ACM
103	12" x 12" Floor Tile with mastic White W/Brown Flecks	Administration Offices	Good	Non-Friable	5	Miscellaneous	Presumed ACM
200	Ceiling Texture Cement Material	500 Wing Hallway, 600 Wing Hallway	Good	Friable	5	Surfacing	Presumed ACM
201	2' x 4' Ceiling Tile Off White, Medium Fissure Small Holes	Office, Administration Office	Good	Friable	5	Miscellaneous	Presumed ACM
202	2' x 2' Ceiling Tile Small Fissure, Small Hole	Classrooms	Good	Friable	5	Miscellaneous	Presumed ACM
203	2' x 2' Ceiling Tile Insulation W/White Plastic Film	Hallways	Good	Non-Friable	5	Miscellaneous	Presumed ACM
300	Stainless Steel Sink Undercoating	Classrooms	Good	Non-Friable	5	Surfacing	Presumed ACM
301	Blue Stage Curtains	Cafeteria	Good	Non-Friable	5	Miscellaneous	Presumed ACM
302	Cove Base Mastic	Throughout Building	Good	Non-Friable	5	Miscellaneous	Presumed ACM



Category:	1 Damaged/significantly damaged thermal insulation, 2 Damaged friable surfacing 3 Significantly damaged friable surfacing 4 Damaged/Significantly damaged friable miscellaneous 5 Potential for damage 6 Potential for significant damage 7 Remaining ACBM
Inspector Name	Eloy Palacios
Signature:	
Date:	5.31.23
Accreditation:	Asbestos Consultant 105727
PREVENTATIVE MEASURES (to keep undamaged from becoming damaged)	
Do not subject material to cutting, drilling, grinding, abrading, or burning. Prevent further damage by protecting from impact or vibration. Minimize entry to area by personnel.	
RESPONSE ACTIONS:	
Follow response action section of the management plan for maintenance activities. Follow response action section of the management plan for renovation and remodeling activities. Follow response action section of the management plan for emergency response procedures.	