

Lead in Water Testing Results
 South Washington County Schools
Bailey Elementary – 4125 Woodlane Drive, Woodbury, MN 55129

On March 8th, 2024, Bailey Elementary’s drinking water was tested for the concentration of lead.

The following water sources tested less than our action level of 5 parts-per-billion (ppb), no action will be taken to these water sources at this time.

LOCATION	SOURCE	RESULT (ppb)
Room 101	SINK	1.80
Room 102	SINK	< 1.00
Room 115	SINK	< 1.00
Room 116	SINK	1.85
Room 117	SINK	1.36
Room 118	SINK	1.39
Room 119	SINK	< 1.00
Room 120	SINK	1.22
Room 121	SINK	< 1.00
Room 122	SINK	3.44
Room 123	SINK	1.44
Room 124	SINK	1.51
Room 125	SINK	1.92
Room 126	SINK	< 1.00
Room 127	SINK	1.24
Room 128	SINK	< 1.00
Room 129	SINK	1.32
Room 130	SINK	< 1.00
Room 131	SINK	< 1.00
Room 132	SINK	< 1.00
Room 133	SINK	< 1.00
Room 134	SINK	< 1.00
Room 135	SINK	< 1.00
Room 136	SINK	< 1.00
Room 137	SINK	1.06
Room 138	SINK	< 1.00
Room 181	FOUNTAIN	1.02
Room 185	SINK	4.66
Room 186	SINK	1.18
Room 187	SINK	1.07
Room 188	SINK	1.00
Room 189	SINK	< 1.00

Room 202	SINK	2.82
Gym A	FOUNTAIN	< 1.00
Gym B	FOUNTAIN	< 1.00
Gym C	FOUNTAIN	< 1.00
Hallway outside Room 117	SINK	3.66
Hallway West Bathroom	FOUNTAIN (right)	< 1.00
Hallway outside Room 123	SINK	2.02
Hallway outside Room 124	SINK	3.74
Hallway East Bathroom	FOUNTAIN (right)	1.39
Hallway East Bathroom	BOTTLE FILLER	< 1.00
Hallway outside Room 130	SINK	1.29
Hallway outside Room 135	SINK	1.26
Hallway outside Room 136	SINK	1.12
Hallway East Bathroom	FOUNTAIN (left)	< 1.00
Hallway Gym	BOTTLE FILLER	< 1.00
Hallway Gym	FOUNTAIN	< 1.00
Hallway Northwest Bathroom	FOUNTAIN	< 1.00
Hallway Southeast Bathroom	FOUNTAIN (left)	< 1.00
Hallway Southeast Bathroom	FOUNTAIN (right)	< 1.00
Hallway West Bathroom	FOUNTAIN (left)	2.15
Kitchen	SINK	2.42
Kitchen	SINK	1.32
Kitchen	SPRAYER	2.80
Media Center Workroom	SINK (right)	< 1.00
Nurse's Office	SINK	< 1.00
Staff Lounge	SINK	4.15
Workroom	SINK	< 1.00

The following water sources tested above the action level of 5 parts-per-billion (ppb) for the concentration of lead. These sources will not be used for consumption without remediation and re-testing. Actions taken are listed below.

LOCATION	SOURCE	RESULT (ppb)	ACTION
Room 182	SINK	16.5	Identified and labeled as handwashing sink only
Room 183	SINK	10.9	Identified and labeled as handwashing sink only
Room 184	SINK	8.07	Identified and labeled as handwashing sink only
Room 201	SINK (main)	5.36	Identified and labeled as handwashing sink only

Hallway outside 118	SINK	18.2	Identified and labeled as handwashing sink only
Hallway outside 129	SINK	17.5	Identified and labeled as handwashing sink only
Media Center Workroom	SINK (left)	6.27	Identified and labeled as handwashing sink only