

2024 LEAD WATER TESTING - RECOMMENDATION & REMEDIATION ACTION:

Eastview Middle School - White Plains City School District							
School Sample ID#	Sample Location	Outlet Description	Initial/Post Remediation	Lead Result ug/L (ppb)	Recommended Remediation Action	Post Remediation	Lead Result ug/L (ppb)
1	G Level- Lower Gym Locker Room – WF	Water Fountain	Initial	329	DISCONNECT WATER FOUNTAIN - NOT BEING USED	N/A	N/A

George Washington Elementary School - White Plains City School District							
School Sample ID#	Sample Location	Outlet Description	Initial/Post Remediation	Lead Result ug/L (ppb)	Recommended Remediation Action	Post Remediation	Lead Result ug/L (ppb)
30	3016 – Hallway @ Room 310 – WF	WF - Bubbler	Initial	42.5	POU filter and Resample - Bubbler Only	Post	NON-DET

Highland Middle School - White Plains City School District							
School Sample ID#	Sample Location	Outlet Description	Initial/Post Remediation	Lead Result ug/L (ppb)	Recommended Remediation Action	Post Remediation	Lead Result ug/L (ppb)
9	2012-Kitchen-Steamer-Sink (Pot Filler)	Kitchen Faucet	Initial	15.9	POU filter and Resample	Post	3.48

Post Road Elementary School - White Plains City School District							
School Sample ID#	Sample Location	Outlet Description	Initial/Post Remediation	Lead Result ug/L (ppb)	Recommended Remediation Action	Post Remediation	Lead Result ug/L (ppb)
29	2026 – Rm 118 – WF	Classroom Faucet	Initial	10.2	Temper Outlets/Disconnect Spouts/Put up Signage	N/A	N/A

White Plains High School - White Plains School District							
School Sample ID#	Sample Location	Outlet Description	Initial/Post Remediation	Lead Result ug/L (ppb)	Recommended Remediation Action	Post Remediation	Lead Result ug/L (ppb)
31	E102C-Auxiliary Locker Room Hallway – WF	Water Fountain	Initial	30.6	DISCONNECT WATER FOUNTAIN - NOT BEING USED	N/A	N/A
66	South Locker Room in Field House-WF	Water Fountain	Initial	5.24	DISCONNECT WATER FOUNTAIN - NOT BEING USED	N/A	N/A

Education House - White Plains School District							
School Sample ID#	Sample Location	Outlet Description	Initial/Post Remediation	Lead Result ug/L (ppb)	Recommended Remediation Action	Post Remediation	Lead Result ug/L (ppb)
9	426A-superintendent's Bathroom Sink – BF	Bathroom Faucet	Initial	25.5	Temper Outlets/Disconnect Spouts/Put up Signage	N/A	N/A