

College Station ISD

2007 Bond Update

October 21, 2008

College Hills Elementary School

Steel Roof Joist Erection



Photo Taken October 20, 2008

Steel Beams and Roof Joists



Photo Taken October 20, 2008

Exterior View from Southeast



Photo Taken October 20, 2008

South Side of Gymnasium



Photo Taken October 20, 2008

Steel Roof Joists



Photo Taken October 20, 2008

Floor Transition Area



Photo Taken October 20, 2008

South Side of Gymnasium



Photo Taken October 20, 2008

Application of Fire Retardant



Photo Taken October 20, 2008

Application of Fire Retardant



Photo Taken October 20, 2008

HVAC Work in Office Area



Photo Taken October 20, 2008

Cafeteria Area



Photo Taken October 20, 2008

HVAC Work in Office Area



Photo Taken October 20, 2008

Kitchen Area Exterior



Photo Taken October 20, 2008

North Side of Gymnasium



Photo Taken October 20, 2008

Kitchen Area Exterior



Photo Taken October 20, 2008

Main Entrance Area



Photos Taken October 20, 2008

Steel Roof Joist Erection



Photo Taken October 20, 2008

Creekview Elementary School

Helicopter Lift of HVAC Equipment



Photo Taken October 17, 2008

Helicopter Lift of HVAC Equipment



Photo Taken October 17, 2008

Helicopter Lift of HVAC Equipment



Photo Taken October 17, 2008

Helicopter Lift of HVAC Equipment




Photo Taken October 17, 2008

Classroom Wings Exterior



Photo Taken October 20, 2008

Classroom Wings Exterior



Photo Taken October 20, 2008

Drywall on Interior Corridor



Photo Taken October 20, 2008

Nurse's Office



Photo Taken October 20, 2008

Interior Wall Framing



Photo Taken October 20, 2008

Office Work Room Area



Photo Taken October 20, 2008

Office Area



Photo Taken October 20, 2008

Interior Wall Framing



Photo Taken October 20, 2008

Interior Wall Framing



Photo Taken October 20, 2008

Interior Wall Framing



Photo Taken October 20, 2008