FACILITIES COMMITTEE MEETING #3 / 05.29.24

NKSD FACILITY COMMITTEE MEETING #3 / AGENDA



AGENDA

SUQUAMISH SITE TOUR

OVERVIEW

OVERVIEW

OVERVIEW

OVERVIEW

NEXT STEPS



UPDATES FROM FAC MTG #2

- INFO IN GOOGLE DRIVE
- STRUCTURE OF A COST ESTIMATE
- HILDER PEARSON ELEMENTARY SCHOOL

- MAJOR DEFICIENCIES & SOLUTIONS
- SUQUAMISH ELEMENTARY SCHOOL

- **MAJOR DEFICIENCIES & SOLUTIONS**
- POULSBO ELEMENTARY SCHOOL
 - **MAJOR DEFICIENCIES & SOLUTIONS**
- DAVID WOLFLE ELEMENTARY SCHOOL

MAJOR DEFICIENCIES & SOLUTIONS




FAC MEETING #2 UPDATES /

NORTH KITSAP SCHOOL DISTRICT / MAY 29, 2024



NKSD FACILITY COMMITTEE MEETING #3 / FILE SHARING



s Commi	>	In
_ Capital Projects D	et	*
eBoundaryMap.pdf		
ee Meeting 2023060	08	*
df 🚢		



NKSD FACILITY COMMITTEE MEETING #3 / COST ESTIMATING



Construction Costs, Soft Costs, Project Cost

CLIENT	Bassetti Architects	DATE	May 28 th , 2024
CLIENT CONTACT	Jordan Kiel, Principal	PROJECT	Construction Cost, Soft Costs, Project Cost

Dear Jordan,

Please see below our explanation of the various costs used when completing bond planning estimates to capture construction costs and soft costs in order to estimate the project cost of a project.

Total Construction Costs Includes:

- **Direct Costs:** These are costs that can be directly attributed to a project for labor, materials and equipment including subcontractor overhead and profit.
- **Design / Estimating Contingency:** These costs are applied to design estimates to cover unforeseen risks and changes that may occur during the project design execution. This is essentially allocated risk contingency and is typically based on the estimator's best judgment following conversations with the design team and / or owner. In early design stage estimates this can range from 10% to 30% and at 100% Construction Documents this is typically 0%. As the design progresses the risk decreases.
- General Conditions / General Requirements: General Contractor indirect expenses, staffing and overhead costs
 associated with building the project.
- General Contractors Fee, Bonds and Insurance: These costs include the General Contractor's profit for the project and bonds and insurance per contractual requirements.
- Escalation: Escalation Is included to allow for increases in the price for labor and materials during the estimating phase of a project in order to account for the potential fluctuation of material prices during design and for labor agreement cost increases.

Soft Costs Includes:

- Washington State Sales Tax, this is applied to the Total Construction Cost on Construction Projects.
- Design, Engineering and Other Consultant Fees & Expenses
- Owner Consultant Fees
- Testing, Inspection, Permits
- Construction Contingency (Cost Impacts for changes to the design during construction (Change Orders))
- Builders Risk Insurance
- Construction / Project Management Services
- Fixtures, Furniture and Equipment (FF&E)
- Management Reserve / Project Contingency (Unallocated Risk Contingency)


TOTAL CONSTRUCTION COSTS + SOFT COSTS = PROJECT COST

Andy Cluness, Managing Partner

	KHS CTE Addit	tion - De	sign, Bid, Bu	ild	
Ecti	mate Date		1/1/2023		
Duild	ding GSF		7,000		
Build	ding Costs	\$	425	\$	2,975,000
Site	Costs			\$	500,000
Fotal Di	rect Cost	\$	496.43	\$	3,475,000
Esti	mating Contingency		3.50%	\$	121,625
	ubtotal			\$	3,596,625
Esca	alation to June 2023		3.00%		107,899
S	ubtotal			\$	3,704,524
Sub	Bonding		1.25%		46,307
GC/	CR		7.5%	\$	281,312
Fee,	/B&O Tax/GLI		5%	\$	201,607
S	ubtotal			\$	4,233,750
Fotal Co	onstruction Cost	\$	604.82	\$	4,233,750
Sale	s Tax		9.3%	\$	393,739
Desi	gn Fees		12.0%	\$	508,050
Own	er consultants, Testing		3.0%	\$	127,012
Perr	nits		2.0%	\$	84,675
Con	struction Contingency		7.5%	\$	317,531
Build	der's Risk		0.5%	\$	21,169
Con	struction Management		3.5%	\$	148,181
FF&	E		4.0%	\$	169,350
Proj	ect Contingency		5.0%	\$	211,687
Total So	oft Costs		46.8%	\$	1,981,395
	oject Cost			\$	6,215,145



NKSD FACILITY COMMITTEE MEETING #3 / LEVY PROJECTIONS





EPO Levy Amt CP Levy Amt New EPO Levy Nov. 24 Levy

NKSD FACILITY COMMITTEE MEETING #3 / SCAP FUNDING

NKSD

2025 SCAP Eligibility Estimate

			_		=		
	SqFt	ССА	FAP	NK	SD sqft	Estimate Availibity	I
K-8 (Total)	272,402	\$ 375.00	39%	\$	147.83	\$ 40,267,826	I
							╞
Breidablik ES	49,620	\$ 375.00	39%	\$	147.83	\$ 7,335,077	+
Gordon ES	51,238	\$ 375.00	39%	\$	147.83	\$ 7,574,257	Ī
Pearson ES	35,895	Not Age	e Eligible				
Poulsbo ES	48,731	Not Age	e Eligible				
Suquamish ES	42,794	Partially	' Eligible				Ī
Vinland ES	58,632	\$ 375.00	39%	\$	147.83	\$ 8,667,275	
Wolfle ES	48,170	\$ 375.00	39%	\$	147.83	\$ 7,120,730	
							Γ
Kingston MS	107,271	\$ 375.00	39%	\$	147.83	\$ 15,857,336	Γ
PMS Building #2	22,179	\$ 375.00	39%	\$	147.83	\$ 3,278,611	
Kingston HS	112,784	Not Age	e Eligible				
NKHS	155,256	Not Age	e Eligible				
						Total	L

	- . - .			
Estimate				
Avail	ibity w/SOFT			
	Costs			
\$	45,301,304			
-				
\$	8,251,961			
\$	8,521,040			
\$	9,750,685			
\$	8,010,822			
\$	17,839,503			
\$	3,688,437			
\$	56,062,446			




ELEMENTARY SCHOOL DATA /

NORTH KITSAP SCHOOL DISTRICT / MAY 29, 2024



NKSD FACILITY COMMITTEE MEETING #3 / SCHOOL COMPARISON





- Preventative Maintenance
- Modernization/Addition
- Major Systems Upgrade
- Furniture





site info

ADDRESS

15650 CENTRAL VALLEY RD NW, POULSBO, WA 98370


SITE AREA 10.12 ACRES











potential scope

- USEFUL LIFE, CONTROLS ARE OBSOLETE
- SUITE
- + IMPROVED SITE VEHICLE DROP-OFF, QUEUING, AND PARKING
- TUCKPOINTING, CLEANING)

+ COMPLETE HVAC REPLACEMENT WITH UPDATED CONTROLS, WSHP END OF THEIR

+ CREATE ACCESSIBLE ENTRY WITH SAFETY VESTIBULE AND EXPANDED ADMIN

+ ADDED GYM SPACE WITH MINOR IMPROVEMENTS TO CURRENT CAFETERIA/GYM

+ EXTERIOR ENVELOPE IMPROVEMENTS (BACKER/SEALANTS, CAULKING,















TOP CHALLENGES


- 1. AND DROP-OFF
- SITE SECURITY / LACK OF FENCING 2.
- З.
- SCHOOL SECURITY / NO SECURE VESTIBULES 4.
- NOT ENOUGH RESTROOMS FOR STAFF/STUDENTS 5.
- NO SMALL GROUP LEARNING OR PUSH-IN SPACES 6.
- LACK OF MAKERSPACES 7.
- 8. PROGRAMS, SPED
- HVAC SYSTEM INCONSISTENT 9.
- 10. NO DESIGNATED COMMUNITY SPACES

PROXIMITY TO THE ROAD, PARKING LOT SIZE, PICK-UP

SITE NOT ACCESSIBLE TO PEOPLE WITH LIMITED MOBILITY

MINIMAL SPACES FOR STUDENT SERVICES - ELL, NATIVE AMERICAN LIAISON, PSYCHOLOGIST, BEFORE/AFTER SCHOOL





Major Systems Upgrade Modernization/Addition Site Improvements Preventative Maintenance



Major Systems Upgrade

Fire alarm replacement New bell and paging system

Replace water heaters, nearing end of useful life.

Replace HVAC Controls

Replace HVAC System

Modernization/Addition

New Gym addition

Small group learning spaces

Makerspace

Replace all lights with new LED fixtures

Replace operable walls between classrooms

Refresh bathroom finishes

Create secure entry vestibule

Update classroom casework

Renovate kitchen

Site Improvements

New playground

Improve site lighting

Replace concrete and asphalt paths and accessible ramps at various locations throughout the site to improve accessibility Install chain link fence gates to secure play areas and fields

Install an accessible concrete path from the crosswalk on Central Valley Road NW to the building entrance.

Install approximately 34 protective bollards

Improve stormwater collection and conveyance.

Remove tree roots in parking lot

Make ADA parking code compliant

Make path between play field and building accessible

Make slopes in parking lot and drive aisle code compliant

Construct a new parking lot in the area of one of the existing play fields. Preserve the existing parking lot for buses and staff.

\$	4,591,799
\$	232,144
\$	198,980
\$	98,164
\$	547,195
\$	3,515,316
\$	12,442,090
\$	4,447,538
\$	158,834
\$	1,976,684
\$	750,141
\$	77,630
\$	185,314
\$	3,514,104
\$	932,515
\$	399,330
\$	3,130,176
\$	255,000
\$	199,665
\$	159,732
\$	79,866
\$	159,732
\$	99,833
\$	119,799
\$	19,967
\$	99,833
\$	139,766
\$	598,995
\$	1,197,990





Preventative Maintenance

New gym flooring Replace exterior sealants (windows and siding) Paint exterior & replace soffits Replace below grade water pipe between buildings Replace classroom carpets Replace classroom acoustic ceiling tiles Replace Roof - full assembly Replace roof - membrane only **Furniture** Replace all furniture **Grand Total**

\$	5,181,945
\$	101,305
\$	66,276
\$	95,250
\$	41,331
\$	367,983
\$	244,031
\$	2,950,696
\$	1,315,074
\$	672,472
\$	672,472
\$	26,018,481










- + IMPROVED SITE VEHICLE DROP-OFF, QUEUING, AND PARKING
- TUCKPOINTING, CLEANING)
- + REPLACE ELECTRICAL SWITCHGEAR
- * 11 in Developmental Pre-K


+ SITE ACCESSIBILITY IMPROVEMENTS (RAMPS, GUARDRAILS, PLAYGROUND)

+ EXTERIOR ENVELOPE IMPROVEMENTS (BACKER/SEALANTS, CAULKING,
















TOP CHALLENGES

- BUILDING PRESENTATION NOT WELCOMING 1.
- 2. AND DROP-OFF
- SITE SECURITY / LACK OF SECURE VESTIBULE З.
- ENTIRE SITE NOT ACCESSIBLE TO PEOPLE WITH 4. LIMITED MOBILITY
- SIGHT LINES OBSTRUCTED 5.
- HVAC SYSTEM INCONSISTENT 6.
- WI-FI IS NOT SECURE 7.
- NO DEDICATED STAFF RESTROOMS 8.

PROXIMITY TO THE ROAD, PARKING LOT SIZE, PICK-UP





Major Systems Upgrade Modernization/Addition Site Improvements Preventative Maintenance



Major Systems Upgrade

Fire alarm replacement	
New bell and paging sys	stem
Replace HVAC System	
Replace electrical switc	hgear
Modernization/Additio	าก
Refresh bathroom finisl	hes
Replace lights with LED	fixtures
Building addition that re	emoves need for portables and builds proper SPED suite
Create secure entry ves	stibule
Site Improvements	
New playground	
Create a paved parking	lot along the south side of the site where the gravel lot exists
Increase the parent loo	p queue length to approximately 1,000 feet.
Replace concrete and a	sphalt paths and accessible ramps at various locations throughout the site to improve accessibility
Remove and replace tw	vo sets of stairs between the public right-of-way and building to bring up to current codes
Install an accessible cor	ncrete path from the south driveway to the building entrance.
Install chain link fence	gates to secure play areas and fields
Create accessible path l	between building and play field
Pave the existing emerg	gency vehicle access road to create a loop around the building.
Preventative Maintena	ance
Replace exterior sealan	its (windows and siding)
Update wall finishes	
Replace acoustic ceiling	zs
Replace carpet	
Replace roof - membra	ne only
Replace Roof and roof of	drains - full assembly
Furniture	
Replace all furniture	
rand Total	


\$	5,033,882
\$ \$	291,222
\$	249,619
\$	4,409,939
\$	83,102
\$	7,277,764
\$	165,098
\$	1,202,332
\$	5,271,156
\$	639,178
\$ \$	2,210,650
	214,000
\$	598,995
\$	598,995
\$	299,498
\$	39,933
\$	79,866
\$	39,933
\$	39,933
\$	299,498
\$	6,505,283
\$	86,328
\$	802,942
\$	370,898
\$	496,966
\$	1,463,784
\$	3,284,365
\$	748,696
\$	748,696
\$	21,776,276




site info

ADDRESS 18531 NOLL RD NE POULSBO, WA 98370


SITE AREA 36.60 ACRES [C0-LOCATED WITH MIDDLE SCHOOL SITE]












- + CREATE ENTRY SAFETY VESTIBULE AND EXPANDED ADMIN SUITE
- + SMALL CLASSROOM ADDITION TO ELIMINATE NEED FOR PORTABLES
- + FIRE ALARM SYSTEM REPLACEMENT
- + SITE STORMWATER MANAGEMENT UPGRADES
- + MISC. INTERIOR IMPROVEMENTS















TOP CHALLENGES

- 1. AND DROP-OFF
- SITE SECURITY / LACK OF FENCING 2.
- 3. PATHWAY IS DANGEROUS
-]4.
- 5.
- 6.
- 7.

PROXIMITY TO THE ROAD, PARKING LOT SIZE, PICK-UP

HEADSTART AND DEVELOPMENTAL PRE-SCHOOL DROP-OFF


SECURITY OF FENCING ON SITE [HEIGHT AND HOLES]

LEARNING COMMONS TOO LARGE - NEED TO BE BROKEN UP

FF&E - NEED FOR FLEXIBLE FURNITURE AND NEW STORAGE

CONCERNED ABOUT ENROLLMENT AND PORTABLES LOCATION





Major Systems Upgrade Modernization/Addition Site Improvements Preventative Maintenance




Major Systems Upgrade	\$ 661,033
Fire alarm replacement	\$ 355,942
New bell and paging system	\$ 305,092
Modernization/Addition	\$ 6,657,002
Remaining LED lighting upgrades	\$ 1,018,463
Add panic hardware for electrical room egress doors.	\$ 1,997
Correct door swing in electrical room for egress.	\$ 1,497
Remove portables, provide 3 classroom additon	\$ 5,078,978
Create secure entry vestibule	\$ 556,06
Preventative Maintenance	\$ 9,519,70
New gym flooring	\$ 96,36
Replace classroom carpets	\$ 379,36
Replace classroom acoustic ceiling tiles	\$ 251,57
Replace Roof - full assembly	\$ 4,183,014
Replace roof - membrane only	\$ 1,864,29
Replace exterior cladding	\$ 2,715,13
Relocate rooftop bathroom exhaust fan	\$ 29,95
Site Improvements	\$ 1,325,292
New playground	\$ 307,00
Relocate the accessible parking stalls	\$ 59,90
Provide a path with stairs and handrails to the athletic fields located north of the site.	\$ 59,90
Lower approximately 6 catch basin grates to improve stormwater collection	\$ 79,86
Remove the gravel pedestrian path	\$ 19,96
Code-required storm drainage improvements.	\$ 798,660
Furniture	\$ 866,54
Replace all furniture	\$ 866,54
rand Total	\$ 19,029,573




site info


ADDRESS 27089 HIGHLAND ROAD NE, KINGSTON, WA 98346

SITE AREA 19.08 ACRES










potential scope

- + CREATE ENTRY SAFETY VESTIBULE AND EXPANDED ADMIN SUITE
- + IMPROVED SITE VEHICLE DROP-OFF, QUEUING, AND PARKING
- + INCREASED ELECTRICAL CAPACITY WITH ADDITION CIRCUITS
- + SEISMIC UPGRADESTOTIE ROOFTO MASONRY WALLS
- + PAINT EXTERIOR CLADDING TO ALIGN WITH GYM ADDITION
- 30 pre-school students, 89 Options students in portables not included











NORTH KITSAP SCHOOL DISTRICT / MAY 29, 2024





TOP CHALLENGES


- 1. AND DROP-OFF
- 2.
- LIGHTING NOT ADJUSTABLE 3.
- PICK-UP AND DROP-OFF LOOPS ARE CONJESTED 4.
- **OPTIONS STUDENTS ARE IN PORTABLES** 5.
- LACK OF FENCING AT PLAY AREAS 6.
- 7.
- 8. NEED FLEXIBLE, ADAPTABLE FURNITURE

PROXIMITY TO THE ROAD, PARKING LOT SIZE, PICK-UP

LACK OF SMALL GROUP LEARNING / PUSH IN SPACE

ACCESSIBILITY OF SITE FOR STUDENTS OF ALL MOBILITIES





Major Systems Upgrade Modernization/Addition Site Improvements Preventative Maintenance



Major Systems Upgrade	\$ 593,987
Fire alarm replacement	\$ 319,839
New bell and paging system	\$ 274,148
Modernization/Addition	\$ 4,068,485
Replace Interior lighting with LED	\$ 1,320,480
Relocate main control panels in attic to a location more accessible to district maintenance personnel.	\$ 79 <i>,</i> 866
Create secure entry vestibule	\$ 977,560
Improve anchorage of the roof to the masonry bearing walls	\$ 1,690,580
Site Improvements	\$ 3,533,773
New playground	\$ 198,000
Replace Covered Play Structure	\$ 1,059,592
Expand parking area to the north into existing playfield.	\$ 798,660
Separate bus loop from parent loop	\$ 199,665
Create drive aisle in the playfield north of parking lot.	\$ 299,498
Repair asphalt surface	\$ 159,732
provide accessible route from lower parking to building	\$ 299,498
Create accessible path between ROW and building	\$ 59,900
replace on-site sidewalks to meet accessiblity requirements	\$ 199,665
Install chainlink fence around play areas and fields	\$ 19,967
Address stormwater ponding	\$ 39,933
Improve site lighting	\$ 199,665
Preventative Maintenance	\$ 1,865,571
Exterior Painting	\$ 107,746
Replace Roof	\$ 789,451
Add circuits to avoid breakers tripping	\$ 19,967
Fix malfuntioning emergency lighting fixtures	\$ 29,950
Replace classroom carpets	\$ 474,204
Replace classroom acoustic ceiling tiles	\$ 314,472
Add pull-down access ladders to mechanical equip	\$ 29,950
Replace buried propane tank to be code compliant	\$ 99,833
Furniture	\$ 866,546
Replace all furniture	\$ 866,546
rand Total	\$ 10,928,363





THANKYOU.

NORTH KITSAP SCHOOL DISTRICT / MAY 29, 2024

