

SIX MONTH PERIODIC SURVEILLANCE

Performed for:

LINCOLNSHIRE-PRAIRIE VIEW SCHOOL DISTRICT #103

111 Barclay Boulevard, Suite #100 Lincolnshire, IL 60069

Project Location:



LAURA B. SPRAGUE ELEMENTARY SCHOOL

2425 Riverwoods Road Lincolnshire, IL 60069

August 5, 2022

MEC PROJECT #: 22-08-436-INSP

Corporate Headquarters 2551 N. Bridge Street Yorkville, Illinois 60560

2551 N. Bridge Street Yorkville, Illinois 60560 P: 630-553-3989

Chicago Office 954 W. Washington Blvd. Suite 425 Chicago, Illinois 60607 P: 312-535-3228

Peoria Office 3100 N. Knoxville Ave. Suite 204 Peoria, Illinois 61603 P: 309-621-4680







LINCOLNSHIRE-PRAIRIE VIEW SCHOOL DISTRICT #103

Daniel Wright Junior High School 1370 N. Riverwoods Road Lincolnshire, IL 60069

Table of Contents
MEC Project #: 22-08-434-INSP

Inspector & Designated Person Compliance Statement	Section 1
Six Month Periodic Surveillance Report	Section 2
Section 855.300 - Local Education Agency (LEA) Requirements	Section 3
Certifications	Section 4

Six Month Periodic Surveillance Compliance Statement

Inspector's Compliance Statement

I hereby certify that I have conducted a six-month periodic surveillance of known and assumed asbestos-containing building materials (ACBM) according to AHERA regulations contained in the Federal Register 40 CFR 763.93(b).

Inspector

Stuart Bruce

IDPH License # 100-03616

August 5, 2022

Date

Designated Person's Compliance Statement

I hereby accept responsibility for implementing the current Management Plan on behalf of Lincolnshire-Prairieview School District #103 and for maintaining Daniel Wright Junior High School in full compliance with EPA, IDPH, and all applicable OSHA requirements with respect to asbestos-containing materials.

Designated Person

Eric Jonasson

Director of Facilities

August 5, 2022

Date

Lincolnshire-Prairieview School District #103 111 Barclay Boulevard, Suite #100 Lincolnshire, IL. 60069 Daniel Wright Junior High School 1370 N. Riverwoods Road Lincolnshire, IL 60069 MEC Project #: 22-08-434-INSP



incolnshire-Prairie View School District #103 **School District:**

August 5, 2022

Reassessment Date:

Daniel Wright Junior High School **Building:**

370 N. Riverwoods Road Address:

incolnshire, IL 60069

Midwest Environmental Consulting Services, Inc. 2551 N. Bridge Street 34-049-1030-1001 School ID #: Conducted By:

22-08-434-INSP

MEC Project #:

Stuart Bruce Inspector:

Yorkville, IL 60560

IDPH #: 100-03616

cation Condition Condition

N/A	Under carpet in Rooms 105, 121, & 122. Abated in Hallway – August - 2020	Abated in Hallway – August, 2020	Abated in Hallway – August, 2020	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
1972 Wing – Rooms 107 & 119	1972 Wing – Cafeteria, Hallways, Room 105, 121, 122, Storage Room in Band Room 125, 127B	1972 Wing – Hallway (Outside Room 119), Room 119 – Closet, Orchestra Storage	Original 1972 Construction – Room 119, 127, SW Hallway (Outside Rooms 111 & 112)	1972 Wing – Boys' & Girls' Locker Rooms, Bathrooms Front Entrance Exterior Overhang & Vestibule	1987 Addition – District Offices – Main Entrance – Vestibule	1972 Wing – Throughout	1972 Wing – Throughout	1972 Wing – Assistant Principal's Office & Room 129	1972 Wing – Main Office – Bathrooms, Rooms 119, 121, 122, & Practice Room	1972 Wing – Fitness Center
Lab Table Tops	9x9 Floor Tile/Mastic – White w/Green & Tan Streaks	12x12 Floor Tile/Mastic – White w/Green Streaks	12x12 Floor Tile/Mastic – White w/Blue Specks	Plaster Ceiling	Plaster Ceiling	Cementitious Pipe Fittings on Fiberglass Lines	3" Baseboard/Adhesive Bluish Gray	3" Baseboard/Adhesive – Black	3" Baseboard/Adhesive – Beige	3" Baseboard/Adhesive – Brown
LT	FT-1	FT-2	FT-3	а	SPB	₽ſŢ	MBA	MBB	MBC	MBD

Environmental Protection Agency §763.93 (b) *Periodic surveillance*. (1) At least once every 6 months after a management plan is in effect, each local education agency shall conduct periodic surveillance shall: surveillance in each building that it leases, owns, or otherwise uses as a school building that contains ACBM or is assumed to contain ACBM. (2) Each person performing periodic surveillance shall: (3) Visually inspect all areas that are identified in the management plan as ACBM or assumed ACBM. (ii) Record the date of the surveillance, his or her name, and any changes in the condition of the materials. (iii) Submit to the person designated to carry out general local education agency responsibilities under §763.84 a copy of such record for inclusion in the management plan.



August 5, 2022 Reassessment Date:

incolnshire-Prairie View School District #103 Daniel Wright Junior High School **Building:** School District:

370 N. Riverwoods Road Address:

incolnshire, IL 60069

22-08-434-INSP MEC Project #:

34-049-1030-1001 School ID #:

Midwest Environmental Consulting Services, Inc. 2551 N. Bridge Street Conducted By:

Yorkville, IL 60560

Stuart Bruce

100-03616

IDPH #: Inspector:

Comments Condition Present Condition Previous Location Material Description HSA

N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
1972 Wing – Boys' Locker Room – Office & Adjacent Hall	1972 Wing – Rooms 109A, 110, & 123	1972 Wing – Maintenance Room 108B	1987 Addition – District Offices - Throughout	1996 Wing – Throughout	1996 Wing – Room 202	1996 Wing – Rooms 205 & 206	1996 Wing – Rooms 224 & 225	1972 Wing – Throughout	1972 Wing – Quest Kitchen & Grooming Room	1972 Wing – Scattered Areas – Throughout
3" Baseboard/Adhesive - Tan	3" Baseboard/Adhesive – Dark Green	3" Baseboard/ Adhesive – Light Green	3" Baseboard/Adhesive – Gray	3" Baseboard/Adhesive Blue	3" Baseboard/Adhesive Cream	3" Baseboard/Adhesive – Green	3" Baseboard/Adhesive – Black	2'x4' Lay-In Ceiling Tile – Pinholes	2'x4' Lay-In Ceiling Tile – Gypsum	2'x4' Lay-In Ceiling Tile – Small Non-Directional Fissures w/Pinholes
MBE	MBF	MBG	MBH	MBI	MBJ	MBK	MBL	MCA	MCC	MCD

Environmental Protection Agency §763.93 (b) *Periodic surveillance*. (1) At least once every 6 months after a management plan is in effect, each local education agency shall conduct periodic surveillance shall: surveillance in each building that it leases, owns, or otherwise uses as a school building that contains ACBM or is assumed to contain ACBM. (2) Each person performing periodic surveillance shall: (i) Visually inspect all areas that are identified in the management plan as ACBM or assumed ACBM. (ii) Record the date of the surveillance, his or her name, and any changes in the condition of the materials. (iii) Submit to the person designated to carry out general local education agency responsibilities under §763.84 a copy of such record for inclusion in the management plan.



August 5, 2022 Reassessment Date:

incolnshire-Prairie View School District #103 Daniel Wright Junior High School **School District: Building:**

1370 N. Riverwoods Road Address:

incolnshire, IL 60069

Yorkville, IL 60560

2551 N. Bridge Street

Midwest Environmental Consulting Services, Inc.

34-049-1030-1001 22-08-434-INSP

> School ID #: Conducted By:

MEC Project #:

100-03616 IDPH #: Stuart Bruce Inspector:

Comments Condition Present Condition Previous Location Material Description HSA

N/A	N/A	N/A	N/A	N/A	N/A	N/A	Under carpet squares.	N/A	N/A
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
1972 Wing – Room 110A, 119, 123, & 128	1972 Wing – Staff Lounge	1987 Addition – District Offices – Throughout	1987 Addition – District Offices – Superintendent's Office	1996 Wing – Throughout	1996 Wing — Rooms 205, 205A, & 206	1996 Wing – Rooms 222, 224, & 225	1972 Wing – Front Entrance Vestibule	1972 Wing – Front Conference Room & Cafeteria	1972 Wing – Nurse's Office
2'x2' Lay-In Ceiling Tile – Smooth Texture	2'x2' Lay-In Ceiling Tile – w/Pinholes	2'x2' Lay-In Ceiling Tile – Rough Texture – Fissures w/Pinholes	2'x2' Lay-In Ceiling Tile – Non- Directional Fissures w/Pinholes	2'x4' Lay-In Ceiling Tile – Non-Directional Fissures w/Pinholes	2'x4' Lay-In Ceiling – Pinholes	2'x4' Lay-In Ceiling Tile – Large Fissures w/Pinholes	12x12 Floor Tile/ Mastic – Gray w/1" Squares	12x12 Floor Tile/Mastic – Beige w/Gray & Tan Flecks	12x12 Floor Tile/Mastic – Light Gray w/Dark Gray Flecks
MCE	MCF	MCG	MCH	MCI	MCJ	MCK	MFA	MFB	MFC

Environmental Protection Agency §763.93 (b) *Periodic surveillance*. (1) At least once every 6 months after a management plan is in effect, each local education agency shall conduct periodic surveillance surveillance in each building that it leases, owns, or otherwise uses as a school building that contains ACBM or is assumed to contain ACBM. (2) Each person performing periodic surveillance shall: (i) Visually inspect all areas that are identified in the management plan as ACBM or assumed ACBM. (ii) Record the date of the surveillance, his or her name, and any changes in the condition of the materials. (iii) Submit to the person designated to carry out general local education agency responsibilities under §763.84 a copy of such record for inclusion in the management plan.



Reassessment Date: August 5, 2022

School District: Lincolnshire-Prairie View School District #103

Building: Daniel Wright Junior High School

Address: 1370 N Riverwoods Road

incolnshire, IL 60069

School ID #: 34-049-1030-1001

Conducted By: Midwest Environmental Consulting Services, Inc. 2551 N. Bridge Street

Yorkville, IL 60560

22-08-434-INSP

MEC Project #:

Inspector: Stuart Bruce

100-03616

IDPH #:

Comments
Previous Present condition Condition
Previous Condition
Location
Material Description
HSA

N/A	N/A	N/A	N/A	N/A	N/A	Ν/A	N/A	N/A	N/A	N/A
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
1972 Wing – Locker Rooms, Bathrooms	1972 Wing – Cafeteria	1972 Wing – Quest Kitchen	1972 Wing – Fitness Center	1972 Wing – Boys' Locker Room – Office & Adjacent Hall	1972 Wing – Boys' Locker Room – Office – Shower Room	1972 Wing – Boys' Locker Room – Shower & Storage Room	1972 Wing — Girls' Locker Room — Shower & Storage Room	1972 Wing – Rooms 123, 109A, & 110	1972 Wing – Band Room 125	1972 Wing – Room 126
2"x2" Ceramic Tile/Grout – Gray w/Dark Gray Specks	12"x12" Floor Tile & Mastic Blue w/Gray Flecks	Anti-Slip Epoxy Flooring – Black, Green, & White Specks	Rubber Mat Flooring/Mastic – Tan w/Black Streaks	2'x4' Linoleum Flooring/Mastic – Tan & Beige	1"x1" Ceramic Tile/Grout Tan	1"x1" Ceramic Tile/Grout – Brown, Tan, & Gray Tiles	1"x1" Ceramic Tile/Grout – Green & Beige Tiles	12x12 Floor Tile/Mastic – Light Green Speckled Pattern	12x12 Floor Tile/Mastic – White w/Green Accent Tiles	Linoleum/Mastic – White w/Gray Specks
MFD	MFE	MFG	MFH	MFI	Γ±W	MFK	MFL	MFM	MFO	MFP

Environmental Protection Agency §763.93 (b) Periodic surveillance. (1) At least once every 6 months after a management plan is in effect, each local education agency shall conduct periodic surveillance shall: surveillance in each building that it leases, owns, or otherwise uses as a school building that contains ACBM or is assumed to contain ACBM. (2) Each person performing periodic surveillance shall: (i) Visually inspect all areas that are identified in the management plan as ACBM or assumed ACBM. (ii) Record the date of the surveillance, his or her name, and any changes in the condition of the materials. (iii) Submit to the person designated to carry out general local education agency responsibilities under §763.84 a copy of such record for inclusion in the management plan.



August 5, 2022 Reassessment Date:

incolnshire-Prairie View School District #103 **School District:**

Daniel Wright Junior High School 1370 N. Riverwoods Road **Building:** Address:

Lincolnshire, IL 60069

34-049-1030-1001 22-08-434-INSP MEC Project #: School ID #:

Midwest Environmental Consulting Services, Inc. Conducted By:

2551 N. Bridge Street Yorkville, IL 60560

Stuart Bruce

100-03616

IDPH #: Inspector:

Comments	Collinellis	Commonte
Present Condition	Conditio	Present
Previous Condition	Condition	Previous
Location	Location	I santian
Material Description	Material Description	Marketin December
HSA	HSA	YOU

N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Ν/A
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
1972 Wing – Room 107 & Maintenance Room 108B	1987 Addition – District Offices – Administration File Closet	1987 Addition – District Offices – Superintendent's Bathroom	1987 Addition – District Offices – Entrance	1987 Addition – District Offices – Lobby	1987 Addition – District Offices – Hall & Men's Room	1987 Addition – District Offices – Women's Room	1987 Addition – District Offices – Kitchen	1996 Wing – Rooms 202, 222, 224, & 225	1996 Wing – Bathrooms	1996 Wing – Rooms 205 & 206
12x12 Floor Tile/Mastic – White w/Gray Specks	12x12 Floor Tile/Mastic – Beige Marble Pattern	2"x2" Ceramic Tile/Grout – Light Green	4"x4" Ceramic Tile/Grout – Light Beige	Vinyl Flooring/Mastic – Wood Pattern	1"x1" Ceramic Tile/Grout – Tan	1"x1" Ceramic Tile/Grout – Light Brown	12x12 Floor Tile/Mastic – Light Blue w/Beige Flecks	12x12 Floor Tile/Mastic – White w/Blue Streaks	2"x2" Ceramic Tile/Grout – Tan	12x12 Floor Tile/Mastic – Light Green Speckled Pattern
MFR	MFS	MFT	MFU	MFV	MFW	MFX	MFY	MFZ	MFAA	MFAB

Environmental Protection Agency §763.93 (b) *Periodic surveillance*. (1) At least once every 6 months after a management plan is in effect, each local education agency shall conduct periodic surveillance shall: surveillance in each building that it leases, owns, or otherwise uses as a school building that contains ACBM or is assumed to contain ACBM. (2) Each person performing periodic surveillance shall: (i) Visually inspect all areas that are identified in the management plan as ACBM or assumed ACBM. (ii) Record the date of the surveillance, his or her name, and any changes in the condition of the materials. (iii) Submit to the person designated to carry out general local education agency responsibilities under §763.84 a copy of such record for inclusion in the management plan.



August 5, 2022

Reassessment Date:

School District: Lincolnshire-Prairie View School District #103

Building: Daniel Wright Junior High School Address: 1370 N. Riverwoods Road

Lincolnshire, IL 60069

MEC Project #: 22-08-434-INSP School ID #: 34-049-1030-1001

School ID #: 34-049-1030-1001

Conducted By: Midwest Environmental Consulting Services, Inc.

2551 N. Bridge Street Yorkville, IL 60560 Inspector: Stuart Bruce IDPH #:

100-03616

N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
1996 Wing – Rooms 205 & 206	1972 Wing – Room 129 & 1996 Wing – Room 210	1972 Wing – Rooms 126 & 127	1987 Addition – District Offices – Kitchen	1972 Wing – Hallway Doors	1972 Wing – Rooms 106, 107, 126, 127, & 128, 132, 133, 134	1972 Wing – Boys' & Girls' Bathrooms	1972 Wing – Boys' & Girls' Locker Room – Showers, Rooms 135 & 139	1987 Addition – District Offices – Bathrooms	1996 Wing – Bathrooms
12x12 Floor Tile/Mastic – White w/Tan Specks	Sink Undercoating – Gray	Sink Undercoating – Black	Sink Undercoating – White	Fire Doors	Transite Window Panels	4"x4" Ceramic Wall Tile/Grout - White & Gray Tiles	4"x4" Ceramic Wall Tile/Grout - White	4"x4" Ceramic Wall Tile/Grout - Tan	4"x4" Ceramic Wall Tile/Grout - White & Gray Tiles
MFAC	MMA	MMB	MMC	MMD	MTA	MWA	MWB	MWC	MWD

Environmental Protection Agency §763.93 (b) Periodic surveillance. (1) At least once every 6 months after a management plan is in effect, each local education agency shall conduct periodic surveillance shall: surveillance in each building that it leases, owns, or otherwise uses as a school building that contains ACBM or is assumed to contain ACBM. (2) Each person performing periodic surveillance shall: (i) Visually inspect all areas that are identified in the management plan as ACBM or assumed ACBM. (ii) Record the date of the surveillance, his or her name, and any changes in the condition of the materials. (iii) Submit to the person designated to carry out general local education agency responsibilities under §763,84 a copy of such record for inclusion in the management plan.

ASBESTOS ABATEMENT FOR PUBLIC AND PRIVATE SCHOOLS AND COMMERCIAL AND PUBLIC BUILDINGS IN ILLINOIS (77 ILL. ADM. CODE 855)

SUBPART E: LOCAL EDUCATIONAL AGENCY RESPONSIBILITIES AND STANDARDS FOR ABATEMENT

SECTION 855.300 LOCAL EDUCATION AGENCY (LEA) REQUIREMENTS

a. Each LEA shall:

- 1. Ensure that any persons who perform inspections and reinspections, develop and update management plans, develop and implement response actions, including operations and maintenance or repair, are licensed in accordance with Section 855.100.
- **2.** Ensure that all custodial and maintenance employees are properly trained as required by the Asbestos Hazard Emergency Response Act (AHERA), the Asbestos Abatement Act, and this Part.
- **3.** Ensure that parents, teachers, and employee organizations are notified in writing at least once each school year of inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. The LEA shall include in the management plan a description of the steps taken to notify such organizations and a dated copy of the notification.
- **4.** The LEA shall designate a person to oversee all management plan activities and ensure that the designated person receives adequate training to perform the assigned duties of the local education agency. Such training shall include:
 - A. Health effects of asbestos.
 - B. Detection, identification and assessment of ACBM.
 - C. Options for controlling ACBM.
 - **D.** Asbestos management programs.
 - **E.** Relevant federal and State regulations concerning asbestos, including those of the Occupational Safety and Health Administration, U.S. Department of Labor, the U.S. Department of Transportation, the U.S. Environmental Protection Agency and the Department.

- **5.** Ensure that short-term workers (e.g., telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations of asbestoscontaining building materials (ACBM) and/or assumed ACBM.
- **6.** Ensure that warning labels are posted in accordance with the following:
 - **A.** The LEA shall attach a warning label immediately adjacent to any ACBM and suspected ACBM assumed to be ACBM located in a routine maintenance area (such as boiler rooms) at each school building.
 - **B.** All labels shall be prominently displayed in readily visible locations and shall remain posted until the ACBM is removed.
 - **C.** The warning label shall state in print which is readily visible: Caution; Asbestos. Hazardous. Do Not Disturb Without Proper Training and Equipment.
- **7.** Ensure that the management plans are available for inspection and notification of such availability has been provided as specified in the management plan.
- **8.** Keep a copy of the plan in each school and district administrative office. Management plans shall be available for inspection by workers before work begins in any area of a school building. The management plans shall be available during normal business office hours, without cost or restriction, for inspection by representatives of the USEPA, the Department, teachers, other school personnel, parents and the general public. The LEA may charge a reasonable cost to make copies of management plans.
- 9. Maintain records as part of the management plan.
- **10.** Ensure that each management plan contains a statement, signed by the individual designated by the LEA, which certifies that the LEA responsibilities have been met or will be met.
- **11.** Ensure that three year reinspections are conducted in accordance with this Part and Section 855.310(m).
- **12.** Ensure that the three year school reinspection information form provided by the Department is submitted to the Department within 30 days from the reinspection.

b. Recordkeeping

- 1. Records required under this Section shall be maintained in a centralized location in the administrative office of both the school and the LEA as part of the management plan. For each homogeneous area where all ACBM has been removed, the LEA shall ensure that such records are retained for six years after completion of removal.
- 2. For each preventive measure and response action taken for ACBM and suspected ACBM assumed to be ACBM, the LEA shall provide:
 - A. A detailed written description of the response action and methods used, the location where the response action was taken, the reasons for selecting the response action, the start and completion dates of the work, the names and addresses of all contractors involved, and if applicable, their IDPH license I.D. number, and if ACBM is removed, the name and location of the disposal site of the ACBM.
 - **B.** The name, signature, and Department-issued license I.D. number of any person collecting any air samples required to be collected at the completion of certain response actions, the locations where samples were collected, date of collection, the name and address of the laboratory analyzing the samples, the date of analysis, the results of the analysis, the method of analysis, the name and signature of the person performing the analysis, and a statement that the laboratory meets the applicable requirements of the National Bureau of Standards TEM laboratory accreditation.
 - **C.** For each time that periodic surveillance is performed, the LEA shall record the name of each person performing the surveillance, the date of the surveillance, and any changes in the conditions of the materials.
 - **D.** For each time that asbestos cleaning is performed, the LEA shall record the name of each person performing the cleaning, the IDPH licensed worker I.D. number, the date of such cleaning, the locations cleaned, and the methods used to perform such cleaning.

- E. For each time that operations and maintenance activities are performed, the LEA shall record the name of each person performing the activity, the Department-issued licensed worker I.D. number, the start and completion dates of the activity, the locations where such activity occurred, a description of the activity including preventive measures used, and if ACBM is removed, the name and location of the storage or disposal site of the ACBM.
- F. For each time that major response action is performed, the local education agency shall provide the name, signature and Department-issued license I.D. number of each person performing the activity, the start and completion dates of the response action, the locations where such response action occurred, a description of the activity, including preventive measures used, and if ACBM is removed, the name and location of the storage or disposal site of the ACBM.
- **G**. For each fiber release episode, the LEA shall provide the date and location of the episode, the method of repair, preventive measures or response action taken, the name of each person performing the work, the IDPH license ID number, and if ACBM is removed, the name and location of the storage or disposal site of the ACBM.



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

STUART J BRUCE

2/17/2022

8241 GRAND AVENUE RIVER GROVE, IL 60171

ASBESTOS PROFESSIONAL LICENSE ID NUMBER:

03616

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

ID NUMBER

ISSUED

EXPIRES

INSPECTOR

11/12/2022

100 - 03616

2/17/2022

05/15/2023

PROJECT MANAGER

9/1/2022

STUART J BRUCE 8241 GRAND AVENUE

RIVER GROVE, IL 60171

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health

This license is valid only when accompanied by a valid training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos EMAIL Address: dph.asbestos@illinois.gov

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Stuart Bruce

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/12/2021

Exam Date: 11/12/2021

Expiration Date: 11/12/2022

Certificate Number: BIR2111122720

Kathy De Salver