



19



19



2



2



9

12

5

19

2


19

27


24

NOTE: IMAGES ARE FOR VISUAL REFERENCES TO HELP UNDERSTAND DAMAGES. THEY DO NOT REPRESENT THE ENTIRE SCOPE OF WORK AND SHOULD BE USED IN CONJUNCTION WITH THE DRAWINGS AND CURRENT CONDITIONS IN THE FIELD. CONTRACTOR SHALL CONFIRM CURRENT CONDITIONS IN THE FIELD PRIOR TO BIDDING - TYPICAL.


NOTE: RED FILLED REGION REPRESENTS MAJOR DAMAGES TO COMPONENT




2 EAST EXTERIOR ELEVATION - BUILDING F  
3/32" = 1'-0"



7 NORTH EXTERIOR ELEVATION - BUILDING F  
3/32" = 1'-0"



12 SOUTH EXTERIOR ELEVATION - BUILDING F  
3/32" = 1'-0"



17 WEST EXTERIOR ELEVATION - BUILDING F  
3/32" = 1'-0"

ROOFING SYMBOL LEGEND

- EXISTING SKYLIGHT SEE KEYNOTE 11 SEE DETAIL 19 / A-00.4
- ROOF DRAIN LOCATION SEE KEYNOTE 5 SEE DETAIL 16 / A-00.4
- ROOF PIPING PENETRATION SEE KEYNOTE 9
- ROOF FAN / VENT SEE KEYNOTE 12
- ROOF FAN / VENT SEE KEYNOTE 12
- DOWNSPOUT SEE KEYNOTE 30
- MISC MEP SEE KEYNOTE 12
- TURBINE VENT SEE KEYNOTE 12
- EXPANSION JOINT SEE DETAIL 3 / A-00.4
- SCUPPER/OPENING FOR DRAINAGE SEE KEYNOTE 28 SEE DETAIL 15 / A-00.4
- ONE-WAY ROOF VENT TO BE REMOVED W/ ROOFING
- CONDUIT/PIPING RUNS SEE KEYNOTE 3


HAZARDOUS MATERIAL GENERAL NOTES

- ALL WORK INDICATED AS HAZARDOUS MATERIALS SHALL BE REMOVED BY ABATEMENT CONTRACTOR. CONTRACTOR IS TO COORDINATE WITH ABATEMENT CONTRACTOR FOR ABATEMENT WORK TO BE PERFORMED IN CONJUNCTION WITH THIS CONTRACT.
- COORDINATE SCHEDULED WORK WITH ABATEMENT CONTRACTOR AS TO NOT EXPOSE ANY EXTERIOR COMPONENTS TO THE WEATHER MORE THAN REQUIRED FOR REPAIRS.
- ABATEMENT OF INTERIOR COMPONENTS WILL NEED TO BE COORDINATED WITH CONTRACTOR'S PHASING PLAN FOR INTERIOR REPAIRS. CONTRACTOR IS RESPONSIBLE FOR PROTECTING BUILDING STRUCTURE AND INTERIOR FINISHES FROM ANY INCLIMATIC WEATHER AT ALL TIMES.


KEYNOTES

1. **PASSIVE AIR ROOF VENT REPLACEMENT:** EXISTING PASSIVE AIR ROOF VENT TO BE REMOVED.
2. **ROOF ASSEMBLY REPLACEMENT:** SHADED REGION INDICATES EXISTING ROOFING ASSEMBLY TO BE REMOVED TO EXISTING METAL ROOF DECKING SUBSTRATE BELOW, AND NEW ROOFING INSTALLED. ALL DEBRIS IS TO BE REMOVED FROM THE SITE. SEE SPECIFICATIONS FOR EXTENT OF DEMOLITION AND SITE CONSTRAINTS.
3. **RIGID CONDUIT REPAIR (VIF):** INDICATES EXISTING RIGID CONDUIT RUNS EXPOSED ON EXISTING ROOF. CONTRACTOR SHALL MAKE VISUAL INSPECTIONS ON SITE TO VERIFY THE EXTENT OF WORK WHICH BE REQUIRED TO MOVE AND RELOCATE THESE CONDUIT RUNS DURING THE PROCESS OF RE-ROOFING AND TO ENSURE THAT THE NEW ROOF SLOPES ARE INTEGRATED AND ACCOUNTED FOR WHERE EXTENSIONS OF THESE CONDUITS AND WIRING IS REQUIRED.
4. **ROOF CURB REPLACEMENT:** ALL EXISTING ROOF CURBS TO BE REMOVED AND REPLACED IN AREAS BEING RE-ROOFED.
5. **ROOF DRAIN REPAIR (VIF):** APPROXIMATE LOCATION OF EXISTING ROOF DRAIN, CONTRACTOR SHALL VISUALLY INSPECT ALL CONDITIONS REPLACE DAMAGED COMPONENTS AND ADJUST TO NEW ROOF SLOPE.
6. **FLASHING VIF:** SEE DETAILS FOR FLASHING AND COUNTERFLASHING WHICH IS TO TIE INTO THE EXISTING BUILDING ENVELOPE. VERIFY CLEARANCES AND LOCATIONS FOR INSTALLATION OF ALL FLASHING AND TERMINATION BARS AS DETAILED.
7. **RUNNER CURB INSTALLMENT:** PROVIDE NEW "RUNNER CURBS" FOR SUPPORT OF ALL HARD PIPING WHICH IS TO REMAIN ON ROOF AFTER NEW INSTALLATION. RAISE CURBS AS REQUIRED SO CONDUIT AND PIPING DOES NOT SAG BETWEEN THESE LOCATIONS. INSTALL AS DETAILED.
8. **ROOF EXPANSION JOINT REPAIR (VIF):** INDICATES APPROXIMATE AREA AND LOCATION OF ROOF EXPANSION JOINT. CONTRACTOR SHALL VISUALLY INSPECT THE EXISTING CONDITIONS AT THE SITE AND PROVIDE A NEW EXPANSION JOINT AS DETAILED WITHIN THESE DOCUMENTS. THE INSTALLER SHOULD ASSUME THAT ALL EXISTING WOOD BLOCKING SHALL BE REPLACED WITH NEW TREATED WOOD BLOCKING AS PER DETAILS. PROVIDE NEW CANT STRIP, FLASHING, PRE-FINISHED EXPANSION JOINT COVER, VINYL BELLOWS, AND BASE FLASHING AS DETAILED. VERIFY EXACT ROUTING AND AREA WHERE THIS EJ IS TO BE REMOVED AND REPLACED. VERIFY ALL EXISTING CONDITIONS, ESPECIALLY ANY PIPING, AND CONDUIT WHICH MIGHT INTERSECT OR CROSS OVER THIS JOINT.
9. **PLUMBING VENT REPLACEMENT (VIF):** CONTRACTOR SHALL VISUALLY INSPECT ALL EXISTING ROOFING PLUMBING VENTS WHICH ARE TO REMAIN. CONFIRM HEIGHTS OF VENT PIPING AND EXTEND WHERE REQUIRED DUE TO INSTALLATION OF NEW TAPERED INSULATION. EXTEND ALL VENTS AS REQUIRED TO MAINTAIN VERTICAL CLEARANCES CALLED FOR ON EACH RELATED CONSTRUCTION DETAIL. REPLACE ALL LEAD VENT & PIPE FLASHING. TYPICAL ALL LOCATIONS.
10. **FLASHING REPLACEMENT:** REMOVE AND REPLACE FLASHING, COUNTERFLASHING AND PRE-FINISHED METAL FASCIA FLASHING AS DETAILED.
11. **SKYLIGHT REPLACEMENT:** INSTALL NEW ALUMINUM SKYLIGHT GUARD TO MATCH EXISTING.
12. **HVAC REPAIR (VIF):** INDICATES EXISTING HVAC EQUIPMENT AT EXISTING ROOF WHICH IS TO REMAIN. COORDINATE WORK INVOLVED WITH THIS


SITE KEYPLAN



13. **SATELLITE INSTALLATION:** SEE DETAILS FOR SATELLITE MOUNTING UNIT.
14. **"A" METAL PANEL REPLACEMENT:** METAL WALL PANEL "E" - REMOVE AND REPLACE DAMAGED/MISSING METAL WALL PANEL AS SPECIFIED. SEE BUILDING ELEVATIONS.
15. **SIGNAGE INSTALLATION:** INSTALL MISSING LETTERING TO MATCH EXISTING.
16. **ROOF ACCESSORY REPLACEMENT:** REPLACE DAMAGED ROOF ACCESSORIES. MATCH EXISTING TYPE, MATERIAL, AND STYLE.
17. **DOWNSPOUT AND GUTTER CLEANING:** DOWNSPOUT/COLLECTOR LOCATIONS. SEE ELEVATIONS. CONTRACTOR IS TO REMOVE ALL DEBRIS FROM GUTTERS AND DOWNSPOUTS.
18. **SATELLITE REMOVAL:** REMOVE ALL SATELLITE COMPONENTS. THESE ARE NO LONGER IN USE.
19. **COPING:** SEE ROOFING SHEETS FOR COPING, OVERHANG & ROOFING SCOPES. TYP.
20. **TEMPORARY CHAIN LINK FENCING -** PROVIDE 6' TEMPORARY CHAIN LINK FENCING TO PROTECT STUDENT TRAFFIC DURING CONSTRUCTION. PROVIDE ACCESS TO THE GREATEST EXTENT POSSIBLE. COORDINATE WITH PHASING AND SCHOOL PRINCIPAL.
21. **WIND TURBINE REPLACEMENT:** REMOVE AND REPLACE WIND TURBINE TO MATCH EXISTING.
22. **PAINTING EXTERIOR:** CLEAN, PREP & RE-PAINT WALLS AND ARTWORK TO COVER SCUFFS AND DAMAGE FROM STORM DEBRIS. COLOR TO MATCH EXISTING AS APPROVED BY ARCHITECT.
23. **GLASS REPLACEMENT:** REMOVE AND REPLACE DAMAGED GLASS (OR PLYWOOD WHERE APPLICABLE) TO MATCH EXISTING. PROVIDE CAULKING AND GASKETING.
24. **STUCCO SOFFIT REPLACEMENT:** SOFFIT REMOVED BY OTHERS (HAZARDOUS MATERIAL). COORDINATE AND INSTALL NEW STUCCO SOFFIT.
25. COORDINATE REMOVAL OF **AGGREGATE PANELS (HAZARDOUS MATERIAL)** WITH ABATEMENT SCOPE AND ABATEMENT CONTRACTOR. COORDINATE AND INSTALL NEW GFRP FACADE PANELS AS SPECIFIED. REMOVE AND REPLACE DAMAGED WALL FRAMING - SEE STRUCTURAL AND WALL SECTIONS. SALVAGE AND REINSTALL MEP COMPONENTS AT SAME LOCATIONS - COORDINATE WITH MEP.
26. **DOWNSPOUT AND GUTTER REPLACEMENT:** REMOVE REMAINING ATTACHMENTS AND COMPONENTS OF DOWNSPOUT, GUTTER AND CONDUCTOR HEADS AND INSTALL NEW TO MATCH EXISTING COLOR, DIMENSION, GAUGE, AND MATERIAL. GROUT HOLES AT OLD STRAPS PRIOR TO NEW INSTALLATION & ATTACH AT INTERVALS EQUAL TO EXISTING SPACING. SALVAGE AND PREP REMAINING COMPONENTS FOR NEW INSTALLATION. CONTRACTOR IS TO REMOVE ALL DEBRIS FROM GUTTERS AND DOWNSPOUTS.
27. **BRICK REPAIR:** REMOVE AND REPLACE BRICK FACADE AS INDICATED. DISPOSE OF OLD BRICK. MATCH NEW BRICK AND MORTAR TO EXISTING AS APPROVED BY ARCHITECT. PRESERVE SUBSTRATE. REMOVE OLD BRICK TIES AND WATER PROOFING. INSTALL NEW WATERPROOFING AND BRICK TIES AT A MIN. OF 24" O.C. VERTICAL AND HORIZONTAL.
28. **PLASTER SOFFIT REPLACEMENT:** REMOVE REMAINING VINYL SOFFIT AND REPLACE TO MATCH EXISTING - PRESERVE LIGHT & REINSTATE AS NECESSARY.



RANDY M. GOODLOE, AIA, APAC  
725 KIRBY STREET  
LAKE CHARLES, LOUISIANA  
OFFICE: 337.436.3036  
FAX: 337.466.3779



LA. LICENSE NO. 4086


HURRICANE LAURA REPAIRS TO  
**A.M. BARBE HIGH SCHOOL**  
2200 W. McNEESE ST.  
FOR  
**CALCASIEU PARISH SCHOOL BOARD**  
LAKE CHARLES, LA 70605  
HL-003-01.03.04.05.06.07

© COPYRIGHT 2021,  
RANDY M. GOODLOE, A.I.A. APAC  
ALL INFORMATION, EITHER DRAWN, WRITTEN,  
OR PRINTED APPEARING IN THIS DOCUMENT  
SHALL NOT BE DUPLICATED, DISCLOSED, OR  
OTHERWISE USED WITHOUT THE WRITTEN  
PERMISSION OF THE AUTHOR, RANDY M.  
GOODLOE, AIA, APAC. THIS DOCUMENT IS AN  
INSTRUMENT OF SERVICE AND IS THE SOLE  
PROPERTY OF THE AUTHOR. FURTHERMORE,  
THE USE OF THIS DOCUMENT FOR ANY  
PURPOSE SHALL BE REVOKED, IF THE INTENT  
OF THE DESIGN OR THE CONSTRUCTION  
TECHNIQUES OR DETAILS SHOWN HEREIN  
ARE NOT AGREED TO BY THE CONTRACTOR.  
CONTRACTUAL AGREEMENT GOVERNING  
THEIR USE ARE NOT STRICTLY ADHERED TO.


RMG PROJECT NO.  
**20042-01-G**  
OWNER PROJECT NO.  
**HL-003-01.03.04.05.06.07**

PROJECT MANAGER  
**TM**  
DATE ISSUED  
**06/28/2024**













REVISED		
B	VIF	Date 2



**(F)A0.1**  
BLDG F ELEVATIONS



6 BUILDING F - FLOOR PLAN  
3/32" = 1'-0"




ROOMS - BUILDING F		
ROOM NUMBER	Area	Perimeter
F101	759 SF	112' - 7"
F102	700 SF	108' - 11"
F103	807 SF	115' - 6"
F104	836 SF	117' - 7"
F105	756 SF	113' - 10"
F106	870 SF	120' - 6"
F107	979 SF	204' - 5"
F109	73 SF	39' - 1"
F110	42 SF	26' - 1"
F112	128 SF	49' - 7"
F113	79 SF	36' - 3"

\*THESE MEASUREMENTS ARE APPROXIMATE TO BE USED AS GUIDELINES ONLY. CONTRACTOR IS RESPONSIBLE FOR ALL FINAL MEASUREMENTS.

**FLOOR PLAN LEGEND**

- CEILING REPAIR REQUIRED
- FLOORING REPAIR REQUIRED. SEE ROOM SCHEDULE.
- WALL/BASE REPAIR REQUIRED. SEE ROOM SCHEDULE.
- MILLWORK REPAIR REQUIRED. SEE ROOM SCHEDULE.



- KEYNOTES**
- SUSPENDED ACOUSTIC CEILING REPLACEMENT:** REMOVE AND REPLACE DAMAGED CEILING GRID AND CEILING TILE AS SPECIFIED.
  - CEILING GRID:** REMOVE AND REPLACE DAMAGED CEILING GRID. MATCH EXISTING. SEE UNIT PRICE NO. 5.
  - VCT FLOORING REPAIRS:** REMOVE AND REPLACE VCT FLOORING AS SPECIFIED IN AREAS WHERE INDICATED. SEE UNIT PRICE NO. 3.
  - WINDOW REPAIRS:** REPLACE BROKEN WINDOW PANE, BLOCKS, AND GASKETS TO MATCH EXISTING. ALL SEALANTS SHALL BE REMOVED AND REPLACED AS SPECIFIED TO ENSURE WEATHER TIGHT SEAL. SEE ELEVATIONS.
  - STRUCTURAL CLAY BLOCK:** GLAZED STRUCTURAL CLAY BLOCK TO BE REMOVED AND REPLACED AS SPECIFIED TO MATCH EXISTING. CLEAN ALL CHALKING RESIDUE FROM EFFERVESCENT.
  - VINYL BASE REPLACEMENT:** REPLACE DAMAGED OR MISSING BASE AS SPECIFIED TO MATCH EXISTING. SEE UNIT PRICE NO. 4.
  - CARPET REPAIRS:** DAMAGED CARPET HAS BEEN REMOVED. CLEAN FLOOR AND INSTALL NEW CARPET TILE AS SPECIFIED.
  - PAINTING:** WALL SURFACE IS TO BE SANDED, PREPARED, AND REPAINT TO MATCH EXISTING CORNER TO CORNER. WATER STAINED WALL FROM ROOF LOSS.
  - PAINTED CEILING STRUCTURE:** CEILING INCLUDING METAL TRUSSES ARE TO BE CLEANED, PREPPED, AND REPAINTED END TO END TO MATCH EXISTING COLOR.
  - VCT FLOORING CLEANING:** CLEAN WATER STAINS FROM VCT FLOORING TO REMOVE ANY DISCOLORATION WHERE INDICATED. MOP AND WAX ALL VCT FLOORING AT THE END OF CONSTRUCTION.
  - SKYLIGHT REPAIRS:** REMOVE AND REPLACE SKYLIGHT TO MATCH EXISTING.
  - TERRAZZO FLOORING CLEANING:** CLEAN AND POLISH EXISTING TERRAZZO FLOORING. REFER TO ROOM SCHEDULE FOR CLARITY.
  - CEILING TILE REPLACEMENT:** REMOVE AND REPLACE DAMAGED OR MISSING ACOUSTIC WITH NEW CEILING TILE AS SPECIFIED IN AREAS INDICATED. MATCH EXISTING TYPE AND SIZE. SEE UNIT PRICE NO. 1. INSTALL R-30 BATT INSULATION OVER TILE. SEE UNIT PRICE NO. 2.
  - NOT USED.**
  - EXTERIOR WINDOWS AND DOORS:** CAULK AND RESEAL PERIMETER OF EXISTING WINDOWS AND DOORS.
  - CMU REPAIR:** RE-POINT DAMAGED CMU JOINTS AS SHOWN. PAINT WALL FROM END TO END IN COLOR TO MATCH EXISTING AS SPECIFIED. SEE PHOTOS.
  - BRICK REPAIR:** CAULK CRACKED AREAS AND REPAIR.
  - LOCKERS:** REPAIR DAMAGED UNITS AS SHOWN. MATCH EXISTING STYLE, SIZE AND COLORS.
  - BRICK WALLS:** CLEAN ALL WATER STAINS FROM ENTIRE BRICK WALL.
  - SHELVING REPLACEMENT:** REMOVE AND REPLACE DAMAGED SHELVING UNITS WITH **GLASS DOORS**. MATCH EXISTING MATERIALS, FINISHES AND CONSTRUCTION STYLE.
  - BASE CABINET:** REMOVE AND REPLACE DAMAGED BASE CABINET. MATCH EXISTING STYLE, SIZE, AND CONSTRUCTION. SALVAGE AND REINSTALL COUNTERTOP.
  - SECTIONAL DOOR:** REMOVE AND REPLACE OVERHEAD SECTIONAL DOOR AS SPECIFIED. CONTRACTOR TO PROVIDE ANY ADDITIONAL SUPPORT REQUIRED BY THE MANUFACTURER.
  - GYPSUM BOARD:** REMOVE AND REPLACE DAMAGED GYPSUM BOARD TO NEAREST FRAMING MEMBER. FINISH AND RE-PAINT WALL CORNER TO CORNER.
  - PREFINISHED GYPSUM BOARD WITH VINYL WALL COVER AND CORNER TRIM:** REMOVE AND REPLACE DAMAGED VINYL COVERED GYPSUM BOARD FROM FLOOR TO CEILING WHERE INDICATED ON FLOOR PLAN.
  - STOREFRONT WINDOW:** REMOVE AND REPLACE STOREFRONT WINDOW AS SPECIFIED.
  - STUCCO SOFFIT:** REMOVE & REPLACE STUCCO SOFFIT. COORDINATE WITH ABATEMENT SCOPE & ABATEMENT CONTRACTOR TO ENSURE WEATHER-TIGHTNESS AND PHASING COORDINATION. SEE WALL SECTIONS & DETAILS.
  - GYPSUM CEILING REPAIRS:** REMOVE AND REPLACE DAMAGED GYPSUM CEILING BOARD TO NEAREST FRAMING MEMBER WHERE INDICATED. FINISH TO MATCH EXISTING AS SPECIFIED.
  - METAL ROOF PANEL REPAIRS:** REMOVE AND REPLACE DEFORMED OR MISSING METAL ROOF PANELS TO MATCH EXISTING.
  - CONCRETE FLOOR CLEANING:** CLEAN AND RESEAL FLOOR AS SPECIFIED.
  - BASE CABINET:** REMOVE AND REPLACE DAMAGED BASE CABINET. MATCH EXISTING STYLE, SIZE, AND CONSTRUCTION. SALVAGE AND REINSTALL COUNTERTOP. PROTECT ALL MECHANICAL CONNECTIONS.
  - TILE CLEANING:** CLEAN STAINS FROM WALL TILE TO REMOVE ANY DISCOLORATION WHERE INDICATED.
  - CLEAN/REPAIR MASONRY WALL:** MECHANICALLY REMOVE ALL LOOSE OR PEELING PAINT AND ALL CHALKING RESIDUE FROM EFFERVESCENT FROM CORNER TO CORNER. PERFORM REQUIRED MOISTURE TESTING PRIOR TO REPAINTING WALL AS SPECIFIED.
  - PLASTER CEILING REPAIRS:** REMOVE AND REPLACE DAMAGED PLASTER CEILING WHERE INDICATED AS SPECIFIED. PAINT IN COLOR TO MATCH EXISTING.
  - MEP DAMAGES:** SEE MECHANICAL, PLUMBING AND ELECTRICAL PLANS.
  - FURNITURE SETTING AND RESETTING:** RELOCATE ALL EXISTING FURNITURE TO TEMPORARY ROOM IN MODULAR BUILDINGS WHILE EXISTING SPACE IS BEING REPAIRED. REINSTALL AND RESET FURNITURE ONCE REPAIRS ARE COMPLETE. SEE PHASING PLAN.
  - SUSPENDED CEILING INSULATION:** INSTALL R-19 BATT INSULATION AS SPECIFIED ABOVE PREVIOUSLY INSTALLED SUSPENDED CEILING TILE. SEE UNIT PRICE NO. 2.
  - BRICK WALL REPLACEMENT:** REMOVE AND REPLACE BRICK WALL AS INDICATED. DISPOSE OF OLD BRICK. MATCH NEW BRICK AND MORTAR TO EXISTING AS APPROVED BY ARCHITECT. SEE STRUCTURAL. BUILDING TO REMAIN WEATHERPROOF AND CONDITIONED DURING REPAIRS.
  - DOOR REPAIR:** CLEAN, PREP AND RE-PAINT DOOR FRAME - SEE DOOR SCHEDULE.
  - CORRIDOR WALL REPAIR:** REMOVE DAMAGED STOREFRONT WINDOW AND EXISTING 3/4" PLYWOOD SHEATHING BELOW WINDOW. INSTALL NEW WINDOW PER SCHEDULE AND NEW 3/4" PLYWOOD SHEATHING. PAINT AS SPECIFIED, IN COLOR AS SELECTED. SEE DETAILS.
  - GLAZING REPAIR:** REMOVE AND REPLACE BROKEN GLASS. MATCH EXISTING TINT. PROVIDE SAFETY GLASS AS REQUIRED.
  - DOOR REPAIR:** REMOVE AND REPLACE EXISTING LEFT DOOR LEAF. PROVIDE AN INSULATED HOLLOW METAL DOOR WITH VISION PANEL TO MATCH RIGHT DOOR LEAF. REINSTALL EXISTING DOOR HARDWARE. PAINT AS DIRECTED.

**RMG**

RANDY M. GOODLOE, AIA, APAC  
725 KIRBY STREET  
LAKE CHARLES, LOUISIANA  
OFFICE: 337.436.3006  
FAX: 337.466.3779

**ARCHITECT**

RANDY MICHAEL GOODLOE  
No. 2858  
REGISTERED ARCHITECT  
LA. LICENSE NO. 4086







HURRICANE LAURA REPAIRS TO  
**A.M. BARBE HIGH SCHOOL**  
2200 W. McNEESE ST.  
FOR  
**CALCASIEU PARISH SCHOOL BOARD**  
LAKE CHARLES, LA 70605  
HL-003-01.03.04.05.06.07

© COPYRIGHT 2021,  
RANDY M. GOODLOE, AIA APAC  
ALL INFORMATION, EITHER DRAWN, WRITTEN,  
OR PRINTED APPEARING IN THIS DOCUMENT  
SHALL NOT BE DUPLICATED, DISCLOSED, OR  
OTHERWISE USED WITHOUT THE WRITTEN  
PERMISSION OF THE AUTHOR, RANDY M.  
GOODLOE, AIA, APAC. THIS DOCUMENT IS AN  
INSTRUMENT OF SERVICE AND IS THE SOLE  
PROPERTY OF THE AUTHOR. FURTHERMORE,  
THE USE OF THIS DOCUMENT FOR ANY  
PURPOSE SHALL BE REVOKED, IF THE INTENT  
OF THE DESIGN OR THE CONSTRUCTION  
TECHNIQUES OR DETAILS SHOWN HEREIN  
ARE NOT ADHERED TO OR THE  
CONTRACTUAL AGREEMENT GOVERNING  
THEIR USE ARE NOT STRICTLY ADHERED TO.

RMG PROJECT NO.  
**20042-01-G**  
OWNER PROJECT NO.  
**HL-003-01.03.04.05.06.07**  
PROJECT MANAGER  
**TM**  
DATE ISSUED  
**06/28/2024**

REVISED

SHEET NUMBER  
**(F)A1.1**  
BLDG F 1ST FLOOR



**DOOR SCHEDULE - BUILDING F**

MARK	OPENING SIZE		HARDWARE	TYPE	DOOR		FRAME		COMMENTS
	WIDTH	HEIGHT			MATERIAL	FINISH	MATERIAL	FINISH	
F101A	3' - 0"	7' - 0"	--	FLUSH	EXISTING	MATCH EXISTING	EXISTING - H.M.	REPAINT	
F102A	3' - 0"	7' - 0"	--	FLUSH	EXISTING	MATCH EXISTING	EXISTING - H.M.	REPAINT	
F103A	3' - 0"	7' - 0"	--	FLUSH	EXISTING	EXISTING	EXISTING - H.M.	REPAINT	
F104A	3' - 0"	7' - 0"	--	FLUSH	EXISTING	EXISTING	EXISTING - H.M.	REPAINT	
F105A	3' - 0"	7' - 0"	--	FLUSH	EXISTING	EXISTING	EXISTING - H.M.	REPAINT	
F106A	3' - 0"	7' - 0"	--	FLUSH	EXISTING	EXISTING	EXISTING - H.M.	REPAINT	
F107A	5' - 8"	6' - 8"	--	FLUSH	EXISTING	EXISTING	EXISTING - STOREFRONT	ANODIZED - DK BRONZE	
F107B	5' - 8"	6' - 8"	H-1	FLUSH	EXISTING	EXISTING	EXISTING - STOREFRONT	ANODIZED - DK BRONZE	REPLACE LEAF INDACATED. TO MATCH EXISTING. PROVIDE VISION PANEL
F109A	3' - 0"	7' - 0"	--	FLUSH	EXISTING	EXISTING	EXISTING - H.M.	REPAINT	
F110A	3' - 0"	7' - 0"	--	FLUSH	EXISTING	EXISTING	EXISTING - H.M.	REPAINT	
F112A	3' - 0"	7' - 0"	--	FLUSH	EXISTING	EXISTING	EXISTING - H.M.	REPAINT	

**GLAZING SCHEDULE**

G1 - CLEAR, INSULATED GLASS AS SPECIFIED.  
 G2 - SPANDRAL GLASS AS SPECIFIED.  
 G3 - TINTED, INSULATED GLASS AS SPECIFIED.  
 G4 - ALUMINUM WINDOW PANEL AS SPECIFIED.


\*GLAZING OF NEW STOREFRONT UNITS ARE TO BE LARGE MISSILE IMPACT AS SPECIFIED. REPLACEMENT GLAZING IS TO MATCH EXISTING.

**HARDWARE**

H-1 - PROVIDE NEW HINGES, WEATHER STRIPPING & SILENCERS. SALVAGE REMAINING HARDWARE AND REINSTALL ON NEW DOOR.

**WINDOW SCHEDULE**

MARK	SIZE	FRAME		COMMENTS
		TYPE	MATERIAL	
W1	SEE ELEVATION	STOREFRONT	ALUMINUM - EXISTING	REPLACE DAMAGED GLASS AS INDICATED
E1	SEE ELEVATION	STOREFRONT	ALUMINUM - EXISTING	REPAIR DOOR AS SCHEDULED



RANDY M. GOODLOE, AIA, APAC  
 725 KIRBY STREET  
 LAKE CHARLES, LOUISIANA  
 OFFICE: 337.436.3036  
 FAX: 337.466.3773




LA. LICENSE NO. 4086

HURRICANE LAURA REPAIRS TO  
**A.M. BARBE HIGH SCHOOL**  
 2200 W. McNEESE ST.  
 FOR  
**CALCASIEU PARISH SCHOOL BOARD**  
 LAKE CHARLES, LA 70605  
 HL-003-01.03.04.05.06.07


© COPYRIGHT 2021,  
 RANDY M. GOODLOE, AIA, APAC  
 ALL INFORMATION, EITHER DRAWN, WRITTEN,  
 OR IMPLIED APPEARING IN THIS DOCUMENT  
 SHALL NOT BE DUPLICATED, DISCLOSED, OR  
 OTHERWISE USED WITHOUT THE WRITTEN  
 PERMISSION OF THE AUTHOR, RANDY M.  
 GOODLOE, AIA, APAC. THIS DOCUMENT IS AN  
 INSTRUMENT OF SERVICE AND IS THE SOLE  
 PROPERTY OF THE AUTHOR. FURTHERMORE,  
 THE USE OF THIS DOCUMENT FOR ANY  
 PURPOSE SHALL BE REVOKED, IF THE INTENT  
 OF THE DESIGN OR THE CONSTRUCTION  
 ARE NOT ADHERED TO OR THE  
 CONTRACTUAL AGREEMENT GOVERNING  
 THEIR USE ARE NOT STRICTLY ADHERED TO.

RMG PROJECT NO.  
**20042-01-G**  
 OWNER PROJECT NO.  
**HL-003-01.03.04.05.06.07**  
 PROJECT MANAGER  
**TM**  
 DATE ISSUED  
**06/28/2024**

REVISED




SHEET NUMBER  
**(F)A1.2**  
 BLDG F 1ST FLOOR



**ROOFING SYMBOL LEGEND**

- EXISTING SKYLIGHT  
SEE KEYNOTE 11  
SEE DETAIL 19 / A-00.4
- ROOF DRAIN LOCATION SEE  
KEYNOTE 5 SEE DETAIL 16 / A-00.4
- ROOF PIPING PENETRATION  
SEE KEYNOTE 9
- ROOF FAN / VENT  
SEE KEYNOTE 12
- ROOF FAN / VENT  
SEE KEYNOTE 12
- DOWNSPOUT  
SEE KEYNOTE 30
- MISC MEP  
SEE KEYNOTE 12
- TURBINE VENT  
SEE KEYNOTE 12
- EXPANSION JOINT  
SEE KEYNOTE 8  
SEE DETAIL 3 / A-00.4
- SCUPPER/OPENING FOR DRAINAGE  
SEE KEYNOTE 28  
SEE DETAIL 15 / A-00.4
- ONE-WAY ROOF VENT TO BE  
REMOVED W/ ROOFING
- CONDUIT/PIPING RUNS  
SEE KEYNOTE 3



**KEYNOTES**


- PASSIVE AIR ROOF VENT REPLACEMENT:** EXISTING PASSIVE AIR ROOF VENT TO BE REMOVED.
- ROOF ASSEMBLY REPLACEMENT:** SHADED REGION INDICATES EXISTING ROOFING ASSEMBLY TO BE REMOVED TO EXISTING METAL ROOF DECKING SUBSTRATE BELOW, AND NEW ROOFING INSTALLED. ALL DEBRIS IS TO BE REMOVED FROM THE SITE. SEE SPECIFICATIONS FOR EXTENT OF DEMOLITION AND SITE CONSTRAINTS.
- RIGID CONDUIT REPAIR (VIF):** INDICATES EXISTING RIGID CONDUIT RUNS EXPOSED ON EXISTING ROOF. CONTRACTOR SHALL MAKE VISUAL INSPECTIONS ON SITE TO VERIFY THE EXTENT OF WORK WHICH BE REQUIRED TO MOVE AND RELOCATE THESE CONDUIT RUNS DURING THE PROCESS OF RE-ROOFING AND TO ENSURE THAT THE NEW ROOF SLOPES ARE INTEGRATED AND ACCOUNTED FOR WHERE EXTENSIONS OF THESE CONDUITS AND WIRING IS REQUIRED.
- ROOF CURB REPLACEMENT:** ALL EXISTING ROOF CURBS TO BE REMOVED AND REPLACED IN AREAS BEING RE-ROOFED.
- ROOF DRAIN REPAIR (VIF):** APPROXIMATE LOCATION OF EXISTING ROOF DRAIN. CONTRACTOR SHALL VISUALLY INSPECT ALL CONDITIONS REPLACE DAMAGED COMPONENTS AND ADJUST TO NEW ROOF SLOPE.
- FLASHING VIF:** SEE DETAILS FOR FLASHING AND COUNTERFLASHING WHICH IS TO TIE INTO THE EXISTING BUILDING ENVELOPE. VERIFY CLEARANCES AND LOCATIONS FOR INSTALLATION OF ALL FLASHING AND TERMINATION BARS AS DETAILED.
- RUNNER CURB INSTALLMENT:** PROVIDE NEW "RUNNER CURBS" FOR SUPPORT OF ALL HARD PIPING WHICH IS TO REMAIN ON ROOF AFTER NEW INSTALLATION. SPACE CURBS AS REQUIRED SO CONDUIT AND PIPING DOES NOT SAG BETWEEN THESE LOCATIONS. INSTALL AS DETAILED.
- ROOF EXPANSION JOINT REPAIR (VIF):** INDICATES APPROXIMATE AREA AND LOCATION OF ROOF EXPANSION JOINT. CONTRACTOR SHALL VISUALLY INSPECT THE EXISTING CONDITIONS AT THE SITE AND PROVIDE A NEW EXPANSION JOINT AS DETAILED WITHIN THESE DOCUMENTS. THE INSTALLER SHOULD ASSUME THAT ALL EXISTING WOOD BLOCKING SHALL BE REPLACED WITH NEW TREATED WOOD BLOCKING AS PER DETAILS. PROVIDE NEW CANT STRIP, FLASHING, PRE-FINISHED EXPANSION JOINT COVER, VINYL BELLOW, AND BASE FLASHING AS DETAILED. VERIFY EXACT ROUTING AND AREA WHERE THIS EJ IS TO BE REMOVED AND REPLACED. VERIFY ALL EXISTING CONDITIONS, ESPECIALLY ANY PIPING, AND CONDUIT WHICH MIGHT INTERSECT OR CROSS OVER THIS JOINT.
- PLUMBING VENT REPLACEMENT (VIF):** CONTRACTOR SHALL VISUALLY INSPECT ALL EXISTING ROOFING PLUMBING VENTS WHICH ARE TO REMAIN. CONFIRM HEIGHTS OF VENT PIPING AND EXTEND WHERE REQUIRED DUE TO INSTALLATION OF NEW TAPERED INSULATION. EXTEND ALL VENTS AS REQUIRED TO MAINTAIN VERTICAL CLEARANCES CALLED FOR ON EACH RELATED CONSTRUCTION DETAIL. REPLACE ALL LEAD VENT & PIPE FLASHING. TYPICAL ALL LOCATIONS.
- FLASHING REPLACEMENT:** REMOVE AND REPLACE FLASHING, COUNTERFLASHING AND PRE-FINISHED METAL FLASHING AS DETAILED.
- SKYLIGHT REPLACEMENT:** INSTALL NEW ALUMINUM SKYLIGHT GUARD TO MATCH EXISTING.
- HVAC REPAIR (VIF):** INDICATES EXISTING HVAC EQUIPMENT AT EXISTING ROOF WHICH IS TO REMAIN. COORDINATE WORK INVOLVED WITH THIS

- EQUIPMENT AND NEW ROOFING ASSEMBLY SO AS TO NOT DISRUPT SERVICE TO THE EXISTING BUILDING. IF SERVICE IS REQUIRED TO BE TEMPORARILY SUSPENDED WHILE NEW WORK IS TAKING PLACE, THE CONTRACTOR SHALL COORDINATE ANY AND ALL OUTAGES WITH THE OWNER AND WILL BE REQUIRED TO ONLY PERFORM THIS WORK AT TIMES WHEN SUSPENSION OF THIS SERVICE MINIMALLY AFFECTS THE OWNER'S USE OF THE BUILDING. IF THE SERVICE CANNOT BE SUSPENDED DURING OWNER'S OPERATING HOURS, WORK MAY HAVE TO BE PERFORMED AFTER HOURS, OR ON WEEKENDS.
- SATELLITE INSTALLATION:** SEE DETAILS FOR SATELLITE MOUNTING UNIT.
- "A" METAL PANEL REPLACEMENT:** METAL WALL PANEL "E" - REMOVE AND REPLACE DAMAGED/MISSING METAL WALL PANEL AS SPECIFIED. SEE BUILDING ELEVATIONS.
- SIGNAGE INSTALLATION:** INSTALL MISSING LETTERING TO MATCH EXISTING.
- ROOF ACCESSORY REPLACEMENT:** REPLACE DAMAGED ROOF ACCESSORIES. MATCH EXISTING TYPE, MATERIAL, AND STYLE.
- DOWNSPOUT AND GUTTER CLEANING:** DOWNSPOUT/COLLECTOR LOCATIONS. SEE ELEVATIONS. CONTRACTOR IS TO REMOVE ALL DEBRIS FROM GUTTERS AND DOWN SPOUTS.
- SATELLITE REMOVAL:** REMOVE ALL SATELLITE COMPONENTS. THESE ARE NO LONGER IN USE.
- COPING:** SEE ROOFING SHEETS FOR COPING, OVERHANG & ROOFING SCOPES - TYPE.
- TEMPORARY CHAIN LINK FENCING** - PROVIDE 6" TEMPORARY CHAIN LINK FENCING TO PROTECT STUDENT TRAFFIC DURING CONSTRUCTION. PROVIDE ACCESS TO THE GREATEST EXTENT POSSIBLE. COORDINATE WITH PHASING AND SCHOOL PRINCIPAL.
- WIND TURBINE REPLACEMENT:** REMOVE AND REPLACE WIND TURBINE TO MATCH EXISTING.
- PAINTING EXTERIOR:** CLEAN, PREP & RE-PAINT WALLS AND ARTWORK TO COVER SCUFFS AND DAMAGE FROM STORM DEBRIS. COLOR TO MATCH EXISTING AS APPROVED BY ARCHITECT.
- GLASS REPLACEMENT:** REMOVE AND REPLACE DAMAGED GLASS (OR PLYWOOD WHERE APPLICABLE) TO MATCH EXISTING. PROVIDE CAULKING AND GASKETING.
- STUCCO SOFFIT REPLACEMENT:** SOFFIT REMOVED BY OTHERS (HAZARDOUS MATERIAL), COORDINATE AND INSTALL NEW STUCCO SOFFIT.
- COORDINATE REMOVAL OF **AGGREGATE PANELS (HAZARDOUS MATERIAL)** WITH ABATEMENT SCOPE AND ABATEMENT CONTRACTOR. COORDINATE AND INSTALL NEW GFRG FACADE PANELS AS SPECIFIED. REMOVE AND REPLACE DAMAGED WALL FRAMING - SEE STRUCTURAL AND WALL SECTIONS. SALVAGE AND REINSTALL MEP COMPONENTS AT SAME LOCATIONS - COORDINATE WITH MEP.
- DOWNSPOUT AND GUTTER REPLACEMENT:** REMOVE REMAINING ATTACHMENTS AND COMPONENTS OF DOWNSPOUT, GUTTER AND CONDUCTOR HEADS AND INSTALL NEW TO MATCH EXISTING COLOR, DIMENSION, GAUGE, AND MATERIAL. GROUT HOLES AT OLD STRAPS PRIOR TO NEW INSTALLATION & ATTACH AT INTERVALS EQUAL TO EXISTING SPACING. SALVAGE AND PREP REMAINING COMPONENTS FOR NEW INSTALLATION. CONTRACTOR IS TO REMOVE ALL DEBRIS FROM GUTTERS AND DOWN SPOUTS.
- BRICK REPAIR:** REMOVE AND REPLACE BRICK FACADE AS INDICATED. DISPOSE OF OLD BRICK. MATCH NEW BRICK AND MORTAR TO EXISTING AS APPROVED BY ARCHITECT. PRESERVE SUBSTRATE. REMOVE OLD BRICK TIES AND WATER PROOFING. INSTALL NEW WATERPROOFING AND BRICK TIES AT A MIN. OF 24" O.C. VERTICAL AND HORIZONTAL.
- PLASTER SOFFIT REPLACEMENT:** REMOVE REMAINING VINYL SOFFIT AND REPLACE TO MATCH EXISTING - PRESERVE LIGHT & REINSTATE AS NECESSARY.

**GENERAL NOTES**

1. WORK FOR THIS BUILDING IS TO BE PERFORMED WITHIN DATES GIVEN IN PHASING SCHEDULE. SEE SECTION 01 10 00 SUMMARY OF THE SPECIFICATION MANUAL.

11 ROOF PLAN - BUILDING G  
3/32" = 1'-0"



**RANDY M. GOODLOE, AIA, APAC**  
725 KIRBY STREET  
LAKE CHARLES, LOUISIANA  
OFFICE: 337.436.3036  
FAX: 337.465.3779

**ARCHITECT**

LA. LICENSE NO. 4086


HURRICANE LAURA REPAIRS TO  
**A.M. BARBE HIGH SCHOOL**  
2200 W. McNEESE ST.  
FOR  
**CALCASIEU PARISH SCHOOL BOARD**  
LAKE CHARLES, LA 70605  
HL-003-01.03.04.05.06.07

© COPYRIGHT 2021,  
RANDY M. GOODLOE, AIA APAC  
ALL INFORMATION, EITHER DRAWN, WRITTEN,  
OR IMPLIED APPEARING IN THIS DOCUMENT  
SHALL NOT BE DUPLICATED, DISCLOSED, OR  
OTHERWISE USED WITHOUT THE WRITTEN  
PERMISSION OF THE AUTHOR, RANDY M.  
GOODLOE, AIA APAC. THIS DOCUMENT IS AN  
INSTRUMENT OF SERVICE AND IS THE SOLE  
PROPERTY OF THE AUTHOR. FURTHERMORE,  
THE USE OF THIS DOCUMENT FOR ANY  
PURPOSE SHALL BE REVOKED, IF THE INTENT  
OF THE DESIGN OR THE CONSTRUCTION  
TECHNIQUES OR DETAILS SHOWN HEREIN  
ARE NOT AGREED TO BY THE CONTRACTOR.  
CONTRACTUAL AGREEMENT GOVERNING  
THEIR USE ARE NOT STRICTLY ADHERED TO.


RMG PROJECT NO.  
**20042-01-G**  
OWNER PROJECT NO.  
**HL-003-01.03.04.05.06.07**  
PROJECT MANAGER  
**TM**  
DATE ISSUED  
**06/28/2024**

REVISED


SHEET NUMBER  
**(G)A0.1**  
BLDG G ROOF




1 NORTH EXTERIOR ELEVATION - BUILDING G  
3/32" = 1'-0"



6 SOUTH EXTERIOR ELEVATION - BUILDING G  
3/32" = 1'-0"








11 EAST EXTERIOR ELEVATION - BUILDING G  
3/32" = 1'-0"



16 WEST EXTERIOR ELEVATION - BUILDING G  
3/32" = 1'-0"

NOTE: IMAGES ARE FOR VISUAL REFERENCES TO HELP UNDERSTAND DAMAGES. THEY DO NOT REPRESENT THE ENTIRE SCOPE OF WORK AND SHOULD BE USED IN CONJUNCTION WITH THE DRAWINGS AND CURRENT CONDITIONS IN THE FIELD. CONTRACTOR SHALL CONFIRM CURRENT CONDITIONS IN THE FIELD PRIOR TO BIDDING - TYPICAL.



**KEYNOTES**

1. "A" METAL PANEL REPLACEMENT: METAL WALL PANEL "A" - REMOVE AND REPLACE DAMAGED/MISSING METAL WALL PANEL AS SPECIFIED. SEE BUILDING ELEVATIONS.
2. SIGNAGE INSTALLATION: INSTALL MISSING LETTERING TO MATCH EXISTING.
3. DOWNSPOUT AND GUTTER REPLACEMENT: REMOVE REMAINING ATTACHMENTS AND COMPONENTS OF DOWNSPOUT, GUTTER AND CONDUCTOR HEADS AND INSTALL NEW TO MATCH EXISTING COLOR, DIMENSION, GAUGE, AND MATERIAL. GROUT HOLES AT OLD STRAPS PRIOR TO NEW INSTALLATION & ATTACH AT INTERVALS EQUAL TO EXISTING SPACING. SALVAGE AND PREP REMAINING COMPONENTS FOR NEW INSTALLATION. CONTRACTOR IS TO REMOVE ALL DEBRIS FROM GUTTERS AND DOWNSPOUTS.
4. COPING: SEE ROOFING SHEETS FOR COPING, OVERHANG & ROOFING SCOPES - TYP.
5. EXISTING LIGHT FIXTURE - CONTRACTOR IS TO WEATHER SEAL FIXTURE AT METAL WALL PANEL.
6. NOT USED.
7. BRICK REPAIR: REMOVE AND REPLACE BRICK FACADE AS INDICATED. DISPOSE OF OLD BRICK. MATCH NEW BRICK AND MORTAR TO EXISTING AS APPROVED BY ARCHITECT. PRESERVE SUBSTRATE. REMOVE OLD BRICK TIES AND WATER PROOFING. INSTALL NEW WATERPROOFING AND BRICK TIES AT A MIN. OF 24" O.C. VERTICAL AND HORIZONTAL.
8. PAINTING EXTERIOR: CLEAN, PREP & RE-PAINT WALLS AND ARTWORK TO MATCH EXISTING AS APPROVED BY ARCHITECT.
9. GLASS REPLACEMENT: REMOVE AND REPLACE DAMAGED GLASS (OR PLYWOOD WHERE APPLICABLE) TO MATCH EXISTING. PROVIDE CAULKING AND GASKETING.
10. STUCCO SOFFIT REPLACEMENT: SOFFIT REMOVED BY OTHERS (HAZARDOUS MATERIAL), COORDINATE AND INSTALL NEW STUCCO SOFFIT.
11. AGGREGATE PANEL REPLACEMENT: DELAMINATED & DAMAGED AGGREGATE PANELS REMOVED BY OTHERS (HAZARDOUS MATERIAL), COORDINATE AND INSTALL NEW FACADE PANEL AS SPECIFIED. REINSTALL MEP COMPONENTS AT SAME LOCATIONS.
12. CONDUIT REPAIR: REPAIR CONDUIT AND MEP EQUIPMENT TO WORKING ORDER PER MEP DOCUMENTS.
13. GLAZING REPLACEMENT: REMOVE DAMAGED GLAZING SYSTEM AND REPLACE WITH NEW TO MATCH EXISTING AS SPECIFIED. PROVIDE NEW CONTINUOUS 4X4 STEEL ANGLE WELDED TO STRUCTURE FOR SUPPORT.
14. DOOR REPLACEMENT: REMOVE REMAINING DOOR DEBRIS AND COVERINGS AND REPLACE TO MATCH EXISTING, INCLUDING FRAMES, HARDWARE, AND GASKETING. SEE DOOR SCHEDULE.
15. METAL PANEL REPLACEMENT: REMOVE REMAINING DAMAGED METAL PANEL ASSEMBLY AND REPLACE WITH NEW SYSTEM TO MATCH EXISTING. COORDINATE REMOVAL AND INSTALLATION TO PREVENT WEATHER INTRUSION.
16. SOFFIT PANEL REPLACEMENT: REMOVE AND REPLACE SOFFIT PANELS TO MATCH EXISTING - APPROX. 3'X3' PANELS.
17. GLASS AND GLAZING REPLACEMENT: REMOVE AND DISPOSE OF MESH, BROKEN & REMAINING GLASS AND GLAZING - REPLACE WITH SOLID PANELS AS SPECIFIED.
18. DOWNSPOUT AND GUTTER CLEANING: DOWNSPOUT/COLLECTOR LOCATIONS. CONTRACTOR IS TO REMOVE ALL DEBRIS FROM GUTTERS AND DOWNSPOUTS.
19. GUTTER REPAIR - RESEAL ALL JOINTS, PROVIDE ALL RIVETS


**GLAZING SCHEDULE**

- G1 - CLEAR, INSULATED GLASS AS SPECIFIED.
- G2 - SPANDRAL GLASS AS SPECIFIED.
- G3 - TINTED, INSULATED GLASS AS SPECIFIED.
- G4 - ALUMINUM WINDOW PANEL AS SPECIFIED.

\*GLAZING OF NEW STOREFRONT UNITS ARE TO BE LARGE MISSLE IMPACT AS SPECIFIED. REPLACEMENT GLAZING IS TO MATCH EXISTING.

**WINDOW SCHEDULE**

MARK	SIZE	FRAME		COMMENTS
		TYPE	MATERIAL	
E1	SEE ELEVATION	STOREFRONT	EXISTING	REPLACE DAMAGED GLASS AS INDICATED
E2	SEE ELEVATION	STOREFRONT	EXISTING	REPLACE DAMAGED GLASS AS INDICATED
W1	SEE ELEVATION	STOREFRONT	EXISTING	REPLACE DAMAGED GLASS AS INDICATED
S1	SEE ELEVATION	STOREFRONT	EXISTING	REPLACE DAMAGED GLASS AS INDICATED



**SITE KEYPLAN**

N.T.S.

\*SIZES ARE APPROXIMATE. VERIFY IN FIELD.



LA. LICENSE NO. 4086


HURRICANE LAURA REPAIRS TO  
**A.M. BARBE HIGH SCHOOL**  
2200 W. McNEESE ST.  
FOR  
**CALCASIEU PARISH SCHOOL BOARD**  
LAKE CHARLES, LA 70605  
HL-003-01.03.04.05.06.07

© COPYRIGHT 2021, RANDY M. GOODLOE, A.I.A. APAC ALL INFORMATION, EITHER DRAWN, WRITTEN, OR PRINTED APPEARING IN THIS DOCUMENT SHALL NOT BE DUPLICATED, DISCLOSED, OR OTHERWISE USED WITHOUT THE WRITTEN PERMISSION OF THE AUTHOR, RANDY M. GOODLOE, A.I.A. APAC. THIS DOCUMENT IS AN INSTRUMENT OF SERVICE AND IS THE SOLE PROPERTY OF THE AUTHOR. FURTHERMORE, THE USE OF THIS DOCUMENT FOR ANY PURPOSE SHALL BE REVOKED, IF THE INTENT OF THE DESIGN OR THE CONSTRUCTION TECHNIQUES OR DETAILS SHOWN HEREIN ARE NOT AGREED TO OR THE CONTRACTUAL AGREEMENT GOVERNING THEIR USE ARE NOT STRICTLY ADHERED TO.


RMG PROJECT NO.  
**20042-01-G**  
OWNER PROJECT NO.  
**HL-003-01.03.04.05.06.07**  
PROJECT MANAGER  
**TM**

DATE ISSUED  
**06/28/2024**

REVISED




SHEET NUMBER  
**(G)A0.2**  
BLDG & ELEVATIONS



NOTE: IMAGES ARE FOR VISUAL REFERENCES TO HELP UNDERSTAND DAMAGES. THEY DO NOT REPRESENT THE ENTIRE SCOPE OF WORK AND SHOULD BE USED IN CONJUNCTION WITH THE DRAWINGS AND CURRENT CONDITIONS IN THE FIELD. CONTRACTOR SHALL CONFIRM CURRENT CONDITIONS IN THE FIELD PRIOR TO BIDDING - TYPICAL.

**KEYNOTES**

- PASSIVE AIR ROOF VENT REPLACEMENT:** EXISTING PASSIVE AIR ROOF VENT TO BE REMOVED.
- ROOF ASSEMBLY REPLACEMENT:** SHADED REGION INDICATES EXISTING ROOFING ASSEMBLY TO BE REMOVED TO EXISTING METAL ROOF DECKING SUBSTRATE BELOW, AND NEW ROOFING INSTALLED. ALL DEBRIS IS TO BE REMOVED FROM THE SITE. SEE SPECIFICATIONS FOR EXTENT OF DEMOLITION AND SITE CONSTRAINTS.
- RIGID CONDUIT REPAIR (VIF):** INDICATES EXISTING RIGID CONDUIT RUNS EXPOSED ON EXISTING ROOF. CONTRACTOR SHALL MAKE VISUAL INSPECTIONS ON SITE TO VERIFY THE EXTENT OF WORK WHICH BE REQUIRED TO MOVE AND RELOCATE THESE CONDUIT RUNS DURING THE PROCESS OF RE-ROOFING AND TO ENSURE THAT THE NEW ROOF SLOPES ARE INTEGRATED AND ACCOUNTED FOR WHERE EXTENSIONS OF THESE CONDUITS AND WIRING IS REQUIRED.
- ROOF CURB REPLACEMENT:** ALL EXISTING ROOF CURBS TO BE REMOVED AND REPLACED IN AREAS BEING RE-ROOFED.
- ROOF DRAIN REPAIR (VIF):** APPROXIMATE LOCATION OF EXISTING ROOF DRAIN. CONTRACTOR SHALL VISUALLY INSPECT ALL CONDITIONS REPLACE DAMAGED COMPONENTS AND ADJUST TO NEW ROOF SLOPE.
- FLASHING VIF:** SEE DETAILS FOR FLASHING AND COUNTERFLASHING WHICH IS TO TIE INTO THE EXISTING BUILDING ENVELOPE. VERIFY CLEARANCES AND LOCATIONS FOR INSTALLATION OF ALL FLASHING AND TERMINATION BARS AS DETAILED.
- RUNNER CURB INSTALLMENT:** PROVIDE NEW "RUNNER CURBS" FOR SUPPORT OF ALL HARD PIPING WHICH IS TO REMAIN ON ROOF AFTER NEW INSTALLATION. SPACE CURBS AS REQUIRED SO CONDUIT AND PIPING DOES NOT SAG BETWEEN THESE LOCATIONS. INSTALL AS DETAILED.
- ROOF EXPANSION JOINT REPAIR (VIF):** INDICATES APPROXIMATE AREA AND LOCATION OF ROOF EXPANSION JOINT. CONTRACTOR SHALL VISUALLY INSPECT THE EXISTING CONDITIONS AT THE SITE AND PROVIDE A NEW EXPANSION JOINT AS DETAILED WITHIN THESE DOCUMENTS. THE INSTALLER SHOULD ASSUME THAT ALL EXISTING WOOD BLOCKING SHALL BE REPLACED WITH NEW TREATED WOOD BLOCKING AS PER DETAILS. PROVIDE NEW CANT STRIP, FLASHING, PRE-FINISHED EXPANSION JOINT COVER, VINYL BELLOWS, AND BASE FLASHING AS DETAILED. VERIFY EXACT ROUTING AND AREA WHERE THIS IS TO BE REMOVED AND REPLACED. VERIFY ALL EXISTING CONDITIONS, ESPECIALLY ANY PIPING, AND CONDUIT WHICH MIGHT INTERSECT OR CROSS OVER THIS JOINT.
- PLUMBING VENT REPLACEMENT (VIF):** CONTRACTOR SHALL VISUALLY INSPECT ALL EXISTING ROOFING PLUMBING VENTS WHICH ARE TO REMAIN. CONFIRM HEIGHTS OF VENT PIPING AND EXTEND WHERE REQUIRED DUE TO INSTALLATION OF NEW TAPERED INSULATION. EXTEND ALL VENTS AS REQUIRED TO MAINTAIN VERTICAL CLEARANCES CALLED FOR ON EACH RELATED CONSTRUCTION DETAIL. REPLACE ALL LEAD VENT & PIPE FLASHING. TYPICAL ALL LOCATIONS.
- FLASHING REPLACEMENT:** REMOVE AND REPLACE FLASHING, COUNTERFLASHING AND PRE-FINISHED METAL FASCIA FLASHING AS DETAILED.
- SKYLIGHT REPLACEMENT:** INSTALL NEW ALUMINUM SKYLIGHT GUARD TO MATCH EXISTING.
- HVAC REPAIR (VIF):** INDICATES EXISTING HVAC EQUIPMENT AT EXISTING ROOF WHICH IS TO REMAIN. COORDINATE WORK INVOLVED WITH THIS EQUIPMENT AND NEW ROOFING ASSEMBLY SO AS TO NOT DISRUPT SERVICE TO THE EXISTING BUILDING. IF SERVICE IS REQUIRED TO BE TEMPORARILY SUSPENDED WHILE NEW WORK IS TAKING PLACE, THE CONTRACTOR SHALL COORDINATE ANY AND ALL OUTAGES WITH THE OWNER AND WILL BE REQUIRED TO ONLY PERFORM THIS WORK AT TIMES WHEN SUSPENSION OF THIS SERVICE MINIMALLY AFFECTS THE OWNERS USE OF THE BUILDING. IF THE SERVICE CANNOT BE SUSPENDED DURING OWNER'S OPERATING HOURS, WORK MAY HAVE TO BE PERFORMED AFTER HOURS, OR ON WEEKENDS.
- SATELLITE INSTALLATION:** SEE DETAILS FOR SATELLITE MOUNTING UNIT.
- "E" METAL PANEL REPLACEMENT:** METAL WALL PANEL "E" - REMOVE AND REPLACE DAMAGED/MISSING METAL WALL PANEL AS SPECIFIED. SEE BUILDING ELEVATIONS.
- SIGNAGE INSTALLATION:** INSTALL MISSING LETTERING TO MATCH EXISTING.
- ROOF ACCESSORY REPLACEMENT:** REPLACE DAMAGED ROOF ACCESSORIES. MATCH EXISTING TYPE, MATERIAL, AND STYLE.
- DOWNSPOUT AND GUTTER CLEANING:** DOWNSPOUT/COLLECTOR LOCATIONS. SEE ELEVATIONS. CONTRACTOR IS TO REMOVE ALL DEBRIS FROM GUTTERS AND DOWN SPOUTS.
- SATELLITE REMOVAL:** REMOVE ALL SATELLITE COMPONENTS. THESE ARE NO LONGER IN USE.
- COPING:** SEE ROOFING SHEETS FOR COPING, OVERHANG & ROOFING SCOPES - TYP.
- EXTERIOR CLEANING:** PRESSURE WASH WALLS TO REMOVE SCUFFS FROM STORM DEBRIS.
- WIND TURBINE REPLACEMENT:** REMOVE AND REPLACE WIND TURBINE TO MATCH EXISTING.
- PAINTING EXTERIOR:** CLEAN, PREP & RE-PAIN WALLS AND ARTWORK TO COVER SCUFFS AND DAMAGE FROM STORM DEBRIS. COLOR TO MATCH EXISTING AS APPROVED BY ARCHITECT.
- GLASS REPLACEMENT:** REMOVE AND REPLACE DAMAGED GLASS (OR PLYWOOD WHERE APPLICABLE) TO MATCH EXISTING. PROVIDE CAULKING AND GASKETING.
- STUCCO SOFFIT REPLACEMENT:** SOFFIT REMOVED BY OTHERS (HAZARDOUS MATERIAL). COORDINATE AND INSTALL NEW STUCCO SOFFIT.
- AGGREGATE PANEL REPLACEMENT:** DELAMINATED & DAMAGED AGGREGATE PANELS REMOVED BY OTHERS (HAZARDOUS MATERIAL). COORDINATE AND INSTALL NEW FACADE PANEL AS SPECIFIED. REINSTALL MEP COMPONENTS AT SAME LOCATIONS.
- DOWNSPOUT AND GUTTER REPLACEMENT:** REMOVE REMAINING ATTACHMENTS AND COMPONENTS OF DOWNSPOUT, GUTTER AND CONDUCTOR HEADS AND INSTALL NEW TO MATCH EXISTING COLOR, DIMENSION, GAUGE, AND MATERIAL. GROUT HOLES AT OLD STRAPS PRIOR TO NEW INSTALLATION & ATTACH AT INTERVALS EQUAL TO EXISTING SPACING. SALVAGE AND PREP REMAINING COMPONENTS FOR NEW INSTALLATION. CONTRACTOR IS TO REMOVE ALL DEBRIS FROM GUTTERS AND DOWN SPOUTS.
- BRICK REPAIR:** REMOVE AND REPLACE BRICK FACADE AS INDICATED. DISPOSE OF OLD BRICK, MATCH NEW BRICK AND MORTAR TO EXISTING AS APPROVED BY ARCHITECT. PRESERVE SUBSTRATE. REMOVE OLD BRICK TIES AND WATER PROOFING. INSTALL NEW WATERPROOFING AND BRICK TIES AT A MIN. OF 24" O.C. VERTICAL AND HORIZONTAL.
- VINYL SOFFIT REPLACEMENT:** REMOVE REMAINING VINYL SOFFIT AND REPLACE TO MATCH EXISTING - PRESERVE LIGHT & REINSTALL AS NECESSARY.



**RMG ARCHITECT**

RANDY M. GOODLOE, AIA, APAC  
725 KIRBY STREET  
LAKE CHARLES, LOUISIANA  
OFFICE: 337.436.3006  
FAX: 337.466.3779

LA. LICENSE NO. 4086


HURRICANE LAURA REPAIRS TO  
**A.M. BARBE HIGH SCHOOL**  
2200 W. McNEESE ST.  
FOR  
**CALCASIEU PARISH SCHOOL BOARD**  
LAKE CHARLES, LA 70605  
HL-003-01.03.04.05.06.07

© COPYRIGHT 2021,  
RANDY M. GOODLOE, AIA APAC  
ALL INFORMATION, EITHER DRAWN, WRITTEN,  
OR APPLIED APPEARING IN THIS DOCUMENT  
SHALL NOT BE DUPLICATED, DISCLOSED, OR  
OTHERWISE USED WITHOUT THE WRITTEN  
PERMISSION OF THE AUTHOR, RANDY M.  
GOODLOE, AIA APAC. THIS DOCUMENT IS AN  
INSTRUMENT OF SERVICE AND IS THE SOLE  
PROPERTY OF THE AUTHOR. FURTHERMORE,  
THE USE OF THIS DOCUMENT FOR ANY  
PURPOSE SHALL BE REVOKED, IF THE INTENT  
OF THE DESIGN OR THE CONSTRUCTION  
TECHNIQUES OR DETAILS SHOWN HEREIN  
ARE NOT AGREED TO BY THE  
CONTRACTUAL AGREEMENT GOVERNING  
THEIR USE ARE NOT STRICTLY ADHERED TO.

RMG PROJECT NO.  
**20042-01-G**  
OWNER PROJECT NO.  
**HL-003-01.03.04.05.06.07**  
PROJECT MANAGER  
**TM**  
DATE ISSUED  
**06/28/2024**

REVISED


SHEET NUMBER  
**(G)A0.3**  
BLDG & REFERENCE  
IMAGES



**KEYNOTES**

1. **PASSIVE AIR ROOF VENT REPLACEMENT:** EXISTING PASSIVE AIR ROOF VENT TO BE REMOVED.
2. **ROOF ASSEMBLY REPLACEMENT:** SHADED REGION INDICATES EXISTING ROOFING ASSEMBLY TO BE REMOVED TO EXPOSE METAL ROOF DECKING SUBSTRATE BELOW, AND NEW ROOFING INSTALLED. ALL DEBRIS IS TO BE REMOVED FROM THE SITE. SEE SPECIFICATIONS FOR EXTENT OF DEMOLITION AND SITE CONSTRAINTS.
3. **RIGID CONDUIT REPAIR (VIF):** INDICATES EXISTING RIGID CONDUIT RUNS EXPOSED ON EXISTING ROOF. CONTRACTOR SHALL MAKE VISUAL INSPECTIONS ON SITE TO VERIFY THE EXTENT OF WORK WHICH BE REQUIRED TO MOVE AND RELOCATE THESE CONDUIT RUNS DURING THE PROCESS OF RE-ROOFING AND TO ENSURE THAT THE NEW ROOF SLOPES ARE INTEGRATED AND ACCOUNTED FOR WHERE EXTENSIONS OF THESE CONDUITS AND WIRING IS REQUIRED.
4. **ROOF CURB REPLACEMENT:** ALL EXISTING ROOF CURBS TO BE REMOVED AND REPLACED IN AREAS BEING RE-ROOFED.
5. **ROOF DRAIN REPAIR (VIF):** APPROXIMATE LOCATION OF EXISTING ROOF DRAIN. CONTRACTOR SHALL VISUALLY INSPECT ALL CONDITIONS REPLACE DAMAGED COMPONENTS AND ADJUST TO NEW ROOF SLOPE.
6. **FLASHING VIF:** SEE DETAILS FOR FLASHING AND COUNTERFLASHING WHICH IS TO TIE INTO THE EXISTING BUILDING ENVELOPE. VERIFY CLEARANCES AND LOCATIONS FOR INSTALLATION OF ALL FLASHING AND TERMINATION BARS AS DETAILED.
7. **RUNNER CURB INSTALLMENT:** PROVIDE NEW "RUNNER CURBS" FOR SUPPORT OF ALL HARD PIPING WHICH IS REMAIN ON ROOF AFTER NEW INSTALLATION. SPACE CURBS AS REQUIRED SO CONDUIT AND PIPING DOES NOT SAG BETWEEN THESE LOCATIONS. INSTALL AS DETAILED.
8. **ROOF EXPANSION JOINT REPAIR (VIF):** INDICATES APPROXIMATE AREA AND LOCATION OF ROOF EXPANSION JOINT. CONTRACTOR SHALL VISUALLY INSPECT THE EXISTING CONDITIONS AT THE SITE AND PROVIDE A NEW EXPANSION JOINT AS DETAILED WITH THESE DOCUMENTS. THE INSTALLER SHOULD ASSUME THAT ALL EXISTING WOOD BLOCKING SHALL BE REPLACED WITH NEW TREATED WOOD BLOCKING AS PER DETAILS. PROVIDE NEW CANT STRIP, FLASHING, PRE-FINISHED EXPANSION JOINT COVER, VINYL BELLOW, AND BASE FLASHING AS DETAILED. VERIFY EXACT ROUTING AND AREA WHERE THIS IS TO BE REMOVED AND REPLACED. VERIFY ALL EXISTING CONDITIONS, ESPECIALLY ANY PIPING, AND CONDUIT WHICH MIGHT INTERSECT OR CROSS OVER THIS JOINT.
9. **PLUMBING VENT REPLACEMENT (VIF):** CONTRACTOR SHALL VISUALLY INSPECT ALL EXISTING ROOFING PLUMBING VENTS WHICH ARE TO REMAIN. CONFIRM HEIGHTS OF VENT PIPING AND EXTEND WHERE REQUIRED DUE TO INSTALLATION OF NEW TAPERED INSULATION. EXTEND ALL VENTS AS REQUIRED TO MAINTAIN VERTICAL CLEARANCES CALLED FOR ON EACH RELATED CONSTRUCTION DETAIL. REPLACE ALL LEAD VENT & PIPE FLASHING. TYPICAL ALL LOCATIONS.
10. **FLASHING REPLACEMENT:** REMOVE AND REPLACE FLASHING, COUNTERFLASHING AND PRE-FINISHED METAL FASCIA FLASHING AS DETAILED.
11. **SKYLIGHT REPLACEMENT:** INSTALL NEW ALUMINUM SKYLIGHT GUARD TO MATCH EXISTING.
12. **HVAC REPAIR (VIF):** INDICATES EXISTING HVAC EQUIPMENT AT EXISTING ROOF WHICH IS TO REMAIN. COORDINATE WORK INVOLVED WITH THIS EQUIPMENT AND NEW ROOFING ASSEMBLY SO AS TO NOT DISRUPT SERVICE TO THE EXISTING BUILDING. IF SERVICE IS REQUIRED TO BE TEMPORARILY SUSPENDED WHILE NEW WORK IS TAKING PLACE, THE CONTRACTOR SHALL COORDINATE ANY AND ALL OUTAGES WITH THE OWNER AND WILL BE REQUIRED TO ONLY PERFORM THIS WORK AT TIMES WHEN SUSPENSION OF THIS SERVICE MINIMALLY AFFECTS THE OWNERS USE OF THE BUILDING. IF THE SERVICE CANNOT BE SUSPENDED DURING OWNER'S OPERATING HOURS, WORK MAY HAVE TO BE PERFORMED AFTER HOURS, OR ON WEEKENDS.
13. **SATELLITE INSTALLATION:** SEE DETAILS FOR SATELLITE MOUNTING UNIT.
14. **"E" METAL PANEL REPLACEMENT:** METAL WALL PANEL "E" - REMOVE AND REPLACE DAMAGED/MISSING METAL WALL PANEL AS SPECIFIED. SEE BUILDING ELEVATIONS.
15. **SIGNAGE INSTALLATION:** INSTALL MISSING LETTERING TO MATCH EXISTING.
16. **ROOF ACCESSORY REPLACEMENT:** REPLACE DAMAGED ROOF ACCESSORIES. MATCH EXISTING TYPE, MATERIAL, AND STYLE.
17. **DOWNSPOUT AND GUTTER CLEANING:** DOWNSPOUT/COLLECTOR LOCATIONS. SEE ELEVATIONS. CONTRACTOR IS TO REMOVE ALL DEBRIS FROM GUTTERS AND DOWN SPOUTS.
18. **SATELLITE REMOVAL:** REMOVE ALL SATELLITE COMPONENTS. THESE ARE NO LONGER IN USE.
19. **COPING:** SEE ROOFING SHEETS FOR COPING, OVERHANG & ROOFING SCOPES - TYP.
20. **EXTERIOR CLEANING:** PRESSURE WASH WALLS TO REMOVE SCUFFS FROM STORM DEBRIS.
21. **WIND TURBINE REPLACEMENT:** REMOVE AND REPLACE WIND TURBINE TO MATCH EXISTING.
22. **PAINTING EXTERIOR:** CLEAN, PREP & RE-PAINT WALLS AND ARTWORK TO COVER SCUFFS AND DAMAGE FROM STORM DEBRIS. COLOR TO MATCH EXISTING AS APPROVED BY ARCHITECT.
23. **GLASS REPLACEMENT:** REMOVE AND REPLACE DAMAGED GLASS (OR PLYWOOD WHERE APPLICABLE) TO MATCH EXISTING. PROVIDE CAULKING AND GASKETING.
24. **STUCCO SOFFIT REPLACEMENT:** SOFFIT REMOVED BY OTHERS (HAZARDOUS MATERIAL). COORDINATE AND INSTALL NEW STUCCO SOFFIT.
25. **AGGREGATE PANEL REPLACEMENT:** DELAMINATED & DAMAGED AGGREGATE PANELS REMOVED BY OTHERS (HAZARDOUS MATERIAL). COORDINATE AND INSTALL NEW FACADE PANEL AS SPECIFIED. REINSTALL MEP COMPONENTS AT SAME LOCATIONS.
26. **DOWNSPOUT AND GUTTER REPLACEMENT:** REMOVE REMAINING ATTACHMENTS AND COMPONENTS OF DOWNSPOUT, GUTTER AND CONDUCTOR HEADS AND INSTALL NEW TO MATCH EXISTING COLOR, DIMENSION, GAUGE, AND MATERIAL. GROUT HOLES AT OLD STRAPS PRIOR TO NEW INSTALLATION & ATTACH AT INTERVALS EQUAL TO EXISTING SPACING. SALVAGE AND PREP REMAINING COMPONENTS FOR NEW INSTALLATION. CONTRACTOR IS TO REMOVE ALL DEBRIS FROM GUTTERS AND DOWN SPOUTS.
27. **BRICK REPAIR:** REMOVE AND REPLACE BRICK FACADE AS INDICATED. DISPOSE OF OLD BRICK, MATCH NEW BRICK AND MORTAR TO EXISTING AS APPROVED BY ARCHITECT. PRESERVE SUBSTRATE. REMOVE OLD BRICK TIES AND WATER PROOFING. INSTALL NEW WATERPROOFING AND BRICK TIES AT A MIN. OF 24" O.C. VERTICAL AND HORIZONTAL.
28. **VINYL SOFFIT REPLACEMENT:** REMOVE REMAINING VINYL SOFFIT AND REPLACE TO MATCH EXISTING - PRESERVE LIGHT & REINSTALL AS NECESSARY.

NOTE: IMAGES ARE FOR VISUAL REFERENCES TO HELP UNDERSTAND DAMAGES. THEY DO NOT REPRESENT THE ENTIRE SCOPE OF WORK AND SHOULD BE USED IN CONJUNCTION WITH THE DRAWINGS AND CURRENT CONDITIONS IN THE FIELD. CONTRACTOR SHALL CONFIRM CURRENT CONDITIONS IN THE FIELD PRIOR TO BIDDING - TYPICAL.



7/1/2024 11:06:00 AM

**RMG ARCHITECT**

RANDY M. GOODLOE, AIA, APAC  
725 KIRBY STREET  
LAKE CHARLES, LOUISIANA  
OFFICE: 337.436.3006  
FAX: 337.466.9779

LA. LICENSE NO. 4086


HURRICANE LAURA REPAIRS TO  
**A.M. BARBE HIGH SCHOOL**  
2200 W. McNEESE ST.  
FOR  
**CALCASIEU PARISH SCHOOL BOARD**  
LAKE CHARLES, LA 70605  
HL-003-01.03.04.05.06.07

© COPYRIGHT 2021, RANDY M. GOODLOE, AIA APAC  
ALL INFORMATION, EITHER DRAWN, WRITTEN, OR PRINTED APPEARING IN THIS DOCUMENT SHALL NOT BE DUPLICATED, DISCLOSED, OR OTHERWISE USED WITHOUT THE WRITTEN PERMISSION OF THE AUTHOR, RANDY M. GOODLOE, AIA APAC. THIS DOCUMENT IS AN INSTRUMENT OF SERVICE AND IS THE SOLE PROPERTY OF THE AUTHOR. FURTHERMORE, THE USE OF THIS DOCUMENT FOR ANY PURPOSE SHALL BE REVOKED, IF THE INTENT OF THE DESIGN OR THE CONSTRUCTION TECHNIQUES OR DETAILS SHOWN HEREIN ARE NOT AGREED TO BY THE CONTRACTOR. CONTRACTOR AGREEMENT GOVERNING THEIR USE ARE NOT STRICTLY ADHERED TO.

RMG PROJECT NO.  
**20042-01-G**  
OWNER PROJECT NO.  
**HL-003-01.03.04.05.06.07**  
PROJECT MANAGER  
**TM**  
DATE ISSUED  
**06/28/2024**

REVISED

SHEET NUMBER  
**(G)A0.4**  
BLDG & REFERENCE IMAGES



11 BUILDING G - FLOOR PLAN  
3/32" = 1'-0"

FLOOR PLAN LEGEND	
	- CEILING REPAIR REQUIRED
	- FLOORING REPAIR REQUIRED. SEE ROOM SCHEDULE.
	- WALL/BASE REPAIR REQUIRED. SEE ROOM SCHEDULE.
	- MILLWORK REPAIR REQUIRED. SEE ROOM SCHEDULE.
	- WORK IN THIS AREA IS TO BE PERFORMED WITHIN DATES GIVEN IN PHASING SCHEDULE. SEE SECTION 01 10 00 SUMMARY OF THE SPECIFICATION MANUAL.

GLAZING SCHEDULE	
G1	- CLEAR, INSULATED GLASS AS SPECIFIED.
G2	- SPANDRAL GLASS AS SPECIFIED.
G3	- TINTED, INSULATED GLASS AS SPECIFIED.
G4	- ALUMINUM WINDOW PANEL AS SPECIFIED.


\*GLAZING OF NEW STOREFRONT UNITS ARE TO BE LARGE MISSILE IMPACT AS SPECIFIED. REPLACEMENT GLAZING IS TO MATCH EXISTING.

ROOMS - BUILDING G		
ROOM NUMBER	Area	Perimeter
G101	371 SF	78' - 10"
G102	526 SF	94' - 2"
G103	521 SF	93' - 10"
G105	253 SF	63' - 8"
G106	295 SF	70' - 3"
G107	278 SF	68' - 8"
G111	141 SF	62' - 8"
G120	172 SF	56' - 3"
G121	129 SF	51' - 3"
G122	120 SF	46' - 0"
G123	113 SF	45' - 1"
G126B	130 SF	46' - 1"
G127	224 SF	87' - 0"
G128	30 SF	24' - 3"
G133	61 SF	31' - 11"
G134	1002 SF	235' - 1"
G136	214 SF	72' - 5"
G137	957 SF	150' - 2"
G146	931 SF	167' - 2"
G147	900 SF	136' - 0"
G148	1283 SF	146' - 10"
G149	106 SF	41' - 6"
G150	108 SF	42' - 1"
G151	426 SF	84' - 0"
G152	958 SF	149' - 7"
G153	929 SF	166' - 5"
G154	924 SF	212' - 0"
G155	318 SF	117' - 5"
G156	512 SF	157' - 5"
G-9	474 SF	87' - 6"
G-10	542 SF	93' - 1"
G-11	507 SF	89' - 3"

- KEYNOTES**
- SUSPENDED ACOUSTIC CEILING REPLACEMENT:** REMOVE AND REPLACE DAMAGED CEILING GRID AND CEILING TILE AS SPECIFIED.
  - CEILING GRID:** REMOVE AND REPLACE DAMAGED CEILING GRID. MATCH EXISTING. SEE UNIT PRICE NO. 5
  - VCT FLOORING REPAIRS:** REMOVE AND REPLACE VCT FLOORING AS SPECIFIED IN AREAS WHERE INDICATED. SEE UNIT PRICE NO. 3
  - WINDOW REPAIRS:** REPLACE BROKEN WINDOW PANE, BLOCKS, AND GASKETS TO MATCH EXISTING. ALL SEALANTS SHALL BE REMOVED AND REPLACED AS SPECIFIED TO ENSURE WEATHER TIGHT SEAL. SEE ELEVATIONS.
  - STRUCTURAL CLAY BLOCK:** GLAZED STRUCTURAL CLAY BLOCK TO BE REMOVED AND REPLACED AS SPECIFIED TO MATCH EXISTING. CLEAN ALL CHALKING RESIDUE FROM EFFERVESCENCE.
  - VINYL BASE REPLACEMENT:** REPLACE DAMAGED OR MISSING BASE AS SPECIFIED TO MATCH EXISTING. SEE UNIT PRICE NO. 4
  - CARPET REPAIRS:** DAMAGED CARPET HAS BEEN REMOVED. CLEAN FLOOR AND INSTALL NEW CARPET TILE AS SPECIFIED.
  - PAINTING:** WALL SURFACE IS TO BE SANDED, PREPARED, AND REPAINT TO MATCH EXISTING CORNER TO CORNER. WATER STAINED WALL FROM ROOF LOSS.
  - PAINTED CEILING STRUCTURE:** CEILING INCLUDING METAL TRUSSES ARE TO BE CLEANED, PREPPED, AND REPAINTED END TO END TO MATCH EXISTING COLOR.
  - VCT FLOORING CLEANING:** CLEAN WATER STAINS FROM VCT FLOORING TO REMOVE ANY DISCOLORATION WHERE INDICATED. MOP AND WAX ALL VCT FLOORING AT THE END OF CONSTRUCTION.
  - SKYLIGHT REPAIRS:** REMOVE AND REPLACE SKYLIGHT TO MATCH EXISTING.
  - TERRAZZO FLOORING CLEANING:** CLEAN AND POLISH EXISTING TERRAZZO FLOORING REFER TO ROOM SCHEDULE FOR CLARITY.
  - CEILING TILE REPLACEMENT:** REMOVE AND REPLACE DAMAGED OR MISSING ACOUSTIC CEILING TILE WITH NEW CEILING TILE AS SPECIFIED IN AREAS INDICATED. MATCH EXISTING TYPE AND SIZE. SEE UNIT PRICE NO. 1. INSTALL R-30 BATT INSULATION OVER TILE. SEE UNIT PRICE NO. 2
  - NOT USED.**
  - EXTERIOR WINDOWS AND DOORS:** CAULK AND RESEAL PERIMETER OF EXISTING WINDOWS AND DOORS.
  - CMU REPAIR:** RE-POINT DAMAGED CMU JOINTS AS SHOWN. PAINT WALL FROM END TO END IN COLOR TO MATCH EXISTING AS SPECIFIED. SEE PHOTOS.
  - BRICK REPAIR:** CAULK CRACKED AREAS AND REPAIR.
  - LOCKERS:** REPLACE DAMAGED UNITS AS SHOWN. MATCH EXISTING STYLE, SIZE AND COLORS.
  - BRICK WALLS:** CLEAN ALL WATER STAINS FROM ENTIRE BRICK WALL.
  - SHELVING REPLACEMENT:** REMOVE AND REPLACE DAMAGED SHELVING UNITS WITH GLASS DOORS. MATCH EXISTING MATERIALS, FINISHES AND CONSTRUCTION STYLE.
  - BASE CABINET:** REMOVE AND REPLACE DAMAGED BASE CABINET. MATCH EXISTING STYLE, SIZE, AND CONSTRUCTION. SALVAGE AND REINSTALL COUNTERTOP.
  - SECTIONAL DOOR:** REMOVE AND REPLACE OVERHEAD SECTIONAL DOOR AS SPECIFIED. CONTRACTOR TO PROVIDE ANY ADDITIONAL SUPPORT REQUIRED BY MANUFACTURER TO REINSTALL DOOR.
  - GYPSUM BOARD:** REMOVE AND REPLACE DAMAGED GYPSUM BOARD TO NEAREST FRAMING MEMBER. FINISH AND RE-PAINT WALL CORNER TO CORNER.
  - PREFINISHED GYPSUM BOARD WITH VINYL WALL COVER AND CORNER TRIM:** REMOVE AND REPLACE DAMAGED VINYL COVERED GYPSUM BOARD FROM FLOOR TO CEILING WHERE INDICATED ON FLOOR PLAN.
  - STOREFRONT WINDOW:** REMOVE AND REPLACE STOREFRONT WINDOW AS SPECIFIED.
  - STUCCO SOFFIT:** REMOVE AND REPLACE STUCCO SOFFIT. COORDINATE WITH ABATEMENT SCOPE & ABATEMENT CONTRACTOR TO ENSURE WEATHER-TIGHTNESS AND PHASING COORDINATION. SEE WALL SECTIONS & DETAILS.
  - GYPSUM CEILING REPAIRS:** REMOVE AND REPLACE DAMAGED GYPSUM CEILING BOARD TO NEAREST FRAMING MEMBER WHERE INDICATED, FINISH TO MATCH EXISTING AS SPECIFIED.
  - METAL ROOF PANEL REPAIRS:** REMOVE AND REPLACE DEFORMED OR MISSING METAL ROOF PANELS TO MATCH EXISTING.
  - CONCRETE FLOOR CLEANING:** CLEAN AND RESEAL FLOOR AS SPECIFIED.
  - BASE CABINET:** REMOVE AND REPLACE DAMAGED BASE CABINET. MATCH EXISTING STYLE, SIZE, AND CONSTRUCTION. SALVAGE AND REINSTALL COUNTERTOP. PROTECT ALL MECHANICAL CONNECTIONS.
  - TILE CLEANING:** CLEAN STAINS FROM WALL TILE TO REMOVE ANY DISCOLORATION WHERE INDICATED.
  - CLEAN/REPAINT MASONRY WALL:** MECHANICALLY REMOVE ALL LOOSE OR PEELING PAINT AND ALL CHALKING RESIDUE FROM EFFERVESCENCE FROM CORNER TO CORNER. PERFORM REQUIRED MOISTURE TESTING PRIOR TO REPAINTING WALL AS SPECIFIED.
  - PLASTER CEILING REPAIRS:** REMOVE AND REPLACE DAMAGED PLASTER CEILING WHERE INDICATED AS SPECIFIED, PAINT IN COLOR TO MATCH EXISTING.
  - MEP DAMAGES:** SEE MECHANICAL, PLUMBING AND ELECTRICAL PLANS.
  - FURNITURE SETTING AND RESETING:** RELOCATE ALL EXISTING FURNITURE TO TEMPORARY ROOM IN MODULAR BUILDINGS WHILE EXISTING SPACE IS BEING REPAIRED. REINSTALL AND RESET FURNITURE ONCE REPAIRS ARE COMPLETE. SEE PHASING PLAN.
  - SUSPENDED CEILING INSULATION:** INSTALL R-19 BATT INSULATION AS SPECIFIED ABOVE PREVIOUSLY INSTALLED SUSPENDED CEILING TILE. SEE UNIT PRICE NO. 2.
  - BRICK WALL REPLACEMENT:** REMOVE AND REPLACE BRICK WALL AS INDICATED. DISPOSE OF OLD BRICK. MATCH NEW BRICK AND MORTAR TO EXISTING AS APPROVED BY ARCHITECT. SEE STRUCTURAL BUILDING TO REMAIN WEATHERPROOF AND CONDITIONED DURING REPAIRS.
  - DOOR REPAIR:** CLEAN, PREP AND RE-PAINT DOOR FRAME - SEE DOOR SCHEDULE.
  - CORRIDOR WALL REPAIR:** REMOVE DAMAGED STOREFRONT WINDOW AND EXISTING 3/4" PLYWOOD SHEATHING BELOW WINDOW. INSTALL NEW WINDOW PER SCHEDULE AND NEW 3/4" PLYWOOD SHEATHING. PAINT AS SPECIFIED, IN COLOR AS SELECTED. SEE DETAILS.
  - GLAZING REPAIR:** REMOVE AND REPLACE BROKEN GLASS. MATCH EXISTING TINT. PROVIDE SAFETY GLASS AS REQUIRED.
  - DOOR REPAIR:** REMOVE AND REPLACE EXISTING LEFT DOOR LEAF. PROVIDE AN INSULATED HOLLOW METAL DOOR WITH VISION PANEL TO MATCH RIGHT DOOR LEAF. REINSTALL EXISTING DOOR HARDWARE. PAINT AS DIRECTED.

HARDWARE SCHEDULE	
H-1	- REMOVE EXISTING HARDWARE AND REINSTALL ON NEW DOOR. PROVIDE NEW WEATHER STRIPPING, SILENCERS.

DOOR SCHEDULE										
MARK	OPENING SIZE		HARDWARE	DOOR			FRAME		GLASS	COMMENTS
	WIDTH	HEIGHT		TYPE	MATERIAL	FINISH	MATERIAL	FINISH		
G108A	3'-0"	7'-0"	H-1	FLUSH	INSULATED H.M.	PAINTED	H.M.	PAINTED	--	REPLACE ENTIRE UNIT, MATCH EXISTING
G110A	11'-0"	12'-0"	MANUF.	OVERHEAD	SEE SPECS	SEE SPECS	MANUFACTURER	MANUFACTURER	--	REPLACE ENTIRE UNIT, MATCH EXISTING
G142A	3'-0"	7'-0"	H-1	FLUSH	INSULATED H.M.	PAINTED	H.M.	PAINTED	--	REPLACE ENTIRE UNIT, MATCH EXISTING
G155A	6'-0"	7'-0"	H-1	FLUSH	INSULATED H.M.	PAINTED	H.M.	PAINTED	--	REPLACE LEAF INDICATED, MATCH EXISTING
G156A	3'-0"	7'-0"	H-1	FLUSH	INSULATED H.M.	PAINTED	H.M.	PAINTED	G1	REPLACE ENTIRE UNIT, MATCH EXISTING



**RMG**  
 RANDY M. GOODLOE, AIA, APAC  
 725 KIRBY STREET  
 LAKE CHARLES, LOUISIANA  
 OFFICE: 337.436.3036  
 FAX: 337.463.3773

**ARCHITECT**  
 RANDY MICHAEL GOODLOE  
 No. 288  
 STATE OF LOUISIANA  
 REGISTERED ARCHITECT  
 LA. LICENSE NO. 4086

HURRICANE LAURA REPAIRS TO  
**A.M. BARBE HIGH SCHOOL**  
 2200 W. McNEESE ST.  
 FOR  
**CALCASIEU PARISH SCHOOL BOARD**  
 LAKE CHARLES, LA 70605  
 HL-003-01.03.04.05.06.07

© COPYRIGHT 2021,  
 RANDY M. GOODLOE, AIA APAC  
 ALL INFORMATION, EITHER DRAWN, WRITTEN,  
 OR IMPRINTED APPEARING IN THIS DOCUMENT  
 SHALL NOT BE DUPLICATED, DISCLOSED, OR  
 OTHERWISE USED WITHOUT THE WRITTEN  
 PERMISSION OF THE AUTHOR, RANDY M.  
 GOODLOE, AIA, APAC. THIS DOCUMENT IS AN  
 INSTRUMENT OF SERVICE AND IS THE SOLE  
 PROPERTY OF THE AUTHOR. FURTHERMORE,  
 THE USE OF THIS DOCUMENT FOR ANY  
 PURPOSE SHALL BE REVOKED, IF THE INTENT  
 OF THE DESIGN OR THE CONSTRUCTION  
 TECHNIQUES OR DETAILS SHOWN HEREIN  
 ARE NOT AGREED TO OR THE  
 CONTRACTUAL AGREEMENT GOVERNING  
 THEIR USE ARE NOT STRICTLY ADHERED TO.

RMG PROJECT NO.  
**20042-01-G**  
 OWNER PROJECT NO.  
**HL-003-01.03.04.05.06.07**  
 PROJECT MANAGER  
**TM**  
 DATE ISSUED  
**06/28/2024**

REVISED

**SHEET NUMBER**  
**(G)A1.1**  
 BLDG G 1ST FLOOR




6/27/2024 1:14:12 PM



G09\_1.jpeg



G09\_2.jpeg



G09\_3.jpeg




G09\_4.jpeg




G09\_5.jpeg




G09\_6.jpeg



G09\_7.jpeg



G9\_10.JPG




G9\_11.JPG




G10\_1.jpeg



G10\_2.jpeg



G10\_3.jpeg




G10\_11.jpeg




G10\_12.jpeg




G10\_13.jpeg



G10\_14.jpeg



G10\_15.jpeg




G10\_16.jpeg




G10\_19.JPG



G10\_20.JPG



G10\_21.JPG



G10\_22.JPG



G11\_1.jpeg



G11\_2.jpeg



G11\_3.jpeg



G11\_4.jpeg




G11\_5.jpeg




G11\_6.jpeg



G11\_7.jpeg



G11\_8.jpeg



RANDY M. GOODLOE, AIA, APAC  
725 KIRBY STREET  
LAKE CHARLES, LOUISIANA

OFFICE: 337.436.3036  
FAX: 337.466.3775

ARCHITECT



LA. LICENSE NO. 4086


HURRICANE LAURA REPAIRS TO  
**A.M. BARBE HIGH SCHOOL**  
2200 W. McNEESE ST.  
FOR  
**CALCASIEU PARISH SCHOOL BOARD**  
LAKE CHARLES, LA 70605  
HL-003-01.03.04.05.06.07

© COPYRIGHT 2021,  
RANDY M. GOODLOE, A.I.A. APAC  
ALL INFORMATION, EITHER DRAWN, WRITTEN,  
OR PRINTED APPEARING IN THIS DOCUMENT  
SHALL NOT BE DUPLICATED, DISCLOSED, OR  
OTHERWISE USED WITHOUT THE WRITTEN  
PERMISSION OF THE AUTHOR, RANDY M.  
GOODLOE, AIA, APAC. THIS DOCUMENT IS AN  
INSTRUMENT OF SERVICE AND IS THE SOLE  
PROPERTY OF THE AUTHOR. FURTHERMORE,  
THE USE OF THIS DOCUMENT FOR ANY  
PURPOSE SHALL BE REVOKED, IF THE INTENT  
OF THE DESIGN OR THE CONSTRUCTION  
TECHNIQUES OR DETAILS SHOWN HEREIN  
ARE NOT ADHERED TO OR THE  
CONTRACTUAL AGREEMENT GOVERNING  
THEIR USE ARE NOT STRICTLY ADHERED TO.

RMG PROJECT NO.  
**20042-01-G**  
OWNER PROJECT NO.  
**HL-003-01.03.04.05.06.07**  
PROJECT MANAGER  
**TM**

DATE ISSUED  
**06/28/2024**


REVISED




SHEET NUMBER  
**(G)A1.2**  
BLDG G 1ST FLOOR



32



G11\_10.jpeg



G11\_11.jpeg



G11\_12.jpeg



G11\_15.jpeg



G11\_16.jpeg



2



G11\_18.jpeg




G11\_23.jpeg



G101\_2.jpeg



G101\_4.JPG



G101\_5.JPG




8




G102\_2.jpeg




G102\_4.jpeg



G102\_5.jpeg



G102\_7.jpeg



G102\_9.jpeg




10




G102\_11.JPG




G102\_12.JPG




G103\_1.jpeg




G103\_2.jpeg




G103\_3.jpeg



6




G103\_5.jpeg



G103\_6.jpeg



G103\_7.jpeg



G103\_9.JPG



G103\_10.JPG



6




G103\_12.JPG



G103\_13.JPG



G103\_14.JPG




G103\_15.JPG



G104\_1.JPG



RANDY M. GOODLOE, AIA, APAC  
725 KIRBY STREET  
LAKE CHARLES, LOUISIANA  
OFFICE: 337.436.3036  
FAX: 337.466.3775




LA. LICENSE NO. 4086

HURRICANE LAURA REPAIRS TO  
**A.M. BARBE HIGH SCHOOL**  
2200 W. McNEESE ST.  
FOR  
**CALCASIEU PARISH SCHOOL BOARD**  
LAKE CHARLES, LA 70605  
HL-003-01.03.04.05.06.07

© COPYRIGHT 2021,  
RANDY M. GOODLOE, A.I.A. APAC  
ALL INFORMATION, EITHER DRAWN, WRITTEN,  
OR MARKED APPEARING IN THIS DOCUMENT  
SHALL NOT BE DUPLICATED, DISCLOSED, OR  
OTHERWISE USED WITHOUT THE WRITTEN  
PERMISSION OF THE AUTHOR, RANDY M.  
GOODLOE, AIA, APAC. THIS DOCUMENT IS AN  
INSTRUMENT OF SERVICE AND IS THE SOLE  
PROPERTY OF THE AUTHOR. FURTHERMORE,  
THE USE OF THIS DOCUMENT FOR ANY  
PURPOSE SHALL BE REVOKED, IF THE INTENT  
OF THE DESIGN OR THE CONSTRUCTION  
TECHNIQUES OR DETAILS SHOWN HEREIN  
ARE NOT ADHERED TO OR THE  
CONTRACTUAL AGREEMENT GOVERNING  
THEIR USE ARE NOT STRICTLY ADHERED TO.


RMG PROJECT NO.  
**20042-01-G**  
OWNER PROJECT NO.  
**HL-003-01.03.04.05.06.07**  
PROJECT MANAGER  
**TM**  
DATE ISSUED  
**06/28/2024**

REVISED





SHEET NUMBER  
**(G)A1.3**  
BLDG G 1ST FLOOR


6/27/2024 1:14:23 PM



G105\_1.jpeg



G105\_3.jpeg




G105\_4.jpeg



G106\_3.jpeg



G106\_4.jpeg



G106\_5.jpeg



G106\_9.jpeg




G106\_10.jpeg



G107\_1.jpeg



G107\_3.jpeg



G108\_3.jpeg



G108\_4.jpeg



G110\_1.JPG



G111\_1.JPG




G115\_1.JPG



G115\_2.JPG




G115\_3.JPG



G115\_4.JPG



G117\_1.jpeg



G117\_2.jpeg



G117\_3.jpeg



G117\_4.JPG



G117\_5.JPG



G117\_6.JPG



G117\_7.JPG



G117\_8.JPG



G117\_9.JPG



G119\_1.JPG



G119\_2.JPG



G120\_3.jpeg



G120\_5.jpeg



G120\_7.jpeg



G121\_2.jpeg



G121\_3.jpeg



G122\_2.jpeg



G122\_3.jpeg

**RMG**  
 RANDY M. GOODLOE, AIA, APAC  
 725 KIRBY STREET  
 LAKE CHARLES, LOUISIANA  
 OFFICE: 337.436.3036  
 FAX: 337.466.3773

**ARCHITECT**

LA. LICENSE NO. 4086

HURRICANE LAURA REPAIRS TO  
**A.M. BARBE HIGH SCHOOL**  
 2200 W. McNEESE ST.  
 FOR  
**CALCASIEU PARISH SCHOOL BOARD**  
 LAKE CHARLES, LA 70605  
 HL-003-01.03.04.05.06.07


© COPYRIGHT 2021, RANDY M. GOODLOE, AIA, APAC  
 ALL INFORMATION, EITHER DRAWN, WRITTEN, OR MARKED APPEARING IN THIS DOCUMENT SHALL NOT BE DUPLICATED, DISCLOSED, OR OTHERWISE USED WITHOUT THE WRITTEN PERMISSION OF THE AUTHOR, RANDY M. GOODLOE, AIA, APAC. THIS DOCUMENT IS AN INSTRUMENT OF SERVICE AND IS THE SOLE PROPERTY OF THE AUTHOR. FURTHERMORE, THE USE OF THIS DOCUMENT FOR ANY PURPOSE SHALL BE REVOKED, IF THE INTENT OF THE DESIGN OR THE CONSTRUCTION ARE NOT AGREED TO OR THE CONTRACTUAL AGREEMENT GOVERNING THEIR USE ARE NOT STRICTLY ADHERED TO.

RMG PROJECT NO.  
**20042-01-G**  
 OWNER PROJECT NO.  
**HL-003-01.03.04.05.06.07**  
 PROJECT MANAGER  
**TM**  
 DATE ISSUED  
**06/28/2024**

REVISED

SHEET NUMBER  
**(G)A1.4**  
 BLDG G 1ST FLOOR

6/27/2024 1:14:32 PM



G122\_4.jpeg




G123\_2.jpeg



G123\_3.JPG



G123\_4.JPG



G126A\_1.jpeg



G126A\_6.jpeg



G126A\_7.jpeg




G126A\_8.jpeg



G126A\_9.jpeg



G126A\_10.jpeg




G126A\_11.jpeg




G126A\_12.jpeg



G126B\_1.jpeg



G126B\_2.JPG



G126B\_3.JPG




G126B\_4.JPG



G126B\_5.JPG




G128\_1.jpeg



G133\_1.jpeg




G136\_1.jpeg



G137\_1.jpeg




G137\_3.jpeg



G142\_3.jpeg



G142\_4.jpeg



G142\_5.jpeg



G142\_6.jpeg



G142\_8.jpeg




G142\_9.jpeg



G142\_11.JPG




G142\_13.JPG



G142\_14.JPG



G143\_1.JPG



G144\_1.jpeg




G144\_2.jpeg



G144\_3.jpeg



G144\_4.jpeg



RANDY M. GOODLOE, AIA, APAC  
725 KIRBY STREET  
LAKE CHARLES, LOUISIANA

OFFICE: 337.436.3086  
FAX: 337.466.3775

ARCHITECT



LA LICENSE NO. 4086

HURRICANE LAURA REPAIRS TO

A.M. BARBE HIGH SCHOOL

2200 W. McNEESE ST.

FOR CALCASIEU PARISH SCHOOL BOARD

LAKE CHARLES, LA 70605

HL-003-01.03.04.05.06.07

© COPYRIGHT 2021, RANDY M. GOODLOE, AIA, APAC  
ALL INFORMATION, EITHER DRAWN, WRITTEN, OR APPLIED APPEARING IN THIS DOCUMENT SHALL NOT BE DUPLICATED, DISCLOSED, OR OTHERWISE USED WITHOUT THE WRITTEN PERMISSION OF THE AUTHOR, RANDY M. GOODLOE, AIA, APAC. THIS DOCUMENT IS AN INSTRUMENT OF SERVICE AND IS THE SOLE PROPERTY OF THE AUTHOR. FURTHERMORE, THE USE OF THIS DOCUMENT FOR ANY PURPOSE SHALL BE REVOKED, IF THE INTENT OF THE DESIGN OR THE CONSTRUCTION TECHNIQUES OR DETAILS SHOWN HEREIN ARE NOT ADHERED TO OR THE CONTRACTUAL AGREEMENT GOVERNING THEIR USE ARE NOT STRICTLY ADHERED TO.


RMG PROJECT NO. 20042-01-G

OWNER PROJECT NO. HL-003-01.03.04.05.06.07

PROJECT MANAGER TM

DATE ISSUED 06/28/2024

REVISED



(G)A1.5  
BLDG G 1ST FLOOR



16




G144\_6.JPG



G144\_7.JPG



G145\_1.jpeg




G147\_1.jpeg



G147\_2.jpeg




G147\_3.jpeg



G147\_4.jpeg




G147\_5.jpeg




G147\_7.jpeg



G147\_8.jpeg



G147\_9.JPG



G147\_10.JPG



G148\_1.jpeg




G148\_2.jpeg



G148\_3.jpeg



G149\_1.jpeg



G151\_1.jpeg



G151\_2.jpeg




G151\_4.jpeg




G151\_5.jpeg



G151\_6.jpeg



G151\_7.jpeg




G151\_1.jpeg




G152\_2.jpeg




G152\_3.jpeg




G152\_4.jpeg



G152\_5.jpeg



G152\_6.jpeg




G152\_7.jpeg




G153\_1.jpeg



G153\_3.jpeg




G154center\_1.jpeg



G154center\_2.jpeg



G154east\_1.jpeg



G154east\_2.jpeg



RANDY M. GOODLOE, AIA, APAC  
725 KIRBY STREET  
LAKE CHARLES, LOUISIANA

OFFICE: 337.436.3036  
FAX: 337.463.3773



LA. LICENSE NO. 4086


HURRICANE LAURA REPAIRS TO  
**A.M. BARBE HIGH SCHOOL**  
2200 W. McNEESE ST.  
FOR  
**CALCASIEU PARISH SCHOOL BOARD**  
LAKE CHARLES, LA 70605  
HL-003-01.03.04.05.06.07

© COPYRIGHT 2021,  
RANDY M. GOODLOE, AIA, APAC  
ALL INFORMATION, EITHER DRAWN, WRITTEN,  
OR PRINTED APPEARING IN THIS DOCUMENT  
SHALL NOT BE DUPLICATED, DISCLOSED, OR  
OTHERWISE USED WITHOUT THE WRITTEN  
PERMISSION OF THE AUTHOR, RANDY M.  
GOODLOE, AIA, APAC. THIS DOCUMENT IS AN  
INSTRUMENT OF SERVICE AND IS THE SOLE  
PROPERTY OF THE AUTHOR. FURTHERMORE,  
THE USE OF THIS DOCUMENT FOR ANY  
PURPOSE SHALL BE REVOKED, IF THE INTENT  
OF THE DESIGN OR THE CONSTRUCTION  
TECHNIQUES OR DETAILS SHOWN HEREIN  
ARE NOT ADHERED TO OR THE  
CONTRACTUAL AGREEMENT GOVERNING  
THEIR USE ARE NOT STRICTLY ADHERED TO.

RMG PROJECT NO.  
**20042-01-G**  
OWNER PROJECT NO.  
**HL-003-01.03.04.05.06.07**  
PROJECT MANAGER  
**TM**

DATE ISSUED  
**06/28/2024**

REVISED



SHEET NUMBER  
**(G)A1.6**  
BLDG G 1ST FLOOR




G154east\_3.jpeg



G154west\_3.jpeg




G154\_1.JPG



G154\_2.JPG



G155\_2.jpeg




G155\_9.jpeg




G156\_1.jpeg




G156\_3.jpeg



G156\_5.jpeg



G156\_7.jpeg



G156\_8.jpeg



G156\_9.jpeg



G156\_10.jpeg



G156\_11.jpeg



G156\_12.jpeg




G156\_13.JPG




G156\_14.JPG



G156\_15.JPG



G156\_16.JPG




G156\_17.JPG



G156\_19.JPG



G156\_20.JPG



RANDY M. GOODLOE, AIA, APAC  
725 KIRBY STREET  
LAKE CHARLES, LOUISIANA  
OFFICE: 337.436.3036  
FAX: 337.466.3775

ARCHITECT



LA. LICENSE NO. 4086


HURRICANE LAURA REPAIRS TO  
**A.M. BARBE HIGH SCHOOL**  
2200 W. McNEESE ST.  
FOR  
**CALCASIEU PARISH SCHOOL BOARD**  
LAKE CHARLES, LA 70605  
HL-003-01.03.04.05.06.07

© COPYRIGHT 2021,  
RANDY M. GOODLOE, A.I.A. APAC  
ALL INFORMATION, EITHER DRAWN, WRITTEN,  
OR MARKED APPEARING IN THIS DOCUMENT  
SHALL NOT BE DUPLICATED, DISCLOSED, OR  
OTHERWISE USED WITHOUT THE WRITTEN  
PERMISSION OF THE AUTHOR, RANDY M.  
GOODLOE, AIA, APAC. THIS DOCUMENT IS AN  
INSTRUMENT OF SERVICE AND IS THE SOLE  
PROPERTY OF THE AUTHOR. FURTHERMORE,  
THE USE OF THIS DOCUMENT FOR ANY  
PURPOSE SHALL BE REVOKED, IF THE INTENT  
OF THE DESIGN OR THE CONSTRUCTION  
TECHNIQUES OR DETAILS SHOWN HEREIN  
ARE NOT ADHERED TO OR THE  
CONTRACTUAL AGREEMENT GOVERNING  
THEIR USE ARE NOT STRICTLY ADHERED TO.

RMG PROJECT NO.  
**20042-01-G**  
OWNER PROJECT NO.  
**HL-003-01.03.04.05.06.07**  
PROJECT MANAGER  
**TM**  
DATE ISSUED  
**06/28/2024**

REVISIONS

NO.	DESCRIPTION	DATE



SHEET NUMBER  
**(G)A1.7**  
BLDG G 1ST FLOOR