

COLUMBIAN ELEMENTARY SCHOOL

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
COL1	1/30/2018	5:59 AM	SC-1S	<1.00	126	<500	2.60	49.9	Backflow Valve #1	No Action Taken
COL2	1/30/2018	6:05 AM	SC-1M	<1.00	51.9	<500	<1.00	12.7	Backflow Valve #2	No Action Taken
COL3	1/30/2018	6:06 AM	TL	<1.00	158	<500	<1.00	886	Teachers Lounge	No Action Taken
COL4	1/30/2018	6:08 AM	KSF	<1.00	445	<500	1.56	76.0	Classroom #24	No Action Taken
COL5	1/30/2018	6:10 AM	DFS	<1.00	282	<500	<1.00	81.7	South Hallway Near Classroom #34	No Action Taken
COL6	1/30/2018	6:11 AM	DFS	<1.00	311	<500	<1.00	13.4	Hallway Near Gymnasium	No Action Taken
COL7	1/30/2018	6:12 AM	DFS	<1.00	253	<500	1.47	203	Hallway Near Gymnasium	No Action Taken
COL8	1/30/2018	6:14 AM	DFS	<1.00	240	<500	<1.00	18.2	Gymnasium	No Action Taken
COL9	1/30/2018	6:15 AM	DFS	<1.00	438	<500	<1.00	19.0	Gymnasium	No Action Taken
COL10	1/30/2018	6:17 AM	DFS	<1.00	1020	<500	10.6	458	Cafeteria	No Action Taken
COL11	1/30/2018	6:19 AM	KSF	<1.00	234	<500	<1.00	307	Kitchen	No Action Taken
COL12	1/30/2018	6:20 AM	DFS	<1.00	246	<500	<1.00	56.2	Office Corridor	No Action Taken
COL13	1/30/2018	6:21 AM	DFS	<1.00	281	<500	<1.00	11.8	Office Corridor	No Action Taken
COL14	1/30/2018	6:23 AM	KSF	<1.00	558	<500	<1.00	388	Main Office	No Action Taken
SL 15SEC	1/30/2018	5:53 AM		<1.00	24.1	<500	<1.00	32.9	Meter	No Action Taken
SL 45SEC	1/30/2018	5:53 AM		<1.00	14.2	<500	<1.00	15.1	Meter	No Action Taken

Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, *SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink

* Service Connection Tap is not a point for consumption water