

Park View Elementary

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
PRKV3	9/28/2017	6:02 AM	DFS	<1.00	685	<500	<1.00	173	Second Floor North Hallway	No Action Taken
PRKV4	9/28/2017	6:03 AM	DFS	<1.00	559	<500	<1.00	71.6	Second Floor North Hallway	No Action Taken
PRKV5	9/28/2017	6:06 AM	DFS	<1.00	275	<500	<1.00	89.9	Second Floor South Hallway	No Action Taken
PRKV6	9/28/2017	6:07 AM	DFS	<1.00	273	<500	<1.00	98.8	Second Floor South Hallway	No Action Taken
PRKV7-F	9/28/2017	6:09 AM	DFD	<1.00	318	<500	<1.00	23.3	First Floor Near Elevator	No Action Taken
PRKV7-B	9/28/2017	6:10 AM	DFD	<1.00	362	<500	<1.00	29.1	First Floor Near Elevator	No Action Taken
PRKV8	9/28/2017	6:11 AM	DFS	<1.00	252	<500	1.66	52.8	Gymnasium	No Action Taken
PRKV9	9/28/2017	6:15 AM	DFS	<1.00	1812	<500	<1.00	164	Basement Near Cafeteria	No Action Taken
PRKV10	9/28/2017	6:16 AM	DFS	<1.00	1493	<500	<1.00	213	Basement Near Cafeteria	No Action Taken
PRKV11	9/28/2017	6:17 AM	DFS	<1.00	344	<500	1.07	341	Cafeteria	No Action Taken
PRKV12	9/28/2017	6:18 AM	KSF	<1.00	151	<500	1.67	1421	Kitchen Sink	No Action Taken
PRKV13	9/28/2017	6:22 AM	DFS	<1.00	298	<500	<1.00	33.1	First Floor Near Computer Lab	No Action Taken
PRKV14	9/28/2017	6:23 AM	DFS	<1.00	241	<500	<1.00	33.0	First Floor Near Computer Lab	No Action Taken
PRKV15	9/28/2017	6:24 AM	KSF	<1.00	828	<500	1.29	620	Teachers Lounge	No Action Taken
PRKV16	9/28/2017	6:25 AM	DFS	<1.00	723	<500	1.08	339	First Floor Classroom 103	No Action Taken
PRKV17	9/28/2017	6:26 AM	DFS	<1.00	254	<500	<1.00	114	First Floor Classroom 102	No Action Taken
PRKV18	9/28/2017	6:27 AM	DFS	<1.00	526	<500	<1.00	206	First Floor Classroom 101	No Action Taken

Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, *SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink

* Service Connection Tap is not a point for consumption water