

Oakview Elementary



3= Needs Replaced
2= Needs Repaired
1= Satisfactory

Built	Enrollment	Bond 2002	PI
1952	479	3.4 million	< 1 million

Reno/Replace Ratio= 84%

Cost to Renovate = \$20,321,000

Heating & Cooling	3
Roofing	3
Ventilation/Air Conditioning	2
Electrical Systems	3
Plumbing & Fixtures	3
Windows	3
Structure: Foundation	2
Structure: Walls & Chimneys	2
Structure: Floors & Roofs	1
General Finishes	3
Interior Lighting	3
Security Systems	2
Emergency/Egress Lighting	1
Fire Alarm	3
Handicapped Access	3
Site Condition	3
Sewage System	1
Water Supply	1
Exterior Doors	3
Hazardous Material	3
Life Safety	3
Loose Furnishings	3
Technology	3