


# Northview Elementary School Strategic Planning Committee Survey Results on Facility Needs and Priorities


	Northview Elementary	
rity	ID	Weight
1	Add grades 2-5 classrooms.	1.461538
2	Improve car-rider and bus traffic flow.	1.653846
3	Add staff workroom.	1.769230
4	Renovate existing student restrooms.	1.807692
4	Renovate south student restrooms.	1.807692
6	Improve playground.	1.923076
7	Add teacher staff restrooms.	
8	Replace the roof.	2.192307
9	Improve athletic entry restroom access.	2.269230
10	Renovate interior finishes for existing facility.	2.307692
11	Maintenance building exterior (i.e., brick, downspouts, fascia, etc.)	2.346153
12	Renovate and expand administration office.	2.423076



## NORTHVIEW ELEMENTARY Strategic Planning Committee Survey January 14, 2025




#### 5. Add grades 2-5 classrooms.




6. How many additional grades 2-5 classrooms do you think are needed?

	Latest Responses
26	"Unknown"
26	"0"
Responses	"6-8"



#### 7. Improve car-rider and bus traffic flow.



8. Renovate interior finishes for existing facility.



9. Renovate and expand administration office.




#### 10. Improve athletic entry restroom access.



11. Renovate existing student restrooms.






12. Renovate south student restrooms.




- 2 13
- 3 4



13. Maintenance building exterior (i.e., brick, downspouts, fascia, etc.)




14. Improve playground.





15. If you think there's a need for playground equipment improvement, describe the need.



16. Add teacher staff restrooms.



### Written responses from the 26 participants based on the following question:

How many additional grades 2-5 classrooms do you think are needed?

- Unsure
- 6-8
- How many are needed
- 5 class rooms
- 2-4 per grade (8-20 rooms)
- 4-6
- 4-6
- Not sure
- No clue
- 2 per grade
- 2-3 per grade level and extra spaces for special education classes, OT, Speech, sensory room, areas for counseling and for conferences and spaces for testing individuals or small groups.
- 6-8
- 4
- 4
- 6-8
- 10
- 4 to 5 additional rooms
- I think we need to first evaluate how many students we have coming in and what the averages are per year.
- At least 2
- 8-10
- 4
- 6
- Would need enrollment numbers for this or testimonials from people in the building. My guess would be 1 per grade??
- 6-8
- 0

• Unknown

If you think there's a need for playground equipment improvement, describe the need.

- None
- move and expand
- Add playground equipment
- Not at this time.
- N/A
- More swings, slides, etc.
- Uncertain
- Not sure
- more equipment
- There needs to be more playground equipment and spaces for kids to play. At times there are 100+ kids outside at a time trying to use one play structure.
- Need additional ADA compliant equipment
- Our school is outgrowing the small amount of equipment we have. We need more equipment for the large amount of students we have.
- I'm not sure improvement is needed since it's been improved within the last several years.
- Safety is a concern with the height of the playground and openings at the top. Several students have broken an arm over the years from falling. My own son fell of the top of the playground between the two slides last year as a second grader.
- just more equipment for the number of kids we have
- Possibly add a smaller sports field/specifically for recess.
- Not necessary, but it would be nice for the kids to have more equipment.
- I don't think it is needed
- Improved, updated, and ADA accessible
- NA
- Add more equipment and an outdoor classroom
- Would need testimonials from people in the building. I would expect normal replacement of degradable surfaces.
- Additional adaptive playground equipment
- None

- None
- Not sure.
- Traffic flow
- Expand the west parking lot to the north (eliminate "H" Street congestion). Improve west lot entrances. Car traffic only west lot. Bus traffic only East lot.
- A staff workroom on the north side of the building would be great. Addition to the west parking lot to help with traffic flow, get more cars off of the street during the afternoon pick up.
- Flooring upgrades in classrooms.
- Not sure
- I'm not sure, but between the 4 buildings, I think westview and northview are the nicest buildings
- New tile floors in halls
- We need spaces for Special education classrooms that are closer to the classrooms they are servicing to eliminate transition time. Current rooms that are sharing a space need their own space with an area large enough to hold all the students, paras, the teacher, and calming/regulation area. Spaces are needed for sensory regulation, OT, speech services, mental health and counseling space, and spaces to do testing and hold conferences with parents. There also would be benefit of having a space for some of the after school clubs/teams that is more of a universal space (robotics, yoga, dance space, lego robotics, etc)
- Update the exterior to a more modern look
- I believe this survey covers our needs.
- I'm not sure
- I have also always thought it would make the most sense to add the additional classrooms at NV to connect the ends of the 2/3 hall with the 4/5 hall. Additional restrooms for staff and students could be added in the middle of the hallway. The playground could also be moved to the center of the square, or an outdoor classroom space could be added there. If the building had that secure center space, teachers could spend more time with their students outdoors without most current safety concerns.
- more parking and desperately improve traffic pick up flow
- You have included multiple suggestions that could be included in the project. Thank you!
- N/A.
- none
- N/A
- NA
- Add additional space for robotics.
- Additional parking in east lot. Pave area east of building and grassy area toward road.

- The addition of at least one large sensory room for all students to utilize (OT and PT could also use this space to provide services), in addition to sensory rooms attached to the self contained special education classrooms.
- Again, many of these items should have been routine maintenance items.