

District Name: Nixa Public S	chools				Project Number: B52	37030 - Rour	nd 3		State Action L	evel: 5 ppb.		dinary found during sampling. Examples of Notes:
ampus Name: High Pointe	Elementary						Retest Sampl	e Collection	•			vater color, low water flow, irregular water spray, does
	•				Faucet Retesting: Sa	amples for fa	ucets water	fountains and	etc with previou	usly reported	water become warm/hot, water filter attached	
Faucet Inventory (outle	t types): Classroom Fau	cet-CF Hall F	ountain-HF, Drinking Fountain-I	DE Kitchen	exceedances at or ab	•		iountains, and	a etc. with previo	usiy reported	*Flushing and "Do not drink from faucet" signs	bove 5 ppb should be re-sampled with a Flush sample.
			-LF, Water Fountain Chilled-WF,		D - This is a First Dray			he first 250 m	illiliters of water t	to come out		placement of lead components are permanent solution
			Maker (Java)-JF, Other Fountair		of the faucet. This sa	•				to come out		pracement of read components are permanent solution be removed from service and/or replaced immediately.
,	(describe), B			,	F - This is a Flush San					aucet for 30	*All values above 5.0 ppb must be remediated a	
	(,,				seconds. This sample						*Elementary schools, Kindergarten, Pre-K and d	-
Building Name	Floor/Room #/Name	Outlet Type	Outlet Name/Sink/Location	Aerator Screen (Y/N)	Sample #	Type (D,F)	Time	Date	Sampler Name	Results ppb	Notes	Recommendations
	Library	DF	office sink with fountain	N	HPE-L-DF-01	D	12:45PM	12/28/2023	Mandy Carlson	3.3		Meets State of Missouri requirement
	204	DF	sink with fountain	N	HPE-204-DF-02	D	12:49PM	12/28/2023	Mandy Carlson	<1.00	high water pressure	Meets State of Missouri requirement
	206	DF	sink with fountain	N	HPE-206-DF-03	D	12:52PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	208	DF	sink with fountain	N	HPE-208-DF-04	D	12:54PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	210	DF	sink with fountain	N	HPE-210-DF-05	D	12:55PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
		BR	bottle filler	Y	HPE-200H-BR-06	D	1:03PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	200 Hallway near 210	HF	fountain on left	N	HPE-200H-LHF-07	D	1:03PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
		HF	fountain on right	N	HPE-200H-RHF-08	D	1:03PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	212	DF	sink with fountain	N	HPE-212-DF-09	D	1:05PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	214	DF	sink with fountain	N	HPE-214-DF-10	D	1:06PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	216	DF	sink with fountain	N	HPE-216-DF-11	D	1:08PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	221	DF	sink with fountain	N	HPE-221-DF-12	D	1:10PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	219	DF	sink with fountain	N	HPE-219-DF-13	D	1:12PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	217	DF	sink with fountain	N	HPE-217-DF-14	D	1:13PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	215	DF	sink with fountain	N	HPE-215-DF-15	D	1:15PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	Office	DF	sink with fountain	N	HPE-O-DF-16	D	1:18PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	Nurse Office	DF	sink with fountain	N	HPE-NO-DF-17	D	1:19PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	301	DF	sink with fountain	N	HPE-301-DF-18	D	1:25PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	303	DF	sink with fountain	N	HPE-303-DF-19	D	1:26PM	12/28/2023	Mandy Carlson	3.6		Meets State of Missouri requirement
	305	DF	sink with fountain	N	HPE-305-DF-20	D	1:27PM	12/28/2023	Mandy Carlson	1.3		Meets State of Missouri requirement
	307	DF	sink with fountain	N	HPE-307-DF-21	D	1:28PM	12/28/2023	Mandy Carlson	1.6		Meets State of Missouri requirement
	309	DF	sink with fountain	N	HPE-309-DF-22	D	1:30PM	12/28/2023	Mandy Carlson	3.8		Meets State of Missouri requirement
		BR	bottle filler	Y	HPE-GH-BR-23	D	1:34PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	Hallway to Gym	HF	fountain on right	N	HPE-GH-HF-24	D	1:34PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
		HF	fountain on left	N	HPE-GH-HF-25	D	1:34PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	310	DF	sink with fountain	N	HPE-310-DF-26	D	1:36PM	12/28/2023	Mandy Carlson	1.2		Meets State of Missouri requirement
	312	DF	sink with fountain	N	HPE-312-DF-27	D	1:38PM	12/28/2023	Mandy Carlson	1.2	high water pressure	Meets State of Missouri requirement
High Pointe Elementary				N	HPE-316-DF-28	D	1:40PM	12/28/2023	Mandy Carlson	8.5	Initial Test	Take out of service, and replace or add filter, perform
												flush (2nd draw) sampling.
												Take out of service OR install NSF/ANSI Standards 4
	316	DF	sink with fountain	N	HPE-316-DF-10	D	8:26AM	10/19/2024	Mandy Carlson	7.71	Retest - faucet replaced	52 approved filter. Perform 1st draw retest after remediation.
	510	DI	Sink with rountain									Take out of service permenately OR install NSF/ANS
												Standards 43 & 52 approved filter. Perform 1st draw
				N	HPE-316-DF-01	D	9:31AM	12/27/2024	Mandy Carlson	7.57	Retest - faucet lines replaced	retest after remediation. Source appears to be from
												beyond the immediate piping to the faucet but is no
												from main school distribution line.
	318	DF	sink with fountain	N	HPE-318-DF-29	D	1:52PM	12/28/2023	Mandy Carlson	1.3		Meets State of Missouri requirement
	320	DF	sink with fountain	N	HPE-320-DF-30	D	1:53PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	326	DF	sink with fountain	N	HPE-326-DF-31	D	1:56PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	323	DF	sink with fountain	N	HPE-323-DF-32	D	1:57PM	12/28/2023	Mandy Carlson	3.7		Meets State of Missouri requirement
	321	DF	sink with fountain	N	HPE-321-DF-33	D	1:59PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	319	DF	sink with fountain	N	HPE-319-DF-34	D	2:01PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	400 Hallway	HF	shorter fountain on right	N	HPE-400H-HF-35	D	2:04PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
		HF	taller fountain on left	N	HPE-400H-HF-36	D	2:04PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	406	DF	sink with fountain	N	HPE-406-DF-37	D	2:06PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	408	DF	sink with fountain	N	HPE-408-DF-38	D	2:08PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	410	DF	sink with fountain	N	HPE-410-DF-39	D	2:09PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	412	DF	sink with fountain	N	HPE-412-DF-40	D	2:11PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	414	DF	sink with fountain	N	HPE-414-DF-41	D	2:12PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	411	DF	sink with fountain	N	HPE-411-DF-42	D	2:13PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	409	DF	sink with fountain	N	HPE-409-DF-43	D	2:14PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	407	DF	sink with fountain	N	HPE-407-DF-44	D	2:19PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	405	DF	sink with fountain	N	HPE-405-DF-45	D	2:20PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	403	DF	sink with fountain	N	HPE-403-DF-46	D	2:22PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement



	Kitchen	KF	handwashing sink near restroom	Y	HPE-K-HKF-47	D	2:26PM	12/28/2023	Mandy Carlson	<1.00	Meets State of Missouri requirement
		KF	double sink faucet	N	HPE-K-KF-48	D	2:29PM	12/28/2023	Mandy Carlson	3.7	Meets State of Missouri requirement
High Pointe Elementary		KF	triple sink, left faucet	N	HPE-K-LKF-49	D	2:31PM	12/28/2023	Mandy Carlson	2.8	Meets State of Missouri requirement
Fight Pointe Elementary	Kitchen	KF	triple sink, right faucet	Y	HPE-K-RKF-50	D	2:31PM	12/28/2023	Mandy Carlson	3.3	Meets State of Missouri requirement
	Kitchen	KF	handwashing sink near dish room	Y	HPE-K-HKF-51	D	2:34PM	12/28/2023	Mandy Carlson	1	Meets State of Missouri requirement
		KF	sprayer	N	HPE-K-SKF-52	D	2:34PM	12/28/2023	Mandy Carlson	1.4	Meets State of Missouri requirement

## Red Bold = at or above state action level

ppb = parts per billion

< = below laboratory reporting limit Initial Sample Below 5 ppb Initial Sample Above 5 ppb

Retest Sample Collection Event



District Name: Nixa Publ	lic Schools				Project Number: B	5237030 - Rc	ound 3		State Action Leve	el: 5 ppb	Notes - *Notes are about anything out of the ordi	
Campus Name: Century	Elementary						Retest Sam	ple Collection				ter color, low water flow, irregular water spray, does
ampus Nume. century	Elementary										water become warm/hot, water filter attached to	faucet, leaky faucet ove 5 ppb should be re-sampled with a Flush sample.
aurat Invantany (autla	t tumos); Classroom Fausat	CE Hall Founts	ain-HF, Drinking Fountain-DF, Kitcl	han Fausat KE	Faucet Retesting:			er fountains, an	d etc. with previo	usly reported	*Flushing and "Do not drink from faucet" signs an	
			Fountain Chilled-WF, Nurse Room		exceedances at or a		•	the first 250 m	illilitors of water	o como out	5	acement of lead components are permanent solution
			F, Other Fountain/Faucet-OF (des		<u>D</u> - This is a First Dr of the faucet. This					to come out		removed from service and/or replaced immediately.
		efill Faucet-BR		chiec, bothe	F - This is a Flush Sa					aucet for 30	*All values above 5.0 ppb must be remediated as	soon as possible.
					seconds. This same				-		*Elementary schools, Kindergarten, Pre-K and day	
De Heller e Marrie				Aerator			r ·	Ľ,				<b>a</b> 1.1
Building Name	Floor/Room #/Name	Outlet Type	Outlet Name/Sink/Location	Screen (Y/N)	Sample #	Type (D,F)	Time	Date	Sampler Name	Results ppb	Notes	Recommendations
	Teacher's Work Room 107	DF	sink with fountain	Ν	CES-107-DF-01	D	7:58AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	112	DF	sink with fountain	N	CES-112-DF-02	D	8:05AM	12/28/2023	Mandy Carlson	<1.00	calcium build-up	Meets State of Missouri requirements
	113	DF	sink with fountain	N	CES-113-DF-03	D	8:08AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	100 Hallway	HF	shorter fountain on right	N	CES-100H-RHF-04	D	8:11AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	-	HF	taller fountain on left	N	CES-100H-LHF-05	D	8:11AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	114	DF	sink with fountain	N	CES-114-DF-06	D	8:14AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	116	DF	sink with fountain	N	CES-116-DF-07	D	8:17AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	117	DF	sink with fountain	N	CES-117-DF-08	D	8:20AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	115	DF	sink with fountain	N	CES-115-DF-09	D	8:21AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	218 219	DF DF	sink with fountain	N	CES-218-DF-10 CES-219-DF-11	D	8:25AM 8:37AM	12/28/2023 12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
		DF	sink with fountain	N		D		12/28/2023	Mandy Carlson			Meets State of Missouri requirements
	220	DF	sink with fountain	N	CES-220-DF-12		8:31AM		Mandy Carlson	1.2		Meets State of Missouri requirements
	221 222	DF	sink with fountain	N	CES-221-DF-13	D	8:33AM 8:35AM	12/28/2023	Mandy Carlson			Meets State of Missouri requirements
			sink with fountain	N	CES-222-DF-14	D		12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	223 224	DF DF	sink with fountain	N	CES-223-DF-15 CES-224-DF-16	D	8:37AM 8:37AM	12/28/2023 12/28/2023	Mandy Carlson	<1.00 <1.00		Meets State of Missouri requirements
	224	DF HF	sink with fountain	N	CES-224-DF-16 CES-H-LHF-17	D	8:37AM 8:43AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	Hallway near 222	HF	taller fountain on left	N	CES-H-RHF-17 CES-H-RHF-18	D	8:43AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	402	DF	shorter fountain on right sink with fountain	N	CES-H-RHF-18 CES-402-DF-19	D	8:43AM 8:47AM	12/28/2023	Mandy Carlson Mandy Carlson	<1.00		Meets State of Missouri requirements Meets State of Missouri requirements
				N			8:47AM 8:49AM					-
	403 404	DF DF	sink with fountain sink with fountain	N	CES-403-DF-20 CES-404-DF-21	D	8:49AM 8:52AM	12/28/2023 12/28/2023	Mandy Carlson Mandy Carlson	<1.00 <1.00		Meets State of Missouri requirements Meets State of Missouri requirements
	404 406	DF	sink with fountain	N	CES-404-DF-21 CES-406-DF-22	D	8:52AM 8:53AM	12/28/2023	Mandy Carlson	<1.00		-
	406	DF	sink with fountain	N	CES-406-DF-22 CES-405-DF-23	D	8:53AIVI 8:57AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements Meets State of Missouri requirements
	403	DF	sink with fountain	N	CES-403-DF-23	D	8:58AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	407	DF	sink with fountain	N	CES-407-DF-25	D	9:02AM	12/28/2023	Mandy Carlson	<1.00	low water pressure	Meets State of Missouri requirements
	410	DF	sink with fountain	N	CES-410-DF-26	D	9:09AM	12/28/2023	Mandy Carlson	<1.00	low water pressure	Meets State of Missouri requirements
Century Elementary	410	DF	sink with fountain	N	CES-409-DF-27	D	9:11AM	12/28/2023	Mandy Carlson	<1.00	low water pressure	Meets State of Missouri requirements
,	405	DF	sink with fountain	N	CES-411-DF-28	D	9:13AM	12/28/2023	Mandy Carlson	1.5	low water pressure	Meets State of Missouri requirements
		HF	taller fountain on left	N	CES-500H-LHF-29	D	9:16AM	12/28/2023	Mandy Carlson	<1.00	low water pressure	Meets State of Missouri requirements
	500 Hallway near 501	HF	shorter fountain on right	N	CES-500H-RHF-30	D	9:16AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	501	DF	sink with fountain	N	CES-501-DF-31	D	9:19AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	502	DF	sink with fountain	N	CES-502-DF-32	D	9:20AM	12/28/2023	Mandy Carlson	1.1		Meets State of Missouri requirements
	503	DF	sink with fountain	N	CES-503-DF-33	D	9:22AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	504	DF	sink with fountain	N	CES-504-DF-34	D	9:24AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	505	DF	sink with fountain	N	CES-505-DF-35	D	9:26AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	507	DF	sink with fountain	N	CES-507-DF-36	D	9:28AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
		BR	bottle filler	Y	CES-GH-BR-37	D	9:33AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	500 Hallway next to Gym	HF	fountain on right	N	CES-GH-RHF-38	D	9:33AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	509	HF	fountain on left	N	CES-GH-LHF-39	D	9:33AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	311	DF	sink with fountain	N	CES-311-DF-40	D	9:35AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	309	DF	sink with fountain	N	CES-309-DF-41	D	9:37AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	310	DF	sink with fountain	N	CES-310-DF-42	D	9:39AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	308	DF	sink with fountain	N	CES-308-DF-43	D	9:41AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	300 Hallway next to 309	HF	shorter fountain on right	N	CES-300H-RHF-44	D	9:44AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	500 mailway next to 309	HF	taller fountain on left	N	CES-300H-LHF-45	D	9:44AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	306	DF	sink with fountain	N	CES-306-DF-46	D	9:47AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	304	DF	sink with fountain	N	CES-304-DF-47	D	9:48AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	307	DF	sink with fountain	N	CES-307-DF-48	D	9:51AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	305	DF	sink with fountain	N	CES-305-DF-49	D	9:51AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	302	DF	sink with fountain	N	CES-302-DF-50	D	9:53AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	303	DF	sink with fountain	N	CES-303-DF-51	D	9:58AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
		HF	shorter fountain on right	N	CES-300H-RHF-52	D	10:01AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	300 Hallway near 209 Gym	HF	taller fountain on left	N	CES-300H-LHF-53	D	10:01AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
		BR	bottle filler	Y	CES-300H-BR-54	D	10:01AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements



		KF	double sink faucet	Y	CES-K-KF-55	D	10:06AM	12/28/2023	Mandy Carlson	1.3		Meets State of Missouri requirements
	Kitchen	KF	handwashing sink near serving area	Y	CES-K-HKF-56	D	10:08AM	12/28/2023	Mandy Carlson	2.7		Meets State of Missouri requirements
				N	CES-K-HKF-57	D	10:09AM	12/28/2023	Mandy Carlson	8.6	Initial Sample	Post a "Not for Drinking or Cooking" Sign or Flush each morning as temporary measure. Take out of service and/or replace or add filter as soon as possible. Perform flush (2nd draw) sampling.
		KF	handwashing sink near dish room	Y	CE-K-KF-OF-20	D	9:23AM	10/19/2024	Mandy Carlson	5.62	Retest - replaced faucet	Post a "Not for Drinking or Cooking" sign. Take out of service and add to non-potable inventory OR install NSF/ANSI Standards 43 & 52 approved filter. Perform 1st draw retest after remediation.
Century Elementary				Y	CE-K-OF-03	D	9:45AM	12/27/2024	Mandy Carlson	4	Retest sample - faucet lines replaced	Meets State of Missouri requirements. No further action required.
century Elementary	Kitchen	KF	sprayer	N	CES-K-SKF-58	D	10:10AM	12/28/2023	Mandy Carlson	1.9		Meets State of Missouri requirements
		KF	triple sink right faucet	Y	CES-K-RKF-59	D	10:12AM	12/28/2023	Mandy Carlson	5.7	Initial Sample	Post a "Not for Drinking or Cooking" Sign or Flush each morning as temporary measure. Take out of service and/or replace or add filter as soon as possible. Perform flush (2nd draw) sampling.
				Y	CE-K-KF-18	D	9:20AM	10/19/2024	Mandy Carlson	2.49	Retest - replaced faucet	Meets State of Missouri requirements
		KF	triple sink left faucet	Y	CES-K-LKF-60	D	10:12AM	12/28/2023	Mandy Carlson	6.1	Initial Sample	Post a "Not for Drinking or Cooking" Sign or Flush each morning as temporary measure. Take out of service and/or replace or add filter as soon as possible. Perform flush (2nd draw) sampling.
				Y	CE-K-KF-19	D	9:21AM	10/19/2024	Mandy Carlson	1.38	Retest - replaced faucet	Meets State of Missouri requirements
	209 Gym	WF	shorter fountain on right	N	CES-G-WF-61	D	10:22AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	209 Gym	WF	taller fountain on left	N	CES-G-WF-62	D	10:22AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements

Reu bolu – at of above state

ppb = parts per billion

< = below laboratory reporting limit

Initial Sample Below 5 ppb

Initial Sample Above 5 ppb

Retest Sample Collection Event



istrict Name: Nixa Public	Schools				Project Number: B52	37030 - Rour	nd 3		State Action L	evel: 5 ppb	Notes - *Notes are about anything out of the ord	inary found during sampling. Examples of Notes: iter color, low water flow, irregular water spray, does
ampus Name: ESPY Elem	ientary						Retest Sampl	e Collection			water become warm/hot, water filter attached to	
Bath Faucet-BF, Ice Ma	aker-IM, Locker Room Fauce F, Shop Faucet-SF, Coffee M	et-LF, Water Fo	n-HF, Drinking Fountain-DF, Kitc untain Chilled-WF, Nurse Room Other Fountain/Faucet-OF (des	Faucet-NF,	Faucet Retesting: Sa exceedances at or ab <u>D</u> - This is a First Drav of the faucet. This sa <u>F</u> - This is a Flush San seconds. This sample	ove 5 parts p w Sample col mple tests th nple collecte	per billion llected from t ne water in th d in a 250 mil	he first 250 m le faucet for le liliter bottle at	lliliters of water t ad. ter flushing the fa	to come out aucet for 30	Recommendations - *All samples with a value ab *Flushing and "Do not drink from faucet" signs ar *Taking a faucet out of service, filters and/or rep	ove 5 ppb should be re-sampled with a Flush sample. e only temporary solutions. lacement of lead components are permanent solutior removed from service and/or replaced immediately. soon as possible.
Building Name	Floor/Room #/Name	Outlet Type	Outlet Name/Sink/Location	Aerator Screen (Y/N)	Sample #	Type (D,F)	Time	Date	Sampler Name	Results ppb	Notes	Recommendations
	Workroom	TF	sink faucet	Y	ESPY-WR-TF-01	D	11:41AM	12/27/2023	Mandy Carlson	3.4		Meets State of Missouri requirements
	103	CF	classroom faucet	Y	ESPY-103-CF-02	D	11:45AM	12/27/2023	Mandy Carlson	20.9	Initial sample	Take out of service and replace or add filter, perform flush (2nd draw) sampling
				Y	ESPY-103-CF-33	D	10:08AM	10/19/2024	Mandy Carlson	1.74	Retest - faucet replaced	Meets State of Missouri requirements
	101	CF	classroom faucet	N	ESPY-101-CF-03	D	11:46AM	12/27/2023	Mandy Carlson	3.9		Meets State of Missouri requirements
	200 Hallway across from	HF	fountain on right	N	ESPY-200H-RHF-04	D	11:50AM	12/27/2023	Mandy Carlson	NA	lid opened during transit, and volume was lost	Resample
	room 200	HF	fountain on left	N	ESPY-200H-LHF-05	D	11:50AM	12/27/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	200	CF	classroom faucet	N	ESPY-200-CF-06	D	11:51AM	12/27/2023	Mandy Carlson	1.6		Meets State of Missouri requirements
	201 202	CF CF	classroom faucet classroom faucet	N N	ESPY-201-CF-07 ESPY-202-CF-08	D	11:58AM 12:01PM	12/27/2023 12/27/2023	Mandy Carlson Mandy Carlson	2.5		Meets State of Missouri requirements Meets State of Missouri requirements
	202	CF	classroom faucet	N	ESPY-202-CF-08	D	12:01PM 12:02PM	12/27/2023	Mandy Carlson	2.4		Meets State of Missouri requirements
	204	CF	classroom faucet	N	ESPY-203-CF-10	D	12:02PM	12/27/2023	Mandy Carlson	1.7		Meets State of Missouri requirements
	205	CF	classroom faucet	N	ESPY-205-CF-11	D	12:07PM	12/27/2023	Mandy Carlson	2.3		Meets State of Missouri requirements
	205	CF	classroom faucet	Y	ESPY-206-CF-12	D	12:09PM	12/27/2023	Mandy Carlson	2.2		Meets State of Missouri requirements
				N	ESPY-207-CF-13	D	12:10PM	12/27/2023	Mandy Carlson	8.5	Initial sample	Post a "Not for Drinking" Sign or Flush each mornir temporary measure. Take out of service and/or re add filter as soon as possible. Perform flush (2nd o sampling.
	207	CF	classroom faucet	Y	ESPY-207-CF-34	D	10:10AM	10/19/2024	Mandy Carlson	11.2	Retest - faucet replaced	Post a "Not for Drinking" sign. Take out of service to non-potable inventory OR install NSF/ANSI Sta 43 & 52 approved filter. Perform 1st draw retes remediation.
ESPY Elementary				Y	ESPY-207-CF-15	D	10:20AM	12/27/2024	Mandy Carlson	10.5	Retest sample - faucet lines replaced	Post a "Not for Drinking" sign. Take out of service add to non-potable inventory OR install NSF/ANS Standards 43 & 52 approved filter. Perform 1st dr retest after remediation. The lead source appears from beyond the immediate piping and associate faucet but not from the schools primary service il
				Y	ESPY-208-CF-14	D	12:12PM	12/27/2023	Mandy Carlson	7.2	Initial sample	Post a "Not for Drinking" Sign or Flush each mornin temporary measure. Take out of service and/or re add filter as soon as possible. Perform flush (2nd o sampling.
	208	CF	classroom faucet	Y	ESPY-208-CF-35	D	10:12AM	10/19/2024	Mandy Carlson	7.49	Retest - faucet replaced	Post a "Not for Drinking" sign. Take out of service a to non-potable inventory OR install NSF/ANSI Stat 43 & 52 approved filter. Perform 1st draw retest remediation.
				Y	ESPY-208-CF-16	D	10:20AM	12/27/2024	Mandy Carlson	6.32	Retest sample - faucet lines replaced	Post a "Not for Drinking" sign. Take out of service add to non-potable inventory OR install NSF/ANS Standards 43 & 52 approved filter. Perform 1st dr retest after remediation. The lead source appears from beyond the immediate piping and associate faucet but not from the schools primary service li
	102	CF	classroom faucet	Y	ESPY-102-CF-15	D	12:15PM	12/27/2023	Mandy Carlson	4		Meets State of Missouri requirements
	102	DF	drinking fountain	N	ESPY-102-DF-16	D	12:15PM	12/27/2023	Mandy Carlson	3.3		Meets State of Missouri requirements
		KF	double sink, faucet on right	Y	ESPY-K-RKF-17 ESPY-K-LKF-18	D	12:19PM 12:19PM	12/27/2023 12/27/2023	Mandy Carlson Mandy Carlson	3.3 5.3	Initial sample	Meets State of Missouri requirements Post a "Not for Drinking or Cooking" Sign or Flush e morning as temporary measure. Take out of service and/or replace or add filter as soon as possible. Pe
	Kitchen	KF	double sink, faucet on left	Y	ESPY-K-KF-28	D	9:59AM	10/19/2024	Mandy Carlson	5.04	Retest - faucet replaced	flush (2nd draw) sampling. Post a "Not for Drinking or Cooking" sign. Install NS Standards 43 & 52 approved filter. Perform 1st retest after remediation.
				Y	ESPY-K-KF-10	D	10:12AM	12/27/2024	Mandy Carlson	3.7	Retest sample - faucet lines replaced	Meets State of Missouri requirements. No further required.



Standards 43 & 52 approved filter. Perform 1st draw

retest after remediation. The lead source appears to be from beyond the immediate piping and associated faucet but not from the schools primary service line.

Meets State of Missouri requirements

Meets State of Missouri requirements

		KF	sprayer	N	ESPY-K-SKF-19	D	12:21PM	12/27/2023	Mandy Carlson	6.4	Initial sample	Post a "Not for Drinking or Cooking" Sign or Flush each morning as temporary measure. Take out of service and/or replace or add filter as soon as possible. Perform flush (2nd draw) sampling.
		KF	sprayer								Added to Non-Potable Inventory	No further action required
				Y	ESPY-K-RKF-20	D	12:26PM	12/27/2023	Mandy Carlson	23.2	Initial sample	Take out of service and replace or add filter, perform flush (2nd draw) sampling
				Y	ESPY-K-KF-29	D	10:01AM	10/19/2024	Mandy Carlson	25.1	Retest - faucet replaced	Take out of service, immediately. Post a "Not for Drinking or Cooking" sign. Install NSF/ANSI Standards 43 & 52 approved filter. Perform 1st draw retest after remediation.
	Kitchen	KF	triple sink, faucet on right	Y	ESPY-K-KF-12	D	10:13AM	12/27/2024	Mandy Carlson	8.79	Retest sample - faucet lines replaced	Post a "Not for Drinking or Cooking" sign. Take out of service and add to non-potable inventory OR install NSF/ANSI Standards 43 & 52 approved filter. Perform 1st draw retest after remediation. The lead source appears to be from beyond the immediate piping and associated faucet but not from the schools primary service line.
		KF	triple sink, faucet on left	N	ESPY-K-LKF-21	D	12:26PM	12/27/2023	Mandy Carlson	16.3	Initial sample	Take out of service and replace or add filter, perform flush (2nd draw) sampling
		KF	triple sink, faucet on left	Y	ESPY-K-KF-30	D	10:02AM	10/19/2024	Mandy Carlson	6.32	Retest - faucet replaced	Post a "Not for Drinking or Cooking" sign. Install NSF/ANSI Standards 43 & 52 approved filter. Perform 1st draw retest after remediation.
		KF	triple sink, facuet on left	Y	ESPY-K-KF-11	D	10:13AM	12/27/2024	Mandy Carlson	8.61	Retest sample - faucet lines replaced	Post a "Not for Drinking or Cooking" sign. Take out of service and add to non-potable inventory OR install NSF/ANSI Standards 43 & 52 approved filter. Perform 1st draw retest after remediation. The lead source appears to be from beyond the immediate piping and associated faucet but not from the schools primary service line.
		KF	handwashing sink	Y	ESPY-K-HKF-22	D	12:28PM	12/27/2023	Mandy Carlson	2.2		Meets State of Missouri requirements
ESPY Elementary				N	ESPY-113-CF-23	D	12:30PM	12/27/2023	Mandy Carlson	9.8	Initial sample	Post a "Not for Drinking" Sign or Flush each morning as temporary measure. Take out of service and/or replace or add filter as soon as possible. Perform flush (2nd draw) sampling.
	113	CF	classroom faucet	Y	ESPY-113-CF-31	D	10:03AM	10/19/2024	Mandy Carlson	6.13	Retest - faucet replaced	Post a "Not for Drinking" sign. Take out of service and add to non-potable inventory OR install NSF/ANSI Standards 43 & 52 approved filter. Perform 1st draw retest after remediation.
				Y	ESPY-113-CF-13	D	10:05AM	12/27/2024	Mandy Carlson	22.1	Retest sample - faucet lines replaced	Post a "Not for Drinking" sign. Take out of service and add to non-potable inventory OR install NSF/ANSI Standards 43 & 52 approved filter. Perform 1st draw retest after remediation. The lead source appears to be from beyond the immediate piping and associated faucet but not from the schools primary service line.
	Main Hallway outside of	BR	bottle filler	Y	ESPY-MH-BR-24	D	12:33PM	12/27/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	Multi-Purpose Room	HF	taller fountain on left	N	ESPY-MH-LHF-25	D	12:35PM	12/27/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
		HF	shorter fountain on right	N	ESPY-MH-RHF-26	D	12:35PM	12/27/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	115	CF	classroom faucet	N	ESPY-115-CF-27	D	12:36PM	12/27/2023	Mandy Carlson	1.3	laboratory mislabled as EPSY-HS-CF-27	Meets State of Missouri requirements
				N	ESPY-117-CF-28	D	12:37PM	12/27/2023	Mandy Carlson	9.2	Initial sample	Post a "Not for Drinking" Sign or Flush each morning as temporary measure. Take out of service and/or replace or add filter as soon as possible. Perform flush (2nd draw) sampling.
	117	CF	classroom faucet	Y	ESPY-117-CF-32	D	10:05AM	10/19/2024	Mandy Carlson	12.1	Retest - faucet replaced	Post a "Not for Drinking" sign. Take out of service and add to non-potable inventory OR install NSF/ANSI Standards 43 & 52 approved filter. Perform 1st draw retest after remediation.
												Post a "Not for Drinking" sign. Take out of service and add to non-potable inventory OR install NSF/ANSI

ESPY-117-CF-14

ESPY-SL-CF-29

ESPY-SL-DF-30

Υ

Ν

CF

DF

Secondary Lab

classroom faucet

drinking fountain

D

D

D

10:16AM

12:40PM

12/27/2024

12/27/2023

12:40PM 12/27/2023 Mandy Carlson

Mandy Carlson

Mandy Carlson

10.4

2.5

1

Retest sample - faucet lines replaced



January 9, 2025 Terracon Project No. B5237030

	Main Hallway across from	BR	bottle filler	Y	ESPY-MH-BR-31	D	12:45PM	12/27/2023	Mandy Carlson	<1.00	Meets State of Missouri requirements
	Secondary Lab	HF	fountain on left	N	ESPY-MH-LHF-32	D	12:46PM	12/27/2023	Mandy Carlson	<1.00	Meets State of Missouri requirements
	Secondary Lab	HF	fountain on right	N	ESPY-MH-RHF-33	D	12:46PM	12/27/2023	Mandy Carlson	<1.00	Meets State of Missouri requirements
	121	CF	classroom faucet	Y	ESPY-121-CF-34	D	12:50PM	12/27/2023	Mandy Carlson	4	Meets State of Missouri requirements
	121	DF	drinking fountain	N	ESPY-121-DF-35	D	12:50PM	12/27/2023	Mandy Carlson	1.7	Meets State of Missouri requirements
	123	CF	classroom faucet	Y	ESPY-123-CF-36	D	12:55PM	12/27/2023	Mandy Carlson	1.5	Meets State of Missouri requirements
	125	DF	drinking fountain	N	ESPY-123-DF-37	D	12:55PM	12/27/2023	Mandy Carlson	<1.00	Meets State of Missouri requirements
	124	CF	classroom faucet	N	ESPY-124-CF-38	D	12:57PM	12/27/2023	Mandy Carlson	<1.00	Meets State of Missouri requirements
		BR	bottle filler	Y	ESPY-FEMA-BR-39	D	1:00PM	12/27/2023	Mandy Carlson	<1.00	Meets State of Missouri requirements
	FEMA GYM	WF	fountain on the right	N	ESPY-FEMA-RWF-40	D	1:00PM	12/27/2023	Mandy Carlson	<1.00	Meets State of Missouri requirements
		WF	fountain on the left	N	ESPY-FEMA-LWF-41	D	1:00PM	12/27/2023	Mandy Carlson	<1.00	Meets State of Missouri requirements
	300 Hallway next boy's	BR	bottle filler	Y	ESPY-300H-BR-42	D	1:05PM	12/27/2023	Mandy Carlson	<1.00	Meets State of Missouri requirements
ESPY Elementary	restroom	HF	fountain	N	ESPY-300H-HF-43	D	1:05PM	12/27/2023	Mandy Carlson	<1.00	Meets State of Missouri requirements
ESPT Elementary	300 Hallway next girl's restroom	HF	single fountain	N	ESPY-300H-HF-44	D	1:13PM	12/27/2023	Mandy Carlson	<1.00	Meets State of Missouri requirements
	301	CF	classroom faucet	N	ESPY-301-CF-45	D	1:16PM	12/27/2023	Mandy Carlson	1.2	Meets State of Missouri requirements
	302	CF	classroom faucet	N	ESPY-302-CF-46	D	1:17PM	12/27/2023	Mandy Carlson	2.9	Meets State of Missouri requirements
	304	CF	classroom faucet	N	ESPY-304-CF-47	D	1:18PM	12/27/2023	Mandy Carlson	2.2	Meets State of Missouri requirements
	303	CF	classroom faucet	Y	ESPY-303-CF-48	D	1:20PM	12/27/2023	Mandy Carlson	1.2	Meets State of Missouri requirements
	305	CF	classroom faucet	Y	ESPY-305-CF-49	D	1:21PM	12/27/2023	Mandy Carlson	2.1	Meets State of Missouri requirements
	306	CF	classroom faucet	N	ESPY-306-CF-50	D	1:23PM	12/27/2023	Mandy Carlson	1.8	Meets State of Missouri requirements
	308	CF	classroom faucet	N	ESPY-308-CF-51	D	1:24PM	12/27/2023	Mandy Carlson	1.5	Meets State of Missouri requirements
	307	CF	classroom faucet	N	ESPY-307-CF-52	D	1:26PM	12/27/2023	Mandy Carlson	1.1	Meets State of Missouri requirements
	309	CF	classroom faucet	Y	ESPY-309-CF-53	D	1:27PM	12/27/2023	Mandy Carlson	2.1	Meets State of Missouri requirements
	310	CF	classroom faucet	N	ESPY-310-CF-54	D	1:30PM	12/27/2023	Mandy Carlson	2.4	Meets State of Missouri requirements
	311	CF	classroom faucet	Y	ESPY-311-CF-55	D	1:31PM	12/27/2023	Mandy Carlson	4	Meets State of Missouri requirements
	312	CF	classroom faucet	N	ESPY-312-CF-56	D	1:32PM	12/27/2023	Mandy Carlson	4.9	Meets State of Missouri requirements

ppb = parts per billion

< = below laboratory reporting limit</p>

Initial Sample Below 5 ppb

Initial Sample Above 5 ppb

Retest Sample Collection Event



District Name: Nixa Pub	lic Schools				Project Number: B52	37030 - Rour	nd 3		State Action L	evel: 5 ppb	<u>Notes</u> - *Notes are about anything out of the ord	inary found during sampling. Examples of Notes: iter color, low water flow, irregular water spray, does
Campus Name: JTSD							Retest Samp	le Collection			water become warm/hot, water filter attached to	
			Fountain-HF, Drinking Founta ucet-LF, Water Fountain Chill		Faucet Retesting: Sa exceedances at or ab	ove 5 parts p	per billion				*Flushing and "Do not drink from faucet" signs and	ove 5 ppb should be re-sampled with a Flush sample. e only temporary solutions. lacement of lead components are permanent solutions.
		t-TF, Shop Fau	cet-SF, Coffee Maker (Java)-J		<u>D</u> - This is a First Draw the faucet. This samp <u>F</u> - This is a Flush Sam	ple tests the ple collected	water in the fa d in a 250 mill	aucet for lead. iliter bottle aft	er flushing the fa	ucet for 30	*Any faucet with a value above 15 ppb should be *All values above 5.0 ppb must be remediated as	removed from service and/or replaced immediately. soon as possible.
Building Name	Floor/Room #/Name	Outlet Type	Outlet Name/Sink/Location	Aerator Screen (Y/N)	seconds. This sample Sample #	tests the wa	1	e system servi Date	cing the faucet for Sampler Name	r lead. Results ppb	*Elementary schools, Kindergarten, Pre-K and da Notes	Recommendations
	124 Nurse Office	NF	sink faucet	N	JTSD-NO-NF-01	D	9:23AM	12/27/2023	Mandy Carlson	2.9		Meets State of Missouri requirements
	109	CF	classroom faucet	N	JTSD-109-CF-02	D	9:25AM	12/27/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	109	DF	drinking fountain	N	JTSD-109-DF-03	D	9:25AM	12/27/2023	Mandy Carlson	2.4		Meets State of Missouri requirements
	108	CF	classroom faucet	N	JTSD-108-CF-04	D	9:29AM	12/27/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
		DF CF	drinking fountain	N	JTSD-108-DF-05	D	9:29AM 9:33AM	12/27/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	107	DF	classroom faucet drinking fountain	Y N	JTSD-107-CF-06 JTSD-107-DF-07	D	9:33AM 9:33AM	12/27/2023 12/27/2023	Mandy Carlson Mandy Carlson	1.1		Meets State of Missouri requirements Meets State of Missouri requirements
	106 - Teacher											
	Workroom	TF	sink faucet	Y	JTSD-106-TF-08	D	9:34AM	12/27/2023	Mandy Carlson	2.1		Meets State of Missouri requirements
	Hallway near 123	BR	bottle filler	Y	JTSD-H-BR-09	D	9:39AM	12/27/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	Multipurpose Room	HF	fountain on left side	Ν	JTSD-H-LHF-10	D	9:39AM	12/27/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
		HF	fountain on right side	N	JTSD-H-RHF-11	D	9:39AM	12/27/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
		KF	double sink, single faucet	Y	JTSD-K-KF-12	D	9:42AM	12/27/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
		KF	handwashing sink in dish	Y	JTSD-K-HKF-13	D	9:44AM	12/27/2023	Mandy Carlson	6.5	Initial Sample	Post a "Not for Drinking or Cooking" Sign or Flush ea morning as temporary measure. Take out of servic and/or replace or add filter as soon as possible. Perfo flush (2nd draw) sampling.
	Kitchen	KF	room								Faucet leaking, sample not collected	Post a "Not for Drinking or Cooking" sign. Take out service and add to non-potable inventory OR insta NSF/ANSI Standards 43 & 52 approved filter. Perform draw retest after remediation.
		KF	sprayer	N	JTSD-K-SKF-14	D	9:45AM	12/27/2023	Mandy Carlson	5.8	Initial Sample	Post a "Not for Drinking or Cooking" Sign or Flush ex morning as temporary measure. Take out of servic and/or replace or add filter as soon as possible. Perf flush (2nd draw) sampling.
JTSD											Added to Non-Potable Inventory	No further action required
		KF	triple sink faucet on right	N	JTSD-K-RKF-15	D	9:49AM	12/27/2023	Mandy Carlson	2.7		Meets State of Missouri requirements
		KF	triple sink faucet on left	Y	JTSD-K-LKF-16	D	9:49AM	12/27/2023	Mandy Carlson	2.1		Meets State of Missouri requirements
				Y	JTSD-300-CF-17	D	9:52AM	12/27/2023	Mandy Carlson	8.8	Initial Sample	Post a "Not for Drinking" Sign or Flush each mornin temporary measure. Take out of service and/or repla add filter as soon as possible. Perform flush (2nd dr sampling.
		CF	classroom faucet	Y	JTSD-300-CF-21	D	9:34AM	10/19/2024	Mandy Carlson	10.2	Retest - faucet replaced	Post a "Not for Drinking" sign. Take out of service and to non-potable inventory OR install NSF/ANSI Stand 43 & 52 approved filter. Perform 1st draw retest af remediation.
	300			Y	JTSD-300-CF-04	D	9:55AM	12/27/2024	Mandy Carlson	11.9	Retest sample - faucet lines replaced	Take out of service and add to non-potable inventor install NSF/ANSI Standards 43 & 52 approved filter. Perform 1st draw retest after remediation. The lead source appears to be from beyond the immediate p and associated faucet but not from the schools prin service line.
				N	JTSD-300-DF-18	D	9:52AM	12/27/2023	Mandy Carlson	12.2	Initial Sample	Take out of service and replace or add filter, perform flush (2nd draw) sampling
		DF	drinking fountain	N	JTSD-300-DF-22	D	9:34AM	10/19/2024	Mandy Carlson	13.3	Retest - faucet replaced	Take out of service and add to non-potable inventory install NSF/ANSI Standards 43 & 52 approved filter Perform 1st draw retest after remediation.
				N	JTSD-300-DF-05	D	9:55AM	12/27/2024	Mandy Carlson	9.49	Retest sample - faucet lines replaced	Take out of service permenately OR install NSF/ANS Standards 43 & 52 approved filter. Perform 1st draw retest after remediation. The lead source appears to from beyond the immediate piping and associated faucet but not from the schools primary service line.



												Post a "Not for Drinking" Sign or Flush each morning as
	314	CF	classroom faucet	Y	JTSD-314-CF-19	D	9:56AM	12/27/2023	Mandy Carlson	8.6		temporary measure. Take out of service and/or replace or
	514	CI	classioonnaddet		3130-314-01-13	U	5.50AW	12/2//2023	wanuy canson	0.0		add filter as soon as possible. Perform flush (2nd draw)
												sampling.
												Post a "Not for Drinking" sign. Take out of service and add
				Y	JTSD-314-CF-23	D	9:37AM	10/19/2024	Mandy Carlson	9.62	Retest - faucet replaced	to non-potable inventory OR install NSF/ANSI Standards
												43 & 52 approved filter. Perform 1st draw retest after remediation.
												Take out of service and add to non-potable inventory OR
		CF	classroom faucet									install NSF/ANSI Standards 43 & 52 approved filter.
												Perform 1st draw retest after remediation. The lead
				Y	JTSD-314-CF-06	D	9:57AM	12/27/2024	Mandy Carlson	15.4	Retest sample - faucet lines replaced	source appears to be from beyond the immediate piping
												and associated faucet but not from the schools primary
	314											service line.
				N	JTSD-314-DF-20	D	9:56AM	12/27/2023	Mandy Carlson	16.9		Take out of service and replace or add filter, perform
								,,				flush (2nd draw) sampling
							0.27444	40/40/2024	Manda Carlaga		Detect forward and	Take out of service and add to non-potable inventory OR
				N	JTSD-314-DF-24	D	9:37AM	10/19/2024	Mandy Carlson	8.54	Retest - faucet replaced	install NSF/ANSI Standards 43 & 52 approved filter. Perform 1st draw retest after remediation.
		DF	drinking fountain									Take out of service permenately OR install NSF/ANSI
												Standards 43 & 52 approved filter. Perform 1st draw
				N	JTSD-314-DF-07	D	9:57AM	12/27/2024	Mandy Carlson	6.4	Retest sample - faucet lines replaced	retest after remediation. The lead source appears to be
									·			from beyond the immediate piping and associated
												faucet but not from the schools primary service line.
	Hallway next to room 301	HF	hallway fountain	N	JTSD-300H-HF-21	D	9:59AM	12/27/2023	Mandy Carlson	4.6		Meets State of Missouri requirements
	501											Post a "Not for Drinking" Sign or Flush each morning as
					1707 004 05 00			4.0 /07 /0000				temporary measure. Take out of service and/or replace or
				Y	JTSD-301-CF-22	D	10:01AM	12/2//2023	Mandy Carlson	9.2	Initial Sample	add filter as soon as possible. Perform flush (2nd draw)
												sampling.
												Post a "Not for Drinking" sign. Take out of service and add
				Y	JTSD-301-CF-25	D	9:39AM	10/19/2024	Mandy Carlson	11.3	Retest - faucet replaced	to non-potable inventory OR install NSF/ANSI Standards
JTSD		CF	classroom faucet						,			43 & 52 approved filter. Perform 1st draw retest after
												remediation.
												Take out of service and add to non-potable inventory OR install NSF/ANSI Standards 43 & 52 approved filter.
												Perform 1st draw retest after remediation. The lead
	201			Y	JTSD-301-CF-08	D	9:58AM	12/27/2024	Mandy Carlson	9.08	Retest sample - faucet lines replaced	source appears to be from beyond the immediate piping
	301											and associated faucet but not from the schools primary
												service line.
				N	JTSD-301-DF-23	D	10:01AM	12/27/2023	Mandy Carlson	18	Initial Sample	Take out of service and replace or add filter, perform
												flush (2nd draw) sampling Take out of service and add to non-potable inventory OR
				N	JTSD-301-DF-26	D	9:39AM	10/19/2024	Mandy Carlson	8.06	Retest - faucet replaced	install NSF/ANSI Standards 43 & 52 approved filter.
					5100 001 01 20	2	51057411	10, 10, 202 .	manay canson	0.00		Perform 1st draw retest after remediation.
		DF	drinking fountain									Take out of service permenately OR install NSF/ANSI
												Standards 43 & 52 approved filter. Perform 1st draw
				Y	JTSD-301-DF-09	D	9:58AM	12/27/2024	Mandy Carlson	8.83	Retest sample - faucet lines replaced	retest after remediation. The lead source appears to be
												from beyond the immediate piping and associated
												faucet but not from the schools primary service line.
	302	CF BR	classroom faucet bottle filler	Y Y	JTSD-302-CF-24 JTSD-300H-BR-25	D D	10:03AM 10:06AM	12/27/2023 12/27/2023	Mandy Carlson Mandy Carlson	4.7	calcium build-up around aerator	Meets State of Missouri requirements Meets State of Missouri requirements
	Hallway near 307	HF	water fountain	T N	JTSD-300H-BR-25	D	10:06AM	12/27/2023	Mandy Carlson	3.1	calcium build-up around aerator	Meets State of Missouri requirements
	307	CF	classroom faucet	N	JTSD-307-CF-27	D	10:10AM	12/27/2023	Mandy Carlson	3.1		Meets State of Missouri requirements
												Post a "Not for Drinking" Sign or Flush each morning as
				Y	JTSD-310-CF-28	D	10:16AM	12/27/2022	Mandy Carlson	5.2	Initial Sample	temporary measure. Take out of service and/or replace or
	310	CF	classroom faucet		J130-310-CF-20	U	10.10410	12/2//2023	Manuy Carison	5.2	initial sample	add filter as soon as possible. Perform flush (2nd draw)
							0.45	10/10/202				sampling.
	200	CF.		Y	JTSD-310-CF-27	D	9:43AM	10/19/2024	Mandy Carlson	3.95	Retest - faucet replaced	Meets State of Missouri requirements
	308 309	CF CF	classroom faucet classroom faucet	Y Y	JTSD-308-CF-29 JTSD-309-CF-30	D	10:17AM 10:19AM	12/27/2023 12/27/2023	Mandy Carlson Mandy Carlson	3.1		Meets State of Missouri requirements Meets State of Missouri requirements
	309	CF	classroom faucet	Y	JTSD-309-CF-30 JTSD-311-CF-31	D	10:19AM 10:21AM	12/27/2023	Mandy Carlson	3.8	broken aerator	Meets State of Missouri requirements
	312	CF	classroom faucet	Y	JTSD-312-CF-32	D	10:22AM	12/27/2023	Mandy Carlson	4.5	bioken derdebi	Meets State of Missouri requirements
		WF	fountain on right side	N	JTSD-FEMA-RWF-33	D	-	12/27/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	FEMA Gym	WF	fountain on left side	N	JTSD-FEMA-LWF-34	D	-		Mandy Carlson	<1.00		Meets State of Missouri requirements



January 9, 2025 Terracon Project No. B5237030

	200	CF	classroom faucet	Y	JTSD-200-CF-35	D	10:30AM	12/27/2023	Mandy Carlson	<1.00	calcium build-up and visible mold around aerator	Meets State of Missouri requirements
	24.2	DF	drinking fountain	N	JTSD-212-DF-36	D	10:35AM	12/27/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	212	CF	classroom faucet	Y	JTSD-212-CF-37	D	10:35AM	12/27/2023	Mandy Carlson	<1.00	calcium build-up around aerator	Meets State of Missouri requirements
	201	CF	classroom faucet	Y	JTSD-201-CF-38	D	10:38AM	12/27/2023	Mandy Carlson	1.2	calcium build-up and visible mold around aerator	Meets State of Missouri requirements
		DF	drinking fountain	N	JTSD-201-DF-39	D	10:38AM	12/27/2023	Mandy Carlson	<1.00	calcium build-up around bubbler	Meets State of Missouri requirements
	211	CF	classroom faucet	Y	JTSD-211-CF-40	D	10:40AM	12/27/2023	Mandy Carlson	<1.00	calcium build-up and visible mold around aerator	Meets State of Missouri requirements
		DF	drinking fountain	N	JTSD-211-DF-41	D	10:40AM	12/27/2023	Mandy Carlson	<1.00	calcium build-up around bubbler	Meets State of Missouri requirements
	202	CF	classroom faucet	Y	JTSD-202-CF-42	D	10:44AM	12/27/2023	Mandy Carlson	<1.00	calcium build-up and visible mold around aerator	Meets State of Missouri requirements
		DF	drinking fountain	N	JTSD-202-DF-43	D	10:44AM	12/27/2023	Mandy Carlson	<1.00	calcium build-up around aerator	Meets State of Missouri requirements
	210	CF	classroom faucet	Y	JTSD-210-CF-44	D	10:48AM	12/27/2023	Mandy Carlson	1.5	calcium build-up around aerator	Meets State of Missouri requirements
JTSD	210	DF	drinking fountain	N	JTSD-210-DF-45	D	10:48AM	12/27/2023	Mandy Carlson	1	calcium build-up around bubbler	Meets State of Missouri requirements
1120	203	CF	classroom faucet	Y	JTSD-203-CF-46	D	10:52AM	12/27/2023	Mandy Carlson	<1.00	calcium build-up and visible mold around aerator	Meets State of Missouri requirements
		DF	drinking fountain	N	JTSD-203-DF-47	D	10:52AM	12/27/2023	Mandy Carlson	<1.00	calcium build-up around bubbler	Meets State of Missouri requirements
	209	CF	classroom faucet	Y	JTSD-209-CF-48	D	10:55AM	12/27/2023	Mandy Carlson	<1.00	calcium build-up and visible mold around aerator	Meets State of Missouri requirements
		DF	drinking fountain	N	JTSD-209-DF-49	D	10:55AM	12/27/2023	Mandy Carlson	4.5		Meets State of Missouri requirements
	204	CF	classroom faucet	Y	JTSD-204-CF-50	D	11:00AM	12/27/2023	Mandy Carlson	2.8	calcium build-up and visible mold around aerator	Meets State of Missouri requirements
	204	DF	drinking fountain	N	JTSD-204-DF-51	D	11:00AM	12/27/2023	Mandy Carlson	1.1	calcium build-up around bubbler	Meets State of Missouri requirements
	208	CF	classroom faucet	Y	JTSD-208-CF-52	D	11:03AM	12/27/2023	Mandy Carlson	1.7	calcium build-up around aerator	Meets State of Missouri requirements
	205	CF	classroom faucet	Y	JTSD-205-CF-53	D	11:05AM	12/27/2023	Mandy Carlson	1.3	calcium build-up around aerator	Meets State of Missouri requirements
	206	CF	classroom faucet	Y	JTSD-206-CF-54	D	-	12/27/2023	Mandy Carlson	3.3	broken aerator	Meets State of Missouri requirements
	207	CF	faucet on left	Y	JTSD-207-LCF-55	D	11:11AM	12/27/2023	Mandy Carlson	3.6	calcium build-up around aerator	Meets State of Missouri requirements
	207	CF	faucet on right	Y	JTSD-207-RCF-56	D	11:11AM	12/27/2023	Mandy Carlson	2.4	calcium build-up around aerator	Meets State of Missouri requirements
	Outside (North)	CF	classroom faucet	Y	JTSD-OM-CF-57	D	11:20AM	12/27/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
	Modular	WF	water fountain	N	JTSD-OM-WF-58	D	11:20AM	12/27/2023	Mandy Carlson	<1.00		Meets State of Missouri requirements
- at or above	state action level			•				•			•	

Red Bold = at or above state action level

ppb = parts per billion

< = below laboratory reporting limit Initial Sample Below 5 ppb

Initial Sample Above 5 ppb

Retest Sample Collection Event



District Name: Nixa Public S	Schools				Project Number:	B5237030 - I	Round 3		State Action	Level: 5 ppb	Notes - *Notes are about anything out of the ordinary	
Campus Name: Summit Inte	ermediate						Retest Sar	nple Collectio	1		automatic hand sensor, water odor, change in water co	
					Faucet Retestin	a: Complex f		-		oviouch	water become warm/hot, water filter attached to fauc Recommendations - *All samples with a value above 5	
Faucet Inventory (outlet t	vnes): Classroom Faucet-C	Hall Founta	in-HF, Drinking Fountain-DF, Ki	tchen Faucet-	reported exceeda				, and etc. with pr	eviously	*Flushing and "Do not drink from faucet" signs are only	
			Fountain Chilled-WF, Nurse Roo		D - This is a First				0 milliliters of wa	ater to come	*Taking a faucet out of service, filters and/or replacem	
• •			Other Fountain/Faucet-OF (des		out of the faucet						*Any faucet with a value above 15 ppb should be remo	ved from service and/or replaced immediately.
		Faucet-BR							le after flushing	the faucet for	*All values above 5.0 ppb must be remediated as soon	as possible.
					30 seconds. This	sample tests	the water in	the pipe syste	em servicing the f	aucet for lead.	*Elementary schools, Kindergarten, Pre-K and day care	are highest priorites.
Building Name	Floor/Room #/Name	Outlet Type	Outlet Name/Sink/Location	Aerator Screen (Y/N)	Sample #	Type (D,F)	Time	Date	Sampler Name	Results ppb	Notes	Recommendations
		BR	bottle filler	Y	SI-300H-BR-01	D	10:51AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	300 Hallway near 303	HF	fountain on left	N	SI-300H-LHF-02	D	10:51AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
		HF	fountain on right	N	SI-300H-RHF-03	D	10:51AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	202	DF	cink with fountain	N	SI-303-DF-04	D	10:55AM	12/28/2023	Mandy Carlson	7.4	Initial sample	Take out of service, and replace or add filter,
	303	DF	sink with fountain	N	SI-303-DF-15	D	9:02AM	10/19/2024	Mandy Carlson	2.18	Retest - replaced faucet	perform flush (2nd draw) sampling. Meets State of Missouri requirement
•	304	DF	sink with fountain	N	SI-304-DF-05	D	10:56AM	12/28/2023	Mandy Carlson	3.8	Refest - Teplaced Tadcer	Meets State of Missouri requirement
•	305	DF	sink with fountain	N	SI-305-DF-06	D	10:57AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	505	DI	Sink with foundam									Take out of service, and replace or add filter,
	306	DF	sink with fountain	N	SI-306-DF-07	D	10:59AM	12/28/2023	Mandy Carlson	5.5	Initial sample	perform flush (2nd draw) sampling.
				N	SI-306-DF-16	D	9:04AM	10/19/2024	Mandy Carlson	1.23	Retest - replaced faucet	Meets State of Missouri requirement
												Take out of service, and replace or add filter,
	308	DF	sink with fountain	N	SI-308-DF-08	D	11:01AM	12/28/2023	Mandy Carlson	6.7	Initial sample	perform flush (2nd draw) sampling
				N	SI-308-DF-17	D	9:06AM	10/19/2024	Mandy Carlson	1.04	Retest - replaced faucet	Meets State of Missouri requirement
	309	DF	sink with fountain	N	SI-309-DF-09	D	11:05AM	12/28/2023	Mandy Carlson	2.8		Meets State of Missouri requirement
	310	DF	sink with fountain	N	SI-310-DF-10	D	12:26PM	12/28/2023	Mandy Carlson	1.1		Meets State of Missouri requirement
	311	DF	sink with fountain	N	SI-311-DF-11	D	11:06AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	312	DF	sink with fountain	N	SI-312-DF-12	D	11:09AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	313	DF	sink with fountain	N	SI-313-DF-13	D	11:10AM	12/28/2023	Mandy Carlson	1.8		Meets State of Missouri requirement
	314	DF	sink with fountain	N	SI-314-DF-14	D	11:12AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	315	DF	sink with fountain	N	SI-315-DF-15	D	11:13AM	12/28/2023	Mandy Carlson	2.9	low water pressure	Meets State of Missouri requirement
	316	DF	sink with fountain	N	SI-316-DF-16	D	11:15AM	12/28/2023	Mandy Carlson	3.8		Meets State of Missouri requirement
	247			N	SI-317-DF-17	D	11:17AM	12/28/2023	Mandy Carlson	5.9	Initial sample	Take out of service, and replace or add filter,
	317	DF	sink with fountain		SI-317-DF-14		9:00AM	10/19/2024	Manufa Carlana	1.67	Detect works and forward	perform flush (2nd draw) sampling. Meets State of Missouri requirement
	201	DF	state with farmers in	N	SI-201-DF-14	D	9:00AM 11:20AM	10/19/2024	Mandy Carlson Mandy Carlson	4.8	Retest - replaced faucet	Meets State of Missouri requirement
	201 202	DF	sink with fountain sink with fountain	N	SI-201-DF-18 SI-202-DF-19	D	11:20AM 11:23AM	12/28/2023	Mandy Carlson	4.8		Meets State of Missouri requirement Meets State of Missouri requirement
Summit Intermediate	202	DF	sink with fountain	N	SI-202-DF-19	D	11:25AM	12/28/2023	Mandy Carlson	1.2		Meets State of Missouri requirement
		HF	taller fountain on left side	N	SI-200H-LHF-21	D	11:28AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	200 Hallway near 204	HF	shorter fountain on right side	N	SI-200H-RHF-22	D	11:28AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	205	DF	sink with fountain	N	SI-205-DF-23	D	11:30AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	206	DF	sink with fountain	N	SI-206-DF-24	D	11:31AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
Ī	207	DF	sink with fountain	N	SI-207-DF-25	D	11:32AM	12/28/2023	Mandy Carlson	1.2		Meets State of Missouri requirement
	208	DF	sink with fountain	N	SI-208-DF-26	D	11:42AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	209	DF	sink with fountain	N	SI-209-DF-27	D	11:45AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
[	210	DF	sink with fountain	N	SI-210-DF-28	D	11:47AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
ļ	211	DF	sink with fountain	N	SI-211-DF-29	D	11:48AM	12/28/2023	Mandy Carlson	1.2		Meets State of Missouri requirement
	212	DF	sink with fountain	N	SI-212-DF-30	D	11:50AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
ļ	215	DF	sink with fountain	N	SI-215-DF-31	D	11:52AM	12/28/2023	Mandy Carlson	4.6	low water pressure	Meets State of Missouri requirement
ļ	216	DF	sink with fountain	N	SI-216-DF-32	D	11:53AM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
-	217	DF	sink with fountain	N	SI-217-DF-33	D	11:55AM	12/28/2023	Mandy Carlson	4.3	low water pressure	Meets State of Missouri requirement
	134 -Band Room	DF	sink with fountain	N	SI-134-DF-34	D	11:58AM	12/28/2023	Mandy Carlson	5.9	Initial sample	Take out of service, and replace or add filter, perform flush (2nd draw) sampling.
	104 -Dallu NUUII	UF	SILK WILL IOUILAIN	N	SI-134-DF-13	D	8:57AM	10/19/2024	Mandy Carlson	-	Retest - replaced faucet	Meets State of Missouri requirement
•	133	DF	sink with fountain	N	SI-134-DF-13	D	12:00PM	10/19/2024	Mandy Carlson	2.7		Meets State of Missouri requirement
	133	DF	sink with fountain	N	SI-133-DF-35	D	12:00PM 12:02PM	12/28/2023	Mandy Carlson	4.4		Meets State of Missouri requirement
•	130	DF	sink with fountain	N	SI-130-DF-37	D	12:02PW	12/28/2023	Mandy Carlson	4.4		Meets State of Missouri requirement
1	129	DF	sink with fountain	N	SI-129-DF-38	D	12:07PM	12/28/2023	Mandy Carlson	4.4		Meets State of Missouri requirement
•		HF	shorter fountain on right side	N	SI-100H-RHF-39	D	12:12PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	100 Hallway across from	HF	taller fountain on left side	N	SI-100H-LHF-40	D	12:12PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
	134	BR	bottle filler	Y	SI-100H-BR-41	D	12:12PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
ł		5	bottle inter		1. 10011 51. 41			20, 2020	manay carison	-1.00		Post a "Not for Drinking or Cooking" Sign or Flus
			handwashing sink near									each morning as temporary measure. Take out of
	Kitchen	KF	restroom	Y	SI-K-HKF-42	D	12:16PM	12/28/2023	Mandy Carlson	14.8	Initial sample	service and/or replace or add filter as soon as
			1									possible. Perform flush (2nd draw) sampling.



January 9, 2025 Terracon Project No. B5237030

		KF	handwashing sink near restroom	Y	SI-K-OF-11	D	8:54AM	10/19/2024	Mandy Carlson	10.7	Retest - replaced faucet	Post a "Not for Drinking or Cooking" sign. Take out of service and add to non-potable inventory OR install NSF/ANSI Standards 43 & 52 approved filter. Perform 1st draw retest after remediation.
Summit Intermediate	Kitchoo			Y	SI-K-OF-02	D	9:40AM	12/27/2024	Mandy Carlson	1.44	Retest sample - faucet lines replaced	Meets State of Missouri requirement. No further action required
Summit intermediate	Kitchen	KF	double sink near stove	Y	SI-K-KF-43	D	12:17PM	12/28/2023	Mandy Carlson	<1.00		Meets State of Missouri requirement
		KF	handwashing sink in dish room	Y	SI-K-HKF-44	D	12:19PM	12/28/2023	Mandy Carlson	16.5	Initial sample	Take out of service, and replace or add filter, perform flush (2nd draw) sampling.
			room	Y	SI-K-OF-12	D	8:55AM	10/19/2024	Mandy Carlson	1.22	Retest - replaced faucet	Meets State of Missouri requirement
		KF	sprayer	N	SI-K-SKF-45	D	12:21PM	12/28/2023	Mandy Carlson	1.7		Meets State of Missouri requirement
		KF	triple sink, left faucet	Y	SI-K-LKF-46	D	12:21PM	12/28/2023	Mandy Carlson	1.8		Meets State of Missouri requirement
		KF	triple sink, right faucet	Y	SI-K-RKF-47	D	12:21PM	12/28/2023	Mandy Carlson	1.6		Meets State of Missouri requirement

Red Bold = at or above state action level

ppb = parts per billion

< = below laboratory reporting limit

Initial Sample Below 5 ppb

Initial Sample Above 5 ppb

Retest Sample Collection Event