



Tangier Smith Elementary School



January 14, 2025



Tangier Smith Elementary School

Item #	Description	Comments
56	Sidewalks	Extend pavement to walkways that currently do not comply with ADA
69	Exterior Doors	Replace door frame from pump room/harden all visions/sidelights
72	Windows	Recommend complete replacement of double hung windows in 1993 wing
73	Roof and Skylights	Replace single ply roof/install roof access
74	Interior Bearing Walls and Fire Walls	Masonry cracks in Tower 2/repoint/install fire shutters btwn kit & srv. area
75	Other Interior Walls	Further discussion required: partitions vs. permanent walls
77	Resilient Tiles or Sheet Flooring	Recommend VCT flooring throughout new wing
80	Ceilings	Replacement of old ceiling in 1993 addition/reinstall flat Led lighting
82	Interior Doors	DW replacement classrooms, office and assembly places
88	Ventilation System	Replacement of UVs in 1993 wing, RTUs and reheat coils
89	Mechanical Air-Conditioning Systems	Recommend full building upgrade to DDC
96	Hot Water Heaters	No response
97	Plumbing Fixtures	Renovate all bathrooms original bldg/create handicapped BR Grade K
107	Communication Systems	Recommend full replacement of entire system

Elementary Libraries



January 14, 2025

