



William Floyd Elementary School



William Floyd Elementary School

Item #	Description	Comments
55	Pavements	Replace parking lots, basketball & backboards
56	Sidewalks	Partial sidewalk/curb/extend walkways for handicapped accessibility
66	Exterior Walls/Columns	Misc. exterior cracks
69	Exterior Doors	Replace doors/sidelights/frames/harden glass at multiple locations
72	Windows	Replace double hung windows at 1992 wing
73	Roof and Skylights	Replace built up roofs/single ply EPDM
76	Carpet	Replace main office
80	Ceilings	Replacement of old and sagging ceiling/multi repairs plaster ceiling
82	Interior Doors	DW replace interior doors
87	Heat Generating Systems	Replace boilers/burner at learning center
88	Ventilation System	Pour concrete pads, replace existing roof top gravity relief dampers
92	HVAC Control Systems	Replace outdated controllers
97	Plumbing Fixtures	Renovate bathrooms in converted locker rooms
107	Communication Systems	Full Replacement of PA/Intercom system

Elementary Libraries



January 14, 2025

