


Nathaniel Woodhull Elementary School



Nathaniel Woodhull Elementary School

Item #	Description	Comments
46	Catch Basins/Drop Inlets/Manholes	Raise & repair settling castings at road around bldg adjacent to 2003 wing
55	Pavements	Replacement roadway around bldg and 2 lots
56	Sidewalks	Replacement partial sidewalks throughout campus
66	Exterior Walls/Columns	Replace broken, cracked stone sills, repointing, some extensive repairs
67	Chimneys	Repointing required at entire chimney
69	Exterior Doors	Replace boiler room, elect. room and upper mechanical room doors
70	Exterior Steps, Stairs, Ramps	Wire brush and paint exterior steps upper mechanical room
72	Windows	Replacement of multiple windows
73	Roof and Skylights	Recommend replacement of all existing roofs are/near end useful life
74	Interior Bearing Walls and Fire Walls	Repairs 2003 wing/Fire stop electrical closet 2003 wing
77	Resilient Tiles or Sheet Flooring	Recommend replacement of VCT in 1995 wing
88	Ventilation System	Ventilation custodial office/pour concrete pads
90	Piped Heating & Cooling Dist. Sys.	Boiler room insulation to be installed at uninsulated piping
92	HVAC Control Systems	Replace obsolete controllers
97	Plumbing Fixtures	Add air separator to 2 compartment sinks in kitchen
116	Accessibility standards	Add 12" vertical grab bars to nurses office ADA toilet

Elementary Libraries



January 14, 2025

