

## Bush Construction

5401 Victoria Avenue  
Davenport, IA 52807  
563.344.3791

## Browning Field Concessions & Toilet Improvements Question Log #1 | 2.6.25

1. Shear Wall – SW2
  - a. Is this to be a CFMF wall or CMU?
    - i. Detail 12/S300 notes CMU on Foundation Wall
  - b. Is this to be a thickened slab or Foundation Wall?
    - i. Detail 11/S300 note CFMF on thickened slab
2. Foundation Stub Walls
  - a. Detail 1/A502 show concrete stub wall?
  - b. Details on S300 do not show concrete stub walls.
3. Alternates
  - a. Architectural Site Plans note SN05: Propose Seed, Fertilize and Mat.
  - b. This was not included on the bid form, are we to include this as Alternate #5?

This is a CFMF wall. Refer to the updated structural drawings.  
-ZC, 2/11/25

This is a foundation wall as noted by section cut 12/S300. Refer to the updated structural drawings.  
-ZC, 2/11/25

Note SN05 is to be included with Alternate #4  
-ZC, 2/11/25

