Building Information

Page Last Modified: 02/27/2025

Building Information

1. Name of school	district
East Islip Union Free	School District
2. SED District 8-I	Digit BEDS Code
58-05-03-03	
2 Building Name	
3. Building Name: John F. Kennedy Ele	
4. SED 4-Digit Fac	ility Code:
0-007	
5. Survey Inspect	on Date:
08/20/2024	
6. Building 911 Ac	Idress:
94 Woodland Drive	
7 City	
7. City: East Islip	
8. Zip Code: 11730	
11730	
9. Certificate of O	ccupancy Status:
🗹 A - Annual	
T - Temporary	
N - None	
10. Certificate of (Occupancy Expiration Date:
12/01/2025	
40-	
10a.	Is this a manufactured building? (Relocatable, modular, portable)
☑ No	
11. Have there be	en renovations or construction in the building during the past 12 months?
☑ Yes	
12. Was major co	nstruction/renovation work since 2015 conducted when school was in session?
☑ Yes	
I No	

□ No

13. Estimated capital construction expenses anticipated for this building through the 2024 calendar year excluding maintenance (to be answered after the building inspection is complete)

Building Information

Page Last Modified: 02/27/2025

368,468.4914. Overall building rating (to be answered after the building inspection is complete)

- □ Excellent
- Satisfactory
- Unsatisfactory
- Failing

15. Was overall building rating established after consultation with health and safety committee in accordance with Commissioner's Regulations 155.4(c)(1)?

☑ Yes

□ No

16. A/E Firm Name:

H2M Architects + Engineers

17. A/E Firm Address:

538 Broad Hollow Road, 4th Floor East, Melville, NY 11747

18. A/E Firm Phone Number:

6317568000

19. E-mail:

rwildermuth@h2m.com

20. A/E Name:

Robert Wildermuth

21. A/E License #: 026314

Building Age, Gross Square Footage and Maintenance Staff

22. Building Age

	Year
Original Construction	1964
Addition #1	(No Response)
Addition #2	(No Response)
Addition #3	(No Response)
Addition #4	(No Response)
Addition #5	(No Response)
Addition #6	(No Response)
Addition #7	(No Response)
Addition #8	(No Response)

Building Information

Page Last Modified: 02/27/2025

	Year
Addition #9	(No Response)

23. Square feet of construction

	Sq Feet
Original construction	48,700.00
Addition #1	(No Response)
Addition #2	(No Response)
Addition #3	(No Response)
Addition #4	(No Response)
Addition #5	(No Response)
Addition #6	(No Response)
Addition #7	(No Response)
Addition #8	(No Response)
Addition #9	(No Response)

24. Gross square ft. of Building as currently configured:

48,700

25. Number of Floors:

2

26. How many full-time and part-time custodians are employed at the school (or work in the building)?

	Count Employees
Full-time custodians:	4
Part-time custodians:	0
Totals:	4

Building Ownership and Occupancy Status

27. Building Ownership (check one):

- Owned and used by district
- □ Owned by District and leased to non-district entity
- □ Owned by District, part used by district, part leased to non-district entity
- Owned by non-district entity and leased to district

28. For which of the following purposes is the building currently used? (check all that apply)

- ☑ Used for student instructional purposes
- □ Used for district administration
- □ Used for other district purposes

Building Information

Page Last Modified: 02/27/2025

□ Used by other organization(s)

Building Users

29. How many students were registered to receive instruction in this building as of the last year? (If none, enter

"0") and skip to "Program Spaces" section. (Do not include evening class students) 422

30. Of these registered students, how many receive most of their instruction in:

	Quantity
Permanent instructional spaces (i.e., regular classrooms)	422
Temporary instructional spaces (i.e., portable or demountable classrooms) attached to the building	0
Non-instructional spaces used as instructional spaces	0

31. If the answer is greater than zero, which types of non-instructional spaces were being used for instructional

purposes on October 1, 2019? (check all that apply)

- □ Cafeteria
- □ Gymnasium
- □ Administrative Spaces
- □ Library
- □ Lobby
- □ Stairwell
- Storage space
- □ Other (please describe)
- ☑ None

32. Grades Housed

D Pre-K	□ 7th
□ Kindergarten	□ 8th
□ 1st	□ 9th
□ 2nd	□ 10th
☑ 3rd	□ 11th
☑ 4th	□ 12th
☑ 5th	□ N/A (none)
□ 6th	

33. For how many instructional days during the school year prior to the BCS assigned year (July 1 through June

30) was the building closed due to facilities failures, system malfunctions, structural problems, fire, etc? (if none, enter "0")

0

Building Information

Page Last Modified: 02/27/2025

34. Is the building used for instructional purposes in the summer?

☑ Yes

□ No

Program Spaces

Page Last Modified: 08/22/2024

Program Spaces

35. Number of instructional classrooms:

25

36. Gross square footage of all instructional classrooms (combined):

19,425.00

37. Other spaces provided:

a. N/A (none)b. Administration

d. Audio Visual

□ e. Auditorium

g. Computer Room

☑ f. Cafeteria

□ h. Guidance

☑ i. Gymnasium

🗹 c. Art

☑ j. Health Office□ k. Home & Careers

I. Kitchen

m. Large Group Instruction

n. Library

- o. Multipurpose Rooms
- D. Music

□ q. Pre-K

r. Remedial Rooms

- □ s. Resource Rooms
- □ t. Science Labs
- □ u. Special Education
- □ v. Swimming Pool
- □ w. Teacher Resource
- □ x. Technology/Shop
- □ y. Other (please describe)

37a. Describe other spaces

(No Response)

Space Adequacy

38. Rating of space adequacy:

☑ Good

Fair

Poor

38a. Enter comments: (No Response)

Site Utilities

Page Last Modified: 02/27/2025

SITE UTILITIES

39. Water (H	I)
⊠ Yes	
□ No	
	39a. Type of Service:
	Municipal or Utility provided
	□ Well
	□ Other
	39b. Types of water service piping
	□ Galvanized
	☑ Copper
	Lead
	D PVC
	Other
	N/A (None)
	39c. Overall condition of water service piping
	Excellent
	☑ Satisfactory
	Unsatisfactory
	Non-Functioning
	Critical Failure
	39d. Year of Last Major Reconstruction/Replacement:
	2004
	39e. Expected Remaining Useful Life (Years):
	20
	39f. Cost to Reconstruct/Replace \$:
	(No Response)
	39g. Comments:
	(No Response)
40. Site San	itary (H)
☑ Yes	
□ No	

40a. Type of Service:

Municipal or utility sewer

Site Utilities

Page Last Modified: 02/27/2025

- Site septic
- □ Other

40b. Condition:

- □ Excellent
- ☑ Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

40c. Year of Last Major Reconstruction/Replacement:

1999

40d. Expected Remaining Useful Life (Years):

15

40e. Cost to reconstruct/Replace \$:

(No Response)

40f. Comments: (No Response)

41. Site Gas

☑ Yes

□ No

41a. Type of gas service:

- ☑ Natural Gas
- □ Liquid Petroleum

41b. Condition:

- □ Excellent
- Satisfactory
- Unsatisfactory
- □ Non-Functioning
- Critical Failure

41c. Year of Last Major Reconstruction/Replacement;

1964

41d. Expected Remaining Useful Life (Years):

15

41e. Cost to Reconstruct/Replace \$:

(No Response)

Site Utilities

Page Last Modified: 02/27/2025

	41f. Comments:
	(No Response)
42. Site Fue	el Oil
⊻ Yes	
	42a. Number of Above-Ground Tanks: 0
	42a 4 Canacity of Albany, Organized Tanka (wellows).
	42a.1 Capacity of Above-Ground Tanks (gallons):
	42b. Number of Below-Ground Tanks:
	42b.1 Capacity of Below-Ground Tanks (gallons): 10,000
	42c. Condition:
	 ✓ Satisfactory □ Unsatisfactory
	□ Non-Functioning
	□ Critical Failure
	□ N/A
	42d. Year of Last Major Reconstruction/Replacement:
	1990
	42e. Expected Remaining Useful Life (Years):
	10
	42f. Cost to Reconstruct/Replace \$:
	(No Response)
	42g. Comments:
	(No Response)
43. Site Elec	ctrical, Including Exterior Distribution
☑ Yes	
□ No	
	43a. Service Provider:
	✓ Municipal or utility provided
	Self-Generated

□ Other

Site Utilities

Page Last Modified: 02/27/2025

43b. T	ype of Service:
	ove Ground
🗹 Bel	ow Ground
□ N/A	х
43c. C	Condition:
□ Exc	zellent
□ Sat	isfactory
	satisfactory
	Functioning
Crit	ical Failure
43d V	ear of Last Major Reconstruction/Replacement:
1964	
43e. E	Expected Remaining Useful Life (Years):
1	
	ost to Reconstruct/Replace \$:
500,00	0.00
43g. C	Comments:
The ex	isting service entrance switchgear in the first floor boiler room have reached the end of their serviceable life and
	e replacement.

SITE FEATURES

44. Closed Drainage Pipe Stormwater Management System

44a. Does this facilit	y have a closed	pipe system?
------------------------	-----------------	--------------

🗹 Yes

□ No

44b. Condition:

- □ Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

44c. Year of Last Major Reconstruction/Replacement:

1999

Site Utilities

Page Last Modified: 02/27/2025

44d. Expected Remaining Useful Life (Years):

9

44e. Cost to Reconstruct/Replace \$:

(No Response)

44f. Comments:

(No Response)

45. Open Drainage Pipe Stormwater Management System

45a. Does this facility have an open stormwater system (ditch)?

✓ Yes

□ No

45b. Condition:

- □ Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

45c. Year of Last Major Reconstruction/Replacement:

1999

45d. Expected Remaining Useful Life (Years):

9

45e. Cost to Reconstruct/Replace \$:

(No Response)

45f. Comments: (No Response)

46. Catch Basins/Drop Inlets/Manholes

46a. Does this facility have catch basins/drop inlets/manholes?

⊠ Yes

🗆 No

46b. Condition:

- □ Excellent
- Satisfactory
- Unsatisfactory
- □ Non-Functioning

Site Utilities

Page Last Modified: 02/27/2025

Critical Failure

46c. Year of Last Major Reconstruction/Replacement:

1999

46d. Expected Remaining Useful Life (Years):

9

46e. Cost to Reconstruct/Replace \$:

(No Response)

46f. Comments:

(No Response)

47. Culverts

47a. Does this facility have culverts?

□ Yes

🗹 No

48. Outfalls

□ Yes

⊠ No

49. Infiltration Basins/Chambers

49a. Does this facility have infiltration basins/chambers?

□ Yes

⊠ No

50. Retention Basins

50a. Does this facility have retention basins?

□ Yes

⊠ No

51. Wetponds

51a. Does this facility have wetponds?

□ Yes

Site Utilities

Page Last Modified: 02/27/2025

⊠ No	
52. Manufactured Stormwater Proprietary Units	
52a. Does this facility have proprietary units?	
□ Yes	
☑ No	
53. Point of Outfall Discharge: (check all that apply)	_
☑ Municipal storm sewer system	
Combined sewer system	
Surface Water	
□ On-site recharge	
□ Other (describe)	
☑ Not Applicable	
54. Outfall Reconnaissance Inventory	
Were all stormwater outfalls inspected during dry weather for signs of non-stormwater discharge?	
□ Yes	

- 🗆 No
- Not Applicable

Other Site Features

Page Last Modified: 02/27/2025

SITE FEATURES

- ☑ Yes
- □ No

55a. Type: (check all that apply)

- □ Concrete
- Asphalt
- □ Gravel
- □ Other

55b. Condition:

- Excellent
- Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- □ Critical Failure

55c. Year of Last Major Reconstruction/Replacement:

2021

55d. Expected Remaining Useful Life (Years):

7

55e. Cost to Reconstruct/Replace \$:

75,000.00

55f. Comments:

Replace/repair minor asphalt cracking at north-west parking lot (2,500 S.F.)

56. Sidewalks

☑ Yes

□ No

56a. Type: (check all that apply)

- □ Asphalt
- ☑ Concrete
- □ Gravel
- □ Paver
- □ Other

56b. Condition:

- □ Excellent
- Satisfactory

Other Site Features

Page Last Modified: 02/27/2025

- Unsatisfactory
- Non-Functioning
- □ Critical Failure

56c. Year of Last Major Reconstruction/Replacement:

1999

56d. Expected Remaining Useful Life (Years):

5

56e. Cost to Reconstruct/Replace \$:

17,100.00

56f. Comments:

Replace/repair minor cracking (250 S.F.) and curbing (320 L.F.) near the front entrance and bus-loop

57. Playgrounds and Playground Equipment

☑ Yes

□ No

57a. Condition:

- □ Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

57b. Year of Last Major Reconstruction/Replacement:

2000

57c. Expected Remaining Useful Life (Years):

2

57d. Cost to Reconstruct/Replace \$:

(No Response)

57e. Comments:

(No Response)

58. Athletic Fields and Play Fields

☑ Yes

□ No

58a. Condition:

- Excellent
- Satisfactory

Other Site Features

Page Last Modified: 02/27/2025

- Unsatisfactory
- Non-Functioning
- □ Critical Failure

58b. Year of Last Major Reconstruction/Replacement:

2000

58c. Expected Remaining Useful Life (Years):

4

58d. Cost to Reconstruct/Replace \$:

37,500.00

58e. Comments:

Replace existing perimeter fencing along south-east corner of the site (500 L.F.)

58f. Does the facility have synthetic turf field(s)

□ Yes

⊠ No

58f.1 If Yes, how many synthetic turf fields? (No Response)

• •

58f.2 Expected Remaining Useful Life of Synthetic Turf Field(s):

(No Response)

58f.3 Type of synthetic turf field infill: (No Response)

59. Exterior Bleachers / Stadiums

□ Yes

🗹 No

60. Related Structures (such as Press Boxes, Dugouts, Climbing Walls, etc.)

□ Yes

🗹 No

Building Structure

Page Last Modified: 08/22/2024

Building Structure

61. Foundation (S)

61a. Type (check all that apply):

- □ Reinforced Concrete
- Masonry on Concrete Footing

□ Other (specify)

61a1. If "Other" please specify

(No Response)

61b. Evidence of structural concerns (check all that apply):

- Structural Cracks
- □ Heaving/Jacking
- Decay/Corrosion
- □ Water Penetration
- Unsupported Ends
- □ Other
- None

61c. Condition:

- □ Excellent
- Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

61d. Year of Last Major Reconstruction/Replacement:

1999

61e. Expected Remaining Useful Life (Years):

29

61f. Cost to Reconstruct/Replace \$:

(No Response)

61g. Comments: (No Response)

62. Piers (S)

☑ Yes

□ No

62a. Type (check all that apply)

Building Structure

Page Last Modified: 08/22/2024

- Concrete
- Masonry
- □ Steel
- □ Stone
- □ Wood
- □ Other (specify)
- N/A (none)

62a1. If "Other" please specify

(No Response)

62b. Evidence of structural concerns (check all that apply)

- Structural Cracks
- □ Heaving/Jacking
- □ Decay/Corrosion
- □ Water Penetration
- Unsupported Ends
- □ Other
- ☑ None

62c. Condition:

- □ Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

62d. Year of Last Major Reconstruction/Replacement

1999

62e. Expected Remaining Useful Life (Years):

29

62f. Cost to Reconstruct/Replace \$:

(No Response)

62g. Comments: (No Response)

63. Columns (S)

Type (check all that apply):

- ☑ Concrete
- □ Masonry

Building Structure

Page Last Modified: 08/22/2024

1	□ Steel
1] Stone
	7 Weed
] Wood
ſ	Other (specify)
1	N/A (None)

63.1. If "Other" please specify

(No Response)

63a. Evidence of structural concerns (check all that apply)

- Structural Cracks
- Heaving/Jacking
- Decay/Corrosion
- Water Penetration
- Unsupported Ends
- □ Other
- ☑ None

63b. Condition:

- □ Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- □ Critical Failure

63c. Year of Last Major Reconstruction/Replacement

1999

63d. Expected Remaining Useful Life (Years):

20

63e. Cost to Reconstruct/Replace \$:

(No Response)

63f. Comments:

(No Response)

64. Footings (S)

Type (check all that apply):

☑ Concrete

□ Other (specify)

64a. Evidence of structural concerns (check all that apply)

Building Structure

Page Last Modified: 08/22/2024

- Structural Cracks
- □ Heaving/Jacking
- Decay/Corrosion
- Water Penetration
- Unsupported Ends
- □ Other (specify)
- ☑ None

64.a1. If "Other" please specify

(No Response)

64b. Condition:

- □ Excellent
- ☑ Satisfactory
- Unsatisfactory
- □ Non-Functioning
- Critical Failure

64c. Year of Last Major Reconstruction/Replacement

1999

64d. Expected Remaining Useful Life (Years):

20

64e. Cost to Reconstruct/Replace \$:

(No Response)

64f. Comments:

(No Response)

65. Structural Floors (S)

65a. Type (check all that apply):

- Concrete Deck on Wood Structure
- Concrete/Metal Deck/Metal Joists
- Cast in Place Concrete Structural System
- Precast Concrete Structural System
- Reinforced Concrete Slab on Grade
- □ Wood Deck on Wood Trusses
- Wood Deck on Wood Joists
- □ Other (specify)

65b. Evidence of Structural Concerns with Floor Support System (Beams/Joists/Trusses, etc.) (check all that apply):

Building Structure

Page Last Modified: 08/22/2024

- Structural Cracks
- Unsupported Ends
- Rot/Decay/Corrosion
- Deflection
- □ Seriously Damaged/Missing Components
- □ Other Problems
- ☑ None

65b.1 Describe Other Problems:

(No Response)

65c. Evidence of Structural Concerns with Structural Floor Deck (check all that apply):

- □ Cracks
- □ Deflection
- □ Rot/Decay/Corrosion
- None

65d. Overall Condition of Structural Floors:

- □ Excellent
- Satisfactory
- Unsatisfactory
- □ Non-Functioning
- Critical Failure

65e. Year of Last Major Reconstruction/Replacement:

1999

65f. Expected Remaining Useful Life (Years):

19

65g. Cost to Reconstruct/Replace \$:

(No Response)

65h. Comments:

(No Response)

Building Envelope

Page Last Modified: 02/27/2025

BUILDING ENVELOPE

66. Exterior Walls/Columns (S)

66a. Material (check all that apply):

- □ Aluminum/Glass Curtain Wall
- Brick
- □ Concrete
- Composite Insulated Panels
- □ Masonry
- □ Steel
- □ Wood
- □ Other (specify)

66b. Evidence of Structural Concerns with Support System (columns, base plates, connections, etc.) (check all that apply):

୍ୱା	ICCK	an	ιπαι	appiy

- Structural Cracks
- Rot/Decay/Corrosion
- Other Problems
- ☑ None

66b.1 Describe Other Problems:

(No Response)

66c. Evidence of Concerns with Exterior Cladding (check all that apply):

- □ Cracks/Gaps
- □ Inadequate Flashing
- □ Efflorescence
- □ Moisture Penetration
- □ Rot/Decay/Corrosion
- □ Other Problems
- ☑ None

66c.1 Describe Other Problems:

(No Response)

66d. Overall Condition of Exterior Walls/Columns:

- □ Excellent
- ☑ Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

Building Envelope

Page Last Modified: 02/27/2025

66e. Year of Last Major Reconstruction/Replacement:

1964

66f. Expected Remaining Useful Life (Years):

14

66g. Cost to Reconstruct/Replace \$: (No Response)

66h. Comments:

(No Response)

67. Chimneys (S)

⊠ Yes

□ No

67a. Material (check all that apply):

- □ Masonry
- ☑ Concrete
- □ Metal
- □ Wood
- □ Other

67a.1 Specify other:

(No Response)

67b. Overall Condition of Chimneys:

- □ Excellent
- Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical failure

67c. Year of Last Major Reconstruction/Replacement:

1990

67.d Expected Remaining Useful Life (Years):

12

67e. Cost to Reconstruct/Replace \$:

(No Response)

67f. Comments: (No Response)

68. Parapets (S)

□ Yes

Building Envelope

Page Last Modified: 02/27/2025

☑ No

69. Exterior Doors

69a. Overall Condition of Exterior Door Units:

- □ Excellent
- ☑ Satisfactory
- Unsatisfactory
- Non-Functioning
- □ Critical Failure

69b. Do any exterior doors have magnetic locking devices?

- ☑ Yes
- □ No

69c. Safety/Security features are adequate?

☑ Yes

□ No

69d. Year of Last Major Reconstruction/Replacement: 2021

69e. Expected Remaining Useful Life (Years): 7

69f. Cost to Reconstruct/Replace \$: 60,000.00

69g. Comments: Replace (3) double exterior doors and frames.

70. Exterior Steps, Stairs, Ramps (S)

☑ Yes

□ No

70a. Construction Type (Check all that apply)

- Concrete
- □ Paver
- □ Steel
- □ Wood
- □ Other (specify)

70b. If "other", specify here

(No Response)

Building Envelope

Page Last Modified: 02/27/2025

70c. Overall Condition of Exterior Steps, Stairs and Ramps

- □ Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

70d. Year of Last Major Reconstruction/Replacement:

1964

70e. Expected Remaining Useful Life (Years):

9

70f. Cost to Reconstruct/Replace \$: (No Response)

(- - -)

70g. Comments:

(No Response)

71. Fire Escapes (S)

71a. Does This Facility Have One or More Fire Escapes?

□ Yes

⊠ No

72. Windows

☑ Yes

□ No

72a. Window Material: (check all that apply)

- ☑ Aluminum
- □ Steel
- □ Vinyl
- □ Solid Wood
- Wood w/ External Cladding System
- □ Other

72a1. If "Other" please specify

(No Response)

72b. Overall Condition of Windows:

- □ Excellent
- Satisfactory

Building Envelope

Page Last Modified: 02/27/2025

- Unsatisfactory
- Non-Functioning
- □ Critical Failure

72c. All Rescue Windows are Operable:

- ☑ Yes
- □ No

□ N/A

72d. Year of Last Major Reconstruction/Replacement:

1991

72e. Expected Remaining Useful Life (Years):

10

72f. Cost to Reconstruct/Replace \$:

(No Response)

72g. Comments:

(No Response)

73. Roof and Skylights (S)

🗹 Yes

□ No

73a. Type of roof construction (check all that apply):

- ☑ Concrete on metal deck on metal trusses/joists
- Concrete (poured or plank) on concrete beams
- Gypsum (poured or plank) on metal trusses/joists
- □ Metal deck on metal trusses/joists
- Wood deck on wood trusses/joists
- Wood deck on metal trusses/joists
- Tectum on metal trusses/joists
- □ Other (describe below)

73a.1 Other roof construction type:

(No Response)

73b. Type of roofing material (check all that apply):

- □ Single-ply membrane
- Built-up
- Asphalt shingle
- Pre-formed metal
- □ IRMA

Building Envelope

Page Last Modified: 02/27/2025

- □ Slate
- □ Fluid applied seamless surfacing
- □ Other (describe below)

73b.1 Other roofing material:

(No Response)

73c. Evidence of structural concerns with roof support system (beams/joists/trusses, etc.) (check all that apply):

- □ Structural cracks
- □ Unsupported ends
- □ Rot/Decay/Corrosion
- □ Deflection
- □ Seriously damaged/missing components
- □ Other concerns (describe)
- None

73c.1 Describe other concerns:

(No Response)

73d. Evidence of structural concerns with roof deck (check all that apply):

- □ Cracks
- □ Deflection
- □ Rot/Decay/Corrosion
- None

73e. Does this facility have skylights?

- Yes
- □ No

73f. Skylight material (check all that apply):

- Plastic
- ☑ Glass
- □ Other
- □ N/A

73g. Overall condition of skylights:

- □ Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

Building Envelope

Page Last Modified: 02/27/2025

73h. Evidence of concerns with roofing, skylights, flashings, and drains (check all that apply):

- □ Failures/Splits/Cracks
- □ Rot/Decay/Corrosion
- □ Inadequate flashing/curbs/pitch pockets
- □ Inadequate or poorly functioning roof drains
- □ Evidence of water penetration/active leaks
- □ Other (specify)
- None

73h.1 Specify other concerns:

(No Response)

73i. Overall Condition of Roof and Skylights:

- □ Excellent
- Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- □ Critical Failure

73j. Year of Last Major Reconstruction/Replacement: 2020

73k. Expected Remaining Useful Life (Years):

19

73I. Cost to Reconstruct/Replace \$:

(No Response)

73m. Comments:

(No Response)

Building Interiors

Page Last Modified: 02/27/2025

BUILDING INTERIOR

74. Interior Bearing Walls and Fire Walls (S)

☑ Yes

□ No

74a. Overall condition of interior bearing walls and fire walls:

- □ Excellent
- ☑ Satisfactory
- Unsatisfactory
- Non-functioning
- Critical Failure

74b. Year of Last Major Reconstruction/Replacement:

1964

74c. Expected Remaining Useful Life (Years):

24

74d. Cost to Reconstruct/Replace \$:

(No Response)

74e. Comments:

(No Response)

74.f Regulatory

Have design professionals provided inventory of construction regulated under BCNYS Ch7, including assessment of their condition and maintenance, as required by NYSFC Ch7 and NYSPMC 703? This includes, but is not limited to:

[check each item provided to the district]

- ☑ Fire-resistance rated assemblies;
- Smoke barriers and smoke partitions;
- Penetrations, joints, voids, door
- ☑ Assessment of Ch7 regulated assembly either damaged, altered, breached, or penetrated;

☑ Confirmation of compliant repair or protection of Ch7 regulated assembly either damaged, altered, breached, or

penetrated;

□ Other:

74.f Other:

(No Response)

75. Other Interior Walls

☑ Yes

□ No

Building Interiors

Page Last Modified: 02/27/2025

75a. Overall condition of other interior walls:

- □ Excellent
- ☑ Satisfactory
- Unsatisfactory
- Non-Functioning
- □ Critical Failure

75b. Year of Last Major Reconstruction/Replacement:

1999

75c. Expected Remaining Useful Life (Years):

24

75d. Cost to Reconstruct/Replace \$: 32,000.00

75e. Comments: Replace wireglass/paneglass storefront system at Main Office (160 S.F.)

76. Carpet

☑ Yes

□ No

76a. Where located (check all that apply):

- Classrooms
- □ Corridors
- Offices
- □ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- Other Areas

76b. Condition:

- □ Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

76c. Year of Last Major Reconstruction/Replacement:

2004

76d. Expected Remaining Useful Life (Years):

7

76e. Cost to Reconstruct/Replace \$:

(No Response)

Building Interiors

Page Last Modified: 02/27/2025

76f. Comments: (No Response)

77. Resilient Tiles or Sheet Flooring

☑ Yes □ No

77a. Where located (check all that apply):

- Classrooms
- □ Corridors
- □ Offices
- □ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- □ Other Areas

77b. Overall condition of resilient tiles or sheet flooring:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- □ Critical Failure

77c. Year of Last Major Reconstruction/Replacement:

2005

77d. Expected Remaining Useful Life (Years):

9

77e. Cost to Reconstruct/Replace \$:

40,000.00

77f. Comments: Remove asbestos tile/replace LVT as needed (1,600 SF).

78. Hard Flooring (concrete; ceramic tile; stone; etc)

☑ Yes

□ No

78a. Where located (check all that apply):

- □ Classrooms
- □ Corridors
- □ Offices
- □ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- □ Kitchen
- □ Locker Rooms/Toilet Rooms

Building Interiors

Page Last Modified: 02/27/2025

	☑ Other Areas
	78b. Overall condition of hard flooring:
	Excellent
	☑ Satisfactory
	Unsatisfactory
	Non-Functioning
	Critical Failure
	78c. Year of Last Major Reconstruction/Replacement:
	2003
	78d. Expected Remaining Useful Life (Years):
	20
	78e. Cost to Reconstruct/Replace \$:
	(No Response)
	78f. Comments:
	(No Response)
79. Wood Fl	ooring
⊠ Yes	
. 100	

✓ Yes □ No

79a. Where located (check all that apply):

- Classrooms
- □ Corridors
- □ Offices
- □ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- Other Areas

79b. Overall condition of wood flooring:

- □ Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- □ Critical Failure

79c. Year of Last Major Reconstruction/Replacement:

2005

79d. Expected Remaining Useful Life (Years):

9

79e. Cost to Reconstruct/Replace \$:

Building Interiors

Page Last Modified: 02/27/2025

79f. Comments:

(No Response)

(No Response)

80. Ceilings (H)

☑ Yes

□ No

80a. Overall condition of ceilings:

- □ Excellent
- ☑ Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

80b. Year of Last Major Reconstruction/Replacement:

2005

80c. Expected Remaining Useful Life (Years):

14

80d. Cost to Reconstruct/Replace \$: 250,000.00

80e. Comments:		
beams		

81. Lockers

□ Yes

⊠ No

81d. Cost to Reconstruct/Replace \$:

(No Response)

82. Interior Doors

☑ Yes

□ No

82a. Overall condition of interior door units:

- □ Excellent
- ☑ Satisfactory
- Unsatisfactory
- Non-Functioning
- □ Critical Failure

Building Interiors

Page Last Modified: 02/27/2025

82b. Overall condition of interior door hardware:

- □ Excellent
- ☑ Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

82c. Year of Last Major Reconstruction/Replacement:

2023

82d. Expected Remaining Useful Life (Years):

20

82e. Cost to Reconstruct/Replace \$:

241,000.00

82f. Comments: Replace 24 (Single) and 5 (Double) interior doors. Replace 25 hardware sets throughout

83. Interior Stairs (H)

☑ Yes

□ No

83a. Overall condition of interior stairs:

- Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- Critical Failure

83b. Stair material

- ☑ Concrete
- □ Steel
- □ Wood
- □ Other

83c. Year of Last Major Reconstruction/Replacement:

1964

83d. Expected Remaining Useful Life (Years):

14

83e. Cost to Reconstruct/Replace \$:

25,000.00

83f. Comments:

Building Interiors

Page Last Modified: 02/27/2025

Provide rated stairwell doors and wall enclosures at non enclosed stairs

84.	Elevator,	Lift,	and	Escalators	(H))

☑ Yes

□ No

84a. Overall condition of elevators, lifts, escalators:

- □ Excellent
- Satisfactory
- □ Unsatisfactory
- Non-Functioning
- □ Critical Failure

84b. Year of Last Major Reconstruction/Replacement:

1995

84c. Expected Remaining Useful Life (Years):

9

84d. Cost to Reconstruct/Replace \$ (No Response)

84e. Comments: (No Response)

85. Swimming Pool and Swimming Pool Systems (H)

□ Yes

⊠ No

86. Interior Bleachers

□ Yes

⊠ No

HVAC Systems

Page Last Modified: 02/27/2025

HVAC Systems

87.	Heat	Generating	Systems	(H)
-----	------	------------	---------	-----

Yes

□ No

87a. Heat generation source (check all that apply):

- □ Biomass
- Boiler / Hot Water
- □ Boiler / Steam
- Cogeneration Plant
- □ Electric
- Furnace / Forced Air
- □ Geothermal
- Heat Pump
- ☑ Unit Ventilation
- □ Other (describe below)

87a.1 Other heat generation source:

(No Response)

87b. Overall condition of heat generating systems:

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- Non-Functioning
- □ Critical Failure

87c. Year of Last Major Reconstruction/Replacement:

2009

87d. Expected Remaining Useful Life (Years):

5

87e. Cost to Reconstruct/Replace \$:

25,000.00

87f. Comments:

Provide manual overide controls for existing boiler system.

88. Ventilation System (exhaust fans, etc) (H)

- ☑ Yes
- □ No

88a. Type of ventilation system (check all that apply)

HVAC Systems

Page Last Modified: 02/27/2025

Z	Natural ventilation	Ø	Heat pump
	Central system		Split system/ variable refrigerant
	Energy recovery ventilator		Powered relief air system
Z	Rooftop units		Gravity/barometric relief
Ø	Unitary (UVs, FC/BC, PTAC)		Other (specify)
	Forced air furnace		
	please specify here HVAC upgrades to existing system.		
88c. Overall co	ndition of ventilation systems	_	
Excellent			
Satisfactory			
Unsatisfactory			
□ Non-functionir			
Critical Failure			
2002 88e. Expected	remaining useful life (years):		
5	.		
005 Cast to sa	an at much land a		
665,000	construct/replace \$:		
000,000			
88g. Comments	S		
13			
5			
-			
89a. Types of n	nechanical cooling		
Chiller/chilled	water		
Geothermal			
Air cooled			
□ Water cooled			
DX/Split syste	m		
Heat pump			

89. Mechanical Cooling / Air-Conditioning Systems

⊠ Yes

□ No

89b. Overall condition of cooling/air-conditioning systems:

□ Excellent

HVAC Systems

Page Last Modified: 02/27/2025

- ☑ Satisfactory
- Unsatisfactory
- Non-Functioning
- □ Critical Failure

89c. Year of Last Major Construction/Replacement:

2003

89d. Expected Remaining Useful Life (Years):

19

89e. Cost to Reconstruct/Replace \$:

(No Response)

89f. Comments: (No Response)

90. Piped Heating and Cooling Distribution Systems: Piping, Pumps, Radiators, Convectors, Traps, Insulation, etc.

(H)	_
2 Yes	
] No	

90a. Overall condition of piped heating and cooling distribution systems:

- □ Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

90b. Year of Last Major Reconstruction/Replacement:

2003

90c. Expected Remaining Useful Life (Years):

20

90d. Cost to Reconstruct/Replace \$:

(No Response)

90e. Comments: (No Response)

91. Ducted Heating and Cooling Distribution Systems: Ductwork, Control Dampers, Fire/Smoke Dampers, VAVs, Insulation, etc. (H)

☑ Yes

□ No

91a. Overall condition of ducted heating and cooling distribution systems:

HVAC Systems

Page Last Modified: 02/27/2025

- □ Excellent
- Satisfactory
- □ Unsatisfactory
- Non-Functioning
- Critical Failure

91b. Year of Last Major Reconstruction/Replacement:

2003

91c. Expected Remaining Useful Life (Years):

20

91d. Cost to Reconstruct/Replace \$:

(No Response)

91e. Comments:

(No Response)

92. HVAC Control Systems (H)

☑ Yes

□ No

92a. Type of control system

- Pneumatic
- □ Electric
- Digital Direct Control (DDC)
- □ Web based DDC

92b. Overall condition of control systems:

- □ Excellent
- Satisfactory
- □ Unsatisfactory
- □ Non-Functioning
- □ Critical Failure

92c. Year of Last Major Reconstruction/Replacement: 2018

92d. Expected Remaining Useful Life (Years):

92e. Cost to Reconstruct/Replace \$: (No Response)

92f. Comments: (No Response)

Plumbing Systems

Page Last Modified: 02/27/2025

PLUMBING

- 93. Water Supply System (H)
- ☑ Yes
- □ No

93a. Types of pipes (check all that apply):

- □ Asbestos/transite
- ☑ Copper
- □ Galvanized
- □ Iron
- Lead
- D PVC/CPVC/PEX/Plastic
- □ Other (specify)

93b. If "Other" please specify here

Boiler system conrols.

93c. Overall condition of water supply system:

- □ Excellent
- ☑ Satisfactory
- Unsatisfactory
- □ Non-Functioning
- □ Critical Failure

93d. Year of Last Major Reconstruction/Replacement:

1999

93e. Expected Remaining Useful Life (Years):

20

93f. Cost to Reconstruct/Replace \$:

(No Response)

93g. Comments:

(No Response)

94. Sanitary System (H)

🗹 Yes

□ No

94a. Types of pipes (check all that apply):

- 🗹 Iron
- □ Galvanized
- □ Copper

Plumbing Systems

Page Last Modified: 02/27/2025

- □ Glass/ceramic
- PVC/CPVC/ABS/poly propylene/plastic
- □ Lead
- □ Other (specify)

94a1. If "Other" please specify

(No Response)

94b. Types of special sanitary systems (Check all that apply)

- □ Acid waste and vent
- □ Grease interceptor
- □ Oil separator
- Pumping station
- □ Sediment trap
- Septic tank
- □ Waste water treatment plant

94c. Overall condition of sanitary system:

- □ Excellent
- Satisfactory
- Unsatisfactory
- □ Non-Functioning
- Critical Failure

94d. Year of Last Major Reconstruction/Replacement:

1999

94e. Expected Remaining Useful Life (Years):

20

94f. Cost to Reconstruct/Replace \$:

(No Response)

94g. Comments:

(No Response)

95. Storm Water Drainage System (H)

☑ Yes

□ No

95a. Types of pipes (check all that apply)

- □ Iron
- Galvanized
- □ Copper

Plumbing Systems

Page Last Modified: 02/27/2025

□ Lead
□ Other
95a1. If "Other" please specify
(No Response)
95b. Overall condition of storm water drainage system
Excellent
☑ Satisfactory
□ Unsatisfactory
□ Non-Functioning
Critical Failure
95c. Year of Last Major Reconstruction/Replacement
1999
95d. Expected Remaining Useful Life (Years)
19
95e. Cost to Reconstruct/Replace \$:
(No Response)
95f. Comments:
(No Response)
96. Hot Water Heaters (H)
Z Yes

96a. Type of fuel (check all that apply):

- 🗆 Oil
- Natural Gas
- Electricity
- □ Propane
- Other (specify)

96b. If "Other" please specify

(No Response)

96c. Overall condition of hot water heaters:

- □ Excellent
- Satisfactory
- □ Unsatisfactory
- □ Non-Functioning

✓ Yes □ No

Plumbing Systems

Page Last Modified: 02/27/2025

□ Critical Failure

96d. Year of Last Major Reconstruction/Replacement:

2003

96e. Expected Remaining Useful Life (Years):

15

96f. Cost to Reconstruct/Replace \$:

25,000.00

96g. Comments: Provide manual overide controls for existing boiler system.

97. Plumbing Fixtures (H)

☑ Yes

□ No

97a. Overall condition of plumbing fixtures (including toilets, urinals, lavatories, sinks, showers, etc):

- Excellent
- ☑ Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

97b. Year of Last Major Reconstruction/Replacement:

2021

97c. Expected Remaining Useful Life (Years):

25

97d. Cost to Reconstruct/Replace \$:

(No Response)

97e. Comments:

(No Response)

98. Water Outlets/Taps for Drinking/Cooking Purposes (H)

Yes

□ No

98a. Overall condition of water outlets/taps (drinking fountains, bubblers, bottle fillers, kitchen prep,

ice machines, etc).

- Excellent
- Satisfactory
- Unsatisfactory

Plumbing Systems

Page Last Modified: 02/27/2025

Non-Functioning

Critical Failure

98b. Year of last major reconstruction/replacement:

1999

98c. Expected remaining useful life (years):

15

98d. Cost to reconstruct/replace \$:

(No Response)

98e. Comments

Fire Suppression Systems

Page Last Modified: 01/14/2025

Fire Suppression Systems

99. Fire Suppression System (H)

- ☑ Yes
- □ No

99a. Type of fire suppression system (check all that apply)

- □ Wet sprinkler system
- Dry sprinkler system
- □ Standpipes
- Hose cabinets
- Kitchen hood fire suppression
- Data special agent suppression
- Limited area sprinkler system
- Dust collector spark arrestor
- Paint booth fire suppression
- □ Other (describe)

99b. If "other" please describe below (No Response)

99c. Overall condition of sprinkler systems:

- □ Excellent
- Satisfactory
- □ Unsatisfactory
- Non-Functioning
- □ Critical Failure

99d. Year of Last Major Reconstruction/Replacement:

1964

99e. Expected Remaining Useful Life (Years):

10

99f. Cost to Reconstruct/Replace \$:

(No Response)

99g. Comments: (No Response)

100. Kitchen Hoods (H)

- ☑ Yes
- □ No

100a. Type of hood

Fire Suppression Systems

Page Last Modified: 01/14/2025

- ☑ Yes- Type 1 grease and smoke
- □ Yes- Type 2 heat and condensation

100b. Is kitchen exhaust system appropriate for all current appliances it serves?

☑ Yes

□ No

100c. Overall Condition of Kitchen Hoods

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- Non-Functioning
- □ Critical Failure

100d. Year of Last Major Reconstruction/Replacement:

1964

100e. Expected Remaining Useful Life (Years):

10

100f. Cost to Reconstruct/Replace \$: (No Response)

100g. Comments

Electrical Systems

Page Last Modified: 02/27/2025

ELECTRICAL SYSTEMS

101. Electrical Power Distribution System (H) ☑ Yes □ No 101a. Electrical supply meets current needs: ☑ Yes □ No 101b. Condition of electrical power distribution system: Excellent □ Satisfactory Unsatisfactory Non-Functioning Critical Failure 101c. Year of last major reconstruction/replacement? 2003 101d. Expected remaining useful life (years): 1 101e. Cost to reconstruct/replace: 500,000.00 101f. Comments: Replace Federal Pacific electrical switchboards. 102. Lighting Fixtures (H) ☑ Yes □ No

102a. Condition of lighting figures:

- □ Excellent
- Satisfactory
- □ Unsatisfactory
- Non-functioning
- Critical failure

102b. Year of last major reconstruction/replacement:

2018

102c. Expected remaining useful life (years):

15

Electrical Systems

Page Last Modified: 02/27/2025

102d. Cost to reconstruct/replace:

(No Response)

102e. Comments

(No Response)

103. Emergency/ Exit Lighting Systems (H):

✓ Yes

□ No

103a. Overall condition of emergency/exit lighting systems:

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- Non-functioning
- Critical failure

103b. Year of last manjor reconstruction/replacement:

2003

103c. Expected remaining useful life (years):

13

103d. Cost to reconstruct/replace: (No Response)

103e. Comments

(No Response)

104. Emergency or standby power system (H)

☑ Yes

□ No

104a. Types of back-up power system (check all that apply)

- Generator fuel gas/ propane
- Generator diesel/ fuel oil
- Receptacle for mobile generator connection
- □ Central battery inverter
- Integral fixture/ battery equipment
- ☑ Other (specify)

104b. If "other" please describe here

No existing emergency or standby power system.

104c. Overall condition of emergency/standby power systems:

Electrical Systems

Page Last Modified: 02/27/2025

- □ Excellent
- Satisfactory
- Unsatisfactory
- Non-functioning
- Critical failure
- ☑ N/A

104d. Year of last major reconstruction/replacement

1960

104e. Expected remaining useful life (years):

0

104f. Cost to reconstruct/replace:

500,000

104g. Comments

Install new generator to provide power to emergency life safety equipment.

105. Fire Alarm Systems (manual, automatic fire detection, and notification appliances) (H)

☑ Yes

□ No

105a. Overall condition of fire alarm system:

- □ Excellent
- Satisfactory
- Unsatisfactory
- □ Non-functioning
- □ Critical failure

105b. Year of last major reconstruction/replacement:

2005

105c. Expected remaining useful life (years):

2

105d. Cost to reconstruct/replace: 200.000

105e. Comments

Fire alarm system and controls upgrades.

106. Carbon Monoxide Alarm System (H)

✓ Yes

□ No

Electrical Systems

Page Last Modified: 02/27/2025

106a. Type of alarm system:

- 10-year battery stand alone alarm
- hardwired/interconnected detection and alarm
- □ gas detection (eg NG/CO)
- □ Other (specify)

106b. If "Other" please specify

(No Response)

106c. Overall condition of carbon monoxide alarm system:

- □ Excellent
- ☑ Satisfactory
- □ Unsatisfactory
- □ Non-functioning
- □ Critical failure

106d. Year of last major reconstruction/replacement:

2005

106e. Expected remaining useful life (years):

9

106f. Cost to reconstruct/replace:

(No Response)

106g. Comments

(No Response)

107. Communcation Systems (H)

🗹 Yes

□ No

107a. Type of communication system (check all that apply)

- Public Address
- Phones (VOIP)
- Phones (Cellular)
- □ Phones (other)
- Mass Notification
- Emergency voice communication fire alarm system
- Lockdown notification system
- □ Other (eg. radio) (describe below)

107b. If "Other" please describe

Electrical Systems

Page Last Modified: 02/27/2025

107c. Communication systems are adequate:

- ☑ Yes
- □ No

107d. Condition of communication system:

- □ Excellent
- Satisfactory
- □ Unsatisfactory
- Non-functioning
- □ Critical failure

107e. Year of last major reconstruction/replacement: 2003

107f. Expected remaining useful life: 5

107g. Cost to replace/reconstruct: 160,000.00

107h. Comments

Public adress and master time clock systems upgrades.

Student Transportation Facilities

Page Last Modified: 08/22/2024

Student Transportation Facilities

108. Is this building a transportation facility

□ Yes

⊠ No

109. Does this facility have a fuel dispensing system?

□ Yes

⊠ No

110. Does this facility have vehicle lifts

□ Yes

⊠ No

111. Does this facility have a bus wash system?

□ Yes

⊠ No

Accessibility

Page Last Modified: 08/22/2024

ACCESSIBILITY

112. Exterior Accessible Route to Building (H)

People with disabilities should be able to arrive on site, approach the building, and enter as freely as everyone else. At least one route of travel should be safe and accessible for everyone, including people with disabilities. This route must include handicapped parking, curb cuts, ramps, and automatic door operators as necessary to enter the building.

Is there an accessible exterior route as specified above?

☑ Yes

□ No

112a. Features provided for exterior accessible route (check all that apply)

- ☑ Curb ramps
- Exterior ramps
- ☑ Handicap parking

112b. Cost of improvements needed to provide exterior accessible route to building \$: (No Response)

112c. Comment (No Response)

113. Is there an exterior accessible route to recreational facilities?

🗹 Yes

□ No

113a. Cost of improvements to provide exterior accessible route(s) to recreational facilities \$: (No Response)

113b. Comments (No Response)

114. Exterior recreational facilities that are on an accessible route and meet accessibility standards (check all that

apply)

- Playground and play equipment
- ☑ Playfield(s)
- □ Athletic Field(s)
- Exterior Bleachers
- Bathroom Facilities
- Concession Stand

114a. Cost of improvements to provide exterior accessible recreational facilities \$:

Accessibility

Page Last Modified: 08/22/2024

114b. Comments (No Response)

115. Interior Accessible Route, Access to Goods and Services, and Restroom Facilities (H)

The layout of the building should allow people with disabilities to obtain materials or services and use the facilities without assistance. This should include access to general purpose and specialized classrooms, public assembly spaces (such as libraries, gymnasiums, auditoriums), nurse's office, main office, and restroom facilities. Services include drinking fountains, telephones, and other amenities.

Is there an interior accessible interior route as specified above?

☑ Yes

□ No

115a. Cost of improvements needed to provide interior accessible route(s) as spcified above \$: (No Response)

115b. Comments (No Response)

116. Does this facility have interior spaces that meet accessibility standards (check all that apply)

- □ Classrooms
- □ Labs (science, art, technology, etc)
- □ Shops
- ☑ Main Office
- □ Health Office
- ☑ Gymnasium
- ☑ Cafeteria
- Auditorium
- ☑ Stage
- □ Restrooms on each floor

116a. Cost of improvements to provide interior spaces that meet accessibility standards \$:

(No Response)

116b. Comments

Environment/Comfort/Health

Page Last Modified: 08/22/2024

ENVIRONMENT/COMFORT/HEALTH

117. General Appearance

117a. Overall Rating:

- ☑ Good
- □ Fair

D Poor

117b. Comments:

(No Response)

1	18.	Cleanliness	(H)
---	-----	-------------	-----

118a.	Overall	Rating
-------	---------	--------

- ☑ Good
- Fair
- □ Poor

118b. Comments: (No Response)

119. Are there walk off mats; grills in the entryway?

☑ Yes

□ No

119a. If yes: at least 6 feet long?
⊠ Yes

120. Is there noise in classrooms from HVAC units, traffic, etc. that may impact education? (H)

□ Yes

⊠ No

121. Lighting Quality (H):

121a. Types of lighting in general purpose classrooms (check all that apply):

☑ Daylight (natural)

- Not full spectrum
- □ Full spectrum
- ☑ LED
- □ Flourescent
- Other (describe)

Environment/Comfort/Health

Page Last Modified: 08/22/2024

121b. Are there blinds in the classroom to prevent glare?

⊠ Yes

□ No

121c. Overall Rating:

☑ Good

Fair

□ Poor

121d. Comments:

(No Response)

122. Evidence of Vermin (H)

122a. Is there evidence of active infestations of...(check all that apply)?

- □ Rodents
- □ Wood-boring or Wood-eating Insects
- Cockroaches
- Other Vermin
- None

Indoor Air Quality

Page Last Modified: 02/27/2025

Indoor Air Quality

123. Mold (H)

123a. Is there visible mold or moldy odors?

□ Yes

🗹 No

123b. Are any surfaces constructed of any of the following materials?

- □ Paper-faced or gypsum products
- □ Cellulose products (typically ceiling tiles)
- ☑ Not Applicable

123c. Is there evidence of water intrusion?

□ Yes

⊠ No

123d. Estimated cost of necessary improvements \$: (No Response)

123e. Comments:

(No Response)

124. Humidity/Moisture (H)

124a. Overall rating of humidity/moisture condition in building:

- ☑ Good
- □ Fair
- □ Poor

124b. Are any of the following found in/or around classroom areas (check all that apply)?

- □ Active leaks in roof
- □ Active leaks in plumbing
- □ Moisture condensation
- Visible stains or water damage
- None

124c. Are any of the following found in/or around other areas (check all that apply)?

- □ Active leaks in roof
- □ Active leaks in plumbing
- Moisture condensation
- Visible stains or water damage
- None

Indoor Air Quality

Page Last Modified: 02/27/2025

125. Ventilation: fresh air intake locations, air filters, etc. (H)

125a. Are fresh air intakes near the bus loading, truck delivery, or garbage storage/disposal areas?

□ Yes

🗹 No

125b. Is there accumulated dirt, dust or debris around fresh air intakes?

□ Yes

🗹 No

125c. Are fresh air intakes free of blockage?

☑ Yes

□ No

125d. Is accumulated dirt, dust or debris in ductwork?

□ Yes

🗹 No

125e. Are dampers functioning as designed?

☑ Yes

□ No

125f. Condition of air filters:

☑ Good

□ Fair

□ Poor

125g. Outside air is adequate for occupant load:

☑ Yes

□ No

125h. Rating of ventilation/indoor air quality:

☑ Good

Fair

D Poor

125i. Comments:

(No Response)

126. Indoor Air Quality (IAQ) Plan (H)

126a. Does the school district use EPA's Tools for Schools program?

☑ Yes

Indoor Air Quality

Page Last Modified: 02/27/2025

□ No	
	126b. If No, is some other IAQ management plan used? □ Yes ☑ No
	126c. Has the District assigned IAQ responsibilities to a designated individual? □ Yes
	 ☑ No 126c.1 If Yes, what is their job title? Facilities Administrator
127. Does t ☑ Yes □ No	he school practice Integrated Pest Management (IPM)? (H)
	127a. Is vegetation kept one foot away from the building? □ Yes ☑ No
	 127b. Are crevices and holes in walls, floors and pavement sealed or eliminated? ☑ Yes ☑ No
	127c. Is there a certified pesticide applicator on staff? □ Yes ☑ No
	127d. Are pesticides used in the building? □ Yes ☑ No
	127d.1 If Yes, how are they typically applied?
	 Spot treatment Area wide treatments 1276 Area posticides used on the grounds?
	127e. Are pesticides used on the grounds? □ Yes ☑ No
	127e.1 If Yes, was an emergency exemption granted by the Board of Education?

Indoor Air Quality

Page Last Modified: 02/27/2025

□ No

128. Does the school have a passive radon mitigation system installed (was built with radon resistant features)?
(H)
□ Yes
⊠ No

128a. Has the facility been tested for the presence of radon?□ Yes

🗹 No

128b. Were any of the results of the test greater than or equal to 4 picocuries per liter (pCi/L)?

- □ Yes
- 🗹 No

128c. If Yes, did the school take steps to mitigate the elevated radon levels?

- □ Yes, active mitigation system installed
- □ Yes, passive mitigation system made active
- □ Yes, ventilation controls (HVAC) adjusted
- □ Yes, other (describe)
- No action taken

128c.1 Describe other actions taken to mitigate elevated radon levels:

Emergency Shelter

Page Last Modified: 08/22/2024

Emergency Shelter

129. Does this building serve as an emergency shelter?

□ Yes

⊠ No

130. List the district's occupied buildings which require the BCS (No Response)