

HP Chromebook Fortis G10

Part	Description	Cost for HP Part
AC Adapter/Power Cord	Missing/Damaged	\$25.39
Screen	Damaged	\$29.79
Motherboard	Damaged	\$307.09
Battery	Damaged	\$44.29
Bottom Cover	Damaged	\$30.29
Back Cover (lid)	Damaged	\$32.39
Chromebook Replacement	Damaged	
GumDrop Slim Tech Case	Damaged	
Display Bezel	Damaged	\$19.79
Palmrest w/ Keyboard	Damaged	\$51.29
Hinge Cover	Damaged	
Speaker Set	Damaged	\$2.99
USB-C Port/Daughter Board	Damaged	\$32.99
Touchpad	Damaged	\$26.39
Hinge Set	Damaged	\$9.69
Camera	Damaged	\$2.99