

HP Chromebook Fortis G10

Part	Description	Cost for HP Part
AC Adapter/Power Cord	Missing/Damaged	\$27.59
Screen	Damaged	\$27.59
Motherboard	Damaged	\$307.09
Battery	Damaged	\$39.79
Bottom Cover	Damaged	\$24.49
Back Cover (lid)	Damaged	\$30.59
Chromebook Replacement	Damaged	\$349.00
GumDrop Slim Tech Case	Damaged	\$29.00
Display Bezel	Damaged	\$19.49
Palmrest w/ Keyboard	Damaged	\$46.69
Hinge Cover	Damaged	
Speaker Set	Damaged	\$2.99
USB-C Port/Daughter Board	Damaged	\$32.99
Touchpad	Damaged	\$21.99
Hinge Set	Damaged	\$10.19
Camera	Damaged	\$2.99