Longwood Central School District

Districtwide Lead in Drinking Water Sampling and Remediation Plan

June 2020
(Updated January 18, 2021)

ENVIROSCIENCE
CONSULTANTS INC.

2150 Smithtown Avenue
Ronkonkoma, NY 11779
(631) 580-3191
www.envirohealth.org

Project #19722

Districtwide Lead in Drinking Water Sampling and Remediation Plan

Performed for:

Longwood Central School District
21 Everett Drive
Yaphank, NY 11980

June 2020

Prepared by:

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779
(631) 580-3191

Project #19722

President

Glenn Neuschwender

ENVIROSCIENCE
CONSULTANTS INC.

Table of Contents

I. Executive Summary

II. Sampling Methodology

III. Initial Results

Appendix A – Charles E. Walters Primary School

Appendix B – Charles E. Walters Intermediate School

Appendix C – Coram Primary School

Appendix D – Coram Intermediate School

Appendix E– Ridge Primary School

Appendix F – Ridge Intermediate School

Appendix G – West Middle Island Primary School

Appendix H – West Middle Island Intermediate School

Appendix I – Longwood Middle School

Appendix J – Longwood Junior School

Appendix K – Longwood High School

Appendix L – Longwood Career Center

June 23, 2020

Steven Harding
Longwood Central School District
21 Everett Drive
Yaphank, NY 11980

I. Executive Summary

Longwood CDS has developed their 2020 Lead in Drinking Water Sampling and Analysis Program, as required by the New York State Department of Health (Public Health Law Sections 1370-a and 1110, Subpart 67-4 Lead Testing in School Drinking Water).

In accordance with the regulation, this Lead Remediation Plan is prepared to identify locations deemed as Applicable Drinking Water Sources and report first draw sample results, to mitigate locations where sample results exceed 15 parts per billion, to identify locations deemed as Non-Applicable Water Sources, communicate this designation to building occupants, and to develop strategies for monitoring locations deemed Non-Applicable Water Sources to insure building occupants do not consume water from these locations.

The following locations within the Longwood Central School District buildings have been deemed Applicable Drinking Water Sources by the administration:

1) Water fountains and bottle filling stations;
2) Kitchen water faucets and pot fillers used in food preparation;
3) Ice machines
4) Elementary grade classroom sinks
5) Home Economics classroom sinks
6) Nurse's Office and Faculty Room sinks

First draw samples were collected from each of these locations within the District, and analyzed by a New York State Department of Health ELAP certified laboratory. The chains of custody are available upon request. For results at or below 15 ppb, no further action is required until 2025. For locations above 15 ppb, options include: second and third draw sample collection to determine source of lead, designation of the location as Non-applicable Water Source, or permanent removal of the fixture from the location. In either case, the result was communicated by Enviroscience Consultants, and the fixture was shut off by the District immediately upon receipt of results.

The following locations within the Longwood district buildings were deemed Non-Applicable Water Sources by the administration:

1) Science Laboratory sinks
2) Art Room sinks
3) Technical Classroom sinks
4) Bathroom sinks
5) Outside spigots
6) Custodial Closet sinks

In these cases, the Longwood staff have placed signs adjacent to the fixture to notify occupants that the water is not intended for consumption. To further support this protocol, the following management of the locations is required:

1) Science Laboratory sinks - communicate in writing with students that these locations are for science experiments and hand washing only, not for consumption. This is most easily accomplished by including this language in the laboratory safety paperwork distributed to students at the beginning of the school year. This program should be monitored by the respective science teachers, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.
2) Art Room sinks - communicate in writing to students that these locations are for cleaning of art supplies and hand washing only, not for consumption. This is most easily accomplished by including this language in the course paperwork distributed to students at the beginning of the school year. This program should be monitored by the respective art teachers, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.
3) Other classroom sinks - classrooms in this category often include elementary classrooms, where students are to hand wash after bathroom usage or activities as part of a regular hygiene program. This program should be monitored by teachers and staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.
4) Bathroom sinks - in intermediate buildings, signage should be sufficient for communicating the concept of hand washing only. In elementary schools, personal hygiene should be integrated into curriculum to ensure students understand bathroom sinks are for hand washing only, and not consumption. Further, show what the signage looks like in bathrooms so they learn to recognize its meaning. This program should be monitored by teachers and staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.
5) Outside spigots - all-weather signage will be installed at each location. Further, spigots will have a special key maintained by the custodial staff to ensure that non-authorized persons do not fill sports coolers or use hoses for consumption. This program should be monitored by custodial staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.
6) Custodial Closet sinks - these locations should be accessed by custodial personnel only, and locked when not in use. Access to others should be restricted. This program should be monitored by custodial staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.

II. Sampling Methodology

In accordance with the regulation, Enviroscience Consultants, Inc. performed initial water sampling throughout the Longwood CSD from May 27-29, 2020. Samples were collected in wide-mouth 250 milliliter containers and were collected in the morning hours before the facilities opened. The water sources were not used for at least 8 hours and not more that 18 hours prior to sampling. Unique source numbers and designations were assigned to each source location. Unique sample identification numbers were assigned to each sample taken. The key to fixture type codes and the sampling location schematics are shown below.

Fixture Type Codes

BF Bottle Filler
HB Hose Bib
IM Ice Machine
OS Other Source
PF Pot Filler
SK Sink
SL Supply Line
SP Spigot
SPY Spray
SS Slop Sink
V Valve
WC Water Cooler
WF Water Fountain

Source Designations

App Applicable
N/A Non-applicable

Sampling Location Schematics

KITCHEN DIAGRAM



SAMPLE IDENTIFICATION (example)

LOCATION	SOURCE
Kitchen Dishwash Station @ (A)	SK
Kitchen Dishwash Station @ (B)	SK
Kitchen Dishwasher	SPRAY
Prep. Sink @ (A)	SK
Prep. Sink @ (B)	SK
Kitchen Hand Wash @ (A)	SK
Kitchen Hand Wash @ (B)	SK
Kitchen Pot Filler	SK

HOME ECONOMICS / CAREER DIAGRAM



SAMPLE IDENTIFICATION (example)

LOCATION	SOURCE
Career RM - Station 1	SK
Career RM - Station 2	SK
Career RM - Station 3	SK
Career RM - Station 4	SK
Career RM - Island	SK

GANG BATHROOM DIAGRAM



SAMPLE IDENTIFICATION (example)

LOCATION	SOURCE
Girl's BR @ (A)	SK
Girl's BR @ (B)	SK
Boy's BR @ (A)	SK
Boy's BR @ (B)	SK

SCIENCE ROOM TYPE 1 DIAGRAM



SAMPLE IDENTIFICATION (example)

LOCATION	SOURCE
Room 200 - Teacher Station	SK
Room 200 - Counter 1 @ (A)	SK
Room 200 - Counter 1 @ (B)	SK
Room 200 - Counter 2 @ (A)	SK
Room 200 - Counter 2 @ (B)	SK
Room 200 - Counter 3 @ (A)	SK
Room 200 - Counter 3 @ (B)	SK

SCIENCE ROOM TYPE 2 DIAGRAM



SAMPLE IDENTIFICATION (example)

LOCATION	SOURCE
Room 200 - Teacher Station	SK
Room 200 - Table 1 @ (A)	SK
Room 200 - Table 1 @ (B)	SK
Room 200 - Table 2 @ (A)	SK
Room 200 - Table 2 @ (B)	SK
Room 200 - Table 3 @ (A)	SK
Room 200 - Table 3 @ (B)	SK
Room 200 - Table 4 @ (A)	SK
Room 200 - Table 4 @ (B)	SK
Room 200 - Counter 1 @ (A)	SK
Room 200 - Counter 1 @ (B)	SK
Room 200 - Counter 1 @ (C)	SK
Room 200 - Counter 2 @ (A)	SK
Room 200 - Counter 2 @ (B)	SK
Room 200 - Counter 2 @ (C)	SK

SCIENCE ROOM TYPE 3 DIAGRAM



SAMPLE IDENTIFICATION (example)

LOCATION	SOURCE
Room 200 - Teacher Station	SK
Room 200 - POD 1 @ (A)	SK
Room 200 - POD 1 @ (B)	SK
Room 200 - POD 1 @ (C)	SK
Room 200 - POD 1 @ (D)	SK
Room 200 - POD 1 @ (E)	SK
Room 200 - POD 1 @ (F)	SK
Room 200 - POD 2 @ (A)	SK
Room 200 - POD 2 @ (B)	SK
Room 200 - POD 2 @ (C)	SK
Room 200 - POD 2 @ (D)	SK
Room 200 - POD 2 @ (E)	SK
Room 200 - POD 2 @ (F)	SK
Room 200 - POD 3 @ (A)	SK
Room 200 - POD 3 @ (B)	SK
Room 200 - POD 3 @ (C)	SK
Room 200 - POD 3 @ (D)	SK
Room 200 - POD 3 @ (E)	SK
Room 200 - POD 3 @ (F)	SK

III. Initial Results:

All water source locations in each of the school buildings were assessed**.** Water source locations identified as drinking water sources were considered Applicable, and first draw samples were collected. Water source locations identified as non-drinking water sources were considered Non-applicable and these locations were documented.

The results of the initial sampling and the use of signs warning against water use at Non-applicable sources is documented in the School Water Outlet Inventory for each building (Appendix A through L).

All elevated locations should be taken off line until the remediation is completed. Any other drinking water sources in these buildings that were not functional at the time of initial sampling and have not been tested should be tested. All locations deemed non-applicable, but do not have signs, should be taken off line until signs have been posted.

The following is a summary of results in parts per billion (ppb) of locations where sample results were found above 15 ppb:

Charles E. Walters Primary School

Kitchen 3-Bay @ A	SK	47
Kitchen 3-Bay @ B	SPY	21.8
Hall by Room 555 (right)	WF	27.3
Main Office Break Room	SK	60.2

Charles E. Walters Intermediate School

Hall by Room 201	WF	32.8
Art Room 108 Counter 1	SK	17

Coram Primary School

No Exceedances

Coram Intermediate School

No Exceedances

Ridge Primary School

Kitchen Sink by Entrance	SK	32.6
Kitchen Bathroom	SK	32.5
Room B133 Bathroom	SK	20.1

Ridge Intermediate School

Physical Education Office-Simonton	SK	30.4
Physical Education Office - Glowington	SK	109

West Middle Island Primary School

Girls Locker Room Office Bathroom	SK	80.9
Kitchen 3-Bay	SK	38.1
Kitchen 3-Bay	SPY	16.4

West Middle Island Intermediate School

No Exceedances

Longwood Middle School

No Exceedances		

Longwood Junior High School

Prep Room 1403/1401 @ A	SK	16.2
Prep Room 1413 @ A	SK	41.8
Prep Room 1413 @ B	SK	38.8
Prep Room 1414 @ A	SK	32.2
Prep Room 1414 @ B	SK	84

Longwood High School

Room 1715 Counter @ A	SK	99
Room 1715 Counter @ B	SK	42.1
Room 1715 Counter @ C	SK	19.3
Nurse's Office Exam Room 1	SK	43.5
Nurse's Office Exam Room 2	SK	15.5
Nurse's Office Bathroom 1	SK	29.1
Hall by 1614	WF	16
2nd Floor Cafeteria (right)	WF	64.5
Hall by 2705	WF	33.5
Room 2600/2604 Office @ B	SK	20.7
Room 2612/2616 Office	SK	44

Longwood Career Center

Housekeeping Training Room	SK	32.4

Appendix A

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Kitchen 3-Bay @ A	SK	App	47	5/28/2020				Additional Sampling Required	Fixture Replacement	<1.0	10/7/2020
1001-2	Kitchen 3-Bay @ B	SPY	App	21.8	5/28/2020				Additional Sampling Required	Fixture Replacement	<1.0	10/7/2020
1001-3	Kitchen Handwash	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1001-4	Kitchen Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1001-5	Kitchen Handwash by door	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1002-1	Boy's Bathroom by Kitchen @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1002-2	Boy's Bathroom by Kitchen @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1003-1	Girl's Bathroom by Kitchen @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1003-2	Girl's Bathroom by Kitchen @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1004-1	Room 548	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1005-1	Room 550	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1006-1	Room 552	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1007-1	Room 551	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1008-1	Room 554	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1009-1	Room 553	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1010-1	Hall by Room 555 (left)	WF	App	8.78	5/28/2020	-	-	-	None	-	-	-
1010-2	Hall by Room 555 (right)	WF	App	27.3	5/28/2020				Additional Sampling Required	Removed from Service		
1011-1	Room 555 Birdbath	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1012-1	Boy's Bathroom by Room 555 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1012-2	Boy's Bathroom by Room 555 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1012-3	Boy's Bathroom by Room 555 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1012-4	Boy's Bathroom by Room 555 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1013-1	Custodial Closet by Room 555	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1014-1	Girl's Bathroom by Room 555 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1014-2	Girl's Bathroom by Room 555 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1014-3	Girl's Bathroom by Room 555 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1014-4	Girl's Bathroom by Room 555 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1015-1	Adult Bathroom (left) by Room 555	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1016-1	Adult Bathroom (right) by Room 555	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1017-1	Room 423	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1018-1	Room 425	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1019-1	Room 428	WF	App	11.7	5/28/2020	-	-	-	None	-	-	-
1019-2	Room 428	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1019-3	Room 428 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-1	Room 426	WF	App	3	5/28/2020	-	-	-	None	-	-	-
1020-2	Room 426	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-3	Room 426 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1021-1	Room 421	WF	App	3.14	5/28/2020	-	-	-	None	-	-	-
1022-1	Room 422	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1022-2	Room 422	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1022-3	Room 422 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-1	Room 419	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1024-1	Room 420	WF	App	4.21	5/28/2020	-	-	-	None	-	-	-
1024-2	Room 420	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1024-3	Room 420 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-1	Room 418	WF	App	2.86	5/28/2020	-	-	-	None	-	-	-
1025-2	Room 418	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-3	Room 418 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1026-1	Library Office	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1027-1	Hall by Library	WF	App		5/28/2020	-	-	-	None	Removed from Service	-	-
1027-2	Hall by Library	BF	App	<1.0	10/7/2020	-	-	-	None	-	-	-
1028-1	Boy's Bathroom by Room 406 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1028-2	Boy's Bathroom by Room 406 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1028-3	Boy's Bathroom by Room 406 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1028-4	Boy's Bathroom by Room 406 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-1	Girl's Bathroom by Room 406 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-2	Girl's Bathroom by Room 406 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-3	Girl's Bathroom by Room 406 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-4	Girl's Bathroom by Room 406 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-1	Custodial Closet by Room 403	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1031-1	Room 407	WF	App	3.59	5/28/2020	-	-	-	None	-	-	-
1031-2	Room 407	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1031-3	Room 407 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1032-1	Room 406	WF	App	1.61	5/28/2020	-	-	-	None	-	-	-
1032-2	Room 406	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1032-3	Room 406 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-1	Room 409	WF	App	4.28	5/28/2020	-	-	-	None	-	-	-
1033-2	Room 409	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-3	Room 409 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1034-1	Room 408	WF	App	3.49	5/28/2020	-	-	-	None	-	-	-
1034-2	Room 408	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1034-3	Room 408 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-1	Room 411	WF	App	3.85	5/28/2020	-	-	-	None	-	-	-
1035-2	Room 411	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-3	Room 411 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1036-1	Room 410	WF	App	1.5	5/28/2020	-	-	-	None	-	-	-
1036-2	Room 410	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1036-3	Room 410 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1037-1	Nurse's Office	WF	App	6.07	5/28/2020	-	-	-	None	-	-	-
1037-2	Nurse's Office	SK	App	14.1	5/28/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1037-3	Nurse's Office Bathroom	SK	App	5.52	5/28/2020	-	-	-	None	-	-	-
1038-1	Adult Bathroom by Main Office	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1039-1	Girl's Bathroom by Main Office @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1039-2	Girl's Bathroom by Main Office @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1039-3	Girl's Bathroom by Main Office @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1040-1	Boy's Bathroom by Main Office @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1040-2	Boy's Bathroom by Main Office @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1040-3	Boy's Bathroom by Main Office @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1041-1	Custodial Closet by Main Office	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1042-1	Main Office Break Room	SK	App	60.2	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1043-1	Custodial Closet by Room 515	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1044-1	Boy's Bathroom by Room 515 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1044-2	Boy's Bathroom by Room 515 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1045-1	Girl's Bathroom by Room 515 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1045-2	Girl's Bathroom by Room 515 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1046-1	Hall by Faculty Room	WF	App	6.08	5/28/2020	-	-	-	None	-	-	-
1047-1	Faculty Room	SK	App	4.2	5/28/2020	-	-	-	None	-	-	-
1048-1	Room 527	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1049-1	Room 525	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1050-1	Room 523	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1051-1	Room 521	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1052-1	Room 520	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1053-1	Room 522	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2201957-14572

June 4, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Charles E Walters Primary

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on June 02, 2020. New York Environmental analyzed the samples on June 03, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

Date Collected:	28 May 2020
Date Received:	02 Jun 2020
Date Analyzed:	03 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200602M022	1	Kitchen 3-Bay @ A-SK; Initial	1.00	47.0	µg/L	H
200602M023	2	Kitchen 3-Bay @ B-SPY; Initial	1.00	21.8	µg/L	H
200602M024	3	Hall by Room 555 (left)-WF; Initial	1.00	8.78	µg/L	
200602M025	4	Hall by Room 555 (right)-WF; Initial	1.00	27.3	µg/L	H
200602M026	5	Room 428-WF; Initial	1.00	11.7	µg/L	
200602M027	6	Room 426-WF; Initial	1.00	3.00	µg/L	
200602M028	7	Room 421-WF; Initial	1.00	3.14	µg/L	
200602M029	8	Room 420-WF; Initial	1.00	4.21	µg/L	
200602M030	9	Room 418-WF; Initial	1.00	2.86	µg/L	
200602M031	10	Room 407-WF; Initial	1.00	3.59	µg/L	
200602M032	11	Room 406-WF; Initial	1.00	1.61	µg/L	
200602M033	12	Room 409-WF; Initial	1.00	4.28	µg/L	
200602M034	13	Room 408-WF; Initial	1.00	3.49	µg/L	
200602M035	14	Room 411-WF; Initial	1.00	3.85	µg/L	
200602M036	15	Room 410-WF; Initial	1.00	1.50	µg/L	
200602M037	16	Nurse's Office-WF; Initial	1.00	6.07	µg/L	
200602M038	17	Nurse's Office-SK; Initial	1.00	14.1	µg/L	
200602M039	18	Nurse's Office Bathroom-SK; Initial	1.00	5.52	µg/L	
200602M040	19	Main Office Break Room-SK; Initial	1.00	60.2	µg/L	E,H
200602M041	20	Hall by Faculty Room-WF; Initial	1.00	6.08	µg/L	
200602M042	21	Faculty Room-SK; Initial	1.00	4.20	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2204106-15844

October 12, 2020

Project Manager
Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Charles E. Walters Primary

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on October 09, 2020. New York Environmental analyzed the samples on October 12, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYE Report #: 2204106-15844

Date Collected:	07 Oct 2020
Date Received:	09 Oct 2020
Date Analyzed:	12 Oct 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201009Q010	1	Kitchen 3-Bay @ A-SK, Initial	1.00	<1.00	µg/L	
201009Q011	2	Kitchen 3-Bay @ B-SPY, Initial	1.00	<1.00	µg/L	
201009Q012	3	Hall by Library-BF, Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

Appendix B

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Kitchen 3-Bay @ A	SK	App	2.58	5/28/2020	-	-	-	None	-	-	-
1001-2	Kitchen 3-Bay @ B	SK	App	9.53	5/28/2020	-	-	-	None	-	-	-
1001-3	Kitchen Handwash	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1002-1	Boy's Bathroom by Kitchen @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1002-2	Boy's Bathroom by Kitchen @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1003-1	Girl's Bathroom by Kitchen @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1003-2	Girl's Bathroom by Kitchen @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1004-1	Room 218	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1005-1	Room 211	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1006-1	Room 217	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1007-1	Room 212	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1008-1	Room 216	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1009-1	Room 213	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1010-1	Room 214	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1011-1	Room 215	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1012-1	Adult Bathroom by Faculty Room	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1013-1	Hall by Faculty Room	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1014-1	Faculty Room	SK	App	5.22	5/28/2020	-	-	-	None	-	-	-
1015-1	Custodial Office Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1016-1	Room 202	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1017-1	Hall by 201	WF	App	32.8	5/28/2020	-	-	-	Additional Sampling Required	Removed form Service	-	-
1017-1	Hall by 201	BF	App	2.71	10/7/2020	-	-	-	None	-	-	-
1018-1	Room 201	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1019-1	Boy's Bathroom by 201 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1019-2	Boy's Bathroom by 201 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-1	Women's Bathroom by 210 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-2	Women's Bathroom by 210 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-3	Women's Bathroom by 210 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1021-1	Art Room 108 Counter 1	SK	N/A	17	5/28/2020				Additional Sampling Required	Sign		
1021-2	Art Room Counter 2	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1021-3	Art Room 108 Unit 1 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1021-4	Art Room 108 Unit 1 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1021-5	Art Room 108 Unit 2 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1021-6	Art Room 108 Unit 2 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1021-7	Art Room 108 Unit 3 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1021-8	Art Room 108 Unit 3 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1022-1	Nurse's Office	SK	App	5.75	5/28/2020	-	-	-	None	-	-	-
1022-2	Nurse's Office Bathroom	SK	App	1.53	5/28/2020	-	-	-	None	-	-	-
1023-1	Library Office	SK	App	14.6	5/28/2020	-	-	-	None	-	-	-
1024-1	Room 128	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1025-1	Hall by Room 116	WF	App	5.8	5/28/2020	-	-	-	None	-	-	-
1026-1	Girl's Bathroom by Room 116 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1026-2	Girl's Bathroom by Room 116 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1026-3	Girl's Bathroom by Room 116 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1027-1	Boy's Bathroom by Room 116 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1027-2	Boy's Bathroom by Room 116 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1027-3	Boy's Bathroom by Room 116 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1028-1	Room 117	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-1	Room 118	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-1	Room 119	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1031-1	Room 120	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1032-1	Women's Bathroom by Room 120 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1032-2	Women's Bathroom by Room 120 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-1	Girl's Old Locker Room Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1034-1	Boy's Old Locker Room Bathroom	SK	App	3.18	5/28/2020	-	-	-	None	-	-	-
1035-1	Men's Bathroom by Room 120	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1036-1	Hall by Multipurpose Room	WF	App	3.17	5/28/2020	-	-	-	None	-	-	-
1037-1	Room 308	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1038-1	Room 313	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1039-1	Room 314	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1040-1	Room 307	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1041-1	Room 306	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1042-1	Room 315	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1043-1	Room 316	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1044-1	Room 305	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1045-1	Room 304	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1046-1	Room 317	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1047-1	Room 318	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1048-1	Room 303	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1049-1	Boy's Bathroom by Room 303 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1049-2	Boy's Bathroom by Room 303 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1049-3	Boy's Bathroom by Room 303 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1049-4	Boy's Bathroom by Room 303 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1050-1	Adult Bathroom by Room 303 (left)	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1051-1	Adult Bathroom by Room 303 (right)	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1052-1	Girl's Bathroom by Room 303 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1052-2	Girl's Bathroom by Room 303 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1052-3	Girl's Bathroom by Room 303 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1052-4	Girl's Bathroom by Room 303 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1054-1	Room 324	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1055-1	Room 325	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1056-1	Room 300	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1057-1	Room 301	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1058-1	Hall by 301	WF	App	11.5	5/28/2020	-	-	-	None	-	-	-
1059-1	Principal's Office Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1060-1	Main Office Breakroom	SK	App	9.38	5/28/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2201956-14571

June 4, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Charles E Walters Intermediate

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on June 02, 2020. New York Environmental analyzed the samples on June 03, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYE Report #: 2201956-14571

Date Collected:	28 May 2020
Date Received:	02 Jun 2020
Date Analyzed:	03 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200602M008	1	Kitchen 3-Bay @ A-SK; Initial	1.00	2.58	µg/L	
200602M009	2	Kitchen 3-Bay @ B-SK; Initial	1.00	9.53	µg/L	
200602M010	3	Hall by Faculty Room-WF; Initial	1.00	<1.00	µg/L	
200602M011	4	Faculty Room-SK; Initial	1.00	5.22	µg/L	
200602M012	5	Hall by 201-WF; Initial	1.00	32.8	µg/L	H
200602M013	6	Art Room 108 Counter 1-SK; Initial	1.00	17.0	µg/L	H
200602M014	7	Nurse's Office-SK; Initial	1.00	5.75	µg/L	
200602M015	8	Nurse's Office Bathroom-SK; Initial	1.00	1.53	µg/L	
200602M016	9	Library Office-SK; Initial	1.00	14.6	µg/L	
200602M017	10	Girl's Bathroom by Room 116 @ A-SK; Initial	1.00	5.80	µg/L	
200602M018	11	Boy's Old Locker Room Bathroom-SK; Initial	1.00	3.18	µg/L	
200602M019	12	Hall by Multipurpose Room-WF; Initial	1.00	3.17	µg/L	
200602M020	13	Hall by 301-WF; Initial	1.00	11.5	µg/L	
200602M021	14	Main Office Breakroom-SK; Initial	1.00	9.38	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

H: Sample result exceeds applicable regulatory limit.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2204107-15845

October 12, 2020

Project Manager
Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Charles E. Walters Intermediate

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on October 09, 2020. New York Environmental analyzed the samples on October 12, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYE Report #: 2204107-15845

Date Collected:	07 Oct 2020
Date Received:	09 Oct 2020
Date Analyzed:	12 Oct 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201009Q013	1	Hall by 201-BF, Initial	1.00	2.71	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

Appendix C

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Kitchen 3-Bay @ A	SPY	App	10.4	5/28/2020	-	-	-	None	-	-	-
1001-2	Kitchen 3-Bay @ B	SK	App	11.3	5/28/2020	-	-	-	None	-	-	-
1001-3	Kitchen Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1001-4	Kitchen Handwash	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1002-1	Women's Bathroom 515	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1003-1	Men's Bathroom 514	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1004-1	Hall by Room 512 (left)	WF	App	2.2	5/28/2020	-	-	-	None	-	-	-
1004-2	Hall by Room 512 (right)	WF	App	1.98	5/28/2020	-	-	-	None	-	-	-
1005-1	Faculty Room	SK	App	9.12	5/28/2020	-	-	-	None	-	-	-
1006-1	Nurse's Office	SK	App	2.11	5/28/2020	-	-	-	None	-	-	-
1006-2	Nurse's Office Bathroom	SK	App	5.07	5/28/2020	-	-	-	None	-	-	-
1007-1	Room 507	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1009-1	Room 505	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1010-1	Room 504	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1011-1	Assistant Principal's Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1012-1	Girl's Bathroom 509 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1012-2	Girl's Bathroom 509 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1013-1	Boy's Bathroom 510 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1013-2	Boy's Bathroom 510 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1014-1	Custodial Closet 584	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1015-1	Adult Bathroom 574	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1016-1	Adult Bathroom 575	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1017-1	Hall by Room 575 (left)	WF	App	1.45	5/28/2020	-	-	-	None	-	-	-
1017-2	Hall by Room 575 (right)	WF	App	1.77	5/28/2020	-	-	-	None	-	-	-
1018-1	Girl's Bathroom by 576 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1018-2	Girl's Bathroom by 576 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1018-3	Girl's Bathroom by 576 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1019-1	Boy's Bathroom by 576 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1019-2	Boy's Bathroom by 576 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1019-3	Boy's Bathroom by 576 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-1	Custodial Closet 576-C	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1021-1	Room 572	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1022-1	Room 571	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-1	Hall by 563 (left)	WF	App	1.85	5/28/2020	-	-	-	None	-	-	-
1023-2	Hall by 563 (right)	WF	App	1.83	5/28/2020	-	-	-	None	-	-	-
1024-1	Girl's Bathroom 560 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1024-2	Girl's Bathroom 560 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1024-3	Girl's Bathroom 560 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-1	Boy's Bathroom 559 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-2	Boy's Bathroom 559 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1025-3	Boy's Bathroom 559 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1026-1	Custodial Closet 559-C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1027-1	Room 558	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1028-1	Room 557	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-1	Room 556	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-2	Room 556 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-1	Room 555	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-2	Room 555 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-1	Room 554	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1031-1	Room 554 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1031-2	Room 550	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1032-1	Room 550	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1032-2	Room 550 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-1	Room 549	WF	App	1.48	5/28/2020	-	-	-	None	-	-	-
1033-2	Room 549	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-3	Room 549 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1034-1	Room 548	WF	App	1.61	5/28/2020	-	-	-	None	-	-	-
1034-2	Room 548	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1034-3	Room 548 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-1	Room 547	WF	App	1.09	5/28/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1035-2	Room 547	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-3	Room 547 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1036-1	Room 546	WF	App	1.51	5/28/2020	-	-	-	None	-	-	-
1036-2	Room 546	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1036-3	Room 546 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1037-1	Room 545	WF	App	1.44	5/28/2020	-	-	-	None	-	-	-
1037-2	Room 545	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1037-3	Room 545 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1038-1	Room 544	WF	App	1.24	5/28/2020	-	-	-	None	-	-	-
1038-2	Room 544	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1038-3	Room 544 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1039-1	Room 543	WF	App	1.28	5/28/2020	-	-	-	None	-	-	-
1039-2	Room 543	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1039-3	Room 543 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1040-1	Girl's Bathroom 532 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1040-2	Girl's Bathroom 532 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1040-3	Girl's Bathroom 532 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1041-1	Boy's Bathroom 530 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1041-2	Boy's Bathroom 530 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1042-3	Boy's Bathroom 530 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1043-1	Adult Bathroom 534	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1044-1	Hall by Room 534 (left)	WF	App	1.04	5/28/2020	-	-	-	None	-	-	-
1044-2	Hall by Room 534 (right)	WF	App	1.18	5/28/2020	-	-	-	None	-	-	-
1045-1	Room 526	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1046-1	Room 538	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1047-1	Room 540	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1048-1	Room 542	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1049-1	Room 541	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1050-1	Room 536	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1051-1	Room 537	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1052-1	Art Room Birdbath	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1053-1	Room 527	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1054-1	Room 526	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1055-1	Room 525	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1056-1	Room 524	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1057-1	Room 523	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1058-1	Adult Bathroom 583	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1059-1	Girl's Bathroom 519 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1059-2	Girl's Bathroom 519 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1060-1	Boy's Bathroom 518 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1060-2	Boy's Bathroom 518 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1061-1	Hall by Cafeteria	WF	App		10/7/2020	-	-	-	None	removed from service	-	-
1061-2	Hall by Cafeteria	BF	App		10/7/2020	-	-	-	<1.0	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2201936-14556

June 2, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Coram Primary

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on June 01, 2020. New York Environmental analyzed the samples on June 02, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYE Report #: 2201936-14556

Date Collected:	28 May 2020
Date Received:	01 Jun 2020
Date Analyzed:	02 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200601M001	1	Kitchen 3-Bay @ A-SPY ;Initial	1.00	10.4	µg/L	
200601M002	2	Kitchen 3-Bay @ B-SK ;Initial	1.00	11.3	µg/L	
200601M003	3	Hall by Room 512 (left)-WF ;Initial	1.00	2.20	µg/L	
200601M004	4	Hall by Room 512 (right)-WF ;Initial	1.00	1.98	µg/L	
200601M005	5	Faculty Room-SK ;Initial	1.00	9.12	µg/L	
200601M006	6	Nurse's Office-SK ;Initial	1.00	2.11	µg/L	
200601M007	7	Nurse's Office Bathroom-SK ;Initial	1.00	5.07	µg/L	
200601M008	8	Hall by Room 575 (left)-WF ;Initial	1.00	1.45	µg/L	
200601M009	9	Hall by Room 575 (right)-WF ;Initial	1.00	1.77	µg/L	
200601M010	10	Hall by 563 (left)-WF ;Initial	1.00	1.85	µg/L	
200601M011	11	Hall by 563 (right)-WF ;Initial	1.00	1.83	µg/L	
200601M012	12	Room 550-WF ;Initial	1.00	<1.00	µg/L	
200601M013	13	Room 549-WF ;Initial	1.00	1.48	µg/L	
200601M014	14	Room 548-WF ;Initial	1.00	1.61	µg/L	
200601M015	15	Room 547-WF ;Initial	1.00	1.09	µg/L	
200601M016	16	Room 546-WF ;Initial	1.00	1.51	µg/L	
200601M017	17	Room 545-WF ;Initial	1.00	1.44	µg/L	
200601M018	18	Room 544-WF ;Initial	1.00	1.24	µg/L	
200601M019	19	Room 543-WF ;Initial	1.00	1.28	µg/L	
200601M020	20	Hall by Room 534 (left)-WF ;Initial	1.00	1.04	µg/L	
200601M021	21	Hall by Room 534 (right)-WF ;Initial	1.00	1.18	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2204092-15830

October 12, 2020

Project Manager
Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Coram Primary

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on October 09, 2020. New York Environmental analyzed the samples on October 10, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYE Report #: 2204092-15830

Date Collected:	07 Oct 2020
Date Received:	09 Oct 2020
Date Analyzed:	10 Oct 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201009P001	1	Hall by Cafeteria-BF, Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

Appendix D

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Kitchen 3-Bay @ A	SK	App	2.04	5/28/2020	-	-	-	None	-	-	-
1001-2	Kitchen 3-Bay @ B	SPY	App	1.46	5/28/2020	-	-	-	None	-	-	-
1001-3	Kitchen Handwash	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1001-4	Kitchen Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1002-1	Women's Staff Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1003-1	Faculty Room	SK	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1003-2	Faculty Room	SPY	App	1.02	5/28/2020	-	-	-	None	-	-	-
1004-1	Boy's Bathroom by Nurse's Office @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1004-2	Boy's Bathroom by Nurse's Office @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1004-3	Boy's Bathroom by Nurse's Office @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1005-1	Girl's Bathroom by Nurse's Office @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1005-2	Girl's Bathroom by Nurse's Office @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1006-1	Hall by Nurse's Office	WF	N/A		10/7/2020	-	-	-	None	removed from service	-	-
1006-1	Hall by Nurse's Office	BF	N/A	<1.0	10/7/2020	-	-	-	None	-	-	-
1007-1	Supply Room 123 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1008-1	Book Room 124 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1009-1	Nurse's Office	SK	App	1.8	5/28/2020	-	-	-	None	-	-	-
1009-2	Nurse's Office Bathroom	SK	App	2.13	5/28/2020	-	-	-	None	-	-	-
1010-1	Adult Bathroom by Asst Principal's Office	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1011-1	Main Office Kitchenette	SK	App	1.57	5/28/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1011-2	Main Office Kitchenette	SPY	App	6.41	5/28/2020	-	-	-	None	-	-	-
1012-1	Adult Bathroom by Lobby	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1013-1	Boy's Bathroom by Lobby	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1014-1	Custodial Closet by Lobbly	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1015-1	Girl's Bathroom by Lobby	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1016-1	Room 208	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1017-1	Room 210	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1018-1	Hall by Room 210	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1019-1	Room 212	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-1	Room 214	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1021-1	Room 215	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1022-1	Room 213	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-1	Room 209	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1024-1	Room 207	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-1	Custodial Closet by Gym	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1026-1	Boy's PE Office	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1027-1	Girl's PE Office	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1028-1	Girl's Bathroom by Room 416 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1028-2	Girl's Bathroom by Room 416 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1028-3	Girl's Bathroom by Room 416 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1028-4	Girl's Bathroom by Room 416 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1028-5	Girl's Bathroom by Room 416 @ E	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-1	Custodial Closet by Room 416	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-1	Boy's Bathroom by Room 416 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-2	Boy's Bathroom by Room 416 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-3	Boy's Bathroom by Room 416 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-4	Boy's Bathroom by Room 416 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1031-1	Room 416	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1032-1	Room 418	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-1	Room 420	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1034-1	Room 422	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-1	Room 419	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1036-1	Room 417	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1037-1	Room 411	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1038-1	Hall by 416C (left)	WF	App	5.23	5/28/2020	-	-	-	None	-	-	-
1038-2	Hall by 416C (right)	WF	App	1.84	5/28/2020	-	-	-	None	-	-	-
1039-1	Room 409	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1040-1	Room 410	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1041-1	Room 407	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1042-1	Room 408	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1043-1	Room 405	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1044-1	Room 406	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1045-1	Women's Bathroom by Room 406	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1046-1	Men's Bathroom by Room 406	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1047-1	Room 401	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1048-1	Hall by Room 314	WF	App	2.44	5/28/2020	-	-	-	None	-	-	-
1049-1	Girl's Bathroom by Room 314 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1049-2	Girl's Bathroom by Room 314 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1049-3	Girl's Bathroom by Room 314 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1050-1	Boy's Bathroom by Room 314 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1050-2	Boy's Bathroom by Room 314 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1050-3	Boy's Bathroom by Room 314 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1051-1	Art Room 314 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1051-2	Art Room 314 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1051-3	Art Room 314 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1052-1	Room 315	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1053-1	Room 316	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1054-1	Room 318	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1055-1	Room 319	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1056-1	Room 321	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1057-1	Room 323	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1058-1	Room 322	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1059-1	Room 320	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1060-1	Library Office	SK	App	1.33	5/28/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2201938-14558

June 2, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Coram Intermediate School

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on June 01, 2020. New York Environmental analyzed the samples on June 02, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYE Report #: 2201938-14558

Date Collected:	28 May 2020
Date Received:	01 Jun 2020
Date Analyzed:	02 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200601M034	1	Kitchen 3-Bay @ A-SK ;Initial	1.00	2.04	µg/L	
200601M035	2	Kitchen 3-Bay @ B-SPY ;Initial	1.00	1.46	µg/L	
200601M036	3	Faculty Room-SK ;Initial	1.00	<1.00	µg/L	
200601M037	4	Faculty Room-SPY ;Initial	1.00	1.02	µg/L	
200601M038	5	Nurse's Office-SK ;Initial	1.00	1.80	µg/L	
200601M039	6	Nurse's Office Bathroom-SK ;Initial	1.00	2.13	µg/L	
200601M040	7	Main Office Kitchenette-SK ;Initial	1.00	1.57	µg/L	
200601M041	8	Main Office Kitchenette-SPY ;Initial	1.00	6.41	µg/L	
200601M042	9	Hall by Room 210-WF ;Initial	1.00	<1.00	µg/L	
200601M043	10	Hall by 416C (left)-WF ;Initial	1.00	5.23	µg/L	
200601M044	11	Hall by 416C (right)-WF ;Initial	1.00	1.84	µg/L	
200601M045	12	Hall by Room 314-WF ;Initial	1.00	2.44	µg/L	
200601M046	13	Library Office-SK ;Initial	1.00	1.33	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2204093-15831

October 12, 2020

Project Manager
Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Coram Intermediate

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on October 09, 2020. New York Environmental analyzed the samples on October 10, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYE Report #: 2204093-15831

Date Collected:	07 Oct 2020
Date Received:	09 Oct 2020
Date Analyzed:	10 Oct 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201009P002	1	Hall by Nurse's Office-BF, Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

Appendix E

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Kitchen Handwash Sink by Entrance	SK	App	32.6	5/28/2020				Sign Required	Permanent Sign Posted		
1001-2	Kitchen 3-Bay @A	SK	App	2.4	5/28/2020	-	-	-	None	-	-	-
1001-3	Kitchen 3-Bay @B	SPY	App	4.59	5/28/2020	-	-	-	None	-	-	-
1001-4	Kitchen Handwash	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1001-5	Kitchen Bathroom	SK	App	32.5	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1002-1	Boy's Bathroom by Kitchen @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1002-2	Boy's Bathroom by Kitchen @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1003-1	Girl's Bathroom by Kitchen @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1003-2	Girl's Bathroom by Kitchen @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1004-1	Adult Bathroom (left) by Cafeteria	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1005-2	Adult Bathroom (right) by Cafeteria	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1006-1	Faculty Room	SK	App	11.4	5/28/2020	-	-	-	None	-	-	-
1007-1	Hall by Faculty Room (left)	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1007-2	Hall by Faculty Room (right)	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1008-1	**Room A148**	**SK**	**App**		**5/28/2020**	**-**	**-**	**-**	**Not accessible, sampling required**	**-**	**-**	**-**
1009-1	Room A147	SK	App	1.15	5/28/2020	-	-	-	None	-	-	-
1010-1	Room A146	SK	App	1.76	5/28/2020	-	-	-	None	-	-	-
1011-1	Room A145	SK	App	5.54	5/28/2020	-	-	-	None	-	-	-
1012-1	Room A142	SK	App	2.28	5/28/2020	-	-	-	None	-	-	-
1013-1	Room A141	SK	App	2.22	5/28/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1014-1	Room A140	SK	App	2.43	5/28/2020	-	-	-	None	-	-	-
1015-1	Girl's Bathroom by A140 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1015-2	Girl's Bathroom by A140 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1016-1	Boy's Bathroom by A140 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1016-2	Boy's Bathroom by A140 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1017-1	Hall by Gym (left)	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1017-2	Hall by Gym (right)	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1017-2	Hall by Gym	BF	App	<1.0	10/7/2020	-	-	-	None	-	-	-
1018-1	Boy's Bathroom by A130 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1018-2	Boy's Bathroom by A130 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1018-3	Boy's Bathroom by A130 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1019-1	Girl's Bathroom by A130 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1019-2	Girl's Bathroom by A130 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1019-3	Girl's Bathroom by A130 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-1	Room A121	WF	App	4	5/28/2020	-	-	-	None	-	-	-
1020-2	Room A121	SK	App	2.12	5/28/2020	-	-	-	None	-	-	-
1020-3	Room A121 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1021-1	A120	WF	App	2.47	5/28/2020	-	-	-	None	-	-	-
1021-2	A120	SK	App	1.74	5/28/2020	-	-	-	None	-	-	-
1021-3	A120 Bathroom	SK	App	2.23	5/28/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1022-1	Adult Bathroom by A120 (left)	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-1	Adult Bathroom by A120 (right)	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1024-1	Nurse's Office	WF	App	2.79	5/28/2020	-	-	-	None	-	-	-
1024-2	Nurse's Office	SK	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1024-3	Nurse's Office Bathroom	SK	App	1.3	5/28/2020	-	-	-	None	-	-	-
1025-1	Room A111	WF	App	1.95	5/28/2020	-	-	-	None	-	-	-
1025-2	Room A111	SK	App	3.34	5/28/2020	-	-	-	None	-	-	-
1025-3	Room A111 Bathroom	SK	App	4.17	5/28/2020	-	-	-	None	-	-	-
1026-1	Room A101	WF	App		5/28/2020	-	-	-	None	Removed from Service	-	-
1026-2	Room A101	SK	App	1.13	5/28/2020	-	-	-	None	-	-	-
1026-3	Room A101 Bathroom	SK	App	1.12	5/28/2020	-	-	-	None	-	-	-
1027-1	Room A102	WF	App	1.2	5/28/2020	-	-	-	None	-	-	-
1027-2	Room A102	SK	App	1.17	5/28/2020	-	-	-	None	-	-	-
1027-3	Room A102 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1028-1	Room A103	WF	App	1.3	5/28/2020	-	-	-	None	-	-	-
1028-2	Room A103	SK	App	1.17	5/28/2020	-	-	-	None	-	-	-
1028-3	Room A103 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-1	Hall by Nurse's Office (left)	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1029-2	Hall by Nurse's Office (right)	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1030-1	Library Office	SK	App	14.8	5/28/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1031-1	Room A108	WF	App		5/28/2020	-	-	-	None	Removed from Service	-	-
1031-2	Room A108	SK	App	1.7	5/28/2020	-	-	-	None	-	-	-
1031-3	Room A108 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1032-1	Room A109	WF	App	1.71	5/28/2020	-	-	-	None	-	-	-
1032-2	Room A109	SK	App	1.7	5/28/2020	-	-	-	None	-	-	-
1032-3	Room A109	SK	App	7.48	5/28/2020	-	-	-	None	-	-	-
1033-1	Room A110	WF	App	1.61	5/28/2020	-	-	-	None	-	-	-
1033-2	Room A110	SK	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1033-3	Room A110 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1034-1	Room B119	WF	App	5.07	5/28/2020	-	-	-	None	-	-	-
1034-2	Room B119	SK	App	2.49	5/28/2020	-	-	-	None	-	-	-
1034-3	Room B119 Bathroom	SK	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1035-1	Room B118	WF	App	6.33	5/28/2020	-	-	-	None	-	-	-
1035-2	Room B118	SK	App	3.89	5/28/2020	-	-	-	None	-	-	-
1035-3	Room B188 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1036-1	Boy's Bathoom by B118 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1036-2	Boy's Bathoom by B118 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1036-3	Boy's Bathoom by B118 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1036-4	Boy's Bathoom by B118 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1037-1	Girl's Bathroom by B118 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1037-2	Girl's Bathroom by B118 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1037-3	Girl's Bathroom by B118 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1037-4	Girl's Bathroom by B118 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1038-1	Custodial Closet by B118	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1039-1	Hall by B113 (left)	WF	App	7.73	5/28/2020	-	-	-	None	-	-	-
1039-2	Hall by B113 (right)	WF	App	5.55	5/28/2020	-	-	-	None	-	-	-
1040-1	Room B112	SK	App	8.76	5/28/2020	-	-	-	None	-	-	-
1041-1	Room B107	SK	App	4.88	5/28/2020	-	-	-	None	-	-	-
1042-1	Room B106	SK	App	5.87	5/28/2020	-	-	-	None	-	-	-
1043-1	Room B109 Birdbath	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1044-1	Adult Bathroom by PE Office (right)	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1045-1	Adult Bathroom by PE Office (left)	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1046-1	Room B131	SK	App	3.26	5/28/2020	-	-	-	None	-	-	-
1046-2	Room B131 Bathroom	SK	App	2.89	5/28/2020	-	-	-	None	-	-	-
1047-1	Room B132	SK	App	2.28	5/28/2020	-	-	-	None	-	-	-
1047-2	Room B132 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1048-1	Room B133	SK	App	2.22	5/28/2020	-	-	-	None	-	-	-
1048-2	Room B133 Bathroom	SK	App	20.1	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1049-1	Room B135 School Store	SK	App	7.36	5/28/2020	-	-	-	None	-	-	-
1050-1	Room B136	SK	App	4.43	5/28/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1051-1	Room B137	SK	App	2.73	5/28/2020	-	-	-	None	-	-	-
1052-1	Room B138	SK	App	9.85	5/28/2020	-	-	-	None	-	-	-
1053-1	Room B140	SK	App	12.1	5/28/2020	-	-	-	None	-	-	-
1054-1	Room B141	SK	App	2.63	5/28/2020	-	-	-	None	-	-	-
1055-1	Hall by Serving Room	WF	App	3.07	5/28/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2201941-14561

June 3, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Ridge Primary School

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on June 01, 2020. New York Environmental analyzed the samples on June 02, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

Date Collected:	28 May 2020
Date Received:	01 Jun 2020
Date Analyzed:	02 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200601M155	1	Kitchen Sink by Entrance-SK; Initial	1.00	32.6	µg/L	H
200601M156	2	Kitchen 3-Bay @A-SK; Initial	1.00	2.40	µg/L	
200601M157	3	Kitchen 3-Bay @B-SPY; Initial	1.00	4.59	µg/L	
200601M158	4	Kitchen Bathroom-SK; Initial	1.00	32.5	µg/L	H
200601M159	5	Faculty Room-SK; Initial	1.00	11.4	µg/L	
200601M160	6	Faculty Room-SPY; Initial	1.00	5.80	µg/L	
200601M161	7	Hall by Faculty Room (left)-WF; Initial	1.00	<1.00	µg/L	
200601M162	8	Hall by Faculty Room (right)-WF; Initial	1.00	<1.00	µg/L	
200601M163	9	Room A147-SK; Initial	1.00	1.15	µg/L	
200601M164	10	Room A146-SK; Initial	1.00	1.76	µg/L	
200601M165	11	Room A145-SK; Initial	1.00	5.54	µg/L	
200601M166	12	Room A142-SK; Initial	1.00	2.28	µg/L	
200601M167	13	Room A141-SK; Initial	1.00	2.22	µg/L	
200601M168	14	Room A140-SK; Initial	1.00	2.43	µg/L	
200601M169	15	Hall by Gym/A130 (left)-WF; Initial	1.00	<1.00	µg/L	
200601M170	16	Hall by Gym/A130 (right)-WF; Initial	1.00	<1.00	µg/L	
200601M171	17	Room A121-WF; Initial	1.00	4.00	µg/L	
200601M172	18	Room A121-SK; Initial	1.00	2.12	µg/L	
200601M173	19	A120-WF; Initial	1.00	2.47	µg/L	
200601M174	20	A120-SK; Initial	1.00	1.74	µg/L	
200601M175	21	A120 Bathroom-SK; Initial	1.00	2.23	µg/L	
200601M176	22	Nurse's Office-WF; Initial	1.00	2.79	µg/L	
200601M177	23	Nurse's Office-SK; Initial	1.00	<1.00	µg/L	
200601M178	24	Nurse's Office Bathroom-SK; Initial	1.00	1.30	µg/L	
200601M179	25	Room A111-WF; Initial	1.00	1.95	µg/L	
200601M180	26	Room A111-SK; Initial	1.00	3.34	µg/L	

Date Collected:	28 May 2020
Date Received:	01 Jun 2020
Date Analyzed:	02 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200601M181	27	Room A111 Bathroom-SK; Initial	1.00	4.17	µg/L	
200601M182	28	Room A101-SK; Initial	1.00	1.13	µg/L	
200601M183	29	Room A101 Bathroom-SK; Initial	1.00	1.12	µg/L	
200601M184	30	Room A102-WF; Initial	1.00	1.20	µg/L	
200601M185	31	Room A102-SK; Initial	1.00	<1.00	µg/L	
200601M186	32	Room A103-WF; Initial	1.00	1.30	µg/L	
200601M187	33	Room A103-SK; Initial	1.00	1.17	µg/L	
200601M188	34	Hall by Nurse's Office (left)-WF; Initial	1.00	<1.00	µg/L	
200601M189	35	Hall by Nurse's Office (right)-WF; Initial	1.00	<1.00	µg/L	
200601M190	36	Library Office-SK; Initial	1.00	14.8	µg/L	
200601M191	37	Room A108-SK; Initial	1.00	1.70	µg/L	
200601M192	38	Room A109 -WF; Initial	1.00	1.71	µg/L	
200601M193	39	Room A109 -SK; Initial	1.00	1.70	µg/L	
200601M194	40	Room A109 -SK; Initial	1.00	7.48	µg/L	
200601M195	41	Room A110-WF; Initial	1.00	1.61	µg/L	
200601M196	42	Room A110-SK; Initial	1.00	<1.00	µg/L	
200601M197	43	Room B119-WF; Initial	1.00	5.07	µg/L	
200601M198	44	Room B119-SK; Initial	1.00	2.49	µg/L	
200601M199	45	Room B119 Bathroom-SK; Initial	1.00	<1.00	µg/L	
200601M200	46	Room B118-WF; Initial	1.00	6.33	µg/L	
200601M201	47	Room B118-SK; Initial	1.00	3.89	µg/L	
200601M202	48	Hall by B113 (left)-WF; Initial	1.00	7.73	µg/L	
200601M203	49	Hall by B113 (right)-WF; Initial	1.00	5.55	µg/L	
200601M204	50	Room B112-SK; Initial	1.00	8.76	µg/L	
200601M205	51	Room B107-SK; Initial	1.00	4.88	µg/L	
200601M206	52	Room B106-SK; Initial	1.00	5.87	µg/L	
200601M207	53	Room B131-SK; Initial	1.00	3.26	µg/L	

Date Collected:	28 May 2020
Date Received:	01 Jun 2020
Date Analyzed:	02 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200601M208	54	Room B131 Bathroom-SK; Initial	1.00	2.89	µg/L	
200601M209	55	Room B132-SK; Initial	1.00	2.28	µg/L	
200601M210	56	Room B133-SK; Initial	1.00	2.22	µg/L	
200601M211	57	Room B133 Bathroom-SK; Initial	1.00	20.1	µg/L	H
200601M212	58	Room B135 School Store-SK; Initial	1.00	7.36	µg/L	
200601M213	59	Room B136-SK; Initial	1.00	4.43	µg/L	
200601M214	60	Room B137-SK; Initial	1.00	2.73	µg/L	
200601M215	61	Room B138-SK; Initial	1.00	9.85	µg/L	
200601M216	62	Room B140-SK; Initial	1.00	12.1	µg/L	
200601M217	63	Room B141-SK; Initial	1.00	2.63	µg/L	
200601M218	64	Hall by Serving Room-WF; Initial	1.00	3.07	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

H: Sample result exceeds applicable regulatory limit.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2204108-15846

October 12, 2020

Project Manager
Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Ridge Primary

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on October 09, 2020. New York Environmental analyzed the samples on October 12, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYE Report #: 2204108-15846

Date Collected:	07 Oct 2020
Date Received:	09 Oct 2020
Date Analyzed:	12 Oct 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201009Q014	1	Hall by Gym-BF, Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

Appendix F

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Kitchen Handwash	SK	App	6.53	5/28/2020	-	-	-	None	-	-	-
1001-2	Kitchen 3-Bay @ A	SK	App	4.54	5/28/2020	-	-	-	None	-	-	-
1001-3	Kitchen 3-Bay @ B	SK	App	7.37	5/28/2020	-	-	-	None	-	-	-
1002-1	Hall by Cafeteria	WF	App	7.45	5/28/2020	-	-	-	None	-	-	-
1003-1	Boy's Bathroom by Cafeteria @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1003-2	Boy's Bathroom by Cafeteria @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1004-1	Girl's Bathroom by Cafeteria @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1004-2	Girl's Bathroom by Cafeteria @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1005-1	Room 111	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1005-2	Room 111 Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1006-1	Custodial Closet by Cafeteria	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1007-1	Room 107	KS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1008-1	Room 108	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1009-1	Room 105	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1010-1	Room 103	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1011-1	Hall by Conference Room	WF	App	4.14	5/28/2020	-	-	-	None	-	-	-
1012-1	Adult Bathroom by Main Office	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1013-1	Nurse's Office	SK	App	4.05	5/28/2020	-	-	-	None	-	-	-
1013-2	Nurse's Office Bathroom	SK	App	14.7	5/28/2020	-	-	-	None	-	-	-
1014-1	Girl's Bathroom by Main Office @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1014-2	Girl's Bathroom by Main Office @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1014-3	Girl's Bathroom by Main Office @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1015-1	Boy's Bathroom by Main Office @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1015-2	Boy's Bathroom by Main Office @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1015-3	Boy's Bathroom by Main Office @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1016-1	Adult Bathroom by Faculty Room (left)	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1017-1	Adult Bathroom by Faculty Room (right)	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1018-1	Custodial Closet by Faculty Room	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1019-1	Faculty Room	SK	App	2.12	5/28/2020	-	-	-	None	-	-	-
1019-2	Faculty Room	SPY	App	8.29	5/28/2020	-	-	-	None	-	-	-
1020-1	Physical Education Office Simonton	SK	App	30.4	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1021-1	Hall by Gym	WF	App		5/28/2020				Additional Sampling Required	Removed from service		
1021-1	Hall by Gym	BF	App	<1.0	10/7/2020	-	-	-	None	-	-	-
1022-1	Physical Education Office Glowington	SK	App	109	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1023-1	Girl's Bathroom by Gym @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-2	Girl's Bathroom by Gym @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-3	Girl's Bathroom by Gym @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-4	Girl's Bathroom by Gym @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1024-1	Boy's Bathroom by Gym @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1024-2	Boy's Bathroom by Gym @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1024-3	Boy's Bathroom by Gym @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-1	Custodial Closet by Gym Bathrooms	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1026-1	Hall by Room 305 (left)	WF	App	1.18	5/28/2020	-	-	-	None	-	-	-
1026-2	Hall by Room 305 (right)	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1027-1	Room 400	SK	App	5.14	5/28/2020	-	-	-	None	-	-	-
1028-1	Room 401	SK	App	1.06	5/28/2020	-	-	-	None	-	-	-
1029-1	Room 403	SK	App	2.71	5/28/2020	-	-	-	None	-	-	-
1030-1	Room 402	SK	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1031-1	Room 404	SK	App	9.68	5/28/2020	-	-	-	None	-	-	-
1032-1	Room 405	SK	App	7.31	5/28/2020	-	-	-	None	-	-	-
1033-1	Room 407	SK	App	2.66	5/28/2020	-	-	-	None	-	-	-
1034-1	Girl's Bathroom by 308 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1034-2	Girl's Bathroom by 308 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1034-3	Girl's Bathroom by 308 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1034-4	Girl's Bathroom by 308 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1034-5	Girl's Bathroom by 308 @ E	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-1	Boy's Bathroom by 308 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-2	Boy's Bathroom by 308 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-3	Boy's Bathroom by 308 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-4	Boy's Bathroom by 308 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1036-1	Faculty Bathroom by 308	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1037-1	Faculty Bathroom by 313	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1038-1	Hall by 313 (left)	WF	App	1.31	5/28/2020	-	-	-	None	-	-	-
1038-2	Hall by 313 (right)	WF	App	3.94	5/28/2020	-	-	-	None	-	-	-
1039-1	Room 313	SK	App	26.6	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1040-1	Room 315	SK	App	6.22	5/28/2020	-	-	-	None	-	-	-
1041-1	Room 310	SK	App	2.85	5/28/2020	-	-	-	None	-	-	-
1042-1	Room 312	SK	App	231	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1043-1	Room 317	SK	App	27.9	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1044-1	Room 319	SK	App	23	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1045-1	Room 314	SK	App	1.94	5/28/2020	-	-	-	None	-	-	-
1046-2	Room 316	SK	App	40.9	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1047-1	Room 321	SK	App	1.74	5/28/2020	-	-	-	None	-	-	-
1048-1	Room 323	SK	App	8.32	5/28/2020	-	-	-	None	-	-	-
1049-1	Room 318	SK	App	1.73	5/28/2020	-	-	-	None	-	-	-
1050-1	Room 508	SK	App	5.27	5/28/2020	-	-	-	None	-	-	-
1051-1	Room 506	SK	App	33.1	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1052-1	Hall by Room 506	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1053-1	Library Office	SK	App	2.46	5/28/2020	-	-	-	None	-	-	-
1054-1	Custodial Office	SK	App	7.54	5/28/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1055-1	Room 210	SK	App	2.36	5/28/2020	-	-	-	None	-	-	-
1056-1	Room 211	SK	App	17.6	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1057-1	Room 204	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1058-1	Room 203	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1059-1	Hall by Room 204	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1060-1	Boy's Bathroom by 204 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1060-2	Boy's Bathroom by 204 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1060-3	Boy's Bathroom by 204 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1061-1	Girl's Bathroom by 204 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1061-2	Girl's Bathroom by 204 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1061-3	Girl's Bathroom by 204 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2201958-14573

June 4, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Ridge Intermediate School

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on June 02, 2020. New York Environmental analyzed the samples on June 03, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

Date Collected:	28 May 2020
Date Received:	02 Jun 2020
Date Analyzed:	03 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200602M043	1	Kitchen Handwash-SK; Initial	1.00	6.53	µg/L	
200602M044	2	Kitchen 3-Bay @ A-SK; Initial	1.00	4.54	µg/L	
200602M045	3	Kitchen 3-Bay @ B-SK; Initial	1.00	7.37	µg/L	
200602M046	4	Hall by Cafeteria-WF; Initial	1.00	7.45	µg/L	
200602M047	5	Hall by Conference Room-WF; Initial	1.00	4.14	µg/L	
200602M048	6	Nurse's Office-SK; Initial	1.00	4.05	µg/L	
200602M049	7	Nurse's Office Bathroom-SK; Initial	1.00	14.7	µg/L	
200602M050	8	Faculty Room-SK; Initial	1.00	2.12	µg/L	
200602M051	9	Faculty Room-SPY; Initial	1.00	8.29	µg/L	
200602M052	10	Physical Education Office Simonton-SK; Initial	1.00	30.4	µg/L	H
200602M053	11	Physical Education Office Glowington-SK; Initial	1.00	109	µg/L	E,H
200602M054	12	Hall by Room 305 (left)-WF; Initial	1.00	1.18	µg/L	
200602M055	13	Hall by Room 305 (right)-WF; Initial	1.00	<1.00	µg/L	
200602M056	14	Room 400-SK; Initial	1.00	5.14	µg/L	
200602M057	15	Room 401-SK; Initial	1.00	1.06	µg/L	
200602M058	16	Room 403-SK; Initial	1.00	2.71	µg/L	
200602M059	17	Room 402-SK; Initial	1.00	<1.00	µg/L	
200602M060	18	Room 404-SK; Initial	1.00	9.68	µg/L	
200602M061	19	Room 405-SK; Initial	1.00	7.31	µg/L	
200602M062	20	Room 407-SK; Initial	1.00	2.66	µg/L	
200602M063	21	Hall by 313 (left)-WF; Initial	1.00	1.31	µg/L	
200602M064	22	Hall by 313 (right)-WF; Initial	1.00	3.94	µg/L	
200602M065	23	Room 313-SK; Initial	1.00	26.6	µg/L	H
200602M066	24	Room 315-SK; Initial	1.00	6.22	µg/L	
200602M067	25	Room 310-SK; Initial	1.00	2.85	µg/L	
200602M068	26	Room 312-SK; Initial	1.00	231	µg/L	E,H

Date Collected:	28 May 2020
Date Received:	02 Jun 2020
Date Analyzed:	03 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200602M069	27	Room 317-SK; Initial	1.00	27.9	µg/L	H
200602M070	28	Room 319-SK; Initial	1.00	23.0	µg/L	H
200602M071	29	Room 314-SK; Initial	1.00	1.94	µg/L	
200602M072	30	Room 316-SK; Initial	1.00	40.9	µg/L	H
200602M073	31	Room 321-SK; Initial	1.00	1.74	µg/L	
200602M074	32	Room 323-SK; Initial	1.00	8.32	µg/L	
200602M075	33	Room 318-SK; Initial	1.00	1.73	µg/L	
200602M076	34	Room 508-SK; Initial	1.00	5.27	µg/L	
200602M077	35	Room 506-SK; Initial	1.00	33.1	µg/L	H
200602M078	36	Hall by Room 506-WF; Initial	1.00	<1.00	µg/L	
200602M079	37	Library Office-SK; Initial	1.00	2.46	µg/L	
200602M080	38	Custodial Office-SK; Initial	1.00	7.54	µg/L	
200602M081	39	Room 210-SK; Initial	1.00	2.36	µg/L	
200602M082	40	Room 211-SK; Initial	1.00	17.6	µg/L	H
200602M083	41	Hall by Room 204-WF; Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2204109-15847

October 12, 2020

Project Manager
Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Ridge Intermediate

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on October 09, 2020. New York Environmental analyzed the samples on October 12, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYE Report #: 2204109-15847

Date Collected:	07 Oct 2020
Date Received:	09 Oct 2020
Date Analyzed:	12 Oct 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201009Q015	1	Hall by Gym-BF, Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

Appendix G

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Hall by Room 223	WF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1002-1	Girls Locker Room	WF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1002-2	Girls Locker Room Office Bathroom	SK	App	80.9	5/27/2020				Additional Sampling Required	Permanent Sign Posted		
1002-3	Girls Locker Room Bathroom	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1003-1	Boys Locker Room	WF	App	2.21	5/27/2020	-	-	-	None	-	-	-
1003-2	Boys Locker Room Office	SK	App	8.6	5/27/2020	-	-	-	None	-	-	-
1003-3	Boys Locker Room Bathroom	SK	N/A		5/27/2020	-	-	-	None	-	-	-
1004-1	Room 121	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1005-1	Room 119	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1006-1	Room 120	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1007-1	Room 117	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1008-1	Hall by Room 117	WF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1009-1	Boys Bathroom by 116 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1009-2	Boys Bathroom by 116 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1010-1	Room 114	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1011-1	Custodial Closet by 113	SS	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1012-1	Girls Bathroom by 113 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1012-2	Girls Bathroom by 113 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1013-1	Faculty Bathroom (Left)	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1014-1	Faculty Bathroom (Right)	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1015-1	Room 110	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1016-1	Nurse's Office	SK	App	6.07	5/27/2020	-	-	-	None	-	-	-
1016-2	Nurse's Office Bathroom	SK	App	9.51	5/27/2020	-	-	-	None	-	-	-
1017-1	Room 110	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1018-1	Auditorium Bathroom	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1019-1	Faculty Room	SK	App	3.23	5/27/2020	-	-	-	None	-	-	-
1020-1	Principal's Office Bathroom	SK	N/A		5/27/2020	-	-	-	None	-	-	-
1021-1	Girls Bathroom by Main Office	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1022-1	Womens Bathroom by Main Office @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1022-2	Womens Bathroom by Main Office @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1022-3	Womens Bathroom by Main Office @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1023-1	Mens Bathroom by Main Office @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1023-2	Mens Bathroom by Main Office @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1023-3	Mens Bathroom by Main Office @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1024-1	Hall by 206	WF	App	2.2	5/27/2020	-	-	-	None	-	-	-
1025-1	Room 205	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1026-1	Room 208	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1027-1	Room 209	WF	App	1.05	5/27/2020	-	-	-	None	-	-	-
1027-2	Room 209	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1027-3	Room 209 Bathroom	SK	N/A		5/27/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1028-1	Room 211	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1029-1	Room 216	WF	App	1.15	5/27/2020	-	-	-	None	-	-	-
1029-2	Room 216	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1029-3	Room 216 Bathroom	SK	App	9.96	5/27/2020	-	-	-	None	-	-	-
1030-1	Room 218	WF	App	3.39	5/27/2020	-	-	-	None	-	-	-
1030-2	Room 218	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1030-3	Room 218 Bathroom	SK	N/A		5/27/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1031-1	Room 220	WF	App	1.45	5/27/2020	-	-	-	None	-	-	-
1031-2	Room 220	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1031-3	Room 220 Bathroom	SK	N/A		5/27/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1032-1	Room 222	WF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1032-2	Room 222	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1032-3	Room 222 Bathroom	SK	N/A		5/27/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1033-1	Room 224	WF	App	1.36	5/27/2020	-	-	-	None	-	-	-
1033-2	Room 224	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1033-3	Room 224 Bathroom	SK	N/A		5/27/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1034-1	Room 213	WF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1034-2	Room 213	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1034-3	Room 213 Bathroom	SK	N/A		5/27/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1035-1	Room 215	WF	App	2.04	5/27/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1035-2	Room 215	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1035-3	Room 215 Bathroom	SK	App	2.86	5/27/2020	-	-	-	None	-	-	-
1036-1	Room 226	WF	App	1.49	5/27/2020	-	-	-	None	-	-	-
1036-2	Room 226 Sink	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1036-3	Room 226 Bathroom	SK	N/A		5/27/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1037-1	Room 228	WF	App	1.69	5/27/2020	-	-	-	None	-	-	-
1037-2	Room 228	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1037-3	Room 228 Bathroom	SK	App	6.43	5/27/2020	-	-	-	None	-	-	-
1038-1	Room 217	WF	App	1.45	5/27/2020	-	-	-	None	-	-	-
1038-2	Room 217	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1038-3	Room 217 Bathroom	SK	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1039-1	Room 230	WF	App	1.16	5/27/2020	-	-	-	None	-	-	-
1039-2	Room 230	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1039-3	Room 230 Bathroom	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1040-1	Boys Bathroom by Room 219 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1040-2	Boys Bathroom by Room 219 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1040-3	Boys Bathroom by Room 219 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1041-1	Custodial Closet by Room 221	SS	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1042-1	Girls Bathroom by Room 223 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1042-2	Girls Bathroom by Room 223 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1042-3	Girls Bathroom by Room 223 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1043-1	Kitchen 3-Bay	SK	App	38.1	5/27/2020				Additional Sampling Required	Aerator flushed	4.83	10/7/2020
1043-2	Kitchen 3-Bay	SPY	App	16.4	5/27/2020				Additional Sampling Required	Aerator flushed	7.17	10/7/2020
1043-3	Kitchen by Oven	SK	App	9.02	5/27/2020	-	-	-	None	-	-	-
1044-1	Room 227	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1045-1	Hall by 231	WF	App	1	5/27/2020	-	-	-	None	-	-	-
1046-1	Boys Bathroom	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1047-1	Room 127	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1048-1	Room 125 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1048-2	Room 125 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1049-1	Hall by Cafeteria	WF	App		10/7/2020	-	-	-	None	Removed from Service	-	-
1049-2	Hall by Cafeteria	BF	App		10/7/2020	-	-	-	None	<1.0	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2201939-14559

June 2, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: West Middle Island Primary

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on June 01, 2020. New York Environmental analyzed the samples on June 02, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYE Report #: 2201939-14559

Date Collected:	27 May 2020
Date Received:	01 Jun 2020
Date Analyzed:	02 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200601M047	1	Hall by Room 223 - WF ;Initial	1.00	<1.00	µg/L	
200601M048	2	Girl's Locker Room - WF ;Initial	1.00	<1.00	µg/L	
200601M049	3	Girl's Locker Room Coach's Office Bathroom - SK ;Initial	1.00	80.9	µg/L	E,H
200601M050	4	Boy's Locker Room - WF ;Initial	1.00	2.21	µg/L	
200601M051	5	Boy's Locker Room Coach's Office Bathroom - SK ;Initial	1.00	8.60	µg/L	
200601M052	6	Hall by 117 - WF ;Initial	1.00	<1.00	µg/L	
200601M053	7	Nurse's Office - SK ;Initial	1.00	6.07	µg/L	
200601M054	8	Nurse's Office Bathroom - SK ;Initial	1.00	9.51	µg/L	
200601M055	9	Faculty Room - SK ;Initial	1.00	3.23	µg/L	
200601M056	10	Hall by 206 - WF ;Initial	1.00	2.20	µg/L	
200601M057	11	Room 209 - WF ;Initial	1.00	1.05	µg/L	
200601M058	12	Room 216 - WF ;Initial	1.00	1.15	µg/L	
200601M059	13	Room 216 Bathroom - SK ;Initial	1.00	9.96	µg/L	
200601M060	14	Room 218 - WF ;Initial	1.00	3.39	µg/L	
200601M061	15	Room 220 - WF ;Initial	1.00	1.45	µg/L	
200601M062	16	Room 222 - WF ;Initial	1.00	<1.00	µg/L	
200601M063	17	Room 224 - WF ;Initial	1.00	1.36	µg/L	
200601M064	18	Room 213 - WF ;Initial	1.00	<1.00	µg/L	
200601M065	19	Room 215 - WF ;Initial	1.00	2.04	µg/L	
200601M066	20	Room 215 Bathroom - SK ;Initial	1.00	2.86	µg/L	
200601M067	21	Room 226 - WF ;Initial	1.00	1.49	µg/L	
200601M068	22	Room 228 - WF ;Initial	1.00	1.69	µg/L	
200601M069	23	Room 228 Bathroom - SK ;Initial	1.00	6.43	µg/L	
200601M070	24	Room 217 - WF ;Initial	1.00	1.45	µg/L	
200601M071	25	Room 217 Bathoom - SK ;Initial	1.00	<1.00	µg/L	
200601M072	26	Room 230 - WF ;Initial	1.00	1.16	µg/L	

Date Collected:	27 May 2020
Date Received:	01 Jun 2020
Date Analyzed:	02 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200601M073	27	Kitchen 3-Bay - SK ;Initial	1.00	38.1	µg/L	H
200601M074	28	Kitchen 3-Bay - SKY ;Initial	1.00	16.4	µg/L	H
200601M075	29	Kitchen by oven - SK ;Initial	1.00	9.02	µg/L	
200601M076	30	Hall by 231 - WF ;Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2204097-15835

October 12, 2020

Project Manager
Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: West Middle Island Primary

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on October 09, 2020. New York Environmental analyzed the samples on October 10, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYE Report #: 2204097-15835

Date Collected:	07 Oct 2020
Date Received:	09 Oct 2020
Date Analyzed:	10 Oct 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201009P018	1	Kitchen 3-Bay-SK, Initial	1.00	4.83	µg/L	
201009P019	2	Kitchen 3-Bay-SPY, Initial	1.00	7.17	µg/L	
201009P020	3	Hall by Cafeteria-BF, Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

Appendix H

ENVIROSCIENCE
CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Boy's Bathroom by Electric Room @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1001-2	Boy's Bathroom by Electric Room @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1002-1	Girl's Bathroom by Electric Room @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1002-2	Girl's Bathroom by Electric Room @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1003-1	Kitchen (by door)	SPY	App	5.62	5/27/2020	-	-	-	None	-	-	-
1003-2	Kitchen 2-Bay	SK	App	1.51	5/27/2020	-	-	-	None	-	-	-
1003-3	Kitchen Handwash @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1003-4	Kitchen Handwash @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1003-5	Kitchen Bathroom	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1004-1	Adult Bathroom 412	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1005-1	Adult Bathroom 411	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1006-1	Faculty Room	SK	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1007-1	Room 408	SK	N/A		5/27/2020				None	SIGN		
1008-1	Hall by Room 442	WF	App	1.77	5/27/2020				None	-		
1008-2	Hall by Room 442	BF	App	<1.0	10/7/2020	-	-	-	None	-	-	-
1009-1	Girl's Bathroom 440 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1009-2	Girl's Bathroom 440 @B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1010-1	Boy's Bathroom 441 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1010-2	Boy's Bathroom 441 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1011-1	Adult Bathroom 402	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1012-1	Adult Bathroom 401	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1013-1	Custodial Closet 442	SS	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1014-1	Boy's Bathroom 503 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1014-2	Boy's Bathroom 503 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1014-3	Boy's Bathroom 503 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1015-1	Girl's Bathroom 504 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1015-2	Girl's Bathroom 504 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1015-3	Girl's Bathroom 504 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1016-1	Custodial Closet by 504	SS	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1017-1	Nurse's Office	SK	App	3.8	5/27/2020	-	-	-	None	-	-	-
1017-2	Nurse's Office Bathroom	SK	App	7.06	5/27/2020	-	-	-	None	-	-	-
1018-1	Room 606	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1019-1	Room 601	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1020-1	Room 602	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1021-1	Room 605	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1022-1	Room 604	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1023-1	Room 603	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1024-1	Girl's Bathroom 608 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1024-2	Girl's Bathroom 608 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1024-3	Girl's Bathroom 608 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1025-1	Custodial Closet 609	SS	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1026-1	Boy's Bathroom 610 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1026-2	Boy's Bathroom 610 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1026-3	Boy's Bathroom 610 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1027-1	Hall by 611 (left)	WF	App	5.6	5/27/2020	-	-	-	None	-	-	-
1027-2	Hall by 611 (right)	WF	App	6.11	5/27/2020	-	-	-	None	-	-	-
1028-1	Room 613	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1029-1	Room 614	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1030-1	Room 615	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1031-1	Room 616	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1032-1	Hall by 629 (left)	WF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1032-2	Hall by 629 (right)	WF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1033-1	Girl's Bathroom 627 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1033-2	Girl's Bathroom 627 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1033-3	Girl's Bathroom 627 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1034-1	Boy's Bathroom 618 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1034-2	Boy's Bathroom 618 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1034-3	Boy's Bathroom 618 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1034-4	Boy's Bathroom 618 @ D	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1035-1	Room 619	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1036-1	Room 620	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1037-1	Room 621	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1038-1	Room 622	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1039-1	Room 623	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1040-1	Room 624	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1041-1	Room 625	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1042-1	Room 626	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1043-1	Girl's Bathroom 431 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1043-2	Girl's Bathroom 431 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1043-3	Girl's Bathroom 431 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1044-1	Custodial Closet 431	SS	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1045-1	Boy's Bathroom 432 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1045-2	Boy's Bathroom 432 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1045-3	Boy's Bathroom 432 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1046-1	Room 428	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1047-1	Room 427	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1048-1	Room 426	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1049-1	Room 425	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1050-1	Room 424	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1051-1	Room 423	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1052-1	Room 422	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1053-1	Unisex Bathroom 433	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1054-1	Hall by 421 (left)	WF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1054-2	Hall by 421 (right)	WF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1055-1	Room 420 Birdbath	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1056-1	Room 419	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1057-1	Room 435	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1058-1	Room 418	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1059-1	Room 436	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1060-1	Room 437	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2201937-14557

June 2, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: West Middle Island Intermediate

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on June 01, 2020. New York Environmental analyzed the samples on June 02, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

Date Collected:	27 May 2020
Date Received:	01 Jun 2020
Date Analyzed:	02 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200601M022	1	Kitchen (by door) - SPY ;Initial	1.00	5.62	µg/L	
200601M023	2	Kitchen 2-Bay - SK ;Initial	1.00	1.51	µg/L	
200601M024	3	Faculty Room - SK ;Initial	1.00	<1.00	µg/L	
200601M025	4	Hall by Room 441 - WF ;Initial	1.00	1.77	µg/L	
200601M026	5	Nurse's Office - SK ;Initial	1.00	3.80	µg/L	
200601M027	6	Nurse's Office Bathroom - SK ;Initial	1.00	7.06	µg/L	
200601M028	7	Hall by 611 (left) - WF ;Initial	1.00	5.60	µg/L	
200601M029	8	Hall by 611 (right) - WF ;Initial	1.00	6.11	µg/L	
200601M030	9	Hall by 629 (left) - WF ;Initial	1.00	<1.00	µg/L	
200601M031	10	Hall by 629 (right) - WF ;Initial	1.00	<1.00	µg/L	
200601M032	11	Hall by 421 (left) - WF ;Initial	1.00	<1.00	µg/L	
200601M033	12	Hall by 421 (right) - WF ;Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2204098-15836

October 12, 2020

Project Manager
Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: West Middle Island Intermediate

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on October 09, 2020. New York Environmental analyzed the samples on October 10, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYE Report #: 2204098-15836

Date Collected:	07 Oct 2020
Date Received:	09 Oct 2020
Date Analyzed:	10 Oct 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201009P021	1	Hall by Room 442-BF, Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

Appendix I

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Kitchen Handwash	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1001-2	Kitchen Counter by Cooler	SK	App	<1.0	5/29/2020	-	-	-	None	-	-	-
1001-3	Kitchen 3-Bay @ A	SK	App	1.68	5/29/2020	-	-	-	None	-	-	-
1001-4	Kitchen 3-Bay @ B	SK	App	<1.0	5/29/2020	-	-	-	None	-	-	-
1001-5	Kitchen Island	SK	App	2.59	5/29/2020	-	-	-	None	-	-	-
1001-6	Kitchen Island by Pot Fillers	SK	App	<1.0	5/29/2020	-	-	-	None	-	-	-
1001-7	Kitchen Pot Filler (left)	PF	App	9.73	5/29/2020	-	-	-	None	-	-	-
1001-8	Kitchen Pot Filler (middle)	PF	App	3.82	5/29/2020	-	-	-	None	-	-	-
1001-9	Kitchen Pot Filler (right)	PF	App	2.74	5/29/2020	-	-	-	None	-	-	-
1002-1	Custodial Office Bathroom	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1002-2	Custodial Closet in Custodial Office	SS	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1003-1	Women's Bathroom by Cafeteria @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1003-2	Women's Bathroom by Cafeteria @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1004-1	Handicap Bathroom by Cafeteria	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1005-1	Men's Bathroom by Cafeteria	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1006-1	Hall by Cafeteria	WF	App	<1.0	5/29/2020	-	-	-	None	-	-	-
1006-2	Hall by Cafeteria	BF	App	<1.0	10/7/2021	-	-	-	None	-	-	-
1007-1	Custodial Closet by Cafeteria	SS	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1008-1	Boy's Bathroom by Cafeteria @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1008-2	Boy's Bathroom by Cafeteria @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1009-1	Girl's Bathroom by Cafeteria @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1009-2	Girl's Bathroom by Cafeteria @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1010-1	Room 101-Special Education	SK	App	1.66	5/29/2020	-	-	-	None	-	-	-
1011-1	Room W6- Art Room @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1011-2	Room W6- Art Room @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1011-3	Room W6- Art Room @ C	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1012-1	Room W7 Home Economics @A	SK	App	<1.0	5/29/2020	-	-	-	None	-	-	-
1012-2	Room W7 Home Economics @B	SK	App	1.1	5/29/2020	-	-	-	None	-	-	-
1012-3	Room W7 Home Economics @B	SPY	App	1.45	5/29/2020	-	-	-	None	-	-	-
1013-1	Room W8 Art Room Unit 1 @A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1013-2	Room W8 Art Room Unit 1 @B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1013-3	Room W8 Art Room Unit 1 @C	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1013-4	Room W8 Art Room Unit 2 @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1013-5	Room W8 Art Room Unit 2 @B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1013-6	Room W8 Art Room Unit 2 @C	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1014-1	Special Education Annex Women's Bathroom	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1014-2	Special Education Annex Men's Bathroom	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1014-3	Special Education Annex Kitchenette	SK	App	2.62	5/29/2020	-	-	-	None	-	-	-
1014-4	Special Education Annex Kitchenette	SPY	App	<1.0	5/29/2020	-	-	-	None	-	-	-
1015-1	1 South Faculty Room Kitchenette	SK	App	7.23	5/29/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1016-1	1 South Science Room 111 @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
#REF!	1 South Science Room 111 @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1016-2	1 South Science Room 111 @ C	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1017-1	1 South Boy's Bathroom @A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1017-2	1 South Boy's Bathroom @B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1017-3	1 South Boy's Bathroom @C	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1018-1	1 South Girl's Bathroom @A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1018-2	1 South Girl's Bathroom @B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1018-3	1 South Girl's Bathroom @C	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1019-1	1 South Men's Bathroom	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1020-1	1 South Women's Bathroom	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1021-1	1 South Hall (left)	WF	App	1.46	5/29/2020	-	-	-	None	-	-	-
1021-2	1 South Hall (right)	WF	App	<1.0	5/29/2020	-	-	-	None	-	-	-
1022-1	2 South Faculty Room Kitchenette	SK	App	3.87	5/29/2020	-	-	-	None	-	-	-
1023-1	2 South Hall	WF	App	5.52	5/29/2020	-	-	-	None	-	-	-
1024-1	2 South Boy's Bathroom @A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1024-2	2 South Boy's Bathroom @B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1024-3	2 South Boy's Bathroom @C	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1025-1	2 South Girl's Bathroom @A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1025-2	2 South Girl's Bathroom @B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1025-3	2 South Girl's Bathroom @C	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1026-1	2 South Men's Bathroom	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1027-1	2 South Women's Bathroom	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1028-1	2 South Science Room @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1028-2	2 South Science Room @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1028-3	2 South Science Room @ C	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1029-1	Men's Bathroom in Entrance Lobby @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1029-2	Men's Bathroom in Entrance Lobby @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1030-1	Women's Bathroom in Entrance Lobby @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1030-2	Women's Bathroom in Entrance Lobby @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1031-1	Girl's Locker Room	WF	App	2.33	5/29/2020	-	-	-	None	-	-	-
1031-2	Girl's Locker Room Bathroom @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1031-3	Girl's Locker Room Bathroom @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1031-4	Girl's Locker Room Bathroom @ C	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1031-5	Girl's Locker Room Office Bathroom	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1032-1	Main Office Kitchenette	SK	App	1.32	5/29/2020	-	-	-	None	-	-	-
1033-1	Nurse's Office	SK	App	<1.0	5/29/2020	-	-	-	None	-	-	-
1033-2	Nurse's Office Bathroom (left)	SK	App	4.66	5/29/2020	-	-	-	None	-	-	-
1033-3	Nurse's Office Bathroom (right)	SK	App	9.56	5/29/2020	-	-	-	None	-	-	-
1034-1	Boy's Locker Room	WF	App	4.16	5/29/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1034-2	Boy's Locker Room Bathroom @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1034-3	Boy's Locker Room Bathroom @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1034-4	**Boy's Locker Room Ice Machine**	**IM**	**App**		**5/29/2020**	**-**	**-**	**-**	**None**	**Not currently in use. Sampling Required when functional**	-	-
1035-1	1 East Faculty Room Kitchenette	SK	App	1.79	5/29/2020	-	-	-	None	-	-	-
1036-1	1 East Adult Bathroom (left)	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1037-1	1 East Adult Bathroom (right)	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1038-1	Girl's Bathroom @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1038-2	Girl's Bathroom @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1039-1	Boy's Bathroom @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1039-2	Boy's Bathroom @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1040-1	1 East Hall (left)	WK	App	<1.0	5/29/2020	-	-	-	None	-	-	-
1040-2	1 East Hall (right)	WF	App	<1.0	5/29/2020	-	-	-	None	-	-	-
1041-1	1 East Custodial Closet	SS	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1042-1	2 East Adult Bathroom	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1043-1	2 East Girl's Bathroom @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1043-2	2 East Girl's Bathroom @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1044-1	2 East Boy's Bathroom @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1044-2	2 East Boy's Bathroom @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1045-1	2 East Adult Bathroom by Faculty Room	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1046-1	2 East Faculty Room Kitchenette	SK	App	2.73	5/29/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1047-1	2 East Hall (left)	WF	App	<1.0	5/29/2020	-	-	-	None	-	-	-
1047-2	2 East Hall (right)	WF	App	<1.0	5/29/2020	-	-	-	None	-	-	-
1048-1	2 North Hall (left)	WF	App	7.5	5/29/2020	-	-	-	None	-	-	-
1048-2	2 North Hall (right)	WF	App	7.09	5/29/2020	-	-	-	None	-	-	-
1049-1	2 North Women's Bathroom	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1050-1	2 North Men's Bathroom	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1051-1	2 North Girl's Bathroom @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1051-2	2 North Girl's Bathroom @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1052-1	2 North Boy's Bathroom @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1052-2	2 North Boy's Bathroom @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1053-1	2 North Faculty Room Kitchenette	SK	App	5.66	5/29/2020	-	-	-	None	-	-	-
1054-1	2 North Science Room @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1054-2	2 North Science Room @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1054-3	2 North Science Room @ C	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1055-1	1 North Special Ed Room 300	SK	App	13.6	5/29/2020	-	-	-	None	-	-	-
1056-1	1 North Men's Bathroom	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1057-2	1 North Women's Bathroom	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1058-1	1 North Boy's Bathroom @ A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1058-2	1 North Boy's Bathroom @ B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1059-1	1 North Girl's Bathroom @A	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1059-2	1 North Girl's Bathroom @B	SK	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1060-1	1 North Hall (left)	WF	App	5.62	5/29/2020	-	-	-	None	-	-	-
1060-2	1 North Hall (right)	WF	App	3.96	5/29/2020	-	-	-	None	-	-	-
1061-1	Custodial Closet in Music Suite	SS	N/A		5/29/2020	-	-	-	Sign Required		-	-
2001-1	Central Office Kitchenette	SK	App	<1.0	5/29/2020	-	-	-	None	-	-	-

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report (Revised)

NYE Report #: 2201994-14595R

June 8, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Longwood Middle School - Longwood CSD

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on June 05, 2020. New York Environmental analyzed the samples on June 08, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

Date Collected:	29 May 2020
Date Received:	05 Jun 2020
Date Analyzed:	08 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200605N149	1	Kitchen Counter by Cooler-SK; Initial	1.00	<1.00	µg/L	
200605N150	2	Kitchen 3-Bay @ A-SK; Initial	1.00	1.68	µg/L	
200605N151	3	Kitchen 3-Bay @ B-SK; Initial	1.00	<1.00	µg/L	
200605N152	4	Kitchen Island-SK; Initial	1.00	2.59	µg/L	
200605N153	5	Kitchen Island by Pot Fillers-SK; Initial	1.00	<1.00	µg/L	
200605N154	6	Kitchen Pot Filler (left)-PF; Initial	1.00	9.73	µg/L	
200605N155	7	Kitchen Pot Filler (middle)-PF; Initial	1.00	3.82	µg/L	
200605N156	8	Kitchen Pot Filler (right)-PF; Initial	1.00	2.74	µg/L	
200605N157	9	Kitchen Ice Machine-IM; Initial	1.00	<1.00	µg/L	
200605N158	10	Hall by Cafeteria-WF; Initial	1.00	<1.00	µg/L	
200605N159	11	Hall by Cafeteria-WF; Initial	1.00	<1.00	µg/L	
200605N160	12	Room 101-Special Education-SK; Initial	1.00	1.66	µg/L	
200605N161	13	Room W7 Home Economics @A-SK; Initial	1.00	<1.00	µg/L	
200605N162	14	Room W7 Home Economics @B-SK; Initial	1.00	1.10	µg/L	
200605N163	15	Room W7 Home Economics @B-SPY; Initial	1.00	1.45	µg/L	
200605N164	16	Special Education Annex Kitchenette-SK; Initial	1.00	2.62	µg/L	
200605N165	17	Special Education Annex Kitchenette-SPY; Initial	1.00	<1.00	µg/L	
200605N166	18	1 South Faculty Room Kitchenette-SK; Initial	1.00	7.23	µg/L	
200605N167	19	1 South Hall (left)-WF; Initial	1.00	1.46	µg/L	
200605N168	20	1 South Hall (right)-WF; Initial	1.00	<1.00	µg/L	
200605N169	21	2 South Faculty Room Kitchenette-SK; Initial	1.00	3.87	µg/L	
200605N170	22	2 South Hall-WF; Initial	1.00	5.52	µg/L	
200605N171	23	Girl's Locker Room-WF; Initial	1.00	2.33	µg/L	
200605N172	24	Main Office Kitchenette-SK; Initial	1.00	1.32	µg/L	
200605N173	25	Nurse's Office-SK; Initial	1.00	<1.00	µg/L	
200605N174	26	Nurse's Office Bathroom (left)-SK; Initial	1.00	4.66	µg/L	

Date Collected:	29 May 2020
Date Received:	05 Jun 2020
Date Analyzed:	08 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200605N175	27	Nurse's Office Bathroom (right)-SK; Initial	1.00	9.56	µg/L	
200605N176	28	Boy's Locker Room-WF; Initial	1.00	4.16	µg/L	
200605N177	29	1 East Faculty Room Kitchenette-SK; Initial	1.00	1.79	µg/L	
200605N178	30	1 East Hall (left)-WK; Initial	1.00	<1.00	µg/L	
200605N179	31	1 East Hall (right)-WF; Initial	1.00	<1.00	µg/L	
200605N180	32	2 East Faculty Room Kitchenette-SK; Initial	1.00	2.73	µg/L	
200605N181	33	2 East Hall (left)-WF; Initial	1.00	<1.00	µg/L	
200605N182	34	2 East Hall (right)-WF; Initial	1.00	<1.00	µg/L	
200605N183	35	2 North Hall (left)-WF; Initial	1.00	7.50	µg/L	
200605N184	36	2 North Hall (right)-WF; Initial	1.00	7.09	µg/L	
200605N185	37	2 North Faculty Room Kitchenette-SK; Initial	1.00	5.66	µg/L	
200605N186	38	1 North Special Ed Room 300-SK; Initial	1.00	13.6	µg/L	
200605N187	39	1 North Hall (left)-WF; Initial	1.00	5.62	µg/L	
200605N188	40	1 North Hall (right)-WF; Initial	1.00	3.96	µg/L	
200605N189	41	Central Office Kitchenette-SK; Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

Revision History:

Report revised on 6/8/2020 at 21:51, replaces report generated on 6/8/2020 at 14:51.

-Project location updated to "Longwood CSD"

- Date sampled revised to 5/29/2020 as per chain of custody.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2204099-15837

October 12, 2020

Project Manager
Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Longwood Middle School

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on October 09, 2020. New York Environmental analyzed the samples on October 10, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYE Report #: 2204099-15837

Date Collected:	07 Oct 2020
Date Received:	09 Oct 2020
Date Analyzed:	10 Oct 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201009P022	1	Hall by Cafeteria-BF, Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

Appendix J

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Kitchen 3-Bay @ A	SK	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1001-2	Kitchen 3-Bay @ B	SK	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1001-3	Kitchen Server Station @ A	SK	App	9.84	5/28/2020	-	-	-	None	-	-	-
1001-4	Kitchen Server Station @ B	SK	App	1.35	5/28/2020	-	-	-	None	-	-	-
1001-5	Kitchen Island	SK	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1001-6	Kitchen Handwash	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1001-7	Kitchen Handwash near Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1001-8	Kitchen Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1001-9	Kitchen Breakroom	SK	App	1.19	5/28/2020	-	-	-	None	-	-	-
1001-10	Kitchen Breakroom Handwash	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1002-1	Boy's Bathroom in Cafeteria @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1002-2	Boy's Bathroom in Cafeteria @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1003-1	Girl's Bathroom in Cafeteria @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1003-2	Girl's Bathroom in Cafeteria @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1004-1	Cafeteria	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1004-2	Cafeteria	BF	App	<1.0	10/7/2020	-	-	-	None	-	-	-
1005-1	Faculty Women's Bathroom @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1005-2	Faculty Women's Bathroom @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1006-1	Custodial Closet 1118	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1007-1	Hall by 1118	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1008-1	Boy's Bathroom by 1118 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1008-2	Boy's Bathroom by 1118 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1008-3	Boy's Bathroom by 1118 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1008-4	Boy's Bathroom by 1118 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1009-1	Room 1116 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1009-2	Room 1116 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1009-3	Room 1116 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1010-1	Hall by Mechanical Room	WF	App	4.67	5/28/2020	-	-	-	None	-	-	-
1011-1	Faculty Men's Bathroom by Mechanical Room @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1011-2	Faculty Men's Bathroom by Mechanical Room @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1012-1	Room 1102 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1012-2	Room 1102 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1012-3	Room 1102 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1013-1	Room 1104 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1013-2	Room 1104 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1013-3	Room 1104 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1014-1	Room 1101 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1014-2	Room 1101 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1014-3	Room 1101 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1015-1	Room 1103 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1015-2	Room 1103 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1015-3	Room 1103 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1016-1	Women's Bathroom by Main Office @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1016-2	Women's Bathroom by Main Office @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1016-3	Women's Bathroom by Main Office @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1016-4	Women's Bathroom by Main Office @D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1017-1	Hall by Room 1303 (left)	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1017-2	Hall by Room 1303 (right)	WF	App	1.41	5/28/2020	-	-	-	None	-	-	-
1018-1	Men's Faculty Bathroom 1303 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1018-2	Men's Faculty Bathroom 1303 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1018-3	Men's Faculty Bathroom 1303 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1019-1	Custodial Closet by Room 1303	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-1	Room 1403 Teacher's Station	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-2	Room 1403 Counter 1 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-3	Room 1403 Counter 1 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-4	Room 1403 Counter 1 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-5	Room 1403 Counter 2 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-6	Room 1403 Counter 2 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-7	Room 1403 Counter 2 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-8	Room 1403 Counter 2 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1020-9	Room 1403 Counter 2 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1020-10	Room 1403 Counter 2 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1021-1	Prep Room 1403/1401 @ A	SK	App	16.2	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1021-2	Prep Room 1403/1401 @ B	SK	App	6.87	5/28/2020	-	-	-	None	-	-	-
1022-1	Room 1401 Teacher's Station	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1022-2	Room 1401 Counter 1 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1022-3	Room 1401 Counter 1 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1022-4	Room 1401 Counter 1 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1022-5	Room 1401 Counter 2 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1022-6	Room 1401 Counter 2 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1022-7	Room 1401 Counter 2 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1022-8	Room 1401 Counter 2 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1022-9	Room 1401 Counter 2 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1022-10	Room 1401 Counter 2 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-1	Room 1402 Teacher's Station	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-2	Room 1402 Counter 1 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-3	Room 1402 Counter 1 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-4	Room 1402 Counter 1 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-5	Room 1402 Counter 2	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-6	Room 1402 Counter 3 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1023-7	Room 1402 Counter 3 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-8	Room 1402 Counter 3 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-9	Room 1402 Counter 4 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-10	Room 1402 Counter 4 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1023-11	Room 1402 Counter 4 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1024-1	Prep Room 1402/1404 @ A	SK	App	8.75	5/28/2020	-	-	-	None	-	-	-
1024-2	Prep Room 1402/1404 @ B	SK	App	14.7	5/28/2020	-	-	-	None	-	-	-
1025-1	Room 1404 Teacher's Station	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-2	Room 1404 Counter 1 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-3	Room 1404 Counter 1 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-4	Room 1404 Counter 1 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-5	Room 1404 Counter 2 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-6	Room 1404 Counter 2 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-7	Room 1404 Counter 2 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-8	Room 1404 Counter 3	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-9	Room 1404 Counter 4 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-10	Room 1404 Counter 4 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1025-11	Room 1404 Counter 4 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1026-1	Hall by Room 1408	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
1027-1	Custodial Closet by Room 1408	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1028-1	Room 1409 Teacher's Station	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-1	Room 1409 Counter 1 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-2	Room 1409 Counter 1 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-3	Room 1409 Counter 1 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-4	Room 1409 Counter 1 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-5	Room 1409 Counter 2 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-6	Room 1409 Counter 2 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-7	Room 1409 Counter 2 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-8	Room 1409 Counter 3	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-9	Room 1409 Counter 4 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-10	Room 1409 Counter 4 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1029-11	Room 1409 Counter 4 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-1	Room 1411 Teacher's Station	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-2	Room 1411 Counter 1 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-3	Room 1411 Counter 1 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-4	Room 1411 Counter 1 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-5	Room 1411 Counter 2	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-6	Room 1411 Counter 3 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-7	Room 1411 Counter 3 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1030-8	Room 1411 Counter 3 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1030-9	Room 1411 Counter 4	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1031-1	Room 1402 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1031-2	Room 1402 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1032-1	Custodial Office Handwash	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-1	Room 1413 Teacher's Station	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-2	Room 1413 Counter 1 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-3	Room 1413 Counter 1 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-4	Room 1413 Counter 1 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-5	Room 1413 Counter 2 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-6	Room 1413 Counter 2 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-7	Room 1413 Counter 2 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-8	Room 1413 Counter 3	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-9	Room 1413 Counter 4 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-10	Room 1413 Counter 4 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-11	Room 1413 Counter 4 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1033-12	Prep Room 1413 @ A	SK	App	41.8	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1033-13	Prep Room 1413 @ B	SK	App	38.8	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1034-1	Boy's Bathroom by 1413 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1034-2	Boy's Bathroom by 1413 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-1	Room 1414 Teacher's Station	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1035-2	Room 1414 Counter 1 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-3	Room 1414 Counter 1 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-4	Room 1414 Counter 1 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-5	Room 1414 Counter 2 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-6	Room 1414 Counter 2 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-7	Room 1414 Counter 2 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-8	Room 1414 Counter 3	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-9	Room 1414 Counter 4 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-10	Room 1414 Counter 4 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-11	Room 1414 Counter 4 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1035-12	Prep Room 1414 @ A	SK	App	32.2	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1035-13	Prep Room 1414 @ B	SK	App	84	5/28/2020				Additional Sampling Required	Permanent Sign Posted		
1036-1	Girl's Bathroom by Room 1414 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1036-2	Girl's Bathroom by Room 1414 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1036-3	Girl's Bathroom by Room 1414 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1036-4	Girl's Bathroom by Room 1414 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1036-5	Girl's Bathroom by Room 1414 @ E	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
1037-1	Principal's Office Bathroom	SK	N/A		5/29/2020				None	SIGN		
2001-1	Custodial Closet by Elevator	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2002-1	Hall by Elevator	WF	App	1.68	5/28/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2003-1	Women's Bathroom by Elevator @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2003-2	Women's Bathroom by Elevator @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2003-3	Women's Bathroom by Elevator @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2003-4	Women's Bathroom by Elevator @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2004-1	Hall by Library	WF	N/A		5/28/2020	-	-	-	None	CAPPED	-	-
2005-1	Library Office	SK	App	2.71	5/28/2020	-	-	-	None	-	-	-
2006-1	Hall by 2130	WF	App	5.16	5/28/2020	-	-	-	None	-	-	-
2007-1	Custodial Closet by 2130	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2008-1	Boy's Bathroom by 2130 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2008-2	Boy's Bathroom by 2130 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2008-3	Boy's Bathroom by 2130 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2008-4	Boy's Bathroom by 2130 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2009-1	Men's Bathroom by 2nd Floor Ramp	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2010-1	Hall by 2111	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
2011-1	Boy's Bathroom by 2107 @A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2011-2	Boy's Bathroom by 2107 @B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2011-3	Boy's Bathroom by 2107 @C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2011-4	Boy's Bathroom by 2107 @D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2011-5	Boy's Bathroom by 2107 @E	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2012-1	Girl's Bathroom by 2107 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2012-2	Girl's Bathroom by 2107 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2012-3	Girl's Bathroom by 2107 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2012-4	Girl's Bathroom by 2107 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2012-5	Girl's Bathroom by 2107 @ E	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2013-1	Custodial Closet by Counseling Ctr	SS	App	2.87	5/28/2020	-	-	-	None	-	-	-
2014-1	Women's Faculty Bathroom by Counseling Ctr	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2015-1	Men's faculty Bathroom by Counseling Ctr @A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2015-2	Men's faculty Bathroom by Counseling Ctr @B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2016-1	Custodial closet by Counseling Ctr	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2017-1	Nurse's Office	SK	App	8.17	5/28/2020	-	-	-	None	-	-	-
2017-2	Nurse's Office Bathroom (left)	SK	App	4.74	5/28/2020	-	-	-	None	-	-	-
2017-3	Nurse's Office Bathroom (right)	SK	App	1.47	5/28/2020	-	-	-	None	-	-	-
2018-1	Hall by Special Ed Office	WF	App	3.26	5/28/2020	-	-	-	None	-	-	-
2019-1	Boy's Bathroom by 2408 @A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2019-2	Boy's Bathroom by 2408 @B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2019-3	Boy's Bathroom by 2408 @C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2019-4	Boy's Bathroom by 2408 @D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2019-5	Boy's Bathroom by 2408 @E	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2020-1	Girl's Bathroom by 2408 @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2020-2	Girl's Bathroom by 2408 @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2020-3	Girl's Bathroom by 2408 @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2020-4	Girl's Bathroom by 2408 @ D	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2020-5	Girl's Bathroom by 2408 @ E	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2021-1	Custodial Closet by 2408	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2022-1	Room 2403 Home Ec Teacher's Station	SK	App	1.51	5/28/2020	-	-	-	None	-	-	-
2022-2	Room 2403 Station 1	SK	App	2.4	5/28/2020	-	-	-	None	-	-	-
2022-3	Room 2403 Station 2	SK	App	<1.0	5/28/2020	-	-	-	None	-	-	-
2022-4	Room 2403 Station 3	SK	App	<1.0	5/28/2020	-	-	-	None	-	-	-
2023-1	Room 2401 Home Ec Teacher's Station	SK	App	<1.0	5/28/2020	-	-	-	None	-	-	-
2023-2	Room 2401 Station 1	SK	App	1.83	5/28/2020	-	-	-	None	-	-	-
2023-3	Room 2401 Station 2	SK	App	1.09	5/28/2020	-	-	-	None	-	-	-
2023-4	Room 2401 Station 3	SK	App	1.31	5/28/2020	-	-	-	None	-	-	-
2024-1	Room 2402 Teacher's Station	SK	App	2.17	5/28/2020	-	-	-	None	-	-	-
2024-2	Room 2402 Station 1	SK	App	1.56	5/28/2020	-	-	-	None	-	-	-
2024-3	Room 2402 Station 2	SK	App	2.6	5/28/2020	-	-	-	None	-	-	-
2024-4	Room 2402 Station 3	SK	App	1.92	5/28/2020	-	-	-	None	-	-	-
2025-1	Room 2404 Teacher's Station	SK	App	1.29	5/28/2020	-	-	-	None	-	-	-
2025-2	Room 2404 Station 1	SK	App	4.64	5/28/2020	-	-	-	None	-	-	-
2025-3	Room 2404 Station 2	SK	App	9.39	5/28/2020	-	-	-	None	-	-	-
2025-4	Room 2404 Station 3	SK	App	<1.0	5/28/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2026-1	Handicap Bathroom by 2nd Floor Rear Ramp	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2027-1	Room 2414 Counter A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2027-2	Room 2414 Counter B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2027-3	Room 2414 Island	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2028-1	Athletic Office	SK	App	1.46	5/28/2020	-	-	-	None	-	-	-
2029-1	Boy's Locker Room	WF	App	3.25	5/28/2020	-	-	-	None	-	-	-
2029-2	Boy's Locker Room Bathroom @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2029-3	Boy's Locker Room Bathroom @B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2029-4	Boy's Locker Room Rear Vestibule	WF	App	3.96	5/28/2020	-	-	-	None	-	-	-
2030-1	Girl's Locker Room Rear Vestibule Custodial Closet	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2030-2	Gym Rear Vestibule	WF	App	2.09	5/28/2020	-	-	-	None	-	-	-
2030-3	Gym Rear Vestibule Bathroom @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2030-4	Gym Rear Vestibule Bathroom @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2030-5	Gym Rear Vestibule Bathroom @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2031-1	Girl's Locker Room	WF	App	4.07	5/28/2020	-	-	-	None	-	-	-
2031-2	Girl's Locker Room Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2031-3	Girl's Locker Room Rear	WF	N/A		5/28/2020	-	-	-	None	CAPPED	-	-
2031-4	Girl's Locker Room Rear Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2031-5	Girl's Locker Room Rear Vestibule	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-
2032-1	Gym	WF	App	<1.0	5/28/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2033-1	Gym Lobby (left)	WF	App	4.24	5/28/2020	-	-	-	None	-	-	-
2033-1	Gym Lobby (right)	WF	App	1.16	5/28/2020	-	-	-	None	-	-	-
2033-1	Gym Lobby Bathroom	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2034-1	Boy's Bathroom by Gym Lobby @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2034-2	Boy's Bathroom by Gym Lobby @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2034-3	Boy's Bathroom by Gym Lobby @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2035-1	Girl's Bathroom by Gym Lobby @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2035-1	Girl's Bathroom by Gym Lobby @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2035-1	Girl's Bathroom by Gym Lobby @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2036-1	Custodial closet by Gym Lobby	SS	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2037-1	Room 2504 Shop @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2037-2	Room 2504 Shop @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2037-3	Room 2504 Shop @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2038-1	Room 2503 Shop @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2038-2	Room 2503 Shop @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2038-3	Room 2503 Shop @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2039-1	Room 2502 Shop @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2039-2	Room 2502 Shop @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2039-3	Room 2502 Shop @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2040-1	Room 2501 Shop @ A	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2040-2	Room 2501 Shop @ B	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-
2040-3	Room 2501 Shop @ C	SK	N/A		5/28/2020	-	-	-	None	SIGN	-	-

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2201959-14574

June 4, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Longwood Junior High School

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on June 02, 2020. New York Environmental analyzed the samples on June 03, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

Date Collected:	29 May 2020
Date Received:	02 Jun 2020
Date Analyzed:	03 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200602M084	1	Kitchen 3-Bay @ A-SK; Initial	1.00	<1.00	µg/L	
200602M085	2	Kitchen 3-Bay @ B-SK; Initial	1.00	<1.00	µg/L	
200602M086	3	Kitchen Server Station @ A-SK; Initial	1.00	9.84	µg/L	
200602M087	4	Kitchen Server Station @ B-SK; Initial	1.00	1.35	µg/L	
200602M088	5	Kitchen Island-SK; Initial	1.00	<1.00	µg/L	
200602M089	6	Kitchen Breakroom-SK; Initial	1.00	1.19	µg/L	
200602M090	7	Cafeteria-WF; Initial	1.00	<1.00	µg/L	
200602M091	8	Cafeteria-BF; Initial	1.00	<1.00	µg/L	
200602M092	9	Hall by 1118-WF; Initial	1.00	<1.00	µg/L	
200602M093	10	Hall by Mechanical Room-WF; Initial	1.00	4.67	µg/L	
200602M094	11	Hall by Room 1303 (left)-WF; Initial	1.00	<1.00	µg/L	
200602M095	12	Hall by Room 1303 (right)-WF; Initial	1.00	1.41	µg/L	
200602M096	13	Prep Room 1403/1401 @ A-SK; Initial	1.00	16.2	µg/L	H
200602M097	14	Prep Room 1403/1401 @ B-SK; Initial	1.00	6.87	µg/L	
200602M098	15	Prep Room 1402/1404 @ A-SK; Initial	1.00	8.75	µg/L	
200602M099	16	Prep Room 1402/1404 @ B-SK; Initial	1.00	14.7	µg/L	
200602M100	17	Hall by Room 1408-WF; Initial	1.00	<1.00	µg/L	
200602M101	18	Prep Room 1413 @ A-SK; Initial	1.00	41.8	µg/L	H
200602M102	19	Prep Room 1413 @ B-SK; Initial	1.00	38.8	µg/L	H
200602M103	20	Prep Room 1414 @ A-SK; Initial	1.00	32.2	µg/L	H
200602M104	21	Prep Room 1414 @ B-SK; Initial	1.00	84.0	µg/L	E,H
200602M105	22	Hall by Elevator-WF; Initial	1.00	1.68	µg/L	
200602M106	23	Library Office-SK; Initial	1.00	2.71	µg/L	
200602M107	24	Hall by 2130-WF; Initial	1.00	5.16	µg/L	
200602M108	25	Hall by 2111-WF; Initial	1.00	<1.00	µg/L	
200602M109	26	Custodial Closet by Counseling Ctr-SS; Initial	1.00	2.87	µg/L	

Date Collected:	29 May 2020
Date Received:	02 Jun 2020
Date Analyzed:	03 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200602M110	27	Nurse's Office-SK; Initial	1.00	8.17	µg/L	
200602M111	28	Nurse's Office Bathroom (left)-SK; Initial	1.00	4.74	µg/L	
200602M112	29	Nurse's Office Bathroom (right)-SK; Initial	1.00	1.47	µg/L	
200602M113	30	Hall by Special Ed Office-WF; Initial	1.00	3.26	µg/L	
200602M114	31	Room 2403 Home Ec Teacher's Station-SK; Initial	1.00	1.51	µg/L	
200602M115	32	Room 2403 Station 1-SK; Initial	1.00	2.40	µg/L	
200602M116	33	Room 2403 Station 2-SK; Initial	1.00	<1.00	µg/L	
200602M117	34	Room 2403 Station 3-SK; Initial	1.00	<1.00	µg/L	
200602M118	35	Room 2401 Home Ec Teacher's Station-SK; Initial	1.00	<1.00	µg/L	
200602M119	36	Room 2401 Station 1-SK; Initial	1.00	1.83	µg/L	
200602M120	37	Room 2401 Station 2-SK; Initial	1.00	1.09	µg/L	
200602M121	38	Room 2401 Station 3-SK; Initial	1.00	1.31	µg/L	
200602M122	39	Room 2402 Teacher's Station-SK; Initial	1.00	2.17	µg/L	
200602M123	40	Room 2402 Station 1-SK; Initial	1.00	1.56	µg/L	
200602M124	41	Room 2402 Station 2-SK; Initial	1.00	2.60	µg/L	
200602M125	42	Room 2402 Station 3-SK; Initial	1.00	1.92	µg/L	
200602M126	43	Room 2404 Teacher's Station-SK; Initial	1.00	1.29	µg/L	
200602M127	44	Room 2404 Station 1-SK; Initial	1.00	4.64	µg/L	
200602M128	45	Room 2404 Station 2-SK; Initial	1.00	9.39	µg/L	
200602M129	46	Room 2404 Station 3-SK; Initial	1.00	<1.00	µg/L	
200602M130	47	Athletic Office-SK; Initial	1.00	1.46	µg/L	
200602M131	48	Boy's Locker Room-WF; Initial	1.00	3.25	µg/L	
200602M132	49	Boy's Locker Room Rear Vestibule-WF; Initial	1.00	3.96	µg/L	
200602M133	50	Gym Rear Vestibule -WF; Initial	1.00	2.09	µg/L	
200602M134	51	Girl's Locker Room -WF; Initial	1.00	4.07	µg/L	
200602M135	52	Girl's Locker Room Rear Vestibule -WF; Initial	1.00	<1.00	µg/L	
200602M136	53	Gym-WF; Initial	1.00	<1.00	µg/L	

Date Collected:	29 May 2020
Date Received:	02 Jun 2020
Date Analyzed:	03 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200602M137	54	Gym Lobby (left)-WF; Initial	1.00	4.24	µg/L	
200602M138	55	Gym Lobby (right)-WF; Initial	1.00	1.16	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2204100-15838

October 12, 2020

Project Manager
Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Longwood Junior High School

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on October 09, 2020. New York Environmental analyzed the samples on October 10, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYE Report #: 2204100-15838

Date Collected:	07 Oct 2020
Date Received:	09 Oct 2020
Date Analyzed:	10 Oct 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201009P023	1	Cafeteria-BF, Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

Appendix K

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
0001-1	Custodial Office	SS	N/A		5/27/2020	-	-	-	None	SIGN	-	-
0002-1	Loading Dock	SP	N/A		5/27/2020	-	-	-	None	SIGN	-	-
0003-1	Ladies Bathroom-Basement @A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
0003-2	Ladies Bathroom-Basement @B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
0004-1	Men's Bathroom-Basement @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
0004-2	Men's Bathroom-Basement @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1001-1	Kitchen 1 Island	SK	App	11.7	5/27/2020	-	-	-	None	-	-	-
1001-2	Kitchen 1 3-Bay @ A	SK	App	5.73	5/27/2020	-	-	-	None	-	-	-
1001-3	Kitchen 1 3-Bay @ B	SK	App	14.5	5/27/2020	-	-	-	None	-	-	-
1001-4	Kitchen Handwash @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1001-5	Kitchen Handwash @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1001-6	Kitchen Handwash @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1001-7	Kitchen closet	SS	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1002-1	Cafeteria (left)	WF	App	3.32	5/27/2020	-	-	-	None	-	-	-
1002-2	Cafeteria (right)	WF	N/A		5/27/2020	-	-	-	None	CAPPED	-	-
1003-1	Hall by 1107	WF	App	1.31	5/27/2020	-	-	-	None	-	-	-
1004-1	Girl's Bathroom by 1116 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1004-2	Girl's Bathroom by 1116 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1004-3	Girl's Bathroom by 1116 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1004-4	Girl's Bathroom by 1116 @ D	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1004-5	Girl's Bathroom by 1116 @ E	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1005-1	Hall by 1116	WF	N/A		5/27/2020	-	-	-	None	CAPPED	-	-
1006-1	Boy's Bathroom by 1116 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1006-2	Boy's Bathroom by 1116 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1006-3	Boy's Bathroom by 1116 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1006-5	Boy's Bathroom by 1116 @ E	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1007-1	Custodial Closet by 1116	SS	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1008-1	Staff Bathroom by 1502	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1009-1	Room 1400 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1009-2	Room 1400 Counter @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1009-3	Room 1400 Counter @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1010-1	Room 1400 Prep @ A	SK	App	13.2	5/27/2020	-	-	-	None	-	-	-
1010-2	Room 1400 Prep @ B	SK	App	8.68	5/27/2020	-	-	-	None	-	-	-
1011-1	Room 1404 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1011-2	Room 1404 Counter @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1011-3	Room 1404 Counter @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1012-1	Girl's Bathroom 1405 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1012-2	Girl's Bathroom 1405 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1012-3	Girl's Bathroom 1405 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1012-4	Girl's Bathroom 1405 @ D	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1013-1	Hall by 1405	WF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1014-1	Men's Bathroom by 1407	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1015-1	Women's Bathroom by 1407	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1016-1	Kitchen 3 3-Bay @ A	SK	App	3.25	5/27/2020	-	-	-	None	-	-	-
1016-2	Kitchen 3 3-Bay @ B	SK	App	2.2	5/27/2020	-	-	-	None	-	-	-
1016-3	Kitchen 3 Island by 3 Bay	SK	App	7.08	5/27/2020	-	-	-	None	-	-	-
1016-4	Kitchen 3 Island by Clock	SK	App	3.7	5/27/2020	-	-	-	None	-	-	-
1017-1	Hall by 1305	WF	App	2.58	5/27/2020	-	-	-	None	-	-	-
1018-1	Boy's Bathroom 1306 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1018-2	Boy's Bathroom 1306 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1018-3	Boy's Bathroom 1306 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1018-4	Boy's Bathroom 1306 @ D	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1019-1	Staff Bathroom by 1306	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1020-1	Boy's Bathroom by 1148 Birdbath	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1020-2	Girl's Bathroom by 1148 Birdbath	WF	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1021-1	Hall by 1148	WF	App	7.09	5/27/2020	-	-	-	None	-	-	-
1022-1	Hall by Auditorium	WF	App	5.78	5/27/2020	-	-	-	None	-	-	-
1023-1	Art Room 1701 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1023-2	Art Room 1701 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1023-3	Art Room 1701 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1024-1	Art Room 1705 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1024-2	Art Room 1705 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1024-3	Art Room 1705 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1025-1	Hall by Auditorium Concession	WF	N/A		5/27/2020	-	-	-	None	CAPPED	-	-
1026-1	Art Room 1707 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1026-2	Art Room 1707 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1026-3	Art Room 1707 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1027-1	Family Services	SK	App	3.12	5/27/2020	-	-	-	None	-	-	-
1028-1	Room 1711 Station 1	SK	App	2.25	5/27/2020	-	-	-	None	-	-	-
1028-2	Room 1711 Station 1	SPY	App	3.38	5/27/2020	-	-	-	None	-	-	-
1028-3	Room 1711 Station 2	SK	App	1.62	5/27/2020	-	-	-	None	-	-	-
1028-4	Room 1711 Station 2	SPY	App	2.38	5/27/2020	-	-	-	None	-	-	-
1028-5	Room 1711 Station 3	SK	App	2.3	5/27/2020	-	-	-	None	-	-	-
1028-6	Room 1711 Station 3	SPY	App	2.71	5/27/2020	-	-	-	None	-	-	-
1028-7	Room 1711 Station 4	SK	App	13.1	5/27/2020	-	-	-	None	-	-	-
1028-8	Room 1711 Station 4	SPY	App	2.67	5/27/2020	-	-	-	None	-	-	-
1028-9	Room 1711 Station 5	SK	App	11.7	5/27/2020	-	-	-	None	-	-	-
1028-10	Room 1711 Station 5	SPY	App	1.65	5/27/2020	-	-	-	None	-	-	-
1029-1	Room 1713 Teacher's Station	SK	App	2.56	5/27/2020	-	-	-	None	-	-	-
1029-2	Room 1713 Counter @ A	SK	App	4.06	5/27/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1029-3	Room 1713 Counter @ B	SK	App	2.5	5/27/2020	-	-	-	None	-	-	-
1029-4	Room 1713 Counter @ C	SK	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1029-5	Room 1713 Counter @ D	SK	App	5.16	5/27/2020	-	-	-	None	-	-	-
1030-1	Room 1715 Counter @ A	SK	App	99	5/27/2020				Additional Sampling Required	Permanent Sign Posted	44.8	10/7/2020
1030-2	Room 1715 Counter @ B	SK	App	42.1	5/27/2020				Additional Sampling Required	Aerator Flushed	9.05	10/7/2020
1030-3	Room 1715 Counter @ C	SK	App	19.3	5/27/2020				Additional Sampling Required	Aerator Flushed	11.3	10/7/2020
1031-1	Art Room 1719 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1031-2	Art Room 1719 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1031-3	Art Room 1719 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1032-1	Art Room 1721 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1032-2	Art Room 1721 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1032-3	Art Room 1721 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1033-1	Shop Room 1801	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1034-1	Shop Room 1803	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1035-1	Boy's Bathroom by 1813 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1035-2	Boy's Bathroom by 1813 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1036-1	Girl's Bathroom by 1813 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1036-2	Girl's Bathroom by 1813 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1037-1	Hall by 1823	WF	App	5.6	5/27/2020	-	-	-	None	-	-	-
1038-1	Room 1815	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1039-1	Room 1816	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1040-1	Room 1814	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1041-1	Room 1812	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1042-1	Men's Bathroom 1810	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1043-1	Women's Bathroom 1808	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1044-1	Dark Room 1804 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1044-2	Dark Room 1804 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1045-1	Custodial closet 1727	SS	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1046-1	Unisex Bathroom 1733	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1047-1	Unisex Bathroom 1735	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1048-1	Main Office handwash	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1048-2	Main Office Bathroom	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1049-1	Nurse's Office	SK	App	7.89	5/27/2020	-	-	-	None	-	-	-
1049-2	Nurse's Office Exam Room 1	SK	App	43.5	5/27/2020				Additional Sampling Required	Permanent Sign Posted	19.8	10/7/2020
1049-3	Nurse's Office Exam Room 2	SK	App	15.5	5/27/2020				Additional Sampling Required	Aerator Flushed	2.02	10/7/2020
1049-4	Nurse's Office Bathroom 1	SK	App	29.1	5/27/2020				Additional Sampling Required	Aerator Flushed	3.61	10/7/2020
1049-5	Nurse's Office Bathroom 2	SK	App	9.8	5/27/2020	-	-	-	None	-	-	-
1050-1	Physical Education Offices Kitchenette	SK	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1050-2	Physical Education Offices Kitchenette	SPY	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1050-3	Men's Physical Education Office	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1050-4	Women's Physical Education Office	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1051-1	Boy's Bathroom 1604 Birdbath	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1052-1	Hall by 1604	WF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1052-2	Hall by 1604	BF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1053-1	Hall by 1614	WF	App	16	5/27/2020				Additional Sampling Required	Removed from service		
1054-1	Girl's Bathroom 1614 Birdbath	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1055-1	Department of Physcial Education Office Handwash	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1056-1	Athletic Trainer	SK	App	10.7	5/27/2020	-	-	-	None	-	-	-
1056-2	Athletic Trainer	IM	App	<1.0	5/27/2020	-	-	-	None	-	-	-
1057-1	Sports Locker Room by Athletic Trainer	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1058-1	Hall by 1628	WF	App	8.97	5/27/2020	-	-	-	None	-	-	-
1059-1	Room 1628 @ A	SK	App	2.66	5/27/2020	-	-	-	None	-	-	-
1059-2	Room 1628 @ B	SK	App	2.71	5/27/2020	-	-	-	None	-	-	-
1059-3	Room 1628 @ C	SK	App	13.3	5/27/2020	-	-	-	None	-	-	-
1060-1	Cardio Room Handwash	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1061-1	Girl's Seasonal Locker Room @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1061-2	Girl's Seasonal Locker Room @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1062-1	Boy's Seasonal Locker Room @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1062-2	Boy's Seasonal Locker Room @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1063-1	Boy's Bathroom 1638 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1063-2	Boy's Bathroom 1638 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1064-1	Girl's Bathroom 1640 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1064-2	Girl's Bathroom 1640 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1065-1	Coach Sipp's Office	SK	App	11.7	5/27/2020	-	-	-	None	-	-	-
1066-1	Hall by 1646 (left)	WF	App	3.72	5/27/2020	-	-	-	None	-	-	-
1066-2	Hall by 1646 (right)	WF	App	1.96	5/27/2020	-	-	-	None	-	-	-
1067-1	Girl's Locker Room @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1067-2	Girl's Locker Room @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1067-3	Girl's Locker Room @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1068-1	Boy's Locker Room @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1068-2	Boy's Locker Room @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1068-3	Boy's Locker Room @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1069-1	Storage Closet by Locker Rooms	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1070-1	Custodial Closet 1642	SS	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1071-1	Boy's Senior Locker Room Office Bathroom	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1071-2	Boy's Senior Locker Room Birdbath	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1072-1	Boy's Junior Locker Room Birdbath	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1073-1	Girl's Junior Locker Room Birdbath	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1074-1	Custodial Closet 1615	SS	N/A		5/27/2020	-	-	-	None	SIGN	-	-
1075-1	Girl's Senior Locker Room Office	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1075-2	Girl's Senior Locker Room Birdbath	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2001-1	Kitchen 2 3-Bay @ A	SK	App	1.28	5/27/2020	-	-	-	None	-	-	-
2001-2	Kitchen 2 3-Bay @ B	SK	App	7.05	5/27/2020	-	-	-	None	-	-	-
2001-3	Kitchen 2 Island	SK	App	2.78	5/27/2020	-	-	-	None	-	-	-
2001-4	Kitchen 2 Handwash @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2001-5	Kitchen 2 Handwash @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2002-1	2nd Floor Cafeteria (left)	WF	App	4.43	5/27/2020	-	-	-	None	-	-	-
2002-2	2nd Floor Cafeteria (right)	WF	App	64.5	5/27/2020				Additional Sampling Required	Removed from service		
2003-1	Unisex Bathroom 2501	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2004-1	Room 2402 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2004-2	Room 2402 Counter @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2004-3	Room 2402 Counter @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2005-1	Room 2402 Prep @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2005-2	Room 2402 Prep @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2006-1	Room 2404 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2006-2	Room 2404 Counter @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2006-3	Room 2404 Counter @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2007-1	Men's Bathroom 2318	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2008-1	Women's Bathroom 2316	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2009-1	Custodial Closet 2314	SS	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2010-1	Girl's Bathroom 2312 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2010-2	Girl's Bathroom 2312 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2010-3	Girl's Bathroom 2312 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2011-1	Men's Bathroom 2310 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2011-2	Men's Bathroom 2310 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2011-3	Men's Bathroom 2310 @ C	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2012-1	Hall by 2305	WF	App	1.03	5/27/2020	-	-	-	None	-	-	-
2013-1	Unisex Bathroom by 2144	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2014-1	Hall by 2144	WF	App	9.88	5/27/2020	-	-	-	None	-	-	-
2015-1	Boy's Bathroom by 2701 Birdbath	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2016-1	Girl's Bathroom by 2701 Birdbath	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2017-1	Room 2701 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2017-2	Room 2701 Counter 1	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2017-3	Room 2701 Counter 2	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2017-4	Room 2701 Pod 1 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2017-5	Room 2701 Pod 1 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2017-6	Room 2701 Pod 2 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2017-7	Room 2701 Pod 2 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2017-8	Room 2701 Pod 3 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2017-9	Room 2701 Pod 3 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2017-10	Room 2701 Pod 4 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2017-11	Room 2701 Pod 4 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2017-12	Room 2701 Pod 5 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2017-13	Room 2701 Pod 5 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2017-14	Room 2701 Pod 6 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2017-15	Room 2701 Pod 6 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2018-1	Office Room 2701/2705	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2019-1	Room 2705 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2019-2	Room 2705 Counter 1	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2019-3	Room 2705 Counter 2	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2019-4	Room 2705 Pod 1 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2019-5	Room 2705 Pod 1 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2019-6	Room 2705 Pod 2 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2019-7	Room 2705 Pod 2 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2019-8	Room 2705 Pod 3 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2019-9	Room 2705 Pod 3 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2019-10	Room 2705 Pod 4 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2019-11	Room 2705 Pod 4 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2019-12	Room 2705 Pod 5 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2019-13	Room 2705 Pod 5 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2019-14	Room 2705 Pod 6 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2019-15	Room 2705 Pod 6 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2020-1	Hall by 2705	WF	App	33.5	5/27/2020				Additional Sampling Required	Removed from service		
2021-1	Room 2707 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2021-2	Room 2707 Counter 1	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2021-3	Room 2707 Counter 2	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2021-4	Room 2707 Pod 1 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2021-5	Room 2707 Pod 1 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2021-6	Room 2707 Pod 2 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2021-7	Room 2707 Pod 2 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2021-8	Room 2707 Pod 3 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2021-9	Room 2707 Pod 3 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2021-10	Room 2707 Pod 4 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2021-11	Room 2707 Pod 4 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2021-12	Room 2707 Pod 5 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2021-13	Room 2707 Pod 5 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2021-14	Room 2707 Pod 6 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2021-15	Room 2707 Pod 6 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2022-1	Room 2707/2711 Office	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2023-1	Room 2711 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2023-2	Room 2711 Counter 1	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2023-3	Room 2711 Counter 2	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2023-4	Room 2711 Pod 1 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2023-5	Room 2711 Pod 1 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2023-6	Room 2711 Pod 2 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2023-7	Room 2711 Pod 2 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2023-8	Room 2711 Pod 3 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2023-9	Room 2711 Pod 3 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2023-10	Room 2711 Pod 4 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2023-11	Room 2711 Pod 4 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2023-12	Room 2711 Pod 5 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2023-13	Room 2711 Pod 5 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2023-14	Room 2711 Pod 6 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2023-15	Room 2711 Pod 6 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2024-1	Room 2715 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2024-2	Room 2715 Counter 1	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2024-3	Room 2715 Counter 2	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2025-1	Room 2715/2717 Office	SK	App	5.83	5/27/2020	-	-	-	None	-	-	-
2026-1	Room 2717 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2026-2	Room 2717 Counter 1	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2026-3	Room 2717 Counter 2	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2027-1	Hall by 2104	WF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
2027-2	Hall by 2104	BF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
2028-1	Teacher's Center Men's Bathroom	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2028-2	Teacher's Center Women's Bathroom	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2028-3	Teacher's Center Cafeteria	WF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
2028-4	Teacher's Center Cafeteria	BF	App	<1.0	5/27/2020	-	-	-	None	-	-	-
2028-5	Teacher's Center Kitchen	SK	App	3.44	5/27/2020	-	-	-	None	-	-	-
2028-6	Teacher's Center Kitchen	SPY	App	2.55	5/27/2020	-	-	-	None	-	-	-
2028-7	Teacher's Center Kitchen Handwash	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2029-1	Bathroom 2136	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2030-1	Bathroom 2138	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2031-1	Men's Room by 2600 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2031-2	Men's Room by 2600 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2032-1	Room 2600 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2032-2	Room 2600 Counter 1	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2032-3	Room 2600 Counter 2	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2032-4	Room 2600 Pod 1 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2032-5	Room 2600 Pod 1 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2032-6	Room 2600 Pod 2 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2032-7	Room 2600 Pod 2 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2032-8	Room 2600 Pod 3 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2032-9	Room 2600 Pod 3 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2032-10	Room 2600 Pod 4 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2032-11	Room 2600 Pod 4 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2032-12	Room 2600 Pod 5 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2032-13	Room 2600 Pod 5 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2032-14	Room 2600 Pod 6 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2032-15	Room 2600 Pod 6 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2033-1	Room 2600/2604 Office @ A	SK	App	8.1	5/27/2020	-	-	-	None	-	-	-
2033-2	Room 2600/2604 Office @ B	SK	App	20.7	5/27/2020				Additional Sampling Required	Permanent Sign Posted		
2034-1	Room 2604 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2034-2	Room 2604 Counter 1	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2034-3	Room 2604 Counter 2	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2034-4	Room 2604 Pod 1 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2034-5	Room 2604 Pod 1 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2034-6	Room 2604 Pod 2 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2034-7	Room 2604 Pod 2 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2034-8	Room 2604 Pod 3 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2034-9	Room 2604 Pod 3 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2034-10	Room 2604 Pod 4 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2034-11	Room 2604 Pod 4 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2034-12	Room 2604 Pod 5 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2034-13	Room 2604 Pod 5 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2034-14	Room 2604 Pod 6 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2034-15	Room 2604 Pod 6 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2035-1	Room 2606 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2035-2	Room 2606 Counter 1	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2035-3	Room 2606 Counter 2	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2035-4	Room 2606 Pod 1 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2035-5	Room 2606 Pod 1 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2035-6	Room 2606 Pod 2 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2035-7	Room 2606 Pod 2 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2035-8	Room 2606 Pod 3 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2035-9	Room 2606 Pod 3 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2035-10	Room 2606 Pod 4 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2035-11	Room 2606 Pod 4 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2035-12	Room 2606 Pod 5 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2035-13	Room 2606 Pod 5 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2035-14	Room 2606 Pod 6 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2035-15	Room 2606 Pod 6 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2036-1	Room 2606/2610 Office @ A	SK	App	13.7	5/27/2020	-	-	-	None	-	-	-
2036-2	Room 2606/2610 Office @ B	SK	App	10.2	5/27/2020	-	-	-	None	-	-	-
2037-1	Room 2610 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2037-2	Room 2610 Counter 1	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2037-3	Room 2610 Counter 2	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2037-4	Room 2610 Pod 1 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2037-5	Room 2610 Pod 1 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2037-6	Room 2610 Pod 2 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2037-7	Room 2610 Pod 2 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2037-8	Room 2610 Pod 3 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2037-9	Room 2610 Pod 3 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2037-10	Room 2610 Pod 4 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2037-11	Room 2610 Pod 4 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2037-12	Room 2610 Pod 5 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2037-13	Room 2610 Pod 5 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2037-14	Room 2610 Pod 6 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2037-15	Room 2610 Pod 6 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2038-1	Room 2612 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2038-2	Room 2612 Counter 1	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2038-3	Room 2612 Counter 2	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2039-1	Room 2612/2616 Office	SK	App	44	5/27/2020				Additional Sampling Required	Permanent Sign Posted		
2040-1	Room 2616 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2040-2	Room 2616 Counter 1	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2040-3	Room 2616 Counter 2	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2041-1	Room 2618 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2041-2	Room 2618 Counter 1	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2041-3	Room 2618 Counter 2 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2041-4	Room 2618 Counter 2 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2041-5	Room 2618 Pod 1 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2041-6	Room 2618 Pod 1 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2041-7	Room 2618 Pod 2 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2041-8	Room 2618 Pod 2 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2041-9	Room 2618 Pod 3 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2041-10	Room 2618 Pod 3 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2041-11	Room 2618 Pod 4 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2041-12	Room 2618 Pod 4 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2041-13	Room 2618 Pod 5 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2041-14	Room 2618 Pod 5 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2041-15	Room 2618 Pod 6 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2041-16	Room 2618 Pod 6 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2042-1	Room 2618/2620 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2042-2	Room 2618/2620 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-1	Room 2620 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-2	Room 2620 Pod 1 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-3	Room 2620 Pod 1 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-4	Room 2620 Pod 2 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-5	Room 2620 Pod 2 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-6	Room 2620 Pod 3 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-7	Room 2620 Pod 3 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-8	Room 2620 Counter 1 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-9	Room 2620 Counter 1 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-10	Room 2620 Counter 2	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-11	Room 2620 Pod 4 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-12	Room 2620 Pod 4 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-13	Room 2620 Pod 5 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-14	Room 2620 Pod 5 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-15	Room 2620 Pod 6 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2043-16	Room 2620 Pod 6 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2044-1	Hall by 2623 (left)	WF	App	6.65	5/27/2020	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2044-2	Hall by 2623 (right)	WF	App	2.41	5/27/2020	-	-	-	None	-	-	-
2045-1	Men's Bathroom by 2623	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2046-1	Women's Bathroom by 2623	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-1	Room 2624 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-2	Room 2624 Pod 1 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-3	Room 2624 Pod 1 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-4	Room 2624 Pod 2 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-5	Room 2624 Pod 2 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-6	Room 2624 Pod 3 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-7	Room 2624 Pod 3 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-8	Room 2624 Counter 1	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-9	Room 2624 Counter 1 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-10	Room 2624 Counter 2 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-11	Room 2624 Pod 4 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-12	Room 2624 Pod 4 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-13	Room 2624 Pod 5 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-14	Room 2624 Pod 5 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-15	Room 2624 Pod 6 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2047-16	Room 2624 Pod 6 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2048-1	Room 2626 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2048-2	Room 2626 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-1	Room 2628 Teacher's Station	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-2	Room 2628 Pod 1 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-3	Room 2628 Pod 1 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-4	Room 2628 Pod 2 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-5	Room 2628 Pod 2 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-6	Room 2628 Pod 3 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-7	Room 2628 Pod 3 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-8	Room 2628 Counter 1	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-9	Room 2628 Counter 1 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-10	Room 2628 Counter 2 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-11	Room 2628 Pod 4 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-12	Room 2628 Pod 4 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-13	Room 2628 Pod 5 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-14	Room 2628 Pod 5 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-15	Room 2628 Pod 6 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2049-16	Room 2628 Pod 6 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2050-1	Room 2635	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2051-1	Room 2033 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2051-2	Room 2033 @B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2052-1	Room 2031 @ A	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2052-2	Room 2031 @ B	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2053-1	Custodial Closet 2613	SS	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2053-2	Custodial Closet 2613	IM	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2054-1	Hall by 2613	WF	App	11.5	5/27/2020	-	-	-	None	-	-	-
2055-1	Hall by 2122	WF	App	11	5/27/2020	-	-	-	None	-	-	-
2056-1	Girl's Bathroom by 2122 Birdbath	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2057-1	Boy's Bathroom by 2122 Birdbath	SK	N/A		5/27/2020	-	-	-	None	SIGN	-	-
2058-1	Hall by Teacher's Center	WF	App		10/7/2021	-	-	-	None	Removed from service	-	-
2058-2	Hall by Teacher's Center	BF	App	<1.0	10/7/2021	-	-	-	None	-	-	-

Action Level = 15.0 parts per billion (ppb) (µg/L)

ENVIROSCIENCE CONSULTANTS INC.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2201940-14560

June 2, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Longwood High School

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on June 01, 2020. New York Environmental analyzed the samples on June 02, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

Date Collected:	27 May 2020
Date Received:	01 Jun 2020
Date Analyzed:	02 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200601M077	1	Kitchen 1 Island-SK ;Initial	1.00	11.7	µg/L	
200601M078	2	Kitchen 1 3-Bay @ A-SK ;Initial	1.00	5.73	µg/L	
200601M079	3	Kitchen 1 3-Bay @ B-SK ;Initial	1.00	14.5	µg/L	
200601M080	4	Cafeteria (left)-WF ;Initial	1.00	3.32	µg/L	
200601M081	5	Hall by 1107-WF ;Initial	1.00	1.31	µg/L	
200601M082	6	Room 1400 Prep @ A-SK ;Initial	1.00	13.2	µg/L	
200601M083	7	Room 1400 Prep @ B-SK ;Initial	1.00	8.68	µg/L	
200601M084	8	Hall by 1405-WF ;Initial	1.00	<1.00	µg/L	
200601M085	9	Kitchen 3 3-Bay @ A-SK ;Initial	1.00	3.25	µg/L	
200601M086	10	Kitchen 3 3-Bay @ B-SK ;Initial	1.00	2.20	µg/L	
200601M087	11	Kitchen 3 Island by 3 Bay-SK ;Initial	1.00	7.08	µg/L	
200601M088	12	Kitchen 3 Island by Clock-SK ;Initial	1.00	3.70	µg/L	
200601M089	13	Hall by 1305-WF ;Initial	1.00	2.58	µg/L	
200601M090	14	Hall by 1148-WF ;Initial	1.00	7.09	µg/L	
200601M091	15	Hall by Auditorium-WF ;Initial	1.00	5.78	µg/L	
200601M092	16	Family Services-SK ;Initial	1.00	3.12	µg/L	
200601M093	17	Room 1711 Station 1-SK ;Initial	1.00	2.25	µg/L	
200601M094	18	Room 1711 Station 1-SPY ;Initial	1.00	3.38	µg/L	
200601M095	19	Room 1711 Station 2-SK ;Initial	1.00	1.62	µg/L	
200601M096	20	Room 1711 Station 2-SPY ;Initial	1.00	2.38	µg/L	
200601M097	21	Room 1711 Station 3-SK ;Initial	1.00	2.30	µg/L	
200601M098	22	Room 1711 Station 3-SPY ;Initial	1.00	2.71	µg/L	
200601M099	23	Room 1711 Station 4-SK ;Initial	1.00	13.1	µg/L	
200601M100	24	Room 1711 Station 4-SPY ;Initial	1.00	2.67	µg/L	
200601M101	25	Room 1711 Station 5-SK ;Initial	1.00	11.7	µg/L	
200601M102	26	Room 1711 Station 5-SPY ;Initial	1.00	1.65	µg/L	

Date Collected:	27 May 2020
Date Received:	01 Jun 2020
Date Analyzed:	02 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200601M103	27	Room 1713 Teacher's Station-SK ;Initial	1.00	2.56	µg/L	
200601M104	28	Room 1713 Counter @ A-SK ;Initial	1.00	4.06	µg/L	
200601M105	29	Room 1713 Counter @ B-SK ;Initial	1.00	2.50	µg/L	
200601M106	30	Room 1713 Counter @ C-SK ;Initial	1.00	<1.00	µg/L	
200601M107	31	Room 1713 Counter @ D-SK ;Initial	1.00	5.16	µg/L	
200601M108	32	Room 1715 Counter @ A-SK ;Initial	1.00	99.0	µg/L	E,H
200601M109	33	Room 1715 Counter @ B-SK ;Initial	1.00	42.1	µg/L	H
200601M110	34	Room 1715 Counter @ C-SK ;Initial	1.00	19.3	µg/L	H
200601M111	35	Hall by 1823-WF ;Initial	1.00	5.60	µg/L	
200601M112	36	Nurse's Office-SK ;Initial	1.00	7.89	µg/L	
200601M113	37	Nurse's Office Exam Room 1-SK ;Initial	1.00	43.5	µg/L	H
200601M114	38	Nurse's Office Exam Room 2-SK ;Initial	1.00	15.5	µg/L	H
200601M115	39	Nurse's Office Bathroom 1-SK ;Initial	1.00	29.1	µg/L	H
200601M116	40	Nurse's Office Bathroom 2-SK ;Initial	1.00	9.80	µg/L	
200601M117	41	Physical Education Offices Kitchenette-SK ;Initial	1.00	<1.00	µg/L	
200601M118	42	Physical Education Offices Kitchenette-SPY ;Initial	1.00	<1.00	µg/L	
200601M119	43	Hall by 1604-WF ;Initial	1.00	<1.00	µg/L	
200601M120	44	Hall by 1604-BF ;Initial	1.00	<1.00	µg/L	
200601M121	45	Hall by 1614-WF ;Initial	1.00	16.0	µg/L	H
200601M122	46	Athletic Trainer-SK ;Initial	1.00	10.7	µg/L	
200601M123	47	Athletic Trainer-IM ;Initial	1.00	<1.00	µg/L	
200601M124	48	Hall by 1628-WF ;Initial	1.00	8.97	µg/L	
200601M125	49	Room 1628 @ A-SK ;Initial	1.00	2.66	µg/L	
200601M126	50	Room 1628 @ B-SK ;Initial	1.00	2.71	µg/L	
200601M127	51	Room 1628 @ C-SK ;Initial	1.00	13.3	µg/L	
200601M128	52	Coach Sipp's Office-SK ;Initial	1.00	11.7	µg/L	
200601M129	53	Hall by 1646 (left)-WF ;Initial	1.00	3.72	µg/L	

Date Collected:	27 May 2020
Date Received:	01 Jun 2020
Date Analyzed:	02 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200601M130	54	Hall by 1646 (right)-WF ;Initial	1.00	1.96	µg/L	
200601M131	55	Kitchen 2 3-Bay @ A-SK ;Initial	1.00	1.28	µg/L	
200601M132	56	Kitchen 2 3-Bay @ B-SK ;Initial	1.00	7.05	µg/L	
200601M133	57	Kitchen 2 Island-SK ;Initial	1.00	2.78	µg/L	
200601M134	58	2nd Floor Cafeteria (left)-WF ;Initial	1.00	4.43	µg/L	
200601M135	59	2nd Floor Cafeteria (right)-WF ;Initial	1.00	64.5	µg/L	E,H
200601M136	60	Hall by 2305-WF ;Initial	1.00	1.03	µg/L	
200601M137	61	Hall by 2144-WF ;Initial	1.00	9.88	µg/L	
200601M138	62	Hall by 2705-WF ;Initial	1.00	33.5	µg/L	H
200601M139	63	Room 2715/2717 Office-SK ;Initial	1.00	5.83	µg/L	
200601M140	64	Hall by 2104-WF ;Initial	1.00	<1.00	µg/L	
200601M141	65	Hall by 2104-BF ;Initial	1.00	<1.00	µg/L	
200601M142	66	Teacher's Center Cafeteria-WF ;Initial	1.00	<1.00	µg/L	
200601M143	67	Teacher's Center Cafeteria-BF ;Initial	1.00	<1.00	µg/L	
200601M144	68	Teacher's Center Kitchen-SK ;Initial	1.00	3.44	µg/L	
200601M145	69	Teacher's Center Kitchen-SPY ;Initial	1.00	2.55	µg/L	
200601M146	70	Room 2600/2604 Office @ A-SK ;Initial	1.00	8.10	µg/L	
200601M147	71	Room 2600/2604 Office @ B-SK ;Initial	1.00	20.7	µg/L	H
200601M148	72	Room 2606/2610 Office @ A-SK ;Initial	1.00	13.7	µg/L	
200601M149	73	Room 2606/2610 Office @ B-SK ;Initial	1.00	10.2	µg/L	
200601M150	74	Room 2612/2616 Office-SK ;Initial	1.00	44.0	µg/L	H
200601M151	75	Hall by 2623 (left)-WF ;Initial	1.00	6.65	µg/L	
200601M152	76	Hall by 2623 (right)-WF ;Initial	1.00	2.41	µg/L	
200601M153	77	Hall by 2613-WF ;Initial	1.00	11.5	µg/L	
200601M154	78	Hall by 2122-WF ;Initial	1.00	11.0	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report

NYE Report #: 2204110-15848

October 12, 2020

Project Manager
Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Longwood High School

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on October 09, 2020. New York Environmental analyzed the samples on October 12, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

NYE Report #: 2204110-15848

Date Collected:	07 Oct 2020
Date Received:	09 Oct 2020
Date Analyzed:	12 Oct 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201009Q016	1	Room 1715 Trough @ A, Initial	1.00	44.8	µg/L	H
201009Q017	2	Room 1715 Trough @ B, Initial	1.00	9.05	µg/L	
201009Q018	3	Room 1715 Trough @ C, Initial	1.00	11.3	µg/L	
201009Q019	4	Nurse's Office Exam Room 1, Initial	1.00	19.8	µg/L	H
201009Q020	5	Nurse's Office Exam Room 2, Initial	1.00	2.02	µg/L	
201009Q021	6	Nurse's Office Bathroom-SK, Initial	1.00	3.61	µg/L	
201009Q022	7	Hall by Faculty Center-BF, Initial	1.00	<1.00	µg/L	
201009Q023	8	Faculty Center Cafeteria-BF, Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

H: Sample result exceeds applicable regulatory limit.

Appendix L

Space #	Sample Location	Fixture Type	App or N/A	1st Draw Results (ppb)	1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	**Housekeeping Training Room**	**SK**	**App**	**32.4**	**5/29/2020**				**Additional Sampling Required**			
1002-1	Kitchen Prep Training Room 3-Bay @ A	SK	App	6.3	5/29/2020	-	-	-	None	-	-	-
1002-2	Kitchen Prep Training Room 3-Bay @ B	SK	App	3.24	5/29/2020	-	-	-	None	-	-	-
1002-3	Kitchen Prep Training Room Island	SK	App	5.7	5/29/2020	-	-	-	None	-	-	-
1002-4	Kitchen Prep Training Room Custodial Closet	SS	N/A		5/29/2020	-	-	-	None	SIGN	-	-
1003-1	Girl's Bathroom	SK	App	2.86	5/29/2020	-	-	-	None	-	-	-
1004-1	Staff Bathroom	SK	App	3.56	5/29/2020	-	-	-	None	-	-	-
1005-1	Boy's Bathroom	SK	App	12.5	5/29/2020	-	-	-	None	-	-	-
1006-1	Back Porch	OS	App		5/29/2020	-	-	-	Turned off. Sampling required if activated and used for garden	-	-	-

NEW YORK ENVIRONMENTAL

88 Harbor Road
Port Washington, NY 11050
(516) 944-9500
www.nyenvironmental.com

Laboratory Report (Revised)

NYE Report #: 2201997-14598R

June 10, 2020

Enviroscience Consultants, Inc.
2150 Smithtown Avenue
Ronkonkoma, NY 11779

Project: Longwood Career Center - Longwood CSD

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on June 05, 2020. New York Environmental analyzed the samples on June 08, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,

Li Tsang, Laboratory Director

Date Collected:	29 May 2020
Date Received:	05 Jun 2020
Date Analyzed:	08 Jun 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
200605N281	1	Home Economics Training Room-SK; Initial	1.00	32.4	µg/L	H
200605N282	2	Kitchen 3-Bay @ A-SK; Initial	1.00	6.30	µg/L	
200605N283	3	Kitchen 3-Bay @ B-SK; Initial	1.00	3.24	µg/L	
200605N284	4	Kitchen Island-SK; Initial	1.00	5.70	µg/L	
200605N285	5	Bathroom by Kitchen-SK; Initial	1.00	2.86	µg/L	
200605N286	6	Women's Bathroom-SK; Initial	1.00	3.56	µg/L	
200605N287	7	Men's Bathroom-SK; Initial	1.00	12.5	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

H: Sample result exceeds applicable regulatory limit.

Revision History:

Report revised on 6/10/2020, replaces report generated on 6/9/2020.

- Project location updated as per client request on 6/10/2020.