ENVOY
environmental consultants inc.

November 17, 2016

Mr. Gerhard Leuer
Medina Central School District
One Mustang Drive
Medina, New York 14103

Re: Environmental Water Sampling – Medina Elementary School

Dear Mr. Leuer,

Envoy Environmental was contracted on September 27, 2016 to perform Environmental Water Sampling at Medina Elementary School located at 335 West Oak Orchard Street in Medina, New York. We understand the Medina Central School District is evaluating the data based on the NYS Department of Health ("NYSDOH") Emergency Regulation, Lead Testing in School Drinking Water (Subpart 67-4) as well as the EPA's 3T's for Reducing Lead in Drinking Water in Schools Guidance Document. All sampling conducted was done in accordance with the NYSDOH regulations as it pertains to testing schools for lead in the drinking water.

Samples taken were based on both the direction of the client, and areas designated as high priority as outlined by the NYSDOH regulations. All water samples collected were 250 mL and taken as a "first draw" from each testing location. First draw samples are defined as a sample of tap water, collected in accordance with the NYSDOH regulations, that has been standing in plumbing pipes at least 8 hours and not more than 18 hours and is collected without prior flushing of the tap. The NYSDOH regulations identifies the Action Level at 15 ppb.

Water sampling analysis was contracted through Con-Test Analytical Laboratory located in Richmond, Virginia, a NYS ELAP approved laboratory. The sampling and analytical testing was conducted in compliance with the USEPA Requirements for Lead Sampling and Testing Protocols. The following USEPA Methodologies were used to prepare and analyze the drinking water samples for Lead:

Drinking Water Sample Preparation	USEPA Method 200.2
Lead by ICP-MS	USEPA Method 200.8

Each sample was preserved, at Con-Test Analytical Laboratory, with nitric acid to reduce the pH to less than 2 as per USEPA Method 200.2.

Chain of Custody ("COC") forms are used to document the history of sample possession from the time the sample containers leave their point of origin to the time the samples are received by the laboratory.

In Table 1 of this report we have listed water samples that are above 15 ppb.

TABLE 1

Medina Elementary School			
Sample ID	**Water Source**	**Level Detected (PPB)**	**Remedial Suggestions**
ES-1-CS-020	Classroom Sink	240	1. Take outlet out of service. 2. Do not use for drinking water purposes – adequate signage. 3. Clean aerator, re-test "first draw" and "flush" samples to identify if the problem is at the outlet or interior plumbing; and/or, 4. Replace outlet with NSF-approved devices and re-test.
ES-1-CS-030	Classroom Sink	72	
ES-1-CS-031	Classroom Sink	28	
ES-1-DW-46	Drinking Water Bubbler	18	
ES-1-DW-069	Drinking Water Bubbler	61	
ES-1-CS-071	Classroom Sink	16	
ES-2-CS-095	Classroom Sink	39	
ES-2-CS-111	Classroom Sink	21	

Solutions to lead problems need to be made on both a short-term and a permanent basis. Short-term measures could include flushing the pipes to bring fresh water to the source, removing the outlet from service or providing bottled water until the source of contamination is resolved. Permanent remedies can be implemented in order to eliminate the contaminant source. These options, outlined in the 3Ts guidance document include:

- Install corrosion control devices for individual buildings, known as point-of-entry devices.
- Install point-of-use devices that control lead at the tap.
- Find alternate grounding for electrical wires that are grounded to water pipes.
- Replace lead service lines and other lead pipes.
- Replace outlets where there is localized contamination with new, certified components. EPA recognizes NSF Standard 61, Section 9 as a performance standard. It limits leaching of lead into the drinking water. The standard regulates devices that dispense water for human ingestion.[1]

Routine control measures can also be implemented by Medina Central School District to properly address each situation, such as cleaning aerators regularly and placard sinks with notices that water should not be consumed, until appropriate permanent actions can be implemented, such as removing/replacing a fixture.

The remedial options are based on the 3Ts guidance document as referenced in the NYSDOH Emergency Regulation:

"The Environmental Protection Agency's *3Ts for Reducing Lead in Drinking Water in Schools, Revised Technical Guidance* will be used as a technical reference for implementation of the regulation."

Please refer to the attached laboratory reports for specific analytical data and sample locations throughout the school. If you have any questions, please contact me at (585) 454-1060. We appreciate the opportunity to provide you with our professional services.

[1]https://www.epa.gov/dwreginfo/testing-schools-and-child-care-centers-lead-drinking-water

Sincerely,

Ted Knapp
Project Manager
Envoy Environmental Consultants, Inc.

[1]https://www.epa.gov/dwreginfo/testing-schools-and-child-care-centers-lead-drinking-water

Table of Contents

Sample Summary 3

Case Narrative 4

Sample Results 5

16K0491-01 5

16K0491-02 6

16K0491-03 7

16K0491-04 8

16K0491-05 9

16K0491-06 10

16K0491-07 11

16K0491-08 12

16K0491-09 13

Sample Preparation Information 14

QC Data 15

Metals Analyses (Total) 15

B163218 15

Flag/Qualifier Summary 16

Certifications 17

Chain of Custody/Sample Receipt 18

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Environmental Hazards Services, LLC
7469 White Pine Road
Richmond, VA 23237
ATTN: Greg Brown

REPORT DATE: 11/16/2016

PURCHASE ORDER NUMBER:

PROJECT NUMBER: E16-1474

ANALYTICAL SUMMARY

WORK ORDER NUMBER: 16K0491

The results of analyses performed on the following samples submitted to the CON-TEST Analytical Laboratory are found in this report.

PROJECT LOCATION: Medina E.S./ 335 W. Oak Orchard

FIELD SAMPLE #	LAB ID:	MATRIX	SAMPLE DESCRIPTION	TEST	SUB LAB
ES-1-DW-1	16K0491-01	Drinking Water	drinking water	EPA 200.8	
ES-1-BS-15	16K0491-02	Drinking Water	bathroom sink	EPA 200.8	
ES-1-CS-18	16K0491-03	Drinking Water	classroom sink	EPA 200.8	
ES-1-DW-46	16K0491-04	Drinking Water	drinking water	EPA 200.8	
ES-1-DW-47	16K0491-05	Drinking Water	drinking water	EPA 200.8	
ES-1-CS-61	16K0491-06	Drinking Water	classroom sink	EPA 200.8	
ES-1-DW-75	16K0491-07	Drinking Water	drinking water	EPA 200.8	
ES-2-CS-90	16K0491-08	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-91	16K0491-09	Drinking Water	classroom sink	EPA 200.8	

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

CASE NARRATIVE SUMMARY

All reported results are within defined laboratory quality control objectives unless listed below or otherwise qualified in this report.

REVISED REPORT - 11/16/2016 - Project location revised.

The results of analyses reported only relate to samples submitted to the Con-Test Analytical Laboratory for testing.
I certify that the analyses listed above, unless specifically listed as subcontracted, if any, were performed under my direction according to the approved methodologies listed in this document, and that based upon my inquiry of those individuals immediately responsible for obtaining the information, the material contained in this report is, to the best of my knowledge and belief, accurate and complete.

Meghan E. Kelley
Project Manager

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Medina E.S./ 335 W. Oak Orchard Sample Description: drinking water Work Order: 16K0491

Date Received: 11/2/2016

Field Sample #: ES-1-DW-1 Sampled: 9/27/2016 00:00

Sample ID: 16K0491-01

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	11/12/16	11/15/16 7:18	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Medina E.S./ 335 W. Oak Orchard Sample Description: bathroom sink Work Order: 16K0491

Date Received: 11/2/2016

Field Sample #: ES-1-BS-15 Sampled: 9/27/2016 00:00

Sample ID: 16K0491-02

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.2	0.50	15	µg/L	1		EPA 200.8	11/12/16	11/15/16 7:31	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Medina E.S./ 335 W. Oak Orchard Sample Description: classroom sink Work Order: 16K0491

Date Received: 11/2/2016

Field Sample #: ES-1-CS-18 Sampled: 9/27/2016 00:00

Sample ID: 16K0491-03

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	0.97	0.50	15	µg/L	1		EPA 200.8	11/12/16	11/15/16 7:35	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Medina E.S./ 335 W. Oak Orchard Sample Description: drinking water Work Order: 16K0491

Date Received: 11/2/2016

Field Sample #: ES-1-DW-46 Sampled: 9/27/2016 00:00

Sample ID: 16K0491-04

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
# Lead	18	0.50	15	µg/L	1		EPA 200.8	11/12/16	11/15/16 7:39	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Medina E.S./ 335 W. Oak Orchard Sample Description: drinking water Work Order: 16K0491

Date Received: 11/2/2016

Field Sample #: ES-1-DW-47 Sampled: 9/27/2016 00:00

Sample ID: 16K0491-05

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	11/12/16	11/15/16 7:52	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Medina E.S./ 335 W. Oak Orchard Sample Description: classroom sink Work Order: 16K0491

Date Received: 11/2/2016

Field Sample #: ES-1-CS-61 Sampled: 9/27/2016 00:00

Sample ID: 16K0491-06

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	1.6	0.50	15	µg/L	1		EPA 200.8	11/12/16	11/15/16 7:56	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Medina E.S./ 335 W. Oak Orchard Sample Description: drinking water Work Order: 16K0491

Date Received: 11/2/2016

Field Sample #: ES-1-DW-75 Sampled: 9/27/2016 00:00

Sample ID: 16K0491-07

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	6.0	0.50	15	µg/L	1		EPA 200.8	11/12/16	11/15/16 8:00	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Medina E.S./ 335 W. Oak Orchard Sample Description: classroom sink Work Order: 16K0491

Date Received: 11/2/2016

Field Sample #: ES-2-CS-90 Sampled: 9/27/2016 00:00

Sample ID: 16K0491-08

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	8.3	0.50	15	µg/L	1		EPA 200.8	11/12/16	11/15/16 8:04	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Medina E.S./ 335 W. Oak Orchard Sample Description: classroom sink Work Order: 16K0491

Date Received: 11/2/2016

Field Sample #: ES-2-CS-91 Sampled: 9/27/2016 00:00

Sample ID: 16K0491-09

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	4.3	0.50	15	µg/L	1		EPA 200.8	11/12/16	11/15/16 8:08	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Sample Extraction Data

Prep Method: EPA 200.8-EPA 200.8

Lab Number [Field ID]	Batch	Initial [mL]	Final [mL]	Date
16K0491-01 [ES-1-DW-1]	B163218	10.0	10.0	11/12/16
16K0491-02 [ES-1-BS-15]	B163218	10.0	10.0	11/12/16
16K0491-03 [ES-1-CS-18]	B163218	10.0	10.0	11/12/16
16K0491-04 [ES-1-DW-46]	B163218	10.0	10.0	11/12/16
16K0491-05 [ES-1-DW-47]	B163218	10.0	10.0	11/12/16
16K0491-06 [ES-1-CS-61]	B163218	10.0	10.0	11/12/16
16K0491-07 [ES-1-DW-75]	B163218	10.0	10.0	11/12/16
16K0491-08 [ES-2-CS-90]	B163218	10.0	10.0	11/12/16
16K0491-09 [ES-2-CS-91]	B163218	10.0	10.0	11/12/16

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

QUALITY CONTROL

Metals Analyses (Total) - Quality Control

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch B163218 - EPA 200.8										
Blank (B163218-BLK1)				Prepared: 11/12/16	Analyzed: 11/15/16					
Lead	ND	0.50	µg/L							
LCS (B163218-BS1)				Prepared: 11/12/16	Analyzed: 11/15/16					
Lead	40.9	0.50	µg/L	40.0		102	85-115			
Duplicate (B163218-DUP1)		**Source: 16K0491-01**		Prepared: 11/12/16	Analyzed: 11/15/16					
Lead	ND	0.50	µg/L		ND			NC	20	
Duplicate (B163218-DUP2)		**Source: 16K0491-02**		Prepared: 11/12/16	Analyzed: 11/15/16					
Lead	2.21	0.50	µg/L		2.19			0.798	20	
Matrix Spike (B163218-MS1)		**Source: 16K0491-01**		Prepared: 11/12/16	Analyzed: 11/15/16					
Lead	28.1	0.62	µg/L	25.0	0.271	111	70-130			
Matrix Spike (B163218-MS2)		**Source: 16K0491-02**		Prepared: 11/12/16	Analyzed: 11/15/16					
Lead	29.1	0.62	µg/L	25.0	2.19	108	70-130			

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

FLAG/QUALIFIER SUMMARY

*	QC result is outside of established limits.
†	Wide recovery limits established for difficult compound.
‡	Wide RPD limits established for difficult compound.
#	Data exceeded client recommended or regulatory level
ND	Not Detected
RL	Reporting Limit
DL	Method Detection Limit
MCL	Maximum Contaminant Level

Percent recoveries and relative percent differences (RPDs) are determined by the software using values in the calculation which have not been rounded.

No results have been blank subtracted unless specified in the case narrative section.

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

CERTIFICATIONS

Certified Analyses included in this Report

Analyte	Certifications
EPA 200.8 in Drinking Water	
Lead	NH,NY,MA,CT,RI,ME,VA

The CON-TEST Environmental Laboratory operates under the following certifications and accreditations:

Code	Description	Number	Expires
AIHA	AIHA-LAP, LLC - ISO17025:2005	100033	02/1/2018
MA	Massachusetts DEP	M-MA100	06/30/2017
CT	Connecticut Department of Publilc Health	PH-0567	09/30/2017
NY	New York State Department of Health	10899 NELAP	04/1/2017
NH-S	New Hampshire Environmental Lab	2516 NELAP	02/5/2017
RI	Rhode Island Department of Health	LAO00112	12/30/2016
NC	North Carolina Div. of Water Quality	652	12/31/2016
NJ	New Jersey DEP	MA007 NELAP	06/30/2017
FL	Florida Department of Health	E871027 NELAP	06/30/2017
VT	Vermont Department of Health Lead Laboratory	LL015036	07/30/2017
ME	State of Maine	2011028	06/9/2017
VA	Commonwealth of Virginia	460217	12/14/2016
NH-P	New Hampshire Environmental Lab	2557 NELAP	09/6/2017

EHS Laboratories™

Environmental Hazards Services, LLC
www.ehslab.com
(800) 347-4010
(804) 278-4907 (fax)
7469 Whitepine Rd
Richmond VA 23237

Project # E16-1474

WaterSmart® Pro LEAD ONLY Chain-of-Custody

Analysis by National Testing Laboratories

16K0491

16-11-01830

Due Date: 11/16/2016 (Wednesday)
AE MC

Company Name: Envoy Environmental Address: 57 Ambrose St City/State/Zip:

Phone: (585) 454-1060 Fax: (585) 454-1062 E-mail: TKnapp@envoyenvironmental.com Acct. Number:

Project Name/Testing Address: MEDINA E.S. / 335 W. OAK ORCHARD City/State (Required): MEDINA, N.Y. Zip: 14103 Age of Property:

Collected by: JEFF HERTEL / ANDREW DISTAFFEN Certification #: Well Tag # (If applicable):

Purchase Order Number: Relinquished by: J. HERTEL / A. DISTAFFEN Date:

[illegible]

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field PH:	Field Chlorine:	Temperature at Time of Collection:
01	1	ES-1 - DW - 1	DRINKING WATER	9-27-16		Lead			
02	2	ES-1 - BS - 15	BATHROOM SINK	↓		Lead			
03	3	ES-1 - CS - 18	CLASSROOM SINK	↓		Lead			
04	4	ES-1 - DW - 46	DRINKING WATER	↓		Lead			
05	5	ES-1 - DW - 47	↓	↓		Lead			
06	6	ES-1 - CS - 61	CLASSROOM SINK	↓		Lead			
07	7	ES-1 - DW - 75	DRINKING WATER	↓		Lead			
08	8	ES-2 - CS - 90	CLASSROOM SINK	↓		Lead			
09	9	ES-2 - CS - 91	↓	↓		Lead			
	10					Lead			

Received by: [illegible] Date: 11/2/16 Time: 1303

Tracking Number: 12 5466 004 904530 8901 Temperature: 19°C

NTL Lab ID Number

Page ____ of ____

Table of Contents

Sample Summary 6

Case Narrative 8

Sample Results 9

16J0615-02 9

16J0615-03 10

16J0615-04 11

16J0615-05 12

16J0615-06 13

16J0615-07 14

16J0615-08 15

16J0615-09 16

16J0615-10 17

16J0615-11 18

16J0615-12 19

16J0615-13 20

16J0615-14 21

16J0615-16 22

16J0615-17 23

16J0615-19 24

16J0615-20 25

16J0615-21 26

16J0615-22 27

16J0615-23 28

16J0615-24 29

16J0615-25 30

Table of Contents (continued)

16J0615-26	31
16J0615-27	32
16J0615-28	33
16J0615-29	34
16J0615-30	35
16J0615-31	36
16J0615-32	37
16J0615-33	38
16J0615-34	39
16J0615-35	40
16J0615-36	41
16J0615-37	42
16J0615-38	43
16J0615-39	44
16J0615-40	45
16J0615-41	46
16J0615-42	47
16J0615-43	48
16J0615-44	49
16J0615-45	50
16J0615-48	51
16J0615-49	52
16J0615-50	53
16J0615-51	54
16J0615-52	55

Table of Contents (continued)

16J0615-53	56
16J0615-54	57
16J0615-55	58
16J0615-56	59
16J0615-57	60
16J0615-58	61
16J0615-59	62
16J0615-60	63
16J0615-62	64
16J0615-63	65
16J0615-64	66
16J0615-65	67
16J0615-66	68
16J0615-67	69
16J0615-68	70
16J0615-69	71
16J0615-70	72
16J0615-71	73
16J0615-72	74
16J0615-73	75
16J0615-74	76
16J0615-76	77
16J0615-77	78
16J0615-78	79
16J0615-79	80

Table of Contents (continued)

16J0615-80 81

16J0615-81 82

16J0615-82 83

16J0615-83 84

16J0615-84 85

16J0615-85 86

16J0615-86 87

16J0615-87 88

16J0615-88 89

16J0615-89 90

Sample Preparation Information 91

QC Data 93

Metals Analyses (Total) 93

B160821 93

B160822 93

B160832 93

B160833 94

B160835 94

B160911 95

Flag/Qualifier Summary 96

Certifications 97

Chain of Custody/Sample Receipt 98

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Environmental Hazards Services, LLC
7469 White Pine Road
Richmond, VA 23237
ATTN: Greg Brown

REPORT DATE: 10/25/2016

PURCHASE ORDER NUMBER:

PROJECT NUMBER: [none]

ANALYTICAL SUMMARY

WORK ORDER NUMBER: 16J0615

The results of analyses performed on the following samples submitted to the CON-TEST Analytical Laboratory are found in this report.

PROJECT LOCATION: Elementary School/ 335 W. Oak Orchard., Medina, NY

FIELD SAMPLE #	LAB ID:	MATRIX	SAMPLE DESCRIPTION	TEST	SUB LAB
ES-1-OS-002	16J0615-02	Drinking Water	office sink	EPA 200.8	
ES-1-BS-003	16J0615-03	Drinking Water	bathroom sink	EPA 200.8	
ES-1-BS-004	16J0615-04	Drinking Water	bathroom sink	EPA 200.8	
ES-1-BS-005	16J0615-05	Drinking Water	bathroom sink	EPA 200.8	
ES-1-DW-006	16J0615-06	Drinking Water	drinking water	EPA 200.8	
ES-1-BS-007	16J0615-07	Drinking Water	bathroom sink	EPA 200.8	
ES-1-BS-008	16J0615-08	Drinking Water	bathroom sink	EPA 200.8	
ES-1-OS-009	16J0615-09	Drinking Water	office sink	EPA 200.8	
ES-1-KS-010	16J0615-10	Drinking Water	kitchen sink	EPA 200.8	
ES-1-KS-011	16J0615-11	Drinking Water	kitchen sink	EPA 200.8	
ES-1-KS-012	16J0615-12	Drinking Water	kitchen sink	EPA 200.8	
ES-1-KS-013	16J0615-13	Drinking Water	kitchen sink	EPA 200.8	
ES-1-KS-014	16J0615-14	Drinking Water	kitchen sink	EPA 200.8	
ES-1-DW-016	16J0615-16	Drinking Water	drinking water	EPA 200.8	
ES-1-DW-017	16J0615-17	Drinking Water	drinking water	EPA 200.8	
ES-1-CS-019	16J0615-19	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-020	16J0615-20	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-021	16J0615-21	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-022	16J0615-22	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-023	16J0615-23	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-024	16J0615-24	Drinking Water	classroom sink	EPA 200.8	
ES-1-BS-025	16J0615-25	Drinking Water	bathroom sink	EPA 200.8	
ES-1-BS-026	16J0615-26	Drinking Water	bathroom sink	EPA 200.8	
ES-1-BS-027	16J0615-27	Drinking Water	bathroom sink	EPA 200.8	
ES-1-DW-028	16J0615-28	Drinking Water	drinking water	EPA 200.8	
ES-1-CS-029	16J0615-29	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-030	16J0615-30	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-031	16J0615-31	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-032	16J0615-32	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-033	16J0615-33	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-034	16J0615-34	Drinking Water	classroom sink	EPA 200.8	
ES-1-BS-035	16J0615-35	Drinking Water	bathroom sink	EPA 200.8	
ES-1-KS-036	16J0615-36	Drinking Water	kitchen sink	EPA 200.8	
ES-1-DW-037	16J0615-37	Drinking Water	drinking water	EPA 200.8	
ES-1-BS-038	16J0615-38	Drinking Water	bathroom sink	EPA 200.8	
ES-1-BS-039	16J0615-39	Drinking Water	bathroom sink	EPA 200.8	
ES-1-BS-040	16J0615-40	Drinking Water	bathroom sink	EPA 200.8	
ES-1-NS-041	16J0615-41	Drinking Water	nurse sink	EPA 200.8	
ES-1-BS-042	16J0615-42	Drinking Water	bathroom sink	EPA 200.8	
ES-1-KS-043	16J0615-43	Drinking Water	kitchen sink	EPA 200.8	
ES-1-BS-044	16J0615-44	Drinking Water	bathroom sink	EPA 200.8	

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Environmental Hazards Services, LLC
7469 White Pine Road
Richmond, VA 23237
ATTN: Greg Brown

REPORT DATE: 10/25/2016

PURCHASE ORDER NUMBER:

PROJECT NUMBER: [none]

ANALYTICAL SUMMARY

WORK ORDER NUMBER: 16J0615

The results of analyses performed on the following samples submitted to the CON-TEST Analytical Laboratory are found in this report.

PROJECT LOCATION: Elementary School/ 335 W. Oak Orchard., Medina, NY

FIELD SAMPLE #	LAB ID:	MATRIX	SAMPLE DESCRIPTION	TEST	SUB LAB
ES-1-BS-045	16J0615-45	Drinking Water	bathroom sink	EPA 200.8	
ES-1-DW-048	16J0615-48	Drinking Water	drinking water	EPA 200.8	
ES-1-OS-049	16J0615-49	Drinking Water	office sink	EPA 200.8	
ES-1-BS-050	16J0615-50	Drinking Water	bathroom sink	EPA 200.8	
ES-1BS-051	16J0615-51	Drinking Water	bathroom sink	EPA 200.8	
ES-1-CS-052	16J0615-52	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-053	16J0615-53	Drinking Water	classroom sink	EPA 200.8	
ES-1-DW-054	16J0615-54	Drinking Water	drinking water	EPA 200.8	
ES-1-CS-055	16J0615-55	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-056	16J0615-56	Drinking Water	classroom sink	EPA 200.8	
ES-1-DW-057	16J0615-57	Drinking Water	drinking water	EPA 200.8	
ES-1-CS-058	16J0615-58	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-059	16J0615-59	Drinking Water	classroom sink	EPA 200.8	
ES-1-DW-060	16J0615-60	Drinking Water	drinking water	EPA 200.8	
ES-1-CS-062	16J0615-62	Drinking Water	classroom sink	EPA 200.8	
ES-1-DW-063	16J0615-63	Drinking Water	drinking water	EPA 200.8	
ES-1-CS-064	16J0615-64	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-065	16J0615-65	Drinking Water	classroom sink	EPA 200.8	
ES-1-DW-066	16J0615-66	Drinking Water	drinking water	EPA 200.8	
ES-1-CS-067	16J0615-67	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-068	16J0615-68	Drinking Water	classroom sink	EPA 200.8	
ES-1-DW-069	16J0615-69	Drinking Water	drinking water	EPA 200.8	
ES-1-CS-070	16J0615-70	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-071	16J0615-71	Drinking Water	classroom sink	EPA 200.8	
ES-1-DW-072	16J0615-72	Drinking Water	drinking water	EPA 200.8	
ES-1-CS-073	16J0615-73	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-074	16J0615-74	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-076	16J0615-76	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-077	16J0615-77	Drinking Water	classroom sink	EPA 200.8	
ES-1-DW-078	16J0615-78	Drinking Water	drinking water	EPA 200.8	
ES-1-CS-079	16J0615-79	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-080	16J0615-80	Drinking Water	classroom sink	EPA 200.8	
ES-1-DW-081	16J0615-81	Drinking Water	drinking water	EPA 200.8	
ES-1-KS-082	16J0615-82	Drinking Water	kitchen sink	EPA 200.8	
ES-1-CS-083	16J0615-83	Drinking Water	classroom sink	EPA 200.8	
ES-1-DW-084	16J0615-84	Drinking Water	drinking water	EPA 200.8	
ES-1-CS-085	16J0615-85	Drinking Water	classroom sink	EPA 200.8	
ES-1-CS-086	16J0615-86	Drinking Water	classroom sink	EPA 200.8	
ES-1-DW-087	16J0615-87	Drinking Water	drinking water	EPA 200.8	
ES-2-BS-088	16J0615-88	Drinking Water	bathroom sink	EPA 200.8	
ES-2-BS-089	16J0615-89	Drinking Water	bathroom sink	EPA 200.8	

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

CASE NARRATIVE SUMMARY

All reported results are within defined laboratory quality control objectives unless listed below or otherwise qualified in this report.

REVISED REPORT - 10/25/2016 - 16J0615-09 & -86 IDs revised.

The results of analyses reported only relate to samples submitted to the Con-Test Analytical Laboratory for testing.
I certify that the analyses listed above, unless specifically listed as subcontracted, if any, were performed under my direction according to the approved methodologies listed in this document, and that based upon my inquiry of those individuals immediately responsible for obtaining the information, the material contained in this report is, to the best of my knowledge and belief, accurate and complete.

Meghan E. Kelley
Project Manager

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: office sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-OS-002 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-02

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	3.8	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 5:38	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-003 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-03

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	1.6	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 5:59	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-004 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-04

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:04	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-005 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-05

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:08	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-006 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-06

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:12	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-007 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-07

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	5.2	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:16	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-008 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-08

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	0.70	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:21	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: office sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-OS-009 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-09

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	14	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:25	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: kitchen sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-KS-010 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-10

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	5.2	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:30	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: kitchen sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-KS-011 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-11

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:34	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: kitchen sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-KS-012 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-12

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	4.0	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:47	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: kitchen sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-KS-013 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-13

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.1	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:51	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: kitchen sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-KS-014 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-14

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	0.87	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:55	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-016 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-16

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	4.6	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:59	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-017 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-17

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	1.2	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 7:04	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-019 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-19

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.8	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 7:08	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-020 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-20

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
# Lead	240	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/18/16 6:06	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-021 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-21

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	3.3	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 7:12	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-022 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-22

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.7	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 7:16	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-023 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-23

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	13	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 7:21	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-024 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-24

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	6.0	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 3:31	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-025 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-25

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	1.1	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 3:43	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-026 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-26

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	0.96	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 3:48	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-027 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-27

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	0.63	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 3:52	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-028 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-28

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 3:56	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-029 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-29

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	10	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 4:09	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-030 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-30

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
# Lead	72	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 4:13	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-031 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-31

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
# Lead	28	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 4:17	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-032 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-32

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	9.3	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 4:21	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-033 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-33

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	9.6	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 4:26	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-034 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-34

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	3.0	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 4:30	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-035 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-35

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 4:34	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: kitchen sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-KS-036 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-36

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	1.0	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 4:38	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-037 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-37

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 4:43	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-038 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-38

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	4.3	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 4:47	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-039 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-39

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	3.1	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 5:00	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-040 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-40

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.4	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 5:04	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: nurse sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-NS-041 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-41

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 5:08	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-042 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-42

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	1.4	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 5:13	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: kitchen sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-KS-043 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-43

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	1.3	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 5:17	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-044 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-44

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.2	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:31	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-045 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-45

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.1	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:36	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-048 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-48

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:38	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: office sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-OS-049 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-49

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.9	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:43	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-BS-050 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-50

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:45	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1BS-051 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-51

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:47	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-052 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-52

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	1.1	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:48	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-053 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-53

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	11	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:50	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-054 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-54

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	7.1	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:52	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-055 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-55

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	1.5	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:53	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-056 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-56

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	11	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:55	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-057 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-57

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	3.0	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:57	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-058 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-58

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	1.3	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 6:58	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-059 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-59

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	9.5	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 7:04	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-060 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-60

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	5.2	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 7:05	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-062 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-62

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	5.6	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 7:07	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-063 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-63

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	4.2	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 7:09	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-064 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-64

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.4	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 7:10	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-065 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-65

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	6.9	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 7:12	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-066 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-66

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	4.7	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 7:13	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-067 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-67

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	4.4	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 7:46	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-068 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-68

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	10	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 7:59	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-069 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-69

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
# Lead	61	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 8:03	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-070 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-70

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	7.0	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 8:07	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-071 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-71

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
# Lead	16	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 8:12	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-072 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-72

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	7.7	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 8:24	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-073 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-73

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.4	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 8:29	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-074 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-74

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	5.5	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 8:33	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-076 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-76

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	4.6	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 8:37	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-077 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-77

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	5.5	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 8:41	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-078 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-78

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	3.9	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 8:45	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-079 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-79

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	1.5	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 8:50	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-080 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-80

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	5.8	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 8:54	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-081 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-81

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	6.4	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 8:58	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: kitchen sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-KS-082 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-82

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	4.3	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 9:03	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-083 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-83

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	11	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 9:15	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-084 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-84

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	3.2	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 9:20	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-085 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-85

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	3.0	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 9:24	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-CS-086 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-86

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	5.3	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 9:28	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: drinking water Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-1-DW-087 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-87

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	7.4	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 9:32	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-2-BS-088 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-88

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.6	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 5:27	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0615

Date Received: 10/12/2016

Field Sample #: ES-2-BS-089 Sampled: 9/27/2016 00:00

Sample ID: 16J0615-89

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.3	0.50	15	µg/L	1		EPA 200.8	10/15/16	10/17/16 5:28	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Sample Extraction Data

Prep Method: EPA 200.8-EPA 200.8

Lab Number [Field ID]	Batch	Initial [mL]	Final [mL]	Date
16J0615-02 [ES-1-OS-002]	B160821	10.0	10.0	10/15/16
16J0615-03 [ES-1-BS-003]	B160821	10.0	10.0	10/15/16
16J0615-04 [ES-1-BS-004]	B160821	10.0	10.0	10/15/16
16J0615-05 [ES-1-BS-005]	B160821	10.0	10.0	10/15/16
16J0615-06 [ES-1-DW-006]	B160821	10.0	10.0	10/15/16
16J0615-07 [ES-1-BS-007]	B160821	10.0	10.0	10/15/16
16J0615-08 [ES-1-BS-008]	B160821	10.0	10.0	10/15/16
16J0615-09 [ES-1-OS-009]	B160821	10.0	10.0	10/15/16
16J0615-10 [ES-1-KS-010]	B160821	10.0	10.0	10/15/16
16J0615-11 [ES-1-KS-011]	B160821	10.0	10.0	10/15/16
16J0615-12 [ES-1-KS-012]	B160821	10.0	10.0	10/15/16
16J0615-13 [ES-1-KS-013]	B160821	10.0	10.0	10/15/16
16J0615-14 [ES-1-KS-014]	B160821	10.0	10.0	10/15/16
16J0615-16 [ES-1-DW-016]	B160821	10.0	10.0	10/15/16
16J0615-17 [ES-1-DW-017]	B160821	10.0	10.0	10/15/16
16J0615-19 [ES-1-CS-019]	B160821	10.0	10.0	10/15/16
16J0615-21 [ES-1-CS-021]	B160821	10.0	10.0	10/15/16
16J0615-22 [ES-1-CS-022]	B160821	10.0	10.0	10/15/16
16J0615-23 [ES-1-CS-023]	B160821	10.0	10.0	10/15/16

Prep Method: EPA 200.8-EPA 200.8

Lab Number [Field ID]	Batch	Initial [mL]	Final [mL]	Date
16J0615-24 [ES-1-CS-024]	B160822	10.0	10.0	10/15/16
16J0615-25 [ES-1-BS-025]	B160822	10.0	10.0	10/15/16
16J0615-26 [ES-1-BS-026]	B160822	10.0	10.0	10/15/16
16J0615-27 [ES-1-BS-027]	B160822	10.0	10.0	10/15/16
16J0615-28 [ES-1-DW-028]	B160822	10.0	10.0	10/15/16
16J0615-29 [ES-1-CS-029]	B160822	10.0	10.0	10/15/16
16J0615-30 [ES-1-CS-030]	B160822	10.0	10.0	10/15/16
16J0615-31 [ES-1-CS-031]	B160822	10.0	10.0	10/15/16
16J0615-32 [ES-1-CS-032]	B160822	10.0	10.0	10/15/16
16J0615-33 [ES-1-CS-033]	B160822	10.0	10.0	10/15/16
16J0615-34 [ES-1-CS-034]	B160822	10.0	10.0	10/15/16
16J0615-35 [ES-1-BS-035]	B160822	10.0	10.0	10/15/16
16J0615-36 [ES-1-KS-036]	B160822	10.0	10.0	10/15/16
16J0615-37 [ES-1-DW-037]	B160822	10.0	10.0	10/15/16
16J0615-38 [ES-1-BS-038]	B160822	10.0	10.0	10/15/16
16J0615-39 [ES-1-BS-039]	B160822	10.0	10.0	10/15/16
16J0615-40 [ES-1-BS-040]	B160822	10.0	10.0	10/15/16
16J0615-41 [ES-1-NS-041]	B160822	10.0	10.0	10/15/16
16J0615-42 [ES-1-BS-042]	B160822	10.0	10.0	10/15/16
16J0615-43 [ES-1-KS-043]	B160822	10.0	10.0	10/15/16

Prep Method: EPA 200.8-EPA 200.8

Lab Number [Field ID]	Batch	Initial [mL]	Final [mL]	Date
16J0615-44 [ES-1-BS-044]	B160832	10.0	10.0	10/15/16
16J0615-45 [ES-1-BS-045]	B160832	10.0	10.0	10/15/16
16J0615-48 [ES-1-DW-048]	B160832	10.0	10.0	10/15/16
16J0615-49 [ES-1-OS-049]	B160832	10.0	10.0	10/15/16
16J0615-50 [ES-1-BS-050]	B160832	10.0	10.0	10/15/16
16J0615-51 [ES-1BS-051]	B160832	10.0	10.0	10/15/16

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Sample Extraction Data

Prep Method: EPA 200.8-EPA 200.8

Lab Number [Field ID]	Batch	Initial [mL]	Final [mL]	Date
16J0615-52 [ES-1-CS-052]	B160832	10.0	10.0	10/15/16
16J0615-53 [ES-1-CS-053]	B160832	10.0	10.0	10/15/16
16J0615-54 [ES-1-DW-054]	B160832	10.0	10.0	10/15/16
16J0615-55 [ES-1-CS-055]	B160832	10.0	10.0	10/15/16
16J0615-56 [ES-1-CS-056]	B160832	10.0	10.0	10/15/16
16J0615-57 [ES-1-DW-057]	B160832	10.0	10.0	10/15/16
16J0615-58 [ES-1-CS-058]	B160832	10.0	10.0	10/15/16
16J0615-59 [ES-1-CS-059]	B160832	10.0	10.0	10/15/16
16J0615-60 [ES-1-DW-060]	B160832	10.0	10.0	10/15/16
16J0615-62 [ES-1-CS-062]	B160832	10.0	10.0	10/15/16
16J0615-63 [ES-1-DW-063]	B160832	10.0	10.0	10/15/16
16J0615-64 [ES-1-CS-064]	B160832	10.0	10.0	10/15/16
16J0615-65 [ES-1-CS-065]	B160832	10.0	10.0	10/15/16
16J0615-66 [ES-1-DW-066]	B160832	10.0	10.0	10/15/16

Prep Method: EPA 200.8-EPA 200.8

Lab Number [Field ID]	Batch	Initial [mL]	Final [mL]	Date
16J0615-67 [ES-1-CS-067]	B160833	10.0	10.0	10/15/16
16J0615-68 [ES-1-CS-068]	B160833	10.0	10.0	10/15/16
16J0615-69 [ES-1-DW-069]	B160833	10.0	10.0	10/15/16
16J0615-70 [ES-1-CS-070]	B160833	10.0	10.0	10/15/16
16J0615-71 [ES-1-CS-071]	B160833	10.0	10.0	10/15/16
16J0615-72 [ES-1-DW-072]	B160833	10.0	10.0	10/15/16
16J0615-73 [ES-1-CS-073]	B160833	10.0	10.0	10/15/16
16J0615-74 [ES-1-CS-074]	B160833	10.0	10.0	10/15/16
16J0615-76 [ES-1-CS-076]	B160833	10.0	10.0	10/15/16
16J0615-77 [ES-1-CS-077]	B160833	10.0	10.0	10/15/16
16J0615-78 [ES-1-DW-078]	B160833	10.0	10.0	10/15/16
16J0615-79 [ES-1-CS-079]	B160833	10.0	10.0	10/15/16
16J0615-80 [ES-1-CS-080]	B160833	10.0	10.0	10/15/16
16J0615-81 [ES-1-DW-081]	B160833	10.0	10.0	10/15/16
16J0615-82 [ES-1-KS-082]	B160833	10.0	10.0	10/15/16
16J0615-83 [ES-1-CS-083]	B160833	10.0	10.0	10/15/16
16J0615-84 [ES-1-DW-084]	B160833	10.0	10.0	10/15/16
16J0615-85 [ES-1-CS-085]	B160833	10.0	10.0	10/15/16
16J0615-86 [ES-1-CS-086]	B160833	10.0	10.0	10/15/16
16J0615-87 [ES-1-DW-087]	B160833	10.0	10.0	10/15/16

Prep Method: EPA 200.8-EPA 200.8

Lab Number [Field ID]	Batch	Initial [mL]	Final [mL]	Date
16J0615-88 [ES-2-BS-088]	B160835	10.0	10.0	10/15/16
16J0615-89 [ES-2-BS-089]	B160835	10.0	10.0	10/15/16

Prep Method: EPA 200.8-EPA 200.8

Lab Number [Field ID]	Batch	Initial [mL]	Final [mL]	Date
16J0615-20 [ES-1-CS-020]	B160911	50.0	50.0	10/17/16

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

QUALITY CONTROL

Metals Analyses (Total) - Quality Control

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch B160821 - EPA 200.8										
Blank (B160821-BLK1)				Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	ND	0.50	µg/L							
LCS (B160821-BS1)				Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	39.8	0.50	µg/L	40.0		99.5	85-115			
Duplicate (B160821-DUP1)		**Source: 16J0615-02**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	3.80	0.50	µg/L		3.82			0.537	20	
Duplicate (B160821-DUP2)		**Source: 16J0615-03**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	1.61	0.50	µg/L		1.60			0.151	20	
Matrix Spike (B160821-MS1)		**Source: 16J0615-02**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	28.8	0.62	µg/L	25.0	3.82	99.8	70-130			
Matrix Spike (B160821-MS2)		**Source: 16J0615-03**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	26.7	0.62	µg/L	25.0	1.60	100	70-130			
Batch B160822 - EPA 200.8										
Blank (B160822-BLK1)				Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	ND	0.50	µg/L							
LCS (B160822-BS1)				Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	39.8	0.50	µg/L	40.0		99.5	85-115			
Duplicate (B160822-DUP1)		**Source: 16J0615-24**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	6.14	0.50	µg/L		6.02			1.93	20	
Duplicate (B160822-DUP2)		**Source: 16J0615-25**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	1.08	0.50	µg/L		1.09			0.692	20	
Matrix Spike (B160822-MS1)		**Source: 16J0615-24**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	30.8	0.62	µg/L	25.0	6.02	99.3	70-130			
Matrix Spike (B160822-MS2)		**Source: 16J0615-25**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	26.2	0.62	µg/L	25.0	1.09	100	70-130			
Batch B160832 - EPA 200.8										
Blank (B160832-BLK1)				Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	ND	0.50	µg/L							

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

QUALITY CONTROL

Metals Analyses (Total) - Quality Control

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch B160832 - EPA 200.8										
LCS (B160832-BS1)				Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	40.8	0.50	µg/L	40.0		102	85-115			
Duplicate (B160832-DUP1)		**Source: 16J0615-44**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	2.21	0.50	µg/L		2.24			1.28	20	
Duplicate (B160832-DUP2)		**Source: 16J0615-45**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	2.09	0.50	µg/L		2.08			0.582	20	
Matrix Spike (B160832-MS1)		**Source: 16J0615-44**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	29.3	0.62	µg/L	25.0	2.24	108	70-130			
Matrix Spike (B160832-MS2)		**Source: 16J0615-45**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	29.0	0.62	µg/L	25.0	2.08	108	70-130			
Batch B160833 - EPA 200.8										
Blank (B160833-BLK1)				Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	ND	0.50	µg/L							
LCS (B160833-BS1)				Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	39.8	0.50	µg/L	40.0		99.5	85-115			
Duplicate (B160833-DUP1)		**Source: 16J0615-67**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	4.38	0.50	µg/L		4.39			0.218	20	
Duplicate (B160833-DUP2)		**Source: 16J0615-68**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	10.8	0.50	µg/L		10.3			5.07	20	
Matrix Spike (B160833-MS1)		**Source: 16J0615-67**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	30.0	0.62	µg/L	25.0	4.39	102	70-130			
Matrix Spike (B160833-MS2)		**Source: 16J0615-68**		Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	35.6	0.62	µg/L	25.0	10.3	101	70-130			
Batch B160835 - EPA 200.8										
Blank (B160835-BLK1)				Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	ND	0.50	µg/L							
LCS (B160835-BS1)				Prepared: 10/15/16	Analyzed: 10/17/16					
Lead	40.8	0.50	µg/L	40.0		102	85-115			

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

QUALITY CONTROL

Metals Analyses (Total) - Quality Control

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch B160911 - EPA 200.8										
Blank (B160911-BLK1)				Prepared: 10/17/16	Analyzed: 10/18/16					
Lead	ND	0.50	µg/L							
LCS (B160911-BS1)				Prepared: 10/17/16	Analyzed: 10/18/16					
Lead	270	2.5	µg/L	250		108	85-115			
LCS Dup (B160911-BSD1)				Prepared: 10/17/16	Analyzed: 10/18/16					
Lead	274	2.5	µg/L	250		110	85-115	1.61	20	
Duplicate (B160911-DUP1)	**Source: 16J0615-20**			Prepared: 10/17/16	Analyzed: 10/18/16					
Lead	241	0.50	µg/L		245			1.58	20	
Matrix Spike (B160911-MS1)	**Source: 16J0615-20**			Prepared: 10/17/16	Analyzed: 10/18/16					
Lead	499	2.5	µg/L	250	245	101	70-130			

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

FLAG/QUALIFIER SUMMARY

*	QC result is outside of established limits.
†	Wide recovery limits established for difficult compound.
‡	Wide RPD limits established for difficult compound.
#	Data exceeded client recommended or regulatory level
ND	Not Detected
RL	Reporting Limit
DL	Method Detection Limit
MCL	Maximum Contaminant Level

Percent recoveries and relative percent differences (RPDs) are determined by the software using values in the calculation which have not been rounded.

No results have been blank subtracted unless specified in the case narrative section.

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

CERTIFICATIONS

Certified Analyses included in this Report

Analyte	Certifications
EPA 200.8 in Drinking Water	
Lead	NH,NY,MA,CT,RI,ME,VA

The CON-TEST Environmental Laboratory operates under the following certifications and accreditations:

Code	Description	Number	Expires
AIHA	AIHA-LAP, LLC - ISO17025:2005	100033	02/1/2018
MA	Massachusetts DEP	M-MA100	06/30/2017
CT	Connecticut Department of Publilc Health	PH-0567	09/30/2017
NY	New York State Department of Health	10899 NELAP	04/1/2017
NH-S	New Hampshire Environmental Lab	2516 NELAP	02/5/2017
RI	Rhode Island Department of Health	LAO00112	12/30/2016
NC	North Carolina Div. of Water Quality	652	12/31/2016
NJ	New Jersey DEP	MA007 NELAP	06/30/2017
FL	Florida Department of Health	E871027 NELAP	06/30/2017
VT	Vermont Department of Health Lead Laboratory	LL015036	07/30/2017
ME	State of Maine	2011028	06/9/2017
VA	Commonwealth of Virginia	460217	12/14/2016
NH-P	New Hampshire Environmental Lab	2557 NELAP	09/6/2017

EHS Laboratories

Environmental Hazards Services, LLC
www.ehslab.com
(800) 347-4010
(804) 276-4007 (fax)
7450 Hilliquin Ave
Richmond VA 23237

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

16J0615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608

Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 Email: tknapp@envoyenv.com Acct Number:

Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State/Region: Medina, NY Zip: 14103 Age of Property:

Collected by: Jeff Hertel / Andrew Distaffen Certification #: Well Tag # (Yes/No):

Purchase Order Number: Relinquished by: Date:

ALL SAMPLES BELOW SHOULD BE ANALYZED FOR LEAD IN DRINKING WATER
SAMPLES SUBMITTED ALL HAVE THE SAME PHYSICAL ADDRESS AS ABOVE WITH DIFFERENT APARTMENT NUMBERS.
PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
1	ES-1-DW-001	Drinking Water	9-27-16		Lead			
2	ES-1-OS-002	Office Sink			Lead			
3	ES-1-BS-003	Bathroom Sink			Lead			
4	ES-1-BS-004	Bathroom Sink			Lead			
5	ES-1-BS-005	Bathroom Sink			Lead			
6	ES-1-DW-006	Drinking Water			Lead			
7	ES-1-BS-007	Bathroom Sink			Lead			
8	ES-1-BS-008	Bathroom Sink			Lead			
9	ES-1-OS-009	Office Sink			Lead			
10	ES-1-KS-010	Kitchen Sink			Lead			

Received by: Date: 10/12/16 Time: 1212
Tracking Number: Temperature: 16.8

NIL Lab ID Number

Page 1 of 12

Table of Contents

EHS Laboratories

Environmental Hazards Services, LLC

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

1606615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608

Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct Number:

Project Name/Testing Address: Elementary School / 335 W. Oak Orchard City/State (Required): Medina, NY Zip: 14103 Agency/Program:

Collected by: Jeff Hertell / Andrew Distaffen Certification#: WSTag#(Reg/Sub/Ind):

Purchase Order Number: Relinquished by: Date:

ALL SAMPLES BELOW SHOULD BE ANALYZED FOR LEAD IN DRINKING WATER

SAMPLES SUBMITTED ALL HAVE THE SAME PHYSICAL ADDRESS AS ABOVE WITH DIFFERENT APARTMENT NUMBERS.

PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
11	1	ES-1-KS-011	Kitchen Sink	9-27-16		Lead			
12	2	ES-1-KS-012	Kitchen Sink			Lead			
13	3	ES-1-KS-013	Kitchen Sink			Lead			
14	4	ES-1-KS-014	Kitchen Sink			Lead			
15	5	ES-1-BS-015	Bathroom Sink			Lead			
16	6	ES-1-DW-016	Drinking Water			Lead			
17	7	ES-1-DW-017	Drinking Water			Lead			
18	8	ES-1-CS-018	Classroom School			Lead			
19	9	ES-1-CS-019	Classroom School			Lead			
20	10	ES-1-CS-020	Classroom School			Lead			

Received by: [signature] Date: 10/12/16 Time: 1012

Tracking Number: Temperature: 16.8°C

NIL Lab ID Number

Page 2 of 12

Table of Contents

EHS Laboratories

Environmental Hazards Services, LLC

(800) 347-4010
(800) 275-4007 (fax)

7009 Middlepointe Rd
Richmond, VA 23237

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

1630615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental
Address: 57 Ambrose Street
City/State/Zip: Rochester, NY 14608
Phone: ( ) 585-454-1060
Fax: ( ) 585-454-1062
E-mail: tknapp@envoyenv.com
Acct Number:
Project Name/Testing Address: Elsbrookery School / 335 W. Oak orchard
City/State (Required): Medina, NY
Zip: 14103
Agent/Engineer:
Collected by: Jeff Hertell / Andrew Distaffen
Confirmed with:
Well Tag # (If applicable):
Purchase Order Number:
Relinquished by:
Date:

ALL SAMPLES BELOW SHOULD BE ANALYZED FOR LEAD IN DRINKING WATER
SAMPLES SUBMITTED ALL HAVE THE SAME PHYSICAL ADDRESS AS ABOVE WITH DIFFERENT APARTMENT NUMBERS.
PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
21	1	ES-1-CS-021	Classroom Sink	9-27-16		Lead			
22	2	ES-1-CS-022	Classroom Sink			Lead			
23	3	ES-1-CS-023	Classroom Sink			Lead			
24	4	ES-1-CS-024	Classroom Sink			Lead			
25	5	ES-1-BS-025	Bathroom Sink			Lead			
26	6	ES-1-BS-026	Bathroom Sink			Lead			
27	7	ES-1-BS-027	Bathroom Sink			Lead			
28	8	ES-1-DW-028	Drinking Water			Lead			
29	9	ES-1-CS-029	Classroom Sink			Lead			
30	10	ES-1-CS-030	Classroom Sink			Lead			

Received by:
Date: 10/12/16
Time: 1212
Testing Venue:
Temperature: 16.8

NIL Lab ID Number

Page 3 of 12

Table of Contents

EHS Laboratories
Environmental Hazards Services, LLC
www.ehslab.com
(800) 347-4010
(800) 276-4007 (fax)
7450 Whitepine Rd
Richmond, VA 23237

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

16S0615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company/Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608
Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct Number:
Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State (Required): Medina, NY Zip: 14103 Age of Property:
Collected by: Jeff Hertell / Andrew Distaffen Certificate#: Well Tag ID (If applicable):
Purchase Order Number: Relinquished by: Date:

ALL SAMPLES BELOW SHOULD BE ANALYZED FOR LEAD IN DRINKING WATER
SAMPLES SUBMITTED ALL HAVE THE SAME PHYSICAL ADDRESS AS ABOVE WITH DIFFERENT APARTMENT NUMBERS.
PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
31	1	ES-1-CS-031	Classroom Sink	9-27-16		Lead			
32	2	ES-1-CS-032	↓	↓		Lead			
33	3	ES-1-CS-033	↓	↓		Lead			
34	4	ES-1-CS-034	↓	↓		Lead			
35	5	ES-1-BS-035	Bathroom Sink	↓		Lead			
36	6	ES-1-KS-036	Kitchen Sink	↓		Lead			
37	7	ES-1-DW-037	Drinking Water	↓		Lead			
38	8	ES-1-BS-038	Bathroom Sink	↓		Lead			
39	9	ES-1-BS-039	Bathroom Sink	↓		Lead			
40	10	ES-1-BS-040	Bathroom Sink	↓		Lead			

Received by: [signature] Date: 10/12/16 Time: 1212
Tracking Number: Temperature: 16.8°C

NIL Lab ID Number

Page 4 of 12

Table of Contents

EHS Laboratories

Environmental Hazards Services, LLC
www.ehsinc.com
(800) 341-4010
(804) 278-4007 (fax)
7439 Millhaven Rd
Richmond VA 23227

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

16J0615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608
Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct Number:
Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State (Required): Medina, NY Zip: 14103 Age of Property:
Collected by: Jeff Hertell / Andrew Distaffen Certification#: Well Tag # (If applicable):
Purchase Order Number: Relinquished by: Date:

ALL SAMPLES BELOW WILL BE ANALYZED FOR LEAD IN DRINKING WATER
SAMPLES SUBMITTED ALL HAVE THE SAME PHYSICAL ADDRESS AS ABOVE WITH DIFFERENT APARTMENT NUMBERS.
PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
41	1	ES-1-NS-041	Nurse Sink	9-27-16		Lead			
42	2	ES-1-BS-042	Bathroom Sink			Lead			
43	3	ES-1-KS-043	Kitchen Sink			Lead			
44	4	ES-1-BS-044	Bathroom Sink			Lead			
45	5	ES-1-BS-045	Bathroom Sink			Lead			
46	6	ES-1-DW-046	Drinking Water			Lead			
47	7	ES-1-DW-047	Drinking Water			Lead			
48	8	ES-1-DW-048	Drinking Water			Lead			
49	9	ES-1-OS-049	Office Sink			Lead			
50	10	ES-1-BS-050	Bathroom Sink			Lead			

Received by: [signature] Date: 10/12/16 Time: 12:12
Tracking Number: Temperature: 16.8

NIL Lab ID Number

Page 5 of 10

Table of Contents

EHS Laboratories

Environmental Hazards Services, LLC
www.ehslab.com
(888) 347-4010
(804) 275-4917 (fax)
7469 Whitepine Rd
Richmond, VA 23237

WaterSmart® Pro
LEAD ONLY
Chain of Custody
Analysis by National Testing Laboratories

16S0615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608

Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct Number:

Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State (Required): Medina, NY Zip: 14103 Age of Property:

Collected by: Jeff Hertel / Andrew Distaffen Certification #: Well Tag # (If applicable):

Purchase Order Number: Relinquished by: Date:

ALL SAMPLES BELOW SHOULD BE ANALYZED FOR LEAD IN DRINKING WATER
SAMPLES SUBMITTED ALL HAVE THE SAME PHYSICAL ADDRESS AS ABOVE WITH DIFFERENT APARTMENT NUMBERS.
PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
51	1	ES-1-BS-051	Bathroom Sink	9-27-16		Lead			
52	2	ES-1-CS-052	Classroom Sink	↓	↓	Lead			
53	3	ES-1-CS-053	Classroom Sink			Lead			
54	4	ES-1-DW-054	Drinking Water			Lead			
55	5	ES-1-CS-055	Classroom Sink			Lead			
56	6	ES-1-CS-056	Classroom Sink			Lead			
57	7	ES-1-DW-057	Drinking Water			Lead			
58	8	ES-1-CS-058	Classroom Sink			Lead			
59	9	ES-1-CS-059	Classroom Sink			Lead			
60	10	ES-1-DW-060	Drinking Water	↓	↓	Lead			

Received by: [signature] Date: 10/12/16 Time: 1212
Tracking Number: Temperature: 16.8°C

NIL Lab ID Number

Page 6 of 12

Table of Contents

EHS Laboratories

Environmental Health Services, LLC
www.ehslab.com
(800) 347-4015
(804) 275-4017 (fax)
7469 Whitepine Rd
Richmond, VA 23237

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

1610615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608
Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct Number:
Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State (Required): Medina, NY Zip: 14103 Age of Property:
Collected by: Jeff Hertell / Andrew Distaffen Certification #: Well Tag # (If applicable):
Purchase Order Number: Relinquished by: Date:

ALL SAMPLES HERE ONLY SHOULD BE ANALYZED FOR LEAD IN DRINKING WATER
SAMPLES SUBMITTED ALL HAVE THE SAME PHYSICAL ADDRESS AS ABOVE WITH DIFFERENT APARTMENT NUMBERS.
PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
61	1	ES-1-CS-061	Classroom Sink	9-27-16		Lead			
62	2	ES-1-CS-062	Classroom Sink	↓		Lead			
63	3	ES-1-DW-063	Drinking water	↓		Lead			
64	4	ES-1-CS-064	Classroom Sink	↓		Lead			
65	5	ES-1-CS-065	Classroom Sink	↓		Lead			
66	6	ES-1-DW-066	Drinking water	↓		Lead			
67	7	ES-1-CS-067	Classroom Sink	↓		Lead			
68	8	ES-1-CS-068	Classroom Sink	↓		Lead			
69	9	ES-1-DW-069	Drinking water	↓		Lead			
70	10	ES-1-CS-070	Classroom Sink	↓		Lead			

Received by: [illegible] Date: 10/12/16 Time: 1212
Tracking Number: Temperature: 16.8

NTL Lab ID Number

Page 7 of 12

Table of Contents

EHS Laboratories

Environmental Health Services, LLC
www.ehslab.com
(888) 367-4016
(804) 270-4067 (fax)
7459 Whitepine Rd
Richmond, VA 23237

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

1650615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608
Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct Number:
Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State (Required): Medina, NY Zip: 14103 Age of Property:
Collected by: Jeff Hertel / Andrew Distaffen Certification#: Well Tag # (If applicable):
Purchase Order Number: Relinquished by: Date:

ALL SAMPLES SHOULD BE ANALYZED FOR LEAD IN DRINKING WATER
SAMPLES SUBMITTED ALL HAVE THE SAME PHYSICAL ADDRESS AS ABOVE WITH DIFFERENT APARTMENT NUMBERS.
PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
71	1	ES-1-CS-071	Classroom Sink	9-27-16		Lead			
72	2	ES-1-DW-072	Drinking Water			Lead			
73	3	ES-1-CS-073	Classroom Sink			Lead			
74	4	ES-1-CS-074	Classroom Sink			Lead			
75	5	ES-1-DW-075	Drinking Water			Lead			
76	6	ES-1-CS-076	Classroom Sink			Lead			
77	7	ES-1-CS-077	Classroom Sink			Lead			
78	8	ES-1-DW-078	Drinking Water			Lead			
79	9	ES-1-CS-079	Classroom Sink			Lead			
80	10	ES-1-CS-080	Classroom Sink			Lead			

Received by: [illegible] Date: 10/12/16 Time: 1212
Testing Number: Temperature: 16.8

NIL Lab ID Number

Page 8 of 12

Table of Contents

EHS Laboratories

Environmental Hazards Services, LLC
www.ehslab.com
(800) 347-4010
(804) 275-4007 (fax)
7469 Whitepine Rd
Richmond, VA 23237

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

16J0615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608
Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct. Number:
Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State (Required): Medina, NY Zip: 14103 Age of Property:
Collected by: Jeff Hertel / Andrew Distaffen Certification #: Well Tag # (If applicable):
Purchase Order Number: Relinquished by: Date:

ALL SAMPLES BELOW SHOULD BE ANALYZED FOR LEAD IN DRINKING WATER.
SAMPLES SUBMITTED ALL HAVE THE SAME PHYSICAL ADDRESS AS ABOVE WITH DIFFERENT APARTMENT NUMBERS.
PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
81	1	ES-1-DW-081	Drinking Water	9-27-16		Lead			
82	2	ES-1-KS-082	Kitchen Sink	↓	↓	Lead			
83	3	ES-1-CS-083	Classroom Sink	↓	↓	Lead			
84	4	ES-1-DW-084	Drinking Water	↓	↓	Lead			
85	5	ES-1-CS-085	Classroom Sink	↓	↓	Lead			
86	6	ES-1-CS-086	Classroom Sink	↓	↓	Lead			
87	7	ES-1-DW-087	Drinking Water	↓	↓	Lead			
88	8	ES-2-BS-088	Bathroom Sink	↓	↓	Lead			
89	9	ES-2-BS-089	Bathroom Sink	↓	↓	Lead			
90	10	ES-2-CS-090	Classroom Sink	↓	↓	Lead			

Received by: [signature] Date: 10/12/16 Time: 1012
Tracking Number: Temperature: 16.8

NTL Lab ID Number

Page 9 of 12

Table of Contents

39 Spruce St.
East Longmeadow, MA. 01028
P: 413-525-2332
F: 413-525-6405
www.contestlabs.com

con-test® ANALYTICAL LABORATORY

Sample Receipt Checklist

CLIENT NAME: EHS **RECEIVED BY:** RLF **DATE:** 10/12/16

1) **Was the chain(s) of custody relinquished and signed?** **Yes** ____ **No** X **No COC Incl.**
2) **Does the chain agree with the samples?** **Yes** X **No** ____
   If not, explain:
3) **Are all the samples in good condition?** **Yes** X **No** ____
   If not, explain:
4) **How were the samples received:**

On Ice____ Direct from Sampling____ Ambient X In Cooler(s) ____

Were the samples received in Temperature Compliance of (2-6°C)? **Yes** ____ **No** X **N/A** ____

Temperature °C by Temp blank ____ Temperature °C by Temp gun 16.8°C

5) **Are there Dissolved samples for the lab to filter?** **Yes** ____ **No** X
   Who was notified ____ Date ____ Time ____
6) **Are there any RUSH or SHORT HOLDING TIME samples?** **Yes** ____ **No** X
   Who was notified ____ Date ____ Time ____
7) **Location where samples are stored:**

Permission to subcontract samples? Yes No
(Walk-in clients only) if not already approved
Client Signature: ____

8) **Do all samples have the proper Acid pH:** **Yes** ____ **No** ____ **N/A** X
9) **Do all samples have the proper Base pH:** **Yes** ____ **No** ____ **N/A** X
10) **Was the PC notified of any discrepancies with the CoC vs the samples:** **Yes** ____ **N/A** X

Containers received at Con-Test

	# of containers		# of containers
1 Liter Amber		16 oz amber	
500 mL Amber		8 oz amber/clear jar	
250 mL Amber (8oz amber)		4 oz amber/clear jar	
1 Liter Plastic		2 oz amber/clear jar	
500 mL Plastic		Plastic Bag / Ziploc	
250 mL plastic	82	SOC Kit	
40 mL Vial - type listed below		Perchlorate Kit	
Colisure / bacteria bottle		Flashpoint bottle	
Dissolved Oxygen bottle		Other glass jar	
Encore		Other	

did not receive ES-1-DW-001, ES-1-BS-015, ES-1-CS-018, ES-1-DW-046, ES-1-DW-047, ES-1-CS-061, ES-1-DW-075, ES-2-CS-090

40 mL vials:	# HCl ____	# Methanol ____	Time and Date Frozen:
Doc# 277	# Bisulfate ____	# DI Water ____	
Rev. 4 August 2013	# Thiosulfate ____	Unpreserved ____	

Login Sample Receipt Checklist

(Rejection Criteria Listing - Using Sample Acceptance Policy)

Any False statement will be brought to the attention of Client

Question	Answer (True/False) T/F/NA	Comment
1) The cooler's custody seal, if present, is intact.	NA	
2) The cooler or samples do not appear to have been compromised or tampered with.	T	
3) Samples were received on ice.	F	received in boxes via UPS
4) Cooler Temperature is acceptable.	T	drinking water
5) Cooler Temperature is recorded.	T	
6) COC is filled out in ink and legible.	T	
7) COC is filled out with all pertinent information.	T	
8) Field Sampler's name present on COC.	T	
9) There are no discrepancies between the sample IDs on the container and the COC.	T	
10) Samples are received within Holding Time.	T	
11) Sample containers have legible labels.	T	
12) Containers are not broken or leaking.	T	
13) Air Cassettes are not broken/open.	NA	
14) Sample collection date/times are provided.	T	
15) Appropriate sample containers are used.	T	
16) Proper collection media used.	T	
17) No headspace sample bottles are completely filled.	NA	
18) There is sufficient volume for all requsted analyses, including any requested MS/MSDs.	F	did not receive 8 samples
19) Trip blanks provided if applicable.	NA	
20) VOA sample vials do not have head space or bubble is <6mm (1/4") in diameter.	NA	
21) Samples do not require splitting or compositing.	T	

Who notified of False statements? **Date/Time:**

Doc #277 Rev. 4 August 2013 **Log-In Technician Initials:** **Date/Time:**

RLF 10/12/16 1212

16-10-02887

Due Date:
10/26/2016
(Wednesday)
AE MC

EHS Laboratories

Environmental Health Services, LLC

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

16J0615

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608

Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 Email: tknapp@envoyenv.com Alt. Number:

Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State/Zip: Medina, NY. Zip: 14103 Age of Sample:

Collected by: Jeff Hertel / Andrew Distaffen Certification #: Well Tag # (if applicable):

Purchase Order Number: Relinquished by: Date:

ALL SAMPLES MUST BE ANALYZED FOR LEAD IN DRINKING WATER.
SAMPLES MUST BE ALL TAKEN THE SAME DAY AT ONE ADDRESS AS A GROUP WITH DIFFERENT APARTMENT NUMBERS.
PLEASE PROVIDE A SEPARATE SHEET FOR ALL SAMPLES NOT LISTED ON THIS CHAIN OF CUSTODY.

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
1	ES-1-DW-001	Drinking Water	9-27-16		Lead			
2	ES-1-OS-002	Office Sink	↓	↓	Lead			
3	ES-1-BS-003	Bathroom Sink			Lead			
4	ES-1-BS-004	Bathroom Sink			Lead			
5	ES-1-BS-005	Bathroom Sink			Lead			
6	ES-1-DW-006	Drinking Water			Lead			
7	ES-1-BS-007	Bathroom Sink			Lead			
8	ES-1-BS-008	Bathroom Sink			Lead			
9	ES-1-OS-009	Office Sink			Lead			
10	ES-1-KS-010	Kitchen Sink	↓	↓	Lead			

Received by: Date: 10/12/16 Time: 1212
Receiving Temp: 16.8

NTL Lab ID Number

Page 1 of 12

2887

EHS Laboratories

Environmental Health Services, LLC

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

1606615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608
Phone( ) 585-454-1060 Fax( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct. Number:
Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State/Zip: Medina, NY Zip: 14103 Agent/Reports:
Collected by: Jeff Hertell / Andrew Distaffen Co-Collected: Will Tag*/Bag/Bottle:
Purchase Order Number: Relinquished by: Date:

ALL SAMPLES MUST BE ANALYZED FOR LEAD IN DRINKING WATER
SAMPLES SUBMITTED ALL TO BE ANALYZED FOR LEAD. ADDRESS AS ABOVE WITH DIFFERENT APARTMENT NUMBERS.
WILL BE TRACKED AS SEPARATE SAMPLES FOR ALL RESULTS INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field Pb	Field Chlorine	Temperature at Time of Collection
11	1	ES-1-KS-011	Kitchen Sink	9-27-16		Lead			
12	2	ES-1-KS-012	Kitchen Sink			Lead			
13	3	ES-1-KS-013	Kitchen Sink			Lead			
14	4	ES-1-KS-014	Kitchen Sink			Lead			
15	5	ES-1-BS-015	Bathroom Sink			Lead			
16	6	ES-1-DW-016	Drinking Water			Lead			
17	7	ES-1-DW-017	Drinking Water			Lead			
18	8	ES-1-CS-018	Classroom School			Lead			
19	9	ES-1-CS-019	Classroom School			Lead			
20	10	ES-1-CS-020	Classroom School			Lead			

Received by: [signature] Date: 10/21/16 Time: 1012
Tracking Number: Temperature: 16.8°C

NIL Lab ID Number

Page 2 of 12

2887

EHS Laboratories

Environmental Health Services, LLC

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

1636615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608

Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct Number:

Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State/Zip: Medina, NY Zip: 14103 Agent/Inspector:

Collected by: Jose Hertell / Andrew Distaffen Certification #: Will Tag/Seal Be Used:

Purchase Order Number: Relinquished by: Date:

ALL SAMPLES ARE ONLY BEING TO BE ANALYZED FOR LEAD IN DRINKING WATER
SAMPLES MUST BE ALL THE SAME PRESERVATIVE AND ARE ALSO WITH DIFFERENT APARTMENT NUMBERS.
PLEASE PROVIDE A UNIQUE NUMBER FOR ALL SAMPLES LISTED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
21	1	ES-1-CS-021	Classroom Sink	9-27-16		Lead			
22	2	ES-1-CS-022	Classroom Sink			Lead			
23	3	ES-1-CS-023	Classroom Sink			Lead			
24	4	ES-1-CS-024	Classroom Sink			Lead			
25	5	ES-1-BS-025	Bathroom Sink			Lead			
26	6	ES-1-BS-026	Bathroom Sink			Lead			
27	7	ES-1-BS-027	Bathroom Sink			Lead			
28	8	ES-1-DW-028	Drinking Water			Lead			
29	9	ES-1-CS-029	Classroom Sink			Lead			
30	10	ES-1-CS-030	Classroom Sink			Lead			

Received by: [illegible] Date: 10/12/16 Time: 1212
Tracking Number: Temperature: 16.8

NIL Lab ID Number

Page 3 of 12

2887

EHS Laboratories

Environmental Health Services, LLC.

[redacted]

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

16S06615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company/Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608

Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct Number:

Project Name/Testing Address: Elementary School / 335 N. Oak Orchard City/State/Zip: Melrose, NY. Zip: 14103 Agent/Requestor:

Collected by: Jeff Hertel / Andrew Distaffen Certificate#: Well Tag #/Supplier:

Purchase Order Number: Relinquished by: Date:

[redacted]

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
31	1	ES-1-CS-031	Classroom Sink	9-27-16		Lead			
32	2	ES-1-CS-032	↓	↓		Lead			
33	3	ES-1-CS-033	↓	↓		Lead			
34	4	ES-1-CS-034	↓	↓		Lead			
35	5	ES-1-BS-035	Bathroom Sink	↓		Lead			
36	6	ES-1-KS-036	Kitchen Sink	↓		Lead			
37	7	ES-1-DW-037	Drinking Water	↓		Lead			
38	8	ES-1-BS-038	Bathroom Sink	↓		Lead			
39	9	ES-1-BS-039	Bathroom Sink	↓		Lead			
40	10	ES-1-BS-040	Bathroom Sink	↓		Lead			

Received by: [signature] Date: 10/12/16 Time: 1212

Tracking Number: Temperature: 16.8°C

NIL Lab ID Number

Page 4 of 12

2887

EHS Laboratories

Environmental Health Service, LLC

WaterGuard® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

1610615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental | Address: 57 Ambrose Street | City/State/Zip: Rochester, NY 14608

Phone: ( ) 585-454-1060 | Fax: ( ) 585-454-1062 | E-mail: tknapp@envoyenv.com | Acct Number:

Project Name/Testing Address: Elementary School / 335 W. Oak Orchard | City/State/Region: Medina, NY | Zip: 14103 | Agent/Property:

Collected by: Jeff Hertell / Andrew Dishaffen | Certification #: | Will Pay COD/Applicable:

Purchase Order Number: | Relinquished by: | Date:

ALL SAMPLES MUST BE COLLECTED AS FIRST DRAW FOR LEAD IN DRINKING WATER.
SAMPLES MUST BE TAKEN AT THE SAME LOCATION AS PREVIOUS SAMPLES AS ABOVE WITH DIFFERENT APARTMENT NUMBERS.
PLEASE PROVIDE A CITY/STATE/ZIP FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature Time of Collection
41	1	ES-1-NS-041	Nurse Sink	9-27-16		Lead			
42	2	ES-1-BS-042	Bathroom Sink			Lead			
43	3	ES-1-KS-043	Kitchen Sink			Lead			
44	4	ES-1-BS-044	Bathroom Sink			Lead			
45	5	ES-1-BS-045	Bathroom Sink			Lead			
46	6	ES-1-DW-046	Drinking Water			Lead			
47	7	ES-1-DW-047	Drinking Water			Lead			
48	8	ES-1-DW-048	Drinking Water			Lead			
49	9	ES-1-OS-049	Office Sink			Lead			
50	10	ES-1-BS-050	Bathroom Sink			Lead			

Received by: [signature] | Date: 10/12/16 | Time: 1212
Tracking Number: | Temperature: 16-8

NIL Lab ID Number

Page 5 of 10

2887

EHS Laboratories

Environmental Health Services, LLC

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

16J0615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company/Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608

Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 Email: tknapp@envoyenv.com Acct Number:

Project Name/Testing Address: Elementary School / 335 W. Oak Orchard City/State (Required): Medina, N.Y. Zip: 14103 Agent/Inspector:

Collected by: Jeff Hertell / Andrew Distefen Certificate#: Billing (If Applicable):

Purchase Order Number: Billing Contact by: Date:

ALL SAMPLES MUST BE COLLECTED AND ANALYZED FOR LEAD IN DRINKING WATER.
SAMPLES MUST BE COLLECTED FROM DIFFERENT APARTMENTS OR AREAS WITH DIFFERENT APARTMENT NUMBERS.
PLEASE PROVIDE A UNIQUE NUMBER FOR ALL SAMPLES LISTED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
51	1	ES-1-BS-051	Bathroom Sink	9-27-16		Lead			
52	2	ES-1-CS-052	Classroom Sink	↓	↓	Lead			
53	3	ES-1-CS-053	Classroom Sink			Lead			
54	4	ES-1-DW-054	Drinking Water			Lead			
55	5	ES-1-CS-055	Classroom Sink			Lead			
56	6	ES-1-CS-056	Classroom Sink			Lead			
57	7	ES-1-DW-057	Drinking Water			Lead			
58	8	ES-1-CS-058	Classroom Sink			Lead			
59	9	ES-1-CS-059	Classroom Sink			Lead			
60	10	ES-1-DW-060	Drinking Water	↓	↓	Lead			

Received by: [signature] Date: 10/12/16 Time: 1212
Receiving Number: Temperature: 16.8°C

NIL Lab ID Number

Page 6 of 12

2887

EHS Laboratories

Environmental Health Services, LLC

WaterGuard® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

1610615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608
Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Job Number:
Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State/Zip: Medina, NY Zip: 14103 Agent/Supplier:
Collected by: Jeff Hertel / Andrew Distaffen Certificate#: Well Type/Sample Point:
Purchase Order Number: Relinquished by: Date:

ALL SAMPLES MUST BE ANALYZED FOR LEAD IN DRINKING WATER
SAMPLES SUBMITTED ARE TO BE ANALYZED BY ANALYTICAL METHODS AS ABOVE WITH INDEPENDENT ASSESSMENT NUMBERS.
PLEASE PROVIDE A SEPARATE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
61	1	ES-1-CS-061	Classroom Sink	9-27-16		Lead			
62	2	ES-1-CS-062	Classroom Sink			Lead			
63	3	ES-1-DW-063	Drinking water			Lead			
64	4	ES-1-CS-064	Classroom Sink			Lead			
65	5	ES-1-CS-065	Classroom Sink			Lead			
66	6	ES-1-DW-066	Drinking water			Lead			
67	7	ES-1-CS-067	Classroom Sink			Lead			
68	8	ES-1-CS-068	Classroom Sink			Lead			
69	9	ES-1-DW-069	Drinking water			Lead			
70	10	ES-1-CS-070	Classroom sink			Lead			

Received by: [illegible] Date: 10/12/16 Time: 1212
Tracking Number: Signature: 16.8

NIL Lab ID Number

Page 7 of 12

2887

EHS Laboratories

Environmental Health Services, LLC

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

1650615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608

Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 Email: tknapp@envoyenv.com Alt. Number:

Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State/Region: Medina, NY Zip: 14103 Age of Property:

Collected by: Josh Hertell / Andrew Distaffen Certificate#: Will Tag Of Supplied:

Purchase Order Number: Relinquished by: Date:

ALL SAMPLES MUST BE ALALYZED FOR LEAD IN DRINKING WATER.
SAMPLES MUST BE ALL FROM THE SAME PREMISE AND BE ARCHIVE WITH DIFFERENT APARTMENT NUMBERS.
PLEASE PROVIDE A PHOTO SUMMARY FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field Pb	Field Chlorine	Temperature at Time of Collection
71	1	ES-1-CS-071	Classroom Sink	9-27-16		Lead			
72	2	ES-1-DW-072	Drinking Water			Lead			
73	3	ES-1-CS-073	Classroom Sink			Lead			
74	4	ES-1-CS-074	Classroom Sink			Lead			
75	5	ES-1-DW-075	Drinking Water			Lead			
76	6	ES-1-CS-076	Classroom Sink			Lead			
77	7	ES-1-CS-077	Classroom Sink			Lead			
78	8	ES-1-DW-078	Drinking Water			Lead			
79	9	ES-1-CS-079	Classroom Sink			Lead			
80	10	ES-1-CS-080	Classroom Sink			Lead			

Received by: [illegible] Date: 10/12/16 Time: 1212

Testing Number: Temperature: 16.8

NTL Lab ID Number

Page 8 of 12

2887

EHS Laboratories

Environmental Health Services, LLC

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

16J0615

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608
Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct. Number:
Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State (Required): Medina, NY Zip: 14103 Agent/Inspector:
Collected by: Jeff Hertel / Andrew Distaffen Certification #: Well Tag # (Required):
Purchase Order Number: Relinquished by: Date:

ALL SAMPLES MUST BE ALIQUOTED FOR LEAD IN DRINKING WATER
SAMPLES SUBMITTED ALL TOGETHER MUST BE PRESERVED AS ABOVE WITH DIFFERENT ALIQUOT NUMBERS.
MEANS PROVIDE A SEPARATE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field PH	Field Chlorine	Temperature at Time of Collection
81	1	ES-1-DW-081	Drinking Water	9-27-16		Lead			
82	2	ES-1-KS-082	Kitchen Sink			Lead			
83	3	ES-1-CS-083	Classroom Sink			Lead			
84	4	ES-1-DW-084	Drinking Water			Lead			
85	5	ES-1-CS-085	Classroom Sink			Lead			
86	6	ES-1-CS-086	Classroom Sink			Lead			
87	7	ES-1-DW-087	Drinking Water			Lead			
88	8	ES-2-BS-088	Bathroom Sink			Lead			
89	9	ES-2-BS-089	Bathroom Sink			Lead			
90	10	ES-2-CS-090	Classroom Sink			Lead			

Received by: [signature] Date: 10/12/16 Time: 1012
Tracking Number: Temperature: 16.8

NIL Lab ID Number

Page 9 of 12

Table of Contents

Sample Summary 4

Case Narrative 5

Sample Results 6

16J0616-02 6

16J0616-03 7

16J0616-04 8

16J0616-05 9

16J0616-06 10

16J0616-07 11

16J0616-08 12

16J0616-09 13

16J0616-10 14

16J0616-11 15

16J0616-12 16

16J0616-13 17

16J0616-14 18

16J0616-15 19

16J0616-16 20

16J0616-17 21

16J0616-18 22

16J0616-19 23

16J0616-20 24

16J0616-21 25

16J0616-22 26

16J0616-23 27

Table of Contents (continued)

16J0616-24 28

16J0616-25 29

16J0616-26 30

Sample Preparation Information 31

QC Data 32

Metals Analyses (Total) 32

B160841 32

B160842 32

Flag/Qualifier Summary 33

Certifications 34

Chain of Custody/Sample Receipt 35

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Environmental Hazards Services, LLC
7469 White Pine Road
Richmond, VA 23237
ATTN: Greg Brown

REPORT DATE: 10/24/2016

PURCHASE ORDER NUMBER:

PROJECT NUMBER: [none]

ANALYTICAL SUMMARY

WORK ORDER NUMBER: 16J0616

The results of analyses performed on the following samples submitted to the CON-TEST Analytical Laboratory are found in this report.

PROJECT LOCATION: Elementary School/ 335 W. Oak Orchard., Medina, NY

FIELD SAMPLE #	LAB ID:	MATRIX	SAMPLE DESCRIPTION	TEST	SUB LAB
ES-2-CS-092	16J0616-02	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-093	16J0616-03	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-094	16J0616-04	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-095	16J0616-05	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-096	16J0616-06	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-097	16J0616-07	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-098	16J0616-08	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-099	16J0616-09	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-100	16J0616-10	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-101	16J0616-11	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-102	16J0616-12	Drinking Water	classroom sink	EPA 200.8	
ES-2-BS-103	16J0616-13	Drinking Water	bathroom sink	EPA 200.8	
ES-2-BS-104	16J0616-14	Drinking Water	bathroom sink	EPA 200.8	
ES-2-BS-105	16J0616-15	Drinking Water	bathroom sink	EPA 200.8	
ES-2-BS-106	16J0616-16	Drinking Water	bathroom sink	EPA 200.8	
ES-2-BS-107	16J0616-17	Drinking Water	bathroom sink	EPA 200.8	
ES-2-BS-108	16J0616-18	Drinking Water	bathroom sink	EPA 200.8	
ES-2-DW-109	16J0616-19	Drinking Water	bathroom sink	EPA 200.8	
ES-2-CS-110	16J0616-20	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-111	16J0616-21	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-112	16J0616-22	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-113	16J0616-23	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-114	16J0616-24	Drinking Water	classroom sink	EPA 200.8	
ES-2-CS-115	16J0616-25	Drinking Water	classroom sink	EPA 200.8	
ES-1-IM-116	16J0616-26	Drinking Water	ice machine	EPA 200.8	

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

CASE NARRATIVE SUMMARY

All reported results are within defined laboratory quality control objectives unless listed below or otherwise qualified in this report.

REVISED REPORT - 10/24/2016 - 16J0616-20 sample description revised.

The results of analyses reported only relate to samples submitted to the Con-Test Analytical Laboratory for testing.
I certify that the analyses listed above, unless specifically listed as subcontracted, if any, were performed under my direction according to the approved methodologies listed in this document, and that based upon my inquiry of those individuals immediately responsible for obtaining the information, the material contained in this report is, to the best of my knowledge and belief, accurate and complete.

Meghan E. Kelley
Project Manager

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-092 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-02

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	3.7	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 7:31	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-093 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-03

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.1	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 7:36	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-094 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-04

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	10	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 7:38	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-095 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-05

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
# Lead	39	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 7:39	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-096 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-06

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	3.6	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 7:41	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-097 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-07

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.9	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 7:46	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-098 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-08

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.1	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 7:48	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-099 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-09

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	5.9	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 7:49	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-100 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-10

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	3.3	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 7:51	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-101 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-11

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	3.0	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 7:52	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-102 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-12

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	5.4	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 7:54	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-BS-103 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-13

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	0.85	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 7:56	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-BS-104 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-14

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	1.2	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 7:57	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-BS-105 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-15

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	1.2	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 7:59	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-BS-106 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-16

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 8:01	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-BS-107 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-17

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 8:06	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-BS-108 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-18

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 8:08	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: bathroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-DW-109 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-19

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 8:09	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-110 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-20

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	3.3	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 8:11	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-111 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-21

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
# Lead	21	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 8:13	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-112 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-22

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	3.1	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 9:53	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-113 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-23

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	2.3	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 9:58	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-114 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-24

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	5.0	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 10:10	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: classroom sink Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-2-CS-115 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-25

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	1.7	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 10:15	MJH

con-test® ANALYTICAL LABORATORY
39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Project Location: Elementary School/ 335 W. Oak O Sample Description: ice machine Work Order: 16J0616

Date Received: 10/12/2016

Field Sample #: ES-1-IM-116 Sampled: 9/27/2016 00:00

Sample ID: 16J0616-26

Sample Matrix: Drinking Water

Metals Analyses (Total)

Analyte	Results	RL	MCL/SMCL MA ORSG	Units	Dilution	Flag/Qual	Method	Date Prepared	Date/Time Analyzed	Analyst
Lead	ND	0.50	15	µg/L	1		EPA 200.8	10/17/16	10/17/16 10:19	MJH

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

Sample Extraction Data

Prep Method: EPA 200.8-EPA 200.8

Lab Number [Field ID]	Batch	Initial [mL]	Final [mL]	Date
16J0616-02 [ES-2-CS-092]	B160841	10.0	10.0	10/17/16
16J0616-03 [ES-2-CS-093]	B160841	10.0	10.0	10/17/16
16J0616-04 [ES-2-CS-094]	B160841	10.0	10.0	10/17/16
16J0616-05 [ES-2-CS-095]	B160841	10.0	10.0	10/17/16
16J0616-06 [ES-2-CS-096]	B160841	10.0	10.0	10/17/16
16J0616-07 [ES-2-CS-097]	B160841	10.0	10.0	10/17/16
16J0616-08 [ES-2-CS-098]	B160841	10.0	10.0	10/17/16
16J0616-09 [ES-2-CS-099]	B160841	10.0	10.0	10/17/16
16J0616-10 [ES-2-CS-100]	B160841	10.0	10.0	10/17/16
16J0616-11 [ES-2-CS-101]	B160841	10.0	10.0	10/17/16
16J0616-12 [ES-2-CS-102]	B160841	10.0	10.0	10/17/16
16J0616-13 [ES-2-BS-103]	B160841	10.0	10.0	10/17/16
16J0616-14 [ES-2-BS-104]	B160841	10.0	10.0	10/17/16
16J0616-15 [ES-2-BS-105]	B160841	10.0	10.0	10/17/16
16J0616-16 [ES-2-BS-106]	B160841	10.0	10.0	10/17/16
16J0616-17 [ES-2-BS-107]	B160841	10.0	10.0	10/17/16
16J0616-18 [ES-2-BS-108]	B160841	10.0	10.0	10/17/16
16J0616-19 [ES-2-DW-109]	B160841	10.0	10.0	10/17/16
16J0616-20 [ES-2-CS-110]	B160841	10.0	10.0	10/17/16
16J0616-21 [ES-2-CS-111]	B160841	10.0	10.0	10/17/16

Prep Method: EPA 200.8-EPA 200.8

Lab Number [Field ID]	Batch	Initial [mL]	Final [mL]	Date
16J0616-22 [ES-2-CS-112]	B160842	10.0	10.0	10/17/16
16J0616-23 [ES-2-CS-113]	B160842	10.0	10.0	10/17/16
16J0616-24 [ES-2-CS-114]	B160842	10.0	10.0	10/17/16
16J0616-25 [ES-2-CS-115]	B160842	10.0	10.0	10/17/16
16J0616-26 [ES-1-IM-116]	B160842	10.0	10.0	10/17/16

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

QUALITY CONTROL

Metals Analyses (Total) - Quality Control

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch B160841 - EPA 200.8										
Blank (B160841-BLK1)				Prepared & Analyzed: 10/17/16						
Lead	ND	0.50	µg/L							
LCS (B160841-BS1)				Prepared & Analyzed: 10/17/16						
Lead	40.8	0.50	µg/L	40.0		102	85-115			
Duplicate (B160841-DUP1)		**Source: 16J0616-02**		Prepared & Analyzed: 10/17/16						
Lead	3.70	0.50	µg/L		3.72			0.524	20	
Duplicate (B160841-DUP2)		**Source: 16J0616-03**		Prepared & Analyzed: 10/17/16						
Lead	1.95	0.50	µg/L		2.09			7.13	20	
Matrix Spike (B160841-MS1)		**Source: 16J0616-02**		Prepared & Analyzed: 10/17/16						
Lead	30.8	0.62	µg/L	25.0	3.72	108	70-130			
Matrix Spike (B160841-MS2)		**Source: 16J0616-03**		Prepared & Analyzed: 10/17/16						
Lead	29.3	0.62	µg/L	25.0	2.09	109	70-130			
Batch B160842 - EPA 200.8										
Blank (B160842-BLK1)				Prepared & Analyzed: 10/17/16						
Lead	ND	0.50	µg/L							
LCS (B160842-BS1)				Prepared & Analyzed: 10/17/16						
Lead	39.8	0.50	µg/L	40.0		99.5	85-115			
Duplicate (B160842-DUP1)		**Source: 16J0616-22**		Prepared & Analyzed: 10/17/16						
Lead	3.13	0.50	µg/L		3.13			0.0967	20	
Matrix Spike (B160842-MS1)		**Source: 16J0616-22**		Prepared & Analyzed: 10/17/16						
Lead	28.4	0.62	µg/L	25.0	3.13	101	70-130			

con-test® ANALYTICAL LABORATORY

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

FLAG/QUALIFIER SUMMARY

*	QC result is outside of established limits.
†	Wide recovery limits established for difficult compound.
‡	Wide RPD limits established for difficult compound.
#	Data exceeded client recommended or regulatory level
ND	Not Detected
RL	Reporting Limit
DL	Method Detection Limit
MCL	Maximum Contaminant Level

Percent recoveries and relative percent differences (RPDs) are determined by the software using values in the calculation which have not been rounded.

No results have been blank subtracted unless specified in the case narrative section.

39 Spruce Street * East Longmeadow, MA 01028 * FAX 413/525-6405 * TEL. 413/525-2332

CERTIFICATIONS

Certified Analyses included in this Report

Analyte	Certifications
EPA 200.8 in Drinking Water	
Lead	NH,NY,MA,CT,RI,ME,VA

The CON-TEST Environmental Laboratory operates under the following certifications and accreditations:

Code	Description	Number	Expires
AIHA	AIHA-LAP, LLC - ISO17025:2005	100033	02/1/2018
MA	Massachusetts DEP	M-MA100	06/30/2017
CT	Connecticut Department of Publilc Health	PH-0567	09/30/2017
NY	New York State Department of Health	10899 NELAP	04/1/2017
NH-S	New Hampshire Environmental Lab	2516 NELAP	02/5/2017
RI	Rhode Island Department of Health	LAO00112	12/30/2016
NC	North Carolina Div. of Water Quality	652	12/31/2016
NJ	New Jersey DEP	MA007 NELAP	06/30/2017
FL	Florida Department of Health	E871027 NELAP	06/30/2017
VT	Vermont Department of Health Lead Laboratory	LL015036	07/30/2017
ME	State of Maine	2011028	06/9/2017
VA	Commonwealth of Virginia	460217	12/14/2016
NH-P	New Hampshire Environmental Lab	2557 NELAP	09/6/2017

EHS Laboratories

Environmental Health Service, LLC
www.ehslab.com
(800) 347-4916
(804) 275-4007 (fax)
7400 Whitepine Rd
Richmond, VA 23237

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

16J0616

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608

Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct Number:

Project Name/Testing Address: Elementary School / 335 W. Oak Orchard City/State (Required): Medina, NY Zip: 14103 Age of Property:

Collected by: Jeff Hertell / Andrew Distaffen Certification #: Well Tag # (If applicable):

Purchase Order Number: Relinquished by: Date:

ALL SAMPLES BELOW SHOULD BE ANALYZED FOR LEAD IN DRINKING WATER

SAMPLES SUBMITTED ALL HAVE THE SAME FIRST ADDRESS AS ABOVE WITH DIFFERENT APARTMENT NUMBERS.

PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field Pb	Field Chlorine	Temperature at Time of Collection
01	1	ES-2-CS-091	Classroom Sink	9-27-16		Lead			
02	2	ES-2-CS-092	↓	↓		Lead			
03	3	ES-2-CS-093				Lead			
04	4	ES-2-CS-094				Lead			
05	5	ES-2-CS-095				Lead			
06	6	ES-2-CS-096				Lead			
07	7	ES-2-CS-097				Lead			
08	8	ES-2-CS-098				Lead			
09	9	ES-2-CS-099				Lead			
10	10	ES-2-CS-100	↓	↓		Lead			

Received by: [signature] Date: 10/12/16 Time: 1212

Receiving Location: Temperature: 16.8°C

NIL Lab ID Number

Page 10 of 12

Table of Contents

EHS Laboratories
Environmental Health Services, LLC
www.ehslab.com
(800) 567-4010
(804) 275-4007 (fax)
7603 Midlothian Tpk
Richmond, VA 23225

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

16J0616

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608
Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct Number:
Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State (Required): Medina, NY Zip: 14103 Age of Property:
Collected by: Jeff Hertel / Andrew Distaffen Certification #: Well Tag # (If applicable):
Purchase Order Number: Relinquished by: Date:

ALL SAMPLES BELOW SHOULD BE ANALYZED FOR LEAD IN DRINKING WATER
SAMPLES SUBMITTED ALL HAVE THE SAME PHYSICAL ADDRESS AS ABOVE WITH DIFFERENT APARTMENT NUMBERS.
PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
11	1	ES-2-CS-101	Classroom Sink	9-27-16		Lead			
12	2	ES-2-CS-102	Classroom Sink			Lead			
13	3	ES-2-BS-103	~~Classroom~~ Bathroom Sink			Lead			
14	4	ES-2-BS-104	Bathroom Sink			Lead			
15	5	ES-2-BS-105				Lead			
16	6	ES-2-BS-106				Lead			
17	7	ES-2-BS-107				Lead			
18	8	ES-2-BS-108				Lead			
19	9	ES-2-DW-109	Drinking water			Lead			
20	10	ES-2-CS-110	Classroom Sink			Lead			

Received by: [signature] Date: 10/12/16 Time: 1210
Tracking Number: Temperature: 16 8 C

NIL Lab ID Number

Page 11 of 12

Table of Contents

EHS Laboratories

Environmental Hazards Services, LLC
www.ehslab.com
(800) 347-4010
(804) 275-4007 (fax)
7469 Whitepine Rd
Richmond, VA 23237

WaterSmart® Pro
LEAD ONLY 165 Clelle
Chain-of-Custody
Analysis by National Testing Laboratories

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608

Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct Number:

Project Name/Testing Address: Elmwood Lawn School / 335 W. Oak orchard City/State/Zip: Medina, NY Zip: 14103 Agent/Inspector:

Collected by: Jeff Hertell / Andrew Distaffen Certification #: Well Reg # (If applicable):

Purchase Order Number: Relinquished by: Date:

ALL SAMPLES BELOW SHOULD BE ANALYZED FOR LEAD IN DRINKING WATER.
SAMPLES SUBMITTED ALL HAVE THE SAME PHYSICAL ADDRESS AS ABOVE WITH DIFFERENT APARTMENT NUMBERS.
PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
21	1	ES-2-CS-111	Classroom sink	9-27-16		Lead			
22	2	ES-2-CS-112				Lead			
23	3	ES-2-CS-113				Lead			
24	4	ES-2-CS-114				Lead			
25	5	ES-2-CS-115				Lead			
26	6	ES1 FM 116	Ice machine	9/29/16		Lead			
	7					Lead			
	8					Lead			
	9					Lead			
	10					Lead			

Received by: [illegible] Date: 10/12/16 Time: 1212
Tracking Number: Temperature: 16.8 C

NIL Lab ID Number

Page 12 of 12

Table of Contents

39 Spruce St.
East Longmeadow, MA. 01028
P: 413-525-2332
F: 413-525-6405
www.contestlabs.com

con-test® ANALYTICAL LABORATORY

Sample Receipt Checklist

CLIENT NAME: EHS **RECEIVED BY:** BLF **DATE:** 10/12/16

1) Was the chain(s) of custody relinquished and signed? Yes ____ No X **No COC Incl.**

2) Does the chain agree with the samples? Yes X No ____

If not, explain:

3) Are all the samples in good condition? Yes X No ____

If not, explain:

4) How were the samples received:

On Ice ____ Direct from Sampling ____ Ambient X In Cooler(s) ____

Were the samples received in Temperature Compliance of (2-6°C)? Yes ____ No X N/A ____

Temperature °C by Temp blank ____ Temperature °C by Temp gun 16.8°C

5) Are there Dissolved samples for the lab to filter? Yes ____ No X

Who was notified ____ Date ____ Time ____

6) Are there any RUSH or SHORT HOLDING TIME samples? Yes ____ No X

Who was notified ____ Date ____ Time ____

7) Location where samples are stored:

Permission to subcontract samples? Yes No
(Walk-in clients only) if not already approved
Client Signature: ____

8) Do all samples have the proper Acid pH: Yes ____ No ____ N/A X

9) Do all samples have the proper Base pH: Yes ____ No ____ N/A X

10) Was the PC notified of any discrepancies with the CoC vs the samples: Yes ____ N/A X

Containers received at Con-Test

	# of containers		# of containers
1 Liter Amber		16 oz amber	
500 mL Amber		8 oz amber/clear jar	
250 mL Amber (8oz amber)		4 oz amber/clear jar	
1 Liter Plastic		2 oz amber/clear jar	
500 mL Plastic		Plastic Bag / Ziploc	
250 mL plastic	25	SOC Kit	
40 mL Vial - type listed below		Perchlorate Kit	
Colisure / bacteria bottle		Flashpoint bottle	
Dissolved Oxygen bottle		Other glass jar	
Encore		Other	

did not receive ES-2-CS-091

40 mL vials:	# HCl ____	# Methanol ____	Time and Date Frozen:
	# Bisulfate ____	# DI Water ____	
	# Thiosulfate ____	Unpreserved ____	

Page 2 of 2

Login Sample Receipt Checklist

(Rejection Criteria Listing - Using Sample Acceptance Policy)

Any False statement will be brought to the attention of Client

Question	Answer (True/False) T/F/NA	Comment
1) The cooler's custody seal, if present, is intact.	NA	
2) The cooler or samples do not appear to have been compromised or tampered with.	T	
3) Samples were received on ice.	F	received in box via UPS
4) Cooler Temperature is acceptable.	T	drinking water
5) Cooler Temperature is recorded.	T	
6) COC is filled out in ink and legible.	T	
7) COC is filled out with all pertinent information.	T	
8) Field Sampler's name present on COC.	T	
9) There are no discrepancies between the sample IDs on the container and the COC.	T	
10) Samples are received within Holding Time.	T	
11) Sample containers have legible labels.	T	
12) Containers are not broken or leaking.	T	
13) Air Cassettes are not broken/open.	NA	
14) Sample collection date/times are provided.	T	
15) Appropriate sample containers are used.	T	
16) Proper collection media used.	T	
17) No headspace sample bottles are completely filled.	NA	
18) There is sufficient volume for all requsted analyses, including any requested MS/MSDs.	F	no ES-2-CS-091
19) Trip blanks provided if applicable.	NA	
20) VOA sample vials do not have head space or bubble is <6mm (1/4") in diameter.	NA	
21) Samples do not require splitting or compositing.	T	

Who notified of False statements? **Date/Time:**

Doc #277 Rev. 4 August 2013 **Log-In Technician Initials:** **Date/Time:**

RLF 10/12/16 1212

16-10-02886

Due Date:
10/26/2016
(Wednesday)
AE MC

EHS Laboratories
Environmental Health Services, LLC

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

16J06116

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608
Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct Number:
Project Name/Testing Address: Elementary School / 335 W. Oak Orchard City/State/Zip: Medina, NY Zip: 14103 Agent/Inspector:
Collected by: Jeff Hertel / Andrew Distaffen Certificate #: Billing Office/Supplier:
Purchase Order Number: Relinquished by: Date:

ALL SAMPLES MUST BE PRESERVED AND ANALYZED FOR LEAD IN DRINKING WATER
SAMPLES NUMBERED ONLY. PROVIDE CORRESPONDING ADDRESSES AS ARCHIVE WITH DIFFERENT ADDRESSES NUMBERS.
REFER TO PROPER LABORATORY FORM FOR ALL ANALYSES NOT LISTED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
01	1	ES-2-CS-091	Classroom Sink	9-27-16		Lead			
02	2	ES-2-CS-092	↓	↓		Lead			
03	3	ES-2-CS-093	↓	↓		Lead			
04	4	ES-2-CS-094	↓	↓		Lead			
05	5	ES-2-CS-095	↓	↓		Lead			
06	6	ES-2-CS-096	↓	↓		Lead			
07	7	ES-2-CS-097	↓	↓		Lead			
08	8	ES-2-CS-098	↓	↓		Lead			
09	9	ES-2-CS-099	↓	↓		Lead			
10	10	ES-2-CS-100	↓	↓		Lead			

Received by: [signature] Date: 10/12/16 Time: 1212
Testing Number: Temperature: 16.8°C

NIL Lab ID Number

Page 10 of 12

2886

EHS Laboratories
Environmental Health Services, LLC

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

1610616

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608
Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct Number:
Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State/Zip: Medina, NY Zip: 14103 Agent/Reporter:
Collected by: Jeff Hertel / Andrew Dickaffer Confirmed: Will Tag/Ship Kit:
Purchase Order Number: Relinquished by: Date:

ALL SAMPLES MUST BE ANALYZED FOR LEAD IN DRINKING WATER
SAMPLES SUBMITTED ARE REFERENCED BY NUMERICAL ADDRESS AS ABOVE WITH DIFFERENT ARABIC NUMBERS.
PLEASE PROVIDE A SEPARATE REPORT FOR ALL SAMPLES LISTED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field pH	Field Chlorine	Temperature at Time of Collection
11	1	ES-2-CS-101	Classroom Sink	9-27-16		Lead			
12	2	ES-2-CS-102	Classroom Sink			Lead			
13	3	ES-2-BS-103	Classroom Bathroom Sink			Lead			
14	4	ES-2-BS-104	Bathroom Sink			Lead			
15	5	ES-2-BS-105				Lead			
16	6	ES-2-BS-106				Lead			
17	7	ES-2-BS-107				Lead			
18	8	ES-2-BS-108				Lead			
19	9	ES-2-DW-109	Drinking water			Lead			
20	10	ES-2-CS-110	Classroom Sink			Lead			

Received by: [signature] Date: 10/12/16 Time: 1212
Tracking Number: Temperature: 16.8 C
NIL Lab ID Number

Page 11 of 12

2886

EHS Laboratories

Environmental Health Services, LLC

WaterSmart® Pro
LEAD ONLY
Chain-of-Custody
Analysis by National Testing Laboratories

165 Olelle

~For Lab Use Only~
SEND SAMPLES TO:
556 S. Mansfield St.
Ypsilanti, MI 48197

Company Name: Envoy Environmental Address: 57 Ambrose Street City/State/Zip: Rochester, NY 14608

Phone: ( ) 585-454-1060 Fax: ( ) 585-454-1062 E-mail: tknapp@envoyenv.com Acct Number:

Project Name/Testing Address: Elementary School / 335 W. Oak orchard City/State/Zip: Medina, NY Zip: 14103 Agent/Engineer:

Collected by: Jeff Hertel / Andrew Dishaffen Certification #: Will Pay (Check/Credit):

Purchase Order Number: Billing Contact by: Date:

ALL SAMPLES MUST BE PROPERLY ANALYZED FOR LEAD IN DRINKING WATER.
SAMPLES MUST BE ALL FROM THE SAME PHYSICAL ADDRESS AS ABOVE WITH DIFFERENT ADDRESSES.
PLEASE PROVIDE A SEPARATE SHEET FOR ALL SAMPLES REQUIRED ON THIS CHAIN OF CUSTODY.

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters: Field Temp	Field Chlorine	Temperature at Time of Collection
21	1	ES-2-CS-111	Classroom sink	9-27-16		Lead			
22	2	ES-2-CS-112	↓	↓		Lead			
23	3	ES-2-CS-113	↓	↓		Lead			
24	4	ES-2-CS-114	↓	↓		Lead			
25	5	ES-2-CS-115	↓	↓		Lead			
26	6	ES1 FM 116	Ice machine	9/29/16		Lead			
	7					Lead			
	8					Lead			
	9					Lead			
	10					Lead			

Received by: [signature] Date: 10/12/16 Time: 1212

Tracking Number: Temperature: 16.8 C

NIL Lab ID Number

Page 12 of 12

Oak Orchard 1st Floor



Client: Medina CSD
Location: Elementary School
Work Area: 1st Floor
Work Performed: Water Testing
Date: September 27, 2016
Job Number: E16-1474

Oak Orchard 1st Floor



Client: Medina CSD
Location: Elementary School
Work Area: 1st Floor
Work Performed: Water Testing
Date: September 27, 2016
Job Number: E16-1474

Oak Orchard 1st Floor



Client: Medina CSD
Location: Elementary School
Work Area: 1st Floor
Work Performed: Water Testing
Date: September 27, 2016
Job Number: E16-1474

Oak Orchard 1st Floor

Area D

Client: Medina CSD
Location: Elementary School
Work Area: 1st Floor
Work Performed: Water Testing
Date: September 27, 2016
Job Number: E16-1474



Samples in Room 126:
ES-1-CS-085
ES-1-CS-086
ES-1-DW-087

Oak Orchard 2nd Floor 214 - 224

Client: Medina CSD
Location: Elementary School
Work Area: 2nd Floor
Work Performed: Water Testing
Date: September 27, 2016
Job Number: E16-1474



Oak Orchard 2nd Floor Art Rms - 21

Client: Medina CSD
Location: Elementary School
Work Area: 2nd Floor
Work Performed: Water Testing
Date: September 27, 2016
Job Number: E16-1474