181 US Hwy 46
Mine Hill, NJ 07803
(908) 654-8068
(800) 783-0567
Fax 908-654-8069

LEAD IN DRINKING WATER REPORT

Performed At:
Schools of South Orange- Maplewood

Performed For:
South Orange/Maplewood Board of Education
25 West Parker Ave, Maplewood, NJ, 07040

Prepared By:
LEW Environmental Services, LLC.
181 US Hwy 46
Mine Hill, NJ 07803

Phone (908) 654-8068
Fax (908) 654-8069
Website http://www.LEWCorp.com

Inspection Date: 11/24/2024
Project Number: 2320

Table of Contents

Contact Information 4
Introduction 5
Sampling Methodology 5
Drinking Water Results 6
Recommendations 7
Additional Recommendations 8

Appendices

Appendix A Exceedances
Appendix B Recommendations
Appendix C All results
Appendix D Floor Plan(S)
Appendix E Water Outlet Inventory(ies)
Appendix F Laboratory Data

Contact Information

Education Agency

Client Contact:	Thomas Giglio
Client Name:	South Orange/Maplewood Board of Education
Street Address	25 West Parker Ave, Maplewood, NJ, 07040
Phone Number:	973-378-9651

Sampler(s)

Site Assessor(s):	Erick Ulloa, Marvin Ayumbi
Signature:	
Date:	February 24, 2025

Firm

Organization:	LEW Environmental Services, LLC.
Certification #:	NJDCA 00015 E
Street:	181 US Hwy 46
City, State & Zip:	Mine Hill, NJ 07803
Phone Number:	908-654-8068
Web Address:	http://www.lewcorp.com

Laboratory

Organization:	Environmental Hazard Services, LLC
Street:	7469 Whitepine Road
City, State & Zip:	Richmond, VA 23237
NJDEP Certification #	VA008
Phone Number:	800-347-4010

Introduction

LEW Environmental Services, LLC. was contracted by South Orange/Maplewood Board of Education to test for the presence of lead in drinking water in thirteen facilities in the district.

Sampling Methodology

LEW Environmental Services, LLC. followed NJAC 6A:26. Full details on sampling practices can be found in Districts Sampling Plan.

All samples were collected in 250mL wide mouth plastic containers that was prepackaged by the analytical laboratory. The sample containers may contain nitric acid, if expedited analysis is required. If not, nitric acid will be added to each sample upon arrival at the laboratory. At each sample location, the first draw sample was taken after it was determined that the water had been standing in the plumbing system for greater than eight hours but less than forty-eight hours. If second draw samples were collected, they were collecting following a flushing protocol outlined in the District's Sampling Plan.

Drinking Water Results

On January 26, 2025, LEW Environmental Services, LLC. collected the following number of water samples:

Admin
- 1 first draw samples collected plus 1 QAQC blank sample
- 0 samples above the 15ppb action level

South Mountain
- 26 first draw samples collected plus 1 QAQC blank sample
- 0 samples above the 15ppb action level

South Mountain Annex
- 15 first draw samples collected plus 1 QAQC blank sample
- 0 samples above the 15ppb action level

Clinton
- 29 first draw samples collected plus 1 QAQC blank sample
- 0 samples above the 15ppb action level

Columbia High School
- 40 first draw samples collected plus 1 QAQC blank sample
- 0 samples above the 15ppb action level

Jefferson
- 20 first draw samples collected plus 1 QAQC blank sample
- 0 samples above the 15ppb action level

Maplewood
- 19 first draw samples collected plus 1 QAQC blank sample
- 0 samples above the 15ppb action level

Marshall
- 34 first draw samples collected plus 1 QAQC blank sample
- 0 samples above the 15ppb action level

Montrose
- 30 first draw samples collected plus 1 QAQC blank sample
- 0 samples above the 15ppb action level

MS
- 31 first draw samples collected plus 1 QAQC blank sample
- 0 samples above the 15ppb action level

Seth Boyden

- 26 first draw samples collected plus 1 QAQC blank sample
- 0 samples above the 15ppb action level

Tuscan

- 15 first draw samples collected plus 1 QAQC blank sample
- 0 samples above the 15ppb action level

Underhill Field

- 7 first draw samples collected plus 1 QAQC blank sample
- 1 sample above the 15ppb action level

The complete list of samples that exceeded the 15ppb limit can be found in Appendix A. The complete list of all sample results can be found in Appendix C. The laboratory results can be found in Appendix F.

Certain outlets could not or were not tested due to various reasons. The following table lists those locations and the reason why samples were not collected.

School	Sample Location	Reason for not testing.
Tuscan	Hall byG24C, 1 Bubbler	Not operating
Tuscan	Hall byG24C, 2 Bubbler	Not operating
Tuscan	Hall by 132, Bubbler	Removed
Tuscan	Rm 122, Water cooler	Not operating
Tuscan	Trail #3, Sink	Removed
Jefferson	Room 113, Bubbler	Removed
Jefferson	Hall by A203, Bubbler	Removed
Maplewood	Hall by S03, Bubbler	Not operating
Maplewood	Hall by 21, Bubbler	Not operating
Maplewood	Girls locker Rm, Bubbler	Not operating
Maplewood	Boys locker Rm, Bubbler	Not operating
Columbia	Hall by A129, Bottle filler	Not operating
Columbia	Hall by A241, Bubbler	Not operating
Columbia	Hall by A241, Bubbler	Not operating
Columbia	Hall by B338, Bubbler	Removed

Recommendations

On January 26, 2025, LEW Environmental Services, LLC. collected the first draw samples. We recommend the following actions.

Those outlets where the first draw sample tested below 15ppb are not considered to be elevated and no remediation is necessary.

For those outlets where the first draw sample exceeds 15ppb the following steps are recommended:

1) Immediately discontinue use of the outlets.
2) Conduct second draw (flush) samples on these outlets to further delineate source of contamination.

A complete list of recommendations per outlet can be found in Appendix B.

On January 26, 2025, LEW Environmental Services, LLC. collected the first and second draw samples. We recommend the following actions.

For those outlets where the first draw sample exceeds 15ppb and the second draw sample does not exceed 15ppb, the outlet is contributing lead to the drinking water and very little lead is being picked up upstream of the outlet in the building plumbing. LEW Environmental Services, LLC. recommends immediately stopping use of these outlets. LEW Environmental Services, LLC. then recommends replacing the outlet and associated plumbing up to the wall connection.

For those outlets where the first draw sample exceeds 15pbb and the second draw sample exceeds 15ppb or more, the outlet and the building plumbing are contributing lead to the drinking water. LEW Environmental Services, LLC. recommends immediately stopping use of these outlets. LEW Environmental Services, LLC. then recommends replacing the outlet and associated plumbing up to the wall connection, and installing a lead filter at the wall connection. A filter maintenance plan will need to be implemented, in order to ensure that all filters are in proper working order.

A complete list of recommendations per outlet can be found in Appendix B.

Additional Recommendations

1) Follow-up samples should be collected after any remediation efforts in order to determine the efficacy of the work.
2) Any of the inoperable/non-functioning outlets listed above that are brought back into service should be sampled.
3) Comply with all requirements set forth in NJAC 6A:26.

Appendix A Exceedances

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
Underhill Field	12/15/2024	12/27/2024	8	TRAINERS ROOM	260

Appendix B Recommendations

Building	Location	Remediation Recommendation
Underhill Field	TRAINERS ROOM	Discontinue use and perform second draw sampling

Appendix C All Results

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
Seth Boyden Elementary	12/15/2024	12/26/2024	1	HALL BY G6	<1.00
Seth Boyden Elementary	12/15/2024	12/30/2024	2	ROOM G2	13.6
Seth Boyden Elementary	12/15/2024	12/26/2024	3	ROOM G1	<1.00
Seth Boyden Elementary	12/15/2024	12/26/2024	4	HALL BY G12	1.39
Seth Boyden Elementary	12/15/2024	12/26/2024	5	HALL BY G12	2.31
Seth Boyden Elementary	12/15/2024	12/26/2024	6	HALL BY G14	<1.00
Seth Boyden Elementary	12/15/2024	12/26/2024	7	HALL BY G14	<1.00
Seth Boyden Elementary	12/15/2024	12/26/2024	8	CAFETERIA	<1.00
Seth Boyden Elementary	12/15/2024	12/26/2024	9	CAFETERIA	<1.00
Seth Boyden Elementary	12/15/2024	12/26/2024	9A	CAFETERIA	1.4
Seth Boyden Elementary	12/15/2024	12/26/2024	10	HALL BY 102	4.53
Seth Boyden Elementary	12/15/2024	12/26/2024	11	OFFICE FOYER LEFT	8.37
Seth Boyden Elementary	12/15/2024	12/26/2024	12	OFFICE FOYER RIGHT	10.5
Seth Boyden Elementary	12/15/2024	12/26/2024	13	SB-S-1FL-ND	3.61
Seth Boyden Elementary	12/15/2024	12/26/2024	14	HALL BY 105 LEFT	2.64
Seth Boyden Elementary	12/15/2024	12/26/2024	15	HALL BY 105 RIGHT	3.17
Seth Boyden Elementary	12/15/2024	12/26/2024	19	HALL BY 206 LEFT	3.32
Seth Boyden Elementary	12/15/2024	12/26/2024	20	HALL BY 206 RIGHT	5.12
Seth Boyden Elementary	12/15/2024	12/26/2024	21	ROOM GIG	1.58
Seth Boyden Elementary	12/15/2024	12/26/2024	22	ROOM GIF	<1.00
Seth Boyden Elementary	12/15/2024	12/26/2024	23	HALL BY STORAGE GIE	<1.00
Seth Boyden Elementary	12/15/2024	12/26/2024	24	HALL BY STORAGE GIE	<1.00
Seth Boyden Elementary	12/15/2024	12/26/2024	25	HALL BY STORAGE GIE	<1.00
Seth Boyden Elementary	12/15/2024	12/26/2024	26	HALL BY RM 100E	<1.00
Seth Boyden Elementary	12/15/2024	12/26/2024	27	HALL BY RM 100E	<1.00
Seth Boyden Elementary	12/15/2024	12/26/2024	28	HALL BY RM 100E	<1.00
Seth Boyden Elementary	12/15/2024	12/26/2024	29	ROOM SR	<1.00

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
South Mountain Annex	11/24/2024	12/14/2024	1	ROOM 114	<1.00
South Mountain Annex	11/24/2024	12/14/2024	2	ROOM 117	<1.00
South Mountain Annex	11/24/2024	12/14/2024	3	ROOM 115	<1.00
South Mountain Annex	11/24/2024	12/14/2024	4	ROOM 116	<1.00
South Mountain Annex	11/24/2024	12/14/2024	5	HALL BY BOILER	<1.00
South Mountain Annex	11/24/2024	12/14/2024	6	TEACHER LOUNGE	1.62
South Mountain Annex	11/24/2024	12/14/2024	7	NURSE'S OFFICE	2.5
South Mountain Annex	11/24/2024	12/14/2024	8	HALL BY 103	<1.00
South Mountain Annex	11/24/2024	12/14/2024	8A	HALL BY 103	<1.00
South Mountain Annex	11/24/2024	12/14/2024	9	ROOM 101	<1.00
South Mountain Annex	11/24/2024	12/14/2024	10	ROOM 102	<1.00
South Mountain Annex	11/24/2024	12/14/2024	12	ROOM 121	<1.00
South Mountain Annex	11/24/2024	12/14/2024	13	ROOM 122	<1.00
South Mountain Annex	11/24/2024	12/14/2024	12	ROOM 123	<1.00
South Mountain Annex	11/24/2024	12/14/2024	15	ROOM 124	<1.00
South Mountain Annex	11/24/2024	12/14/2024	16	ROOM SR	<1.00

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
South Mountain Elementary	11/24/2024	12/18/2024	2	HALL BY RM 5	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	2A	HALL BY RM 5	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	4	HALL BY RM 120	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	5	HALL BY RM 120	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	6	HALL BY RM 107	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	8	NURSE BATH 116	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	10	ROOM 102	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	11	HALL BY RM 205	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	12	ROOM 209	1.04
South Mountain Elementary	11/24/2024	12/18/2024	13	CAFETERIA LEFT	1.68
South Mountain Elementary	11/24/2024	12/18/2024	14	CAFETERIA RIGHT	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	15	HALL BY RM 205	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	16	HALL BY RM 107	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	18	HALL BY RM 127	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	19	HALL BY RM 127	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	20	HALL BY RM 127	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	21	HALL BY RM 218	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	22	HALL BY RM 218	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	23	HALL BY RM 218	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	24	HALL BY RM 17	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	25	HALL BY RM 17	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	26	HALL BY RM 17	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	27	RM 17	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	28	RM 16	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	29	RM 15	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	30	ROOM SR	<1.00
South Mountain Elementary	11/24/2024	12/18/2024	9	SME-S-1FL-NB	1.26

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
South Orange Middle School	11/24/2024	12/18/2024	1	HALL BY JC 14	3.11
South Orange Middle School	11/24/2024	12/18/2024	2	HALL BY RM 105	1.09
South Orange Middle School	11/24/2024	12/18/2024	3	HALL BY 107	1.02
South Orange Middle School	11/24/2024	12/18/2024	4	GIRLS LOCKER ROOM	1.28
South Orange Middle School	11/24/2024	12/18/2024	5	GYM LEFT	<1.00
South Orange Middle School	11/24/2024	12/18/2024	6	GYM RIGHT	<1.00
South Orange Middle School	11/24/2024	12/18/2024	7	BOYS LOCKER ROOM	1.57
South Orange Middle School	11/24/2024	12/18/2024	8	HALL BY STORAGE 14 RIGHT	<1.00
South Orange Middle School	11/24/2024	12/18/2024	9	HALL BY STORAGE 14 LEFT	<1.00
South Orange Middle School	11/24/2024	12/18/2024	10	CAFETERIA	<1.00
South Orange Middle School	11/24/2024	12/18/2024	11	CAFETERIA	<1.00
South Orange Middle School	11/24/2024	12/18/2024	12	KITCHEN	1.65
South Orange Middle School	11/24/2024	12/18/2024	13	KITCHEN	1.29
South Orange Middle School	11/24/2024	12/18/2024	14	KITCHEN	2.55
South Orange Middle School	11/24/2024	12/18/2024	15	KITCHEN	1.44
South Orange Middle School	11/24/2024	12/18/2024	16	KITCHEN	2.35
South Orange Middle School	11/24/2024	12/18/2024	17	KITCHEN	<1.00
South Orange Middle School	11/24/2024	12/18/2024	18	HALL BY 129B	<1.00
South Orange Middle School	11/24/2024	12/18/2024	19	HALL BY STORAGE 24	<1.00
South Orange Middle School	11/24/2024	12/18/2024	20	MAIN OFFICE KITCHEN	1
South Orange Middle School	11/24/2024	12/18/2024	21	NURSES OFFICE	1.45
South Orange Middle School	11/24/2024	12/18/2024	22	NURSES EXAM RM	1.27
South Orange Middle School	11/24/2024	12/18/2024	23	HALL BY 226	2.5
South Orange Middle School	11/24/2024	12/18/2024	24	TEACHERS LOUNGE	1.15
South Orange Middle School	11/24/2024	12/18/2024	25	HALL BY JC 22	<1.00
South Orange Middle School	11/24/2024	12/18/2024	26	HALL BY JC 22	<1.00
South Orange Middle School	11/24/2024	12/18/2024	28	HALL BY 283	1.12
South Orange Middle School	11/24/2024	12/18/2024	29	FOYER BY JC 29 LEFT	<1.00
South Orange Middle School	11/24/2024	12/18/2024	30	FOYER BY JC 29 RIGHT	<1.00
South Orange Middle School	11/24/2024	12/18/2024	31	HALL BY 389	<1.00
South Orange Middle School	11/24/2024	12/18/2024	32	HALL BY 362	<1.00
South Orange Middle School	11/24/2024	12/18/2024	34	ROOM SR	<1.00

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
Underhill Field	12/15/2024	12/27/2024	1	OLD FIELD HOUSE	<1.00
Underhill Field	12/15/2024	12/30/2024	2	NEW FIELD HOUSE	<1.00
Underhill Field	12/15/2024	12/27/2024	3	BOYS LOCKER	2.03
Underhill Field	12/15/2024	12/27/2024	4	BOYS SHOWER	3.14
Underhill Field	12/15/2024	12/27/2024	7	CONCESSION STAND	2.17
Underhill Field	12/15/2024	12/27/2024	8	TRAINERS ROOM	260
Underhill Field	12/15/2024	12/27/2024	9	CUSTIDIAL OFFICE	6.39
Underhill Field	12/15/2024	12/27/2024	10	ROOM SR	<1.00

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
Jefferson	1/27/2025	2/6/2025	JE-WC-GFL-B10	HALL BY CUSTODIAL OFFICE BUBBLER	<1.00
Jefferson	1/27/2025	2/6/2025	JE-DW-GFL-112	HALL BY 112 BUBBLER	<1.00
Jefferson	1/27/2025	2/6/2025	JE-DW-GFL-114	ROOM A114 BUBBLER	4.33
Jefferson	1/27/2025	2/6/2025	JE-DW-GFL-116	ROOM A116 BUBBLER	6.82
Jefferson	1/27/2025	2/6/2025	JE-DW-GFL-115-1	ROOM A115 BUBBLER	7.5
Jefferson	1/27/2025	2/6/2025	JE-DW-GFL-115-2	ROOM A115 BUBBLER	12.4
Jefferson	1/27/2025	2/6/2025	JE-DW-GFL-118	ROOM A118 BUBBLER	1.45
Jefferson	1/27/2025	2/6/2025	JE-DW-GFL-119	ROOM A119 BUBBLER	6.08
Jefferson	1/27/2025	2/6/2025	JE-S-GFL-NB	NURSE BATHROOM SINK	<1.00
Jefferson	1/27/2025	2/6/2025	JE-S-GFL-NO	NURSE OFFICE SINK	3.57
Jefferson	1/27/2025	2/6/2025	JE-WC-GFL-CAF-1	HALL BY CAFETERIA BUBBLER	<1.00
Jefferson	1/27/2025	2/6/2025	JE-BF-GFL-CAF	HALL BY CAFETERIA BOTTLE FILLER	<1.00
Jefferson	1/27/2025	2/6/2025	JE-WC-GFL-CAF-2	HALL BY CAFETERIA BUBBLER	1.08
Jefferson	1/27/2025	2/6/2025	JE-WC-1FL-203-1	HALL BY A203 BUBBLER	<1.00
Jefferson	1/27/2025	2/6/2025	JE-WC-1FL-B201	HALL BY B201 BUBBLER	<1.00
Jefferson	1/27/2025	2/6/2025	JE-WC-1FL-B201	HALL BY B201 BOTTLE FILLER	<1.00
Jefferson	1/27/2025	2/6/2025	JE-S-1FL-L	LIBRARY SINK	5.34
Jefferson	1/27/2025	2/6/2025	JE-WC-2FL-TEC	HALL BY B300A BUBBLER	<1.00
Jefferson	1/27/2025	2/6/2025	JE-WC-2FL-304	HALL BY A304 BUBBLER	<1.00
Jefferson	1/27/2025	2/6/2025	JE-S-2FL-TL	TEACHERS LOUNGE SINK	<1.00
Jefferson	1/27/2025	2/6/2025	JE-SR	SUNROOM	<1.00

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
Marshall Elementary	12/15/2024	12/27/2024	1	ROOM 120	2.78
Marshall Elementary	12/15/2024	12/27/2024	2	HALL BY 121	1.86
Marshall Elementary	12/15/2024	12/27/2024	3	ROOM 121	5.37
Marshall Elementary	12/15/2024	12/27/2024	3A	ROOM 121	5.31
Marshall Elementary	12/15/2024	12/27/2024	4	ROOM 119	2.48
Marshall Elementary	12/15/2024	12/27/2024	5	ROOM 122	<1.00
Marshall Elementary	12/15/2024	12/27/2024	6	HALL BY 122	<1.00
Marshall Elementary	12/15/2024	12/27/2024	8	ROOM 125	1.84
Marshall Elementary	12/15/2024	12/27/2024	9	ROOM 126	<1.00
Marshall Elementary	12/15/2024	12/27/2024	10A	ROOM 127	1.84
Marshall Elementary	12/15/2024	12/27/2024	11	ROOM 128	3.96
Marshall Elementary	12/15/2024	12/27/2024	12	CAFETERIA	<1.00
Marshall Elementary	12/15/2024	12/27/2024	12A	CAFETERIA	<1.00
Marshall Elementary	12/15/2024	12/27/2024	14	HALL BY BATH RMS	1.75
Marshall Elementary	12/15/2024	12/27/2024	15	TEACHERS LOUNGE	<1.00
Marshall Elementary	12/15/2024	12/27/2024	16	NURSES BATH	8.04
Marshall Elementary	12/15/2024	12/27/2024	17	ROOM 101	<1.00
Marshall Elementary	12/15/2024	12/27/2024	18	ROOM 107	<1.00
Marshall Elementary	12/15/2024	12/27/2024	19	ROOM 143	6.68
Marshall Elementary	12/15/2024	12/27/2024	20	HALL BY 203	<1.00
Marshall Elementary	12/15/2024	12/27/2024	21	ROOM 213	<1.00
Marshall Elementary	12/15/2024	12/27/2024	22	ROOM 209	2.79
Marshall Elementary	12/15/2024	12/30/2024	23	ROOM 210	6.88
Marshall Elementary	12/15/2024	12/27/2024	24	ROOM 211	2.4
Marshall Elementary	12/15/2024	12/27/2024	25	HALL BY STORAGE 167	<1.00
Marshall Elementary	12/15/2024	12/27/2024	26	HALL BY STORAGE 167	<1.00
Marshall Elementary	12/15/2024	12/27/2024	27	HALL BY STORAGE 167	<1.00
Marshall Elementary	12/15/2024	12/30/2024	28	ROOM 162	6.3
Marshall Elementary	12/15/2024	12/27/2024	29	ROOM 164	<1.00
Marshall Elementary	12/15/2024	12/27/2024	30	HALL BY STORAGE 231	<1.00
Marshall Elementary	12/15/2024	12/27/2024	31	HALL BY STORAGE 231	<1.00
Marshall Elementary	12/15/2024	12/27/2024	32	HALL BY STORAGE 231	<1.00
Marshall Elementary	12/15/2024	12/27/2024	33	ROOM 224	<1.00
Marshall Elementary	12/15/2024	12/27/2024	34	ROOM 226	<1.00
Marshall Elementary	12/15/2024	12/27/2024	35	ROOM SR	<1.00


Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
Montrose School	11/24/2024	12/18/2024	1	HALL BY B3	1.51
Montrose School	11/24/2024	12/19/2024	2	HALL BY B5	2.98
Montrose School	11/24/2024	12/19/2024	3	ROOM 107	2.57
Montrose School	11/24/2024	12/19/2024	4	ROOM 105	3.93
Montrose School	11/24/2024	12/18/2024	5	ROOM 105	3.95
Montrose School	11/24/2024	12/18/2024	6	HALL BY 105	1.06
Montrose School	11/24/2024	12/18/2024	7	ROOM 101	4.13
Montrose School	11/24/2024	12/19/2024	8	ROOM 101	2
Montrose School	11/24/2024	12/18/2024	9	ROOM 106	<1.00
Montrose School	11/24/2024	12/19/2024	10	ROOM 204	1.46
Montrose School	11/24/2024	12/18/2024	11	ROOM 107	1.21
Montrose School	11/24/2024	12/19/2024	13	ROOM 104	1.34
Montrose School	11/24/2024	12/18/2024	14	ROOM 205	<1.00
Montrose School	11/24/2024	12/18/2024	15	ROOM B3	<1.00
Montrose School	11/24/2024	12/19/2024	17	ROOM 201	1.28
Montrose School	11/24/2024	12/18/2024	18	ROOM 206	1.26
Montrose School	11/24/2024	12/19/2024	19	ROOM B4	5.65
Montrose School	11/24/2024	12/18/2024	20	ROOM 204	1.5
Montrose School	11/24/2024	12/18/2024	21	ROOM 106	1.47
Montrose School	11/24/2024	12/19/2024	22	ROOM 202 LEFT	4.83
Montrose School	11/24/2024	12/18/2024	23	ROOM B5	<1.00
Montrose School	11/24/2024	12/18/2024	24	ROOM B5	2.12
Montrose School	11/24/2024	12/18/2024	25	ROOM 203	1.83
Montrose School	11/24/2024	12/18/2024	26	ROOM 201	3.1
Montrose School	11/24/2024	12/18/2024	27	ROOM 206	3.32
Montrose School	11/24/2024	12/18/2024	28	ROOM 104	<1.00
Montrose School	11/24/2024	12/18/2024	29	ROOM 205	2.23
Montrose School	11/24/2024	12/18/2024	30	ROOM 202 RIGHT	2.46
Montrose School	11/24/2024	12/18/2024	31	ROOM SR	<1.00


Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
Clinton Elementary	12/15/2024	12/26/2024	1	CE-DW-1	<1.00
Clinton Elementary	12/15/2024	12/26/2024	2	CE-DW-2	3.65
Clinton Elementary	12/15/2024	12/26/2024	3	CE-FP-GFL-CAF	1.26
Clinton Elementary	12/15/2024	12/26/2024	3A	CE-WC-GFL-CAF	<1.00
Clinton Elementary	12/15/2024	12/26/2024	3B	CE-BF-GFL-CAF	<1.00
Clinton Elementary	12/15/2024	12/26/2024	4	CE-WC-4	<1.00
Clinton Elementary	12/15/2024	12/26/2024	6	CE-WC-6	<1.00
Clinton Elementary	12/15/2024	12/26/2024	7	CE-S-7	2.38
Clinton Elementary	12/15/2024	12/26/2024	8	CE-S-8	<1.00
Clinton Elementary	12/15/2024	12/26/2024	9	CE-WC-9	<1.00
Clinton Elementary	12/15/2024	12/26/2024	10	CE-BF-10	<1.00
Clinton Elementary	12/15/2024	12/26/2024	11	CE-WC-11	<1.00
Clinton Elementary	12/15/2024	12/26/2024	12	CE-BF-12	<1.00
Clinton Elementary	12/15/2024	12/26/2024	13	CE-DW-13	<1.00
Clinton Elementary	12/15/2024	12/26/2024	14	CE-DW-14	<1.00
Clinton Elementary	12/15/2024	12/26/2024	15	CE-DW-15	<1.00
Clinton Elementary	12/15/2024	12/26/2024	16	CE-WC-16	<1.00
Clinton Elementary	12/15/2024	12/26/2024	17	CE-BF-17	<1.00
Clinton Elementary	12/15/2024	12/26/2024	18	CE-WC-18	<1.00
Clinton Elementary	12/15/2024	12/26/2024	19	CE-DW-19	<1.00
Clinton Elementary	12/15/2024	12/26/2024	20	CE-WC-20	<1.00
Clinton Elementary	12/15/2024	12/26/2024	21	CE-WC-21	<1.00
Clinton Elementary	12/15/2024	12/26/2024	22	CE-BF-22	<1.00
Clinton Elementary	12/15/2024	12/26/2024	23	CE-S-23	<1.00
Clinton Elementary	12/15/2024	12/26/2024	24	CE-WC-24	<1.00
Clinton Elementary	12/15/2024	12/26/2024	25	CE-WC-25	<1.00
Clinton Elementary	12/15/2024	12/26/2024	26	CE-WC-26	<1.00
Clinton Elementary	12/15/2024	12/26/2024	27	CE-BF-27	<1.00
Clinton Elementary	12/15/2024	12/26/2024	28	CE-DW-28	2.2
Clinton Elementary	12/15/2024	12/26/2024	29	CE-DW-SR	<1.00

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
25 Harvard Ave	1/27/2025	2/1/2025	TE-WC-BFL-G16	HALL BY G16 BUBBLER	<1.00
25 Harvard Ave	1/27/2025	2/1/2025	TE-BF-BFL-G16	HALL BY G16 BOTTLE FILLER	<1.00
25 Harvard Ave	1/27/2025	2/5/2025	TE-WC-BFL-G24-1	HALL BY G24 BUBBLER	<1.00
25 Harvard Ave	1/27/2025	2/5/2025	TE-BF-BFL-G24-2	HALL BY G24 BOTTLE FILLER	<1.00
25 Harvard Ave	1/27/2025	2/1/2025	TE-WC-1FL-108	HALL BY 108 BUBBLER	1.73
25 Harvard Ave	1/27/2025	2/1/2025	TE-WC-1FL-132-1	HALL BY 132 BUBBLER	<1.00
25 Harvard Ave	1/27/2025	2/1/2025	TE-WC-1FL-117-1	HALL BY 117 BUBBLER	<1.00
25 Harvard Ave	1/27/2025	2/1/2025	TE-WC-1FL-117-2	HALL BY 117 BUBBLER	<1.00
25 Harvard Ave	1/27/2025	2/1/2025	TE-S-1FL-NO	NURSE OFFICE SINK	2.66
25 Harvard Ave	1/27/2025	2/1/2025	TE-WC-1FL-125-1	HALL BY 125 BUBBLER	<1.00
25 Harvard Ave	1/27/2025	2/1/2025	TE-WC-1FL-125-2	HALL BY 125 BUBBLER	1.14
25 Harvard Ave	1/27/2025	2/1/2025	TE-S-FL-1FL-120	ROOM 120 SINK	2.6
25 Harvard Ave	1/27/2025	2/1/2025	TE-S-1FL-122	ROOM 122 SINK	4.33
25 Harvard Ave	1/27/2025	2/1/2025	TE-DW-1FL-123	ROOM 123 BUBBLER	<1.00
25 Harvard Ave	1/27/2025	2/1/2025	TE-WC-2FL-202	HALL BY 202 BUBBLER	1.6
25 Harvard Ave	1/27/2025	2/1/2025	TE-SR	SUNROOM	<1.00

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
17 Parker Ave	1/27/2025	2/3/2025	HS-S-1FL-NO	NURSE OFFICE SINK	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-S-1FL-NB	NURSE BATHROOM SINK	1.38
17 Parker Ave	1/27/2025	2/3/2025	HS-S-1FL-SB	STAFF BATHROOM C106 SINK	2.81
17 Parker Ave	1/27/2025	2/3/2025	HS-WC-1FL-109-1	HALL BY C109 BUBBLER	1.59
17 Parker Ave	1/27/2025	2/3/2025	HS-WC-1FL-109-2	HALL BY C109 BUBBLER	2.05
17 Parker Ave	1/27/2025	2/3/2025	HS-WC-1FL-134-1	HALL BY B134 BUBBLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-DW-1FL-114-1	HALL BY B114 BUBBLER	8.97
17 Parker Ave	1/27/2025	2/3/2025	HS-DW-1FL-114-2	HALL BY B114 BUBBLER	4.03
17 Parker Ave	1/27/2025	2/3/2025	HS-DW-1FL-105-1	HALL BY D105 BUBBLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-DW-1FL-105-2	HALL BY D105 BOTTLE FILLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-WC-1FL-129	HALL BY A129 BUBBLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-S-GFL-KIT-1	KITCHEN SINK	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-S-GFL-KIT-2	KITCHEN KETTLE SINK	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-IM-GFL-KIT	KITCHEN ICE MACHINE	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-WC-GFL-CAF	CAFETERIA WATER COOLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-BF-GFL-CAF	CAFETERIA BOTTLE FILLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-WC-GFL-BB-1	HALL BY BLACK BOX BUBBLER	1.88
17 Parker Ave	1/27/2025	2/3/2025	HS-WC-GFL-BB-2	HALL BY BLACK BOX BUBBLER	2.58
17 Parker Ave	1/27/2025	2/3/2025	HW-DW-2FL-203-1	HALL BY D203 BUBBLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-BF-2FL-203-2	HALL BY D203 BOTTLE FILLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-WC-2FL-FL	FACULTY LOUNGE BUBBLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-S-2FL-FL	FACULTY LOUNGE SINK	2.16
17 Parker Ave	1/27/2025	2/3/2025	HS-WC-2FL-207	HALL BY B207 BUBBLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-BF-2FL-207	HALL BY B207 BOTTLE FILLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-DW-2FL-230-1	HALL BY B230 BUBBLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-DW-2FL-230-2	HALL BY B230 BOTTLE FILLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-WC-2FL-207-1	HALL BY C207 BUBBLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-WC-2FL-207-2	HALL BY C207 BUBBLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-2FL-BF-207-2	HALL BY C207 BOTTLE FILLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-WC-2FL-229-1	HALL BY C229 BUBBLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-BF-2FL-229-2	HALL BY C229 BOTTLE FILLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-WC-3FL-BB	HALL BY BOYS BATHROOM BUBBLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-BF-3FL-BB	HALL BY BOYS BATHROOM BOTTLE FILLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-DW-3FL-301-1	HALL BY D301 BUBBLER	1.37
17 Parker Ave	1/27/2025	2/3/2025	HS-DW-3FL-301-2	HALL BY D301 BUBBLER	7.65
17 Parker Ave	1/27/2025	2/3/2025	HS-DW-3FL-338-1	HALL BY B338 BUBBLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-DW-3FL-328-1	HALL BY B328 BOTTLE FILLER	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-DW-3FL-328-2	HALL BY 328 BOTTLE FILLER	<1.00
17 Parker Ave	1/27/2025	2/5/2025	HS-DW-1FL-128-IM	ROOM C128 ICE MACHINE	<1.00
17 Parker Ave	1/27/2025	2/3/2025	HS-DW-1FL-128	ROO C128 SINK	1.6
17 Parker Ave	1/27/2025	2/3/2025	HS-SR	SUNROOM	<1.00

Appendix D Floor Plan(s)


B1
STORAGE
B3
BOILER ROOM
B2
BOILER ROOM
B4
STAIRWAY
1 BASEMENT
SCALE: 1/16" = 1'-0"
118
PAY ROLL
117
BUS. ADMIN.
116
BOARD SECR.
114
STORAGE
113
BUS. OFFICE
112
BUS. OFFICE
111
BUS. OFFICE
100C
VESTIBULE
109
STORAGE
100B
CORRIDOR
119
STORAGE
120
TOILET
ST# 1
100A
CORRIDOR
110
STORAGE
127
OFFICE
126
OFFICE
126
OFFICE
131
INFORMATION TECHNOLOGY
130
OFFICE
129
OFFICE
128
OFFICE
121
COPY ROOM
101A
TOILET
104
WOMENS TOILET
103
MENS TOILET
122
ACCOUNTS PAYABLE
101
BREAK ROOM
ST# 2
132
STORAGE
102
STORAGE
105
FIRE ALARM
2 GROUND FLOOR
SCALE: 1/16" = 1'-0"
ADMINISTRATION BUILDING
SOM SCHOOL DISTRICT
MASTER BASE PLANS
Element
Architectural Group
A-1




SOUTH MOUNTAIN ELEMENTARY ANNEX

SOM SCHOOL DISTRICT
MASTER BASE PLANS


Element Architectural Group

GROUND FLOOR PLAN

A-6



1 FIRST FLOOR
SCALE: 1/32" = 1'-0"



2 SECOND FLOOR
SCALE: 1/32" = 1'-0"


SETH BOYDEN ELEMENTARY SCHOOL

SOW1 SCHOOL DISTRICT
MASTER BASE PLANS


Element Architectural Group

FIRST AND SECOND FLOOR PLANS

A-8



1 BASEMENT
SCALE: 1/32" = 1'-0"



2 GROUND FLOOR
SCALE: 1/32" = 1'-0"


SETH BOYDEN ELEMENTARY SCHOOL

SOM SCHOOL DISTRICT
MASTER BASE PLANS

Element Architectural Group

BASEMENT & GROUND FLOOR PLANS
A-7
DWG. 7 OF 28

Room #s wrong.



1 GROUND FLOOR
SCALE: 1/32" = 1'-0"


SOM SCHOOL DISTRICT
MASTER BASE PLANS

Element Architectural Group

GROUND FLOOR PLAN

A-3

CLINTON ELEMENTARY SCHOOL



1 FIRST FLOOR
SCALE: 1/32" = 1'-0"

CLINTON ELEMENTARY SCHOOL


SOM SCHOOL DISTRICT
MASTER BASE PLANS

Element Architectural Group

FIRST FLOOR PLAN

A-4


sht. 4 of 28




Columbia High School

Corey Durr

Class of 2013


1 GROUND FLOOR
SCALE: 1/32" = 1'-0"
2 FIRST FLOOR
SCALE: 1/32" = 1'-0"
A100B CORRIDOR
A100E CORRIDOR
A100D CORRIDOR
A100C CORRIDOR
A100A CORRIDOR
A100F CORRIDOR
B200B CORRIDOR
B200A CORRIDOR
A200A CORRIDOR
B103 CLASSROOM
B104 CLASSROOM
B105 CLASSROOM
B106 CLASSROOM
B107 CAFETERIA
A101A PRINC. OFFICE
A101B CONF. RM.
A102 CLASSROOM
A103 WOMEN TOILET
A104 MEN TOILET
A109 NURSE
B110 TOILET
A105 MUSIC CLASSROOM
B111 PE RM.
B108B TOILET
B108A TOILET
B107A KITCHEN
A120 AUDITORIUM
A120A STAGE
A121 GYMNASIUM
A110 CLASSROOM
A111 BOYS TOILET
A112 CLASSROOM
A113 CLASSROOM
A114 CLASSROOM
LIGHT COURT
A115B JAN. CLO.
A116A TOILET
A115A TOILET
A119 CLASSROOM
A118 CLASSROOM
A117 LIFE SKILLS LAB
A116 CLASSROOM
A115 CLASSROOM
A116B STORAGE
B202 LIBRARY
B204 OFFICE
A201 CLASSROOM
A202 RESOURCE CENTER
A203A RESOURCE RM.
A203 SPEECH RM.
A204 WORKROOM
OPEN TO AUDITORIUM ROOM BELOW
A205 WORKROOM
A206 RESOURCE RM.
A208 RESOURCE RM.
A207 CLASSROOM
ST# 1
ST# 2
ST# 3
ST# 4
JEFFERSON ELEMENTARY SCHOOL
SOM SCHOOL DISTRICT
MASTER BASE PLANS
Element Architectural Group
A-14
sht. 14 of 28



1 SECOND FLOOR
SCALE: 1/32" = 1'-0"


JEFFERSON ELEMENTARY SCHOOL

SOM SCHOOL DISTRICT
MASTER BASE PLANS

Element Architectural Group

SECOND FLOOR PLAN

A-15



1 SECOND FLOOR
SCALE: 1/32" = 1'-0"


JEFFERSON ELEMENTARY SCHOOL

SOM SCHOOL DISTRICT
MASTER BASE PLANS


Element Architectural Group

SECOND FLOOR PLAN


A-15



MMS	MAPLEWOOD MIDDLE SCHOOL - SCHEMATIC FIRST FLOOR PLAN	1




MMS | MAPLEWOOD MIDDLE SCHOOL - SCHEMATIC SECOND FLOOR PLAN | **2**



Courtesy of Sandra Pagan - 2014

MMS | MAPLEWOOD MIDDLE SCHOOL - SCHEMATIC BASEMENT PLAN | **B**




SOM SCHOOL DISTRICT
MASTER BASE PLANS

Element Architectural Group

FIRST FLOOR PLAN
SECOND FLOOR PLAN

A-28



Layout of the rooms is not accurate

MONTROSE SCHOOL


SD#M SCHOOL DISTRICT
MASTER BASE PLANS

Element Architectural Group

SECOND FLOOR PLAN

A-11

SHT. 11 OF 28



Layout of the rooms is not accurate

MONTROSE SCHOOL


SOM SCHOOL DISTRICT
MASTER BASE PLANS

Element Architectural Group

FIRST FLOOR PLAN

A-10

sht. 10 of 28



1 BASEMENT FLOOR
SCALE: 1/16" = 1'-0"

Layout of the rooms is not accurate.


MONTROSE SCHOOL


SOM SCHOOL DISTRICT
MASTER BASE PLANS

Element Architectural Group

A-0


9 of 28



16
14
13
9/10
11/12
8
26
27
28
15
1 FIRST FLOOR
SCALE: 1/32" = 1'-0"
SOUTH ORANGE MIDDLE SCHOOL
SOM SCHOOL DISTRICT
MASTER BASE PLANS
Element
Architectural Group
FIRST FLOOR PLAN
A-20




1 SECOND FLOOR
SCALE: 1/32" = 1'-0"

SOUTH ORANGE MIDDLE SCHOOL


24
25
20
21
23
4
6/7
22
5
3
2
1
COURTYARD
GROUND FLOOR
SCALE: 1/32" = 1'-0"
SOUTH ORANGE MIDDLE SCHOOL
SOM SCHOOL DISTRICT
MASTER BASE PLANS
Element
Architectural Group
GROUND FLOOR PLAN
A-19



1 BASEMENT
SCALE: 1/32" = 1'-0"




2 GROUND FLOOR
SCALE: 1/32" = 1'-0"

SETH BOYDEN ELEMENTARY SCHOOL


SOM SCHOOL DISTRICT
MASTER BASE PLANS

Element Architectural Group

BASEMENT & GROUND FLOOR PLANS
A-7
DWG. 7 OF 28



1 FIRST FLOOR
SCALE: 1/32" = 1'-0"



2 SECOND FLOOR
SCALE: 1/32" = 1'-0"


SETH BOYDEN ELEMENTARY SCHOOL

SOW1 SCHOOL DISTRICT
MASTER BASE PLANS

Element Architectural Group

FIRST AND SECOND FLOOR PLANS

A-8



1 SECOND FLOOR
SCALE: 1/32" = 1'-0"

17

TUSCAN ELEMENTARY SCHOOL


SOM SCHOOL DISTRICT
MASTER BASE PLANS


Element Architectural Group

SECOND FLOOR PLAN

A-13

pno. 13 of 28


1 BASEMENT FLOOR
SCALE: 1/32" = 1'-0"
2 FIRST FLOOR
SCALE: 1/32" = 1'-0"
CAFETERIA
UNEXCAVATED
STORAGE
TOILET
GIRLS TOILET
BOYS TOILET
COURTYARD
MUSIC ROOM
INSTRUMENT STORAGE
ART STUDIO
CLASSROOM
LIFE SKILLS LAB
LIGHT COURT
PASSAGEWAY
CONFERENCE ROOM
BOILER ROOM
FAN
JAN. RM.
FACULTY LOUNGE
G100A CORRIDOR
G100B CORRIDOR
G100C CORRIDOR
LIBRARY
TECH.
COMPUTER LAB
SPECIAL EDUCATION
GIRLS TOILET
BOYS TOILET
GYMNASIUM
STAGE
AUDITORIUM
COAT ROOM
NURSE
PRINC. OFFICE
MAIN OFFICE
SPEECH THERAPY
CONF. RM.
ENTRY
100A CORRIDOR
100B CORRIDOR
100C CORRIDOR
100F CORRIDOR
100G CORRIDOR
TUSCAN ELEMENTARY SCHOOL
SOM SCHOOL DISTRICT
MASTER BASE PLANS
Element Architectural Group
A-12


Old Field House
2
New Field House
4
3
5/6
Concession stand
7
1

Appendix E Water Outlet Inventory(ies)

Appendix F Laboratory Data

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 24-12-01528

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 12/09/2024
Reported Date: 12/16/2024
Sampled By: Marvin Ayumbi
Tech Certification #:

Project/Test Address: 2320; South Mountain Annex; 112 Glenview Road; South Orange, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-01528-001	1	11/24/2024	ROOM 114	<1.00	12/14/2024	
24-12-01528-002	2	11/24/2024	ROOM 117	<1.00	12/14/2024	
24-12-01528-003	3	11/24/2024	ROOM 115	<1.00	12/14/2024	
24-12-01528-004	4	11/24/2024	ROOM 116	<1.00	12/14/2024	
24-12-01528-005	5	11/24/2024	HALL BY BOILER	<1.00	12/14/2024	
24-12-01528-006	6	11/24/2024	TEACHER LOUNGE	1.62	12/14/2024	
24-12-01528-007	7	11/24/2024	NURSE'S OFFICE	2.50	12/14/2024	
24-12-01528-008	8	11/24/2024	HALL BY 103	<1.00	12/14/2024	
24-12-01528-009	8A	11/24/2024	HALL BY 103	<1.00	12/14/2024	
24-12-01528-010	9	11/24/2024	ROOM 101	<1.00	12/14/2024	
24-12-01528-011	10	11/24/2024	ROOM 102	<1.00	12/14/2024	
24-12-01528-012	12	11/24/2024	ROOM 121	<1.00	12/14/2024	
24-12-01528-013	13	11/24/2024	ROOM 122	<1.00	12/14/2024	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 24-12-01528

Project/Test Address: 2320; South Mountain Annex; 112 Glenview Road; South Orange, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-01528-014	12	11/24/2024	ROOM 123	<1.00	12/14/2024	
24-12-01528-015	15	11/24/2024	ROOM 124	<1.00	12/14/2024	
24-12-01528-016	16	11/24/2024	ROOM SR	<1.00	12/14/2024	

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

24-12-01528

Due Date:
12/16/2024
(Monday)
AE

10+

Client Name: LEW Environmental Services Account #: 20132Y

Address: 181 US HWY 46

City/State/Zip: Mine Hill, NJ 07803 Phone: 908-654-8069

Email Address: labresults@lewenvironmental.com

Project Name/ Number: South Mountain Annex / 2320

Collection Address: 112 Glenview Road City/State/Zip: South Orange, NJ
(Required) (Required)

Approx. Age Of Property: _____ Collected By: Marvin Ayumbi

Water Source: (Check One) Public ✓ or Well _____ Well Tag # (if applicable): _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte Pb	Analyte Cu
1	1	Room 114	11/24/24	AM / PM	✓	
2	2	Room 117		AM / PM	✓	
3	3	Room 115		AM / PM	✓	
4	4	Room 116		AM / PM	✓	
5	5	Hall by Boiler		AM / PM	✓	
6	6	Teachers Lounge		AM / PM	✓	
7	7	Nurse's office		AM / PM	✓	
8	8	Hall by 103		AM / PM	✓	
9	8A	Hall by 103		AM / PM	✓	
10	9	Room 101		AM / PM	✓	
11	10	Room 102		AM / PM	✓	
12	12	Room 121		AM / PM	✓	
13	13	Room 122		AM / PM	✓	
14	14	Room 123		AM / PM	✓	
15	15	Room 124	11/24/24	AM / PM	✓	

Released by: Marvin Ayumbi Signature: [signature] Date/Time: 11/26/24

Received by: ELMARIS TMAS Signature: [signature] Date/Time: 12/9/24 2:00pm

Client Name: _____ Account #_____ Page 2 of 2

Project Name: _____

Lab I.D. #: 01528

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
16	16	ROOM SR	11/24/24	AM / PM	✓	
17				AM / PM		
18				AM / PM		
19				AM / PM		
20				AM / PM		
21				AM / PM		
22				AM / PM		
23				AM / PM		
24				AM / PM		
25				AM / PM		
26				AM / PM		
27				AM / PM		
28				AM / PM		
29				AM / PM		
30				AM / PM		
31				AM / PM		
32				AM / PM		
33				AM / PM		
34				AM / PM		
35				AM / PM		
36				AM / PM		
37				AM / PM		
38				AM / PM		
39				AM / PM		
40				AM / PM		
41				AM / PM		
42				AM / PM		
43				AM / PM		
44				AM / PM		
45				AM / PM		
46				AM / PM		
47				AM / PM		
48				AM / PM		
49				AM / PM		
50				AM / PM		

Released by:	Signature:	Date/Time:
Received by: E CHRISTMAS	Signature:	Date/Time: 12/9/24

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 24-12-02880

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 12/16/2024
Reported Date: 12/19/2024
Sampled By: Marvin Ayumbi
Tech Certification #:

Project/Test Address: 2320; Admin Building; 525 Academy Street; South Orange, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-02880-001	1	11/24/2024	KITCHEN	<1.00	12/18/2024	
24-12-02880-002	2	11/24/2024	ROOM SR	<1.00	12/18/2024	

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory:



Tasha Eaddy
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

24-12-02880

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Due Date:
12/23/2024
(Monday)
AE

10+

Client Name: LEW Environmental Service Account #: 201327

Address: 181 US HWY 46

City/State/Zip: Mine Hill, NJ 07803 Phone: 908-654-8069

Email Address: labresults@lewenvironmental.com

Project Name/ Number: Admin Building / 2320

Collection Address: 525 Academy Street (Required) City/State/Zip: South Orange, NJ (Required)

Approx. Age Of Property: _____ Collected By: Marvin Ayumbi

Water Source: (Check One) Public X or Well _____ Well Tag # (if applicable): _____

Turn-Around Time ____ 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	1	Kitchen	11/24/24	AM / PM	✓	
2	2	Room SR	11/24/24	AM / PM	✓	
3				AM / PM		
4				AM / PM		
5				AM / PM		
6				AM / PM		
7				AM / PM		
8				AM / PM		
9				AM / PM		
10				AM / PM		
11				AM / PM		
12				AM / PM		
13				AM / PM		
14				AM / PM		
15				AM / PM		

Released by: Marvin Ayumbi Signature: _____ Date/Time: 11/26/24

Received by: E CHRISTMAS Signature: _____ Date/Time: 12/16/24 2:19 pm

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 24-12-02887

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 12/16/2024
Reported Date: 12/19/2024
Sampled By: Marvin Ayumbi
Tech Certification #:

Project/Test Address: 2320; South Mountain Elementary; 444 South Orange Ave; South Orange, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-02887-001	2	11/24/2024	HALL BY RM 5	<1.00	12/18/2024	
24-12-02887-002	2A	11/24/2024	HALL BY RM 5	<1.00	12/18/2024	
24-12-02887-003	4	11/24/2024	HALL BY RM 120	<1.00	12/18/2024	
24-12-02887-004	5	11/24/2024	HALL BY RM 120	<1.00	12/18/2024	
24-12-02887-005	6	11/24/2024	HALL BY RM 107	<1.00	12/18/2024	
24-12-02887-006	8	11/24/2024	NURSE BATH 116	<1.00	12/18/2024	
24-12-02887-007	10	11/24/2024	ROOM 102	<1.00	12/18/2024	
24-12-02887-008	11	11/24/2024	HALL BY RM 205	<1.00	12/18/2024	
24-12-02887-009	12	11/24/2024	ROOM 209	1.04	12/18/2024	
24-12-02887-010	13	11/24/2024	CAFETERIA LEFT	1.68	12/18/2024	
24-12-02887-011	14	11/24/2024	CAFETERIA RIGHT	<1.00	12/18/2024	
24-12-02887-012	15	11/24/2024	HALL BY RM 205	<1.00	12/18/2024	
24-12-02887-013	16	11/24/2024	HALL BY RM 107	<1.00	12/18/2024	

Client Number: 201327 Report Number: 24-12-02887

Project/Test Address: 2320; South Mountain Elementary; 444 South Orange Ave; South Orange, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-02887-014	18	11/24/2024	HALL BY RM 127	<1.00	12/18/2024	
24-12-02887-015	19	11/24/2024	HALL BY RM 127	<1.00	12/18/2024	
24-12-02887-016	20	11/24/2024	HALL BY RM 127	<1.00	12/18/2024	
24-12-02887-017	21	11/24/2024	HALL BY RM 218	<1.00	12/18/2024	
24-12-02887-018	22	11/24/2024	HALL BY RM 218	<1.00	12/18/2024	
24-12-02887-019	23	11/24/2024	HALL BY RM 218	<1.00	12/18/2024	
24-12-02887-020	24	11/24/2024	HALL BY RM 17	<1.00	12/18/2024	
24-12-02887-021	25	11/24/2024	HALL BY RM 17	<1.00	12/18/2024	
24-12-02887-022	26	11/24/2024	HALL BY RM 17	<1.00	12/18/2024	
24-12-02887-023	27	11/24/2024	RM 17	<1.00	12/18/2024	
24-12-02887-024	28	11/24/2024	RM 16	<1.00	12/18/2024	
24-12-02887-025	29	11/24/2024	RM 15	<1.00	12/18/2024	
24-12-02887-026	30	11/24/2024	ROOM SR	<1.00	12/18/2024	
24-12-02887-027	9	11/24/2024	SME-S-1FL-NB	1.26	12/18/2024	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 24-12-02887

Project/Test Address: 2320; South Mountain Elementary; 444 South Orange Ave; South Orange, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory:



Tasha Eaddy

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

24-12-02887

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Due Date:
12/23/2024
(Monday)
AE

Client Name: LEW Environmental Service Account #: 201327

Address: 181 US HWY 46 10+

City/State/Zip: Mine Hill NJ 07803 Phone: 908-654-8069

Email Address: labresults@lewenvironmental.com

Project Name/ Number: South Mountain Elementary /2320

Collection Address: 444 South Orange Ave (Required) City/State/Zip: South orange, NJ (Required)

Approx. Age Of Property: _____ Collected By: Marvin Ayumbi

Water Source: (Check One) Public ✓ or Well _____ Well Tag # (if applicable): _____

Turn-Around Time ✓ 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	2	Hall by Rm 5	11/24/24	AM / PM	✓	
2	2A	Hall by Rm 5		AM / PM	✓	
3	4	Hall by Rm 120		AM / PM	✓	
4	5	Hall by Rm 120		AM / PM	✓	
5	6	Hall by Rm 107		AM / PM	✓	
6	8	Nurse Bath 116		AM / PM	✓	
7	10	Room 102		AM / PM	✓	
8	11	Hall by Rm 205		AM / PM	✓	
9	12	Room 209		AM / PM	✓	
10	13	Cafeteria, Left		AM / PM	✓	
11	14	Cafeteria, Right		AM / PM	✓	
12	15	Hall by Rm 205		AM / PM	✓	
13	16	Hall by Rm 107		AM / PM	✓	
14	18	Hall by Rm 127		AM / PM	✓	
15	19	Hall by Rm 127	11/24/24	AM / PM	✓	

Released by: Marvin Ayumbi	Signature:		Date/Time: 11/26/24
Received by: EHS Courier	Signature:		Date/Time: 12/16/24 2:54pm

Client Name: _____ Account #_____ Page 2 of 2

Project Name: _____

Lab I.D. #: 02887

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
16	20	Hall by Rm 127	11/24/24	AM / PM	✓	
17	21	Hall by Rm 218		AM / PM	✓	
18	22	Hall by Rm 218		AM / PM	✓	
19	23	Hall by Rm 218		AM / PM	✓	
20	24	Hall by Rm 17		AM / PM	✓	
21	25	Hall by Rm 17		AM / PM	✓	
22	26	Hall by Rm 17		AM / PM	✓	
23	27	Room 17		AM / PM	✓	
24	28	Room 16		AM / PM	✓	
25	29	Room 15		AM / PM	✓	
26	30	Room SR	11/24/24	AM / PM	✓	
* 27	9	SME-S-1FL-NB *extra sample received 12/16		AM / PM		
28				AM / PM		
29				AM / PM		
30				AM / PM		
31				AM / PM		
32				AM / PM		
33				AM / PM		
34				AM / PM		
35				AM / PM		
36				AM / PM		
37				AM / PM		
38				AM / PM		
39				AM / PM		
40				AM / PM		
41				AM / PM		
42				AM / PM		
43				AM / PM		
44				AM / PM		
45				AM / PM		
46				AM / PM		
47				AM / PM		
48				AM / PM		
49				AM / PM		
50				AM / PM		

Released by:		Signature:	Date/Time:
Received by:	ECHELSTATS	Signature:	Date/Time: 12/16/24 2:54pm

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 24-12-02888

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 12/16/2024
Reported Date: 12/19/2024
Sampled By: Marvin Ayumbi
Tech Certification #:

Project/Test Address: 2320; Montrose School; 358 Clark Street; South Orange, NJ 07079

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-02888-001	1	11/24/2024	HALL BY B3	1.51	12/18/2024	
24-12-02888-002	2	11/24/2024	HALL BY B5	2.98	12/19/2024	
24-12-02888-003	3	11/24/2024	ROOM 107	2.57	12/19/2024	
24-12-02888-004	4	11/24/2024	ROOM 105	3.93	12/19/2024	
24-12-02888-005	5	11/24/2024	ROOM 105	3.95	12/18/2024	
24-12-02888-006	6	11/24/2024	HALL BY 105	1.06	12/18/2024	
24-12-02888-007	7	11/24/2024	ROOM 101	4.13	12/18/2024	
24-12-02888-008	8	11/24/2024	ROOM 101	2.00	12/19/2024	
24-12-02888-009	9	11/24/2024	ROOM 106	<1.00	12/18/2024	
24-12-02888-010	10	11/24/2024	ROOM 204	1.46	12/19/2024	
24-12-02888-011	11	11/24/2024	ROOM 107	1.21	12/18/2024	
24-12-02888-012	13	11/24/2024	ROOM 104	1.34	12/19/2024	
24-12-02888-013	14	11/24/2024	ROOM 205	<1.00	12/18/2024	

Client Number: 201327 Report Number: 24-12-02888

Project/Test Address: 2320; Montrose School; 358 Clark Street; South Orange, NJ 07079

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-02888-014	15	11/24/2024	ROOM B3	<1.00	12/18/2024	
24-12-02888-015	17	11/24/2024	ROOM 201	1.28	12/19/2024	
24-12-02888-016	18	11/24/2024	ROOM 206	1.26	12/18/2024	
24-12-02888-017	19	11/24/2024	ROOM B4	5.65	12/19/2024	
24-12-02888-018	20	11/24/2024	ROOM 204	1.50	12/18/2024	
24-12-02888-019	21	11/24/2024	ROOM 106	1.47	12/18/2024	
24-12-02888-020	22	11/24/2024	ROOM 202 LEFT	4.83	12/19/2024	
24-12-02888-021	23	11/24/2024	ROOM B5	<1.00	12/18/2024	
24-12-02888-022	24	11/24/2024	ROOM B5	2.12	12/18/2024	
24-12-02888-023	25	11/24/2024	ROOM 203	1.83	12/18/2024	
24-12-02888-024	26	11/24/2024	ROOM 201	3.10	12/18/2024	
24-12-02888-025	27	11/24/2024	ROOM 206	3.32	12/18/2024	
24-12-02888-026	28	11/24/2024	ROOM 104	<1.00	12/18/2024	
24-12-02888-027	29	11/24/2024	ROOM 205	2.23	12/18/2024	
24-12-02888-028	30	11/24/2024	ROOM 202 RIGHT	2.46	12/18/2024	
24-12-02888-029	31	11/24/2024	ROOM SR	<1.00	12/18/2024	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 24-12-02888

Project/Test Address: 2320; Montrose School; 358 Clark Street; South Orange, NJ 07079

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Candace Mason

Candace Mason

QA Chemist

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

24-12-02888

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Due Date:
12/23/2024
(Monday)
AE

Client Name: LEW Environmental Services Account #: 201327

Address: 181 US Hwy 46 10+

City/State/Zip: Mine Hill, NJ 07803 Phone: 908-654-8069

Email Address: labresults@lewenvironmental.com

Project Name/ Number: Montrose School / 2320

Collection Address: 358 Clark Street City/State/Zip: South Orange, NJ 07079
(Required) (Required)

Approx. Age Of Property: _____ Collected By: Marvin Ayumbi

Water Source: (Check One) Public X or Well _____ Well Tag # (if applicable): _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte Pb	Analyte Cu
1	1	Hall by B3	11/24/24	AM / PM	✓	
2	2	Hall by B5		AM / PM	✓	
3	3	Room 107		AM / PM	✓	
4	4	Room 105		AM / PM	✓	
5	5	Room 105		AM / PM	✓	
6	6	Hall by 105		AM / PM	✓	
7	7	Room 101		AM / PM	✓	
8	8	Room 101		AM / PM	✓	
9	9	Room 106		AM / PM	✓	
10	10	Room 204		AM / PM	✓	
11	11	Room 107		AM / PM	✓	
12	13	Room 104		AM / PM	✓	
13	14	Room 205		AM / PM	✓	
14	15	Room B3		AM / PM	✓	
15	16	Room B5	11/24/24	AM / PM	✓	

* Sample not received* See 12/16

Released by: Marvin Ayumbi Signature: [signature] Date/Time: 11/24/24

Received by: EL CHRISTMAS Signature: [signature] Date/Time: 12/16/24 2:46pm

Client Name: _____ Account #_____ Page 2 of 2

Project Name: _____

Lab I.D. #: 02888

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
16	17	Room 201	11/24/24	AM / PM	✓	
17	18	Room 206		AM / PM	✓	
18	19	Room B4		AM / PM	✓	
19	20	Room 204		AM / PM	✓	
20	21	Room 106		AM / PM	✓	
21	22	Room 202, Left		AM / PM	✓	
22	23	Room B5		AM / PM	✓	
23	24	Room B5		AM / PM	✓	
24	25	Room 203		AM / PM	✓	
25	26	Room 201		AM / PM	✓	
26	27	Room 206		AM / PM	✓	
27	28	Room 104		AM / PM	✓	
28	29	Room 205		AM / PM	✓	
29	30	Room 202, Right		AM / PM	✓	
30	31	Room SR	11/24/24	AM / PM	✓	
31				AM / PM		
32				AM / PM		
33				AM / PM		
34				AM / PM		
35				AM / PM		
36				AM / PM		
37				AM / PM		
38				AM / PM		
39				AM / PM		
40				AM / PM		
41				AM / PM		
42				AM / PM		
43				AM / PM		
44				AM / PM		
45				AM / PM		
46				AM / PM		
47				AM / PM		
48				AM / PM		
49				AM / PM		
50				AM / PM		

Released by:		Signature:	Date/Time:
Received by:	ECHARGE TIMES	Signature:	Date/Time: 12/16/24 257pm

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 24-12-02890

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 12/16/2024
Reported Date: 12/19/2024
Sampled By: Marvin Ayumbi
Tech Certification #:

Project/Test Address: 2320; South Orange Middle School; 70 N Ridgewood Rd; South Orange, NJ 07079

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-02890-001	1	11/24/2024	HALL BY JC 14	3.11	12/18/2024	
24-12-02890-002	2	11/24/2024	HALL BY RM 105	1.09	12/18/2024	
24-12-02890-003	3	11/24/2024	HALL BY 107	1.02	12/18/2024	
24-12-02890-004	4	11/24/2024	GIRLS LOCKER ROOM	1.28	12/18/2024	
24-12-02890-005	5	11/24/2024	GYM LEFT	<1.00	12/18/2024	
24-12-02890-006	6	11/24/2024	GYM RIGHT	<1.00	12/18/2024	
24-12-02890-007	7	11/24/2024	BOYS LOCKER ROOM	1.57	12/18/2024	
24-12-02890-008	8	11/24/2024	HALL BY STORAGE 14 RIGHT	<1.00	12/18/2024	
24-12-02890-009	9	11/24/2024	HALL BY STORAGE 14 LEFT	<1.00	12/18/2024	
24-12-02890-010	10	11/24/2024	CAFETERIA	<1.00	12/18/2024	
24-12-02890-011	11	11/24/2024	CAFETERIA	<1.00	12/18/2024	
24-12-02890-012	12	11/24/2024	KITCHEN	1.65	12/18/2024	

Client Number: 201327 Report Number: 24-12-02890

Project/Test Address: 2320; South Orange Middle School; 70 N Ridgewood Rd; South Orange, NJ 07079

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-02890-013	13	11/24/2024	KITCHEN	1.29	12/18/2024	
24-12-02890-014	14	11/24/2024	KITCHEN	2.55	12/18/2024	
24-12-02890-015	15	11/24/2024	KITCHEN	1.44	12/18/2024	
24-12-02890-016	16	11/24/2024	KITCHEN	2.35	12/18/2024	
24-12-02890-017	17	11/24/2024	KITCHEN	<1.00	12/18/2024	
24-12-02890-018	18	11/24/2024	HALL BY 129B	<1.00	12/18/2024	
24-12-02890-019	19	11/24/2024	HALL BY STORAGE 24	<1.00	12/18/2024	
24-12-02890-020	20	11/24/2024	MAIN OFFICE KITCHEN	1.00	12/18/2024	
24-12-02890-021	21	11/24/2024	NURSES OFFICE	1.45	12/18/2024	
24-12-02890-022	22	11/24/2024	NURSES EXAM RM	1.27	12/18/2024	
24-12-02890-023	23	11/24/2024	HALL BY 226	2.50	12/18/2024	
24-12-02890-024	24	11/24/2024	TEACHERS LOUNGE	1.15	12/18/2024	
24-12-02890-025	25	11/24/2024	HALL BY JC 22	<1.00	12/18/2024	
24-12-02890-026	26	11/24/2024	HALL BY JC 22	<1.00	12/18/2024	
24-12-02890-027	28	11/24/2024	HALL BY 283	1.12	12/18/2024	
24-12-02890-028	29	11/24/2024	FOYER BY JC 29 LEFT	<1.00	12/18/2024	
24-12-02890-029	30	11/24/2024	FOYER BY JC 29 RIGHT	<1.00	12/18/2024	
24-12-02890-030	31	11/24/2024	HALL BY 389	<1.00	12/18/2024	
24-12-02890-031	32	11/24/2024	HALL BY 362	<1.00	12/18/2024	
24-12-02890-032	34	11/24/2024	ROOM SR	<1.00	12/18/2024	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 24-12-02890

Project/Test Address: 2320; South Orange Middle School; 70 N Ridgewood Rd; South Orange, NJ 07079

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Tasha Eaddy

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

24-12-02890

Due Date:
12/23/2024
(Monday)
AE

Client Name: LEW Environmental Services Account #: 20327

Address: 181 US HWY 46 10+

City/State/Zip: Mine Hill, NJ 07803 Phone: 908-684-8069

Email Address: labresults@lewenvironmental.com

Project Name/ Number: South Orange Middle School / 2320

Collection Address: 70 N Ridgewood Rd, City/State/Zip: South Orange, NJ 07079
(Required) (Required)

Approx. Age Of Property: Collected By: Marvin Ayumbi

Water Source: (Check One) Public X or Well Well Tag # (if applicable):

Turn-Around Time X 5 Days ___ 3 Days ___ 2 Days ___ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	1	Hall by JC 14	11/24/24	AM / PM	✓	
2	2	Hall by Rm 105		AM / PM	✓	
3	3	Hall by 107		AM / PM	✓	
4	4	Girls Locker room		AM / PM	✓	
5	5	Gym Left		AM / PM	✓	
6	6	Gym Right		AM / PM	✓	
7	7	Boys Locker room		AM / PM	✓	
8	8	Hall by Storage 14 Right		AM / PM	✓	
9	9	Hall by storage 14 Left		AM / PM	✓	
10	10	Cafeteria		AM / PM	✓	
11	11	Cafeteria		AM / PM	✓	
12	12	Kitchen		AM / PM	✓	
13	13	Kitchen		AM / PM	✓	
14	14	Kitchen		AM / PM	✓	
15	15	Kitchen	11/24/24	AM / PM	✓	

Released by: Marvin Ayumbi Signature: Date/Time: 11/26/24

Received by: CHRISTMAS Signature: Date/Time: 12/12/24 2:58pm

Client Name: _____ Account #_____ Page 2 of 2

Project Name: _____

Lab I.D. #: 02890

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
16	16	Kitchen	11/24/24	AM / PM	✓	
17	17	Kitchen		AM / PM	✓	
18	18	Hall by 129B		AM / PM	✓	
19	19	Hall by Storage 24		AM / PM	✓	
20	20	Main office Kitchen		AM / PM	✓	
21	21	Nurse's Office		AM / PM	✓	
22	22	Nurse's Exam Rm		AM / PM	✓	
23	23	Hall by 226		AM / PM	✓	
24	24	Teachers Lounge		AM / PM	✓	
25	25	Hall by JC 22		AM / PM	✓	
26	26	Hall by JC 22		AM / PM	✓	
27	28	Hall by 283		AM / PM	✓	
28	29	Foyer by JC 29 Left		AM / PM	✓	
29	30	Foyer by JC 29 Right		AM / PM	✓	
30	31	Hall by 389		AM / PM	✓	
31	32	Hall by 362		AM / PM	✓	
32	34	Room SR	11/24/24	AM / PM	✓	
33				AM / PM		
34				AM / PM		
35				AM / PM		
36				AM / PM		
37				AM / PM		
38				AM / PM		
39				AM / PM		
40				AM / PM		
41				AM / PM		
42				AM / PM		
43				AM / PM		
44				AM / PM		
45				AM / PM		
46				AM / PM		
47				AM / PM		
48				AM / PM		
49				AM / PM		
50				AM / PM		

Released by:		Signature:	Date/Time:
Received by: ECHRISTMAS		Signature:	Date/Time: 12/16/24

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 24-12-04102

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 12/20/2024
Reported Date: 12/27/2024
Sampled By: Marvin Ayumbi
Tech Certification #:

Project/Test Address: 2320; Clinton Elementary; 27 Berkshire Rd; Maplewood NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-04102-001	1	12/15/2024	CE-DW-1	<1.00	12/26/2024	
24-12-04102-002	2	12/15/2024	CE-DW-2	3.65	12/26/2024	
24-12-04102-003	3	12/15/2024	CE-FP-GFL-CAF	1.26	12/26/2024	
24-12-04102-004	3A	12/15/2024	CE-WC-GFL-CAF	<1.00	12/26/2024	
24-12-04102-005	3B	12/15/2024	CE-BF-GFL-CAF	<1.00	12/26/2024	
24-12-04102-006	4	12/15/2024	CE-WC-4	<1.00	12/26/2024	
24-12-04102-007	6	12/15/2024	CE-WC-6	<1.00	12/26/2024	
24-12-04102-008	7	12/15/2024	CE-S-7	2.38	12/26/2024	
24-12-04102-009	8	12/15/2024	CE-S-8	<1.00	12/26/2024	
24-12-04102-010	9	12/15/2024	CE-WC-9	<1.00	12/26/2024	
24-12-04102-011	10	12/15/2024	CE-BF-10	<1.00	12/26/2024	
24-12-04102-012	11	12/15/2024	CE-WC-11	<1.00	12/26/2024	
24-12-04102-013	12	12/15/2024	CE-BF-12	<1.00	12/26/2024	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 24-12-04102

Project/Test Address: 2320; Clinton Elementary; 27 Berkshire Rd; Maplewood NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-04102-014	13	12/15/2024	CE-DW-13	<1.00	12/26/2024	
24-12-04102-015	14	12/15/2024	CE-DW-14	<1.00	12/26/2024	
24-12-04102-016	15	12/15/2024	CE-DW-15	<1.00	12/26/2024	
24-12-04102-017	16	12/15/2024	CE-WC-16	<1.00	12/26/2024	
24-12-04102-018	17	12/15/2024	CE-BF-17	<1.00	12/26/2024	
24-12-04102-019	18	12/15/2024	CE-WC-18	<1.00	12/26/2024	
24-12-04102-020	19	12/15/2024	CE-DW-19	<1.00	12/26/2024	
24-12-04102-021	20	12/15/2024	CE-WC-20	<1.00	12/26/2024	
24-12-04102-022	21	12/15/2024	CE-WC-21	<1.00	12/26/2024	
24-12-04102-023	22	12/15/2024	CE-BF-22	<1.00	12/26/2024	
24-12-04102-024	23	12/15/2024	CE-S-23	<1.00	12/26/2024	
24-12-04102-025	24	12/15/2024	CE-WC-24	<1.00	12/26/2024	
24-12-04102-026	25	12/15/2024	CE-WC-25	<1.00	12/26/2024	
24-12-04102-027	26	12/15/2024	CE-WC-26	<1.00	12/26/2024	
24-12-04102-028	27	12/15/2024	CE-BF-27	<1.00	12/26/2024	
24-12-04102-029	28	12/15/2024	CE-DW-28	2.20	12/26/2024	
24-12-04102-030	29	12/15/2024	CE-DW-SR	<1.00	12/26/2024	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 24-12-04102

Project/Test Address: 2320; Clinton Elementary; 27 Berkshire Rd; Maplewood NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

24-12-04102

Due Date:
12/30/2024
(Monday)
AE

Client Name: LEW Environmental Services Account #: 201327

Address: 181 US HWY 46

City/State/Zip: Mine Hill NJ 07803 Phone: 908-654-8069

Email Address: labresults@lewenvironmental.com

Project Name/ Number: Clinton Elementary / 2320

Collection Address: 27 Berkshire Rd City/State/Zip: Maplewood NJ
(Required) (Required)

Approx. Age Of Property: _____ Collected By: Marvin Ayumbi

Water Source: (Check One) Public X or Well _____ Well Tag # (if applicable): _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	1	CE-DW-1	12/15/24	AM / PM	✓	
2	2	CE-DW-2		AM / PM	✓	
3	3	CE-FP-GFL-CAF		AM / PM	✓	
4	3A	CE-WC-GFL-CAF		AM / PM	✓	
5	3B	CE-BF-GFL-CAF		AM / PM	✓	
6	4	CE-WC-4		AM / PM	✓	
7	6	CE-WC-6		AM / PM	✓	
8	7	CE-S-7		AM / PM	✓	
9	8	CE-S-8		AM / PM	✓	
10	9	CE-WC-9		AM / PM	✓	
11	10	CE-BF-10		AM / PM	✓	
12	11	CE-WC-11		AM / PM	✓	
13	12	CE-BF-12		AM / PM	✓	
14	13	CE-DW-13		AM / PM	✓	
15	14	CE-DW-14	12/15/24	AM / PM	✓	

Released by: Marvin Ayumbi	Signature:	Date/Time: 12/15/24
Received by: KT HARRIS	Signature: K Harris	Date/Time: 12.20.24 11:10 AM

Client Name: _____ Account #_____ Page 2 of 2

Project Name: _____

Lab I.D. #: ____-____-4102

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
16	15	CE-DW-15	12/15/24	AM / PM	✓	
17	16	CE-WC-16		AM / PM	✓	
18	17	CE-BF-17		AM / PM	✓	
19	18	CE-WC-18		AM / PM	✓	
20	19	CE-DW-19		AM / PM	✓	
21	20	CE-WC-20		AM / PM	✓	
22	21	CE-WC-21		AM / PM	✓	
23	22	CE-BF-22		AM / PM	✓	
24	23	CE-S-23		AM / PM	✓	
25	24	CE-WC-24		AM / PM	✓	
26	25	CE-WC-25		AM / PM	✓	
27	26	CE-WC-26		AM / PM	✓	
28	27	CE-BF-27		AM / PM	✓	
29	28	CE-DW-28		AM / PM	✓	
30	29	CE-DW-SR	12-15-24	AM / PM	✓	
31				AM / PM		
32				AM / PM		
33				AM / PM		
34				AM / PM		
35				AM / PM		
36				AM / PM		
37				AM / PM		
38				AM / PM		
39				AM / PM		
40				AM / PM		
41				AM / PM		
42				AM / PM		
43				AM / PM		
44				AM / PM		
45				AM / PM		
46				AM / PM		
47				AM / PM		
48				AM / PM		
49				AM / PM		
50				AM / PM		

Released by:	Signature:	Date/Time:
Received by: KT HARRIS	Signature: K Harris	Date/Time: 12/20/24 11:10AM

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 24-12-04105

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 12/20/2024
Reported Date: 12/30/2024
Sampled By: Marvin Ayumbi
Tech Certification #:

Project/Test Address: 2320; Seth Boyden Elementary; 274 Boyden Ave; South Orange, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-04105-001	1	12/15/2024	HALL BY G6	<1.00	12/26/2024	
24-12-04105-002	2	12/15/2024	ROOM G2	13.6	12/30/2024	
24-12-04105-003	3	12/15/2024	ROOM G1	<1.00	12/26/2024	
24-12-04105-004	4	12/15/2024	HALL BY G12	1.39	12/26/2024	
24-12-04105-005	5	12/15/2024	HALL BY G12	2.31	12/26/2024	
24-12-04105-006	6	12/15/2024	HALL BY G14	<1.00	12/26/2024	
24-12-04105-007	7	12/15/2024	HALL BY G14	<1.00	12/26/2024	
24-12-04105-008	8	12/15/2024	CAFETERIA	<1.00	12/26/2024	
24-12-04105-009	9	12/15/2024	CAFETERIA	<1.00	12/26/2024	
24-12-04105-010	9A	12/15/2024	CAFETERIA	1.40	12/26/2024	
24-12-04105-011	10	12/15/2024	HALL BY 102	4.53	12/26/2024	
24-12-04105-012	11	12/15/2024	OFFICE FOYER LEFT	8.37	12/26/2024	
24-12-04105-013	12	12/15/2024	OFFICE FOYER RIGHT	10.5	12/26/2024	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 24-12-04105

Project/Test Address: 2320; Seth Boyden Elementary; 274 Boyden Ave; South Orange, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-04105-014	13	12/15/2024	SB-S-1FL-ND	3.61	12/26/2024	
24-12-04105-015	14	12/15/2024	HALL BY 105 LEFT	2.64	12/26/2024	
24-12-04105-016	15	12/15/2024	HALL BY 105 RIGHT	3.17	12/26/2024	
24-12-04105-017	19	12/15/2024	HALL BY 206 LEFT	3.32	12/26/2024	
24-12-04105-018	20	12/15/2024	HALL BY 206 RIGHT	5.12	12/26/2024	
24-12-04105-019	21	12/15/2024	ROOM GIG	1.58	12/26/2024	
24-12-04105-020	22	12/15/2024	ROOM GIF	<1.00	12/26/2024	
24-12-04105-021	23	12/15/2024	HALL BY STORAGE GIE	<1.00	12/26/2024	
24-12-04105-022	24	12/15/2024	HALL BY STORAGE GIE	<1.00	12/26/2024	
24-12-04105-023	25	12/15/2024	HALL BY STORAGE GIE	<1.00	12/26/2024	
24-12-04105-024	26	12/15/2024	HALL BY RM 100E	<1.00	12/26/2024	
24-12-04105-025	27	12/15/2024	HALL BY RM 100E	<1.00	12/26/2024	
24-12-04105-026	28	12/15/2024	HALL BY RM 100E	<1.00	12/26/2024	
24-12-04105-027	29	12/15/2024	ROOM SR	<1.00	12/26/2024	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 24-12-04105

Project/Test Address: 2320; Seth Boyden Elementary; 274 Boyden Ave; South Orange, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

24-12-04105

Due Date:
12/30/2024
(Monday)
AE

Client Name: LEW Environmental services Account #: 201327

Address: 181 US HWY 46

City/State/Zip: Mine Hill NJ 07803 Phone: 908-654-8069

Email Address: labresults@lewenvironmental.com

Project Name/ Number: Seth Boyden Elementary / 2320

Collection Address: 274 Boyden Ave City/State/Zip: South Orange NJ
(Required) (Required)

Approx. Age Of Property: _____ Collected By: Marvin Ayumbi

Water Source: (Check One) Public X or Well _____ Well Tag # (if applicable): _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	1	Hall by G6	12/15/24	AM / PM	✓	
2	2	Room G2		AM / PM	✓	
3	3	Room G1		AM / PM	✓	
4	4	Hall by G12		AM / PM	✓	
5	5	Hall by G12		AM / PM	✓	
6	6	Hall by G14		AM / PM	✓	
7	7	Hall by G14		AM / PM	✓	
8	8	Cafeteria		AM / PM	✓	
9	9	Cafeteria		AM / PM	✓	
10	9A	Cafeteria		AM / PM	✓	
11	10	Hall by 102		AM / PM	✓	
12	11	Office Foyer Left		AM / PM	✓	
13	12	Office Foyer Right	SAMPLE 13 - SB - S-1FL - NO	AM / PM	✓	
14	13 14	Hall by 105 Left		AM / PM	✓	
15	15	Hall by 105 Right	12/15/24	AM / PM	✓	
16						

Released by: Marvin Ayumbi Signature: [signature] Date/Time: 12/17/24

Received by: KTHARRIS Signature: K Harris Date/Time: 12.20.24 11:11AM

Client Name: _____ Account #_____ Page 2 of 2

Project Name: _____

Lab I.D. #: _____-4105-_____

	No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
						Pb	Cu
17	16	19	Hall by 206 Left	12/15/24	AM / PM	✓	
18	17	20	Hall by 206 Right		AM / PM	✓	
19	18	21	Room G1G		AM / PM	✓	
20	19	22	Room G1F		AM / PM	✓	
21	20	23	Hall by Storage G1E		AM / PM	✓	
22	21	24	Hall by Storage G1E		AM / PM	✓	
23	22	25	Hall by storage G1E		AM / PM	✓	
24	23	26	Hall by Rm 100E		AM / PM	✓	
25	24	27	Hall by Rm 100E		AM / PM	✓	
26	25	28	Hall by Rm 100E		AM / PM	✓	
27	26	29	Room SR	12/15/24	AM / PM	✓	
	27				AM / PM		
	28				AM / PM		
	29				AM / PM		
	30				AM / PM		
	31				AM / PM		
	32				AM / PM		
	33				AM / PM		
	34				AM / PM		
	35				AM / PM		
	36				AM / PM		
	37				AM / PM		
	38				AM / PM		
	39				AM / PM		
	40				AM / PM		
	41				AM / PM		
	42				AM / PM		
	43				AM / PM		
	44				AM / PM		
	45				AM / PM		
	46				AM / PM		
	47				AM / PM		
	48				AM / PM		
	49				AM / PM		
	50				AM / PM		

Released by:		Signature:	Date/Time:
Received by:	RT HARRIS	Signature: R Harris	Date/Time: 12.20.24 11:11AM

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 24-12-04158

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 12/20/2024
Reported Date: 12/30/2024
Sampled By: Marvin Ayumbi
Tech Certification #:

Project/Test Address: 2320; Underhill Field; Garfield Place; South Orange, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-04158-001	1	12/15/2024	OLD FIELD HOUSE	<1.00	12/27/2024	
24-12-04158-002	2	12/15/2024	NEW FIELD HOUSE	<1.00	12/30/2024	
24-12-04158-003	3	12/15/2024	BOYS LOCKER	2.03	12/27/2024	
24-12-04158-004	4	12/15/2024	BOYS SHOWER	3.14	12/27/2024	
24-12-04158-005	7	12/15/2024	CONCESSION STAND	2.17	12/27/2024	
24-12-04158-006	8	12/15/2024	TRAINERS ROOM	260	12/27/2024	
24-12-04158-007	9	12/15/2024	CUSTIDIAL OFFICE	6.39	12/27/2024	
24-12-04158-008	10	12/15/2024	ROOM SR	<1.00	12/27/2024	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 24-12-04158

Project/Test Address: 2320; Underhill Field; Garfield Place; South Orange, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

24-12-04158

Due Date:
12/30/2024
(Monday)
AE

Client Name: LEW Environmental Services Account #: 20132-7

Address: 181 US HWY 46

City/State/Zip: Mine Hill NJ 07803 Phone: 973-654-8069

Email Address: labresults@lewenvironmental.com

Project Name/ Number: Underhill Field / 2320

Collection Address: Garfield Place (Required) City/State/Zip: South Orange NJ (Required)

Approx. Age Of Property: _____ Collected By: Marvin Ayumbi

Water Source: (Check One) Public X or Well _____ Well Tag # (if applicable): _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	1	Old Field House	12/15/24	AM / PM	✓	
2	2	New Field House		AM / PM	✓	
3	3	Boys Locker		AM / PM	✓	
4	4	Boys Shower		AM / PM	✓	
5	7	Concession stand		AM / PM	✓	
6	8	Trainer's Room		AM / PM	✓	
7	9	Custodial Office		AM / PM	✓	
8	10	Room SR	12/15/24	AM / PM	✓	
9				AM / PM		
10				AM / PM		
11				AM / PM		
12				AM / PM		
13				AM / PM		
14				AM / PM		
15				AM / PM		

Released by: Marvin Ayumbi Signature: [signature] Date/Time: 12/16/24

Received by: KT HARRIS Signature: K Harris Date/Time: 12.20.24

12:21 pm

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 24-12-04164

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 12/20/2024
Reported Date: 12/30/2024
Sampled By: Marvin Ayumbi
Tech Certification #:

Project/Test Address: 2320; Marshall Elementary; 262 Grove Road; South Orange, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-04164-001	1	12/15/2024	ROOM 120	2.78	12/27/2024	
24-12-04164-002	2	12/15/2024	HALL BY 121	1.86	12/27/2024	
24-12-04164-003	3	12/15/2024	ROOM 121	5.37	12/27/2024	
24-12-04164-004	3A	12/15/2024	ROOM 121	5.31	12/27/2024	
24-12-04164-005	4	12/15/2024	ROOM 119	2.48	12/27/2024	
24-12-04164-006	5	12/15/2024	ROOM 122	<1.00	12/27/2024	
24-12-04164-007	6	12/15/2024	HALL BY 122	<1.00	12/27/2024	
24-12-04164-008	8	12/15/2024	ROOM 125	1.84	12/27/2024	
24-12-04164-009	9	12/15/2024	ROOM 126	<1.00	12/27/2024	
24-12-04164-010	10A	12/15/2024	ROOM 127	1.84	12/27/2024	
24-12-04164-011	11	12/15/2024	ROOM 128	3.96	12/27/2024	
24-12-04164-012	12	12/15/2024	CAFETERIA	<1.00	12/27/2024	
24-12-04164-013	12A	12/15/2024	CAFETERIA	<1.00	12/27/2024	

Client Number: 201327 Report Number: 24-12-04164

Project/Test Address: 2320; Marshall Elementary; 262 Grove Road; South Orange, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-04164-014	14	12/15/2024	HALL BY BATH RMS	1.75	12/27/2024	
24-12-04164-015	15	12/15/2024	TEACHERS LOUNGE	<1.00	12/27/2024	
24-12-04164-016	16	12/15/2024	NURSES BATH	8.04	12/27/2024	
24-12-04164-017	17	12/15/2024	ROOM 101	<1.00	12/27/2024	
24-12-04164-018	18	12/15/2024	ROOM 107	<1.00	12/27/2024	
24-12-04164-019	19	12/15/2024	ROOM 143	6.68	12/27/2024	
24-12-04164-020	20	12/15/2024	HALL BY 203	<1.00	12/27/2024	
24-12-04164-021	21	12/15/2024	ROOM 213	<1.00	12/27/2024	
24-12-04164-022	22	12/15/2024	ROOM 209	2.79	12/27/2024	
24-12-04164-023	23	12/15/2024	ROOM 210	6.88	12/30/2024	
24-12-04164-024	24	12/15/2024	ROOM 211	2.40	12/27/2024	
24-12-04164-025	25	12/15/2024	HALL BY STORAGE 167	<1.00	12/27/2024	
24-12-04164-026	26	12/15/2024	HALL BY STORAGE 167	<1.00	12/27/2024	
24-12-04164-027	27	12/15/2024	HALL BY STORAGE 167	<1.00	12/27/2024	
24-12-04164-028	28	12/15/2024	ROOM 162	6.30	12/30/2024	
24-12-04164-029	29	12/15/2024	ROOM 164	<1.00	12/27/2024	
24-12-04164-030	30	12/15/2024	HALL BY STORAGE 231	<1.00	12/27/2024	
24-12-04164-031	31	12/15/2024	HALL BY STORAGE 231	<1.00	12/27/2024	
24-12-04164-032	32	12/15/2024	HALL BY STORAGE 231	<1.00	12/27/2024	
24-12-04164-033	33	12/15/2024	ROOM 224	<1.00	12/27/2024	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 24-12-04164

Project/Test Address: 2320; Marshall Elementary; 262 Grove Road; South Orange, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
24-12-04164-034	34	12/15/2024	ROOM 226	<1.00	12/27/2024	
24-12-04164-035	35	12/15/2024	ROOM SR	<1.00	12/27/2024	

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

24-12-04164

Due Date:
12/30/2024
(Monday)
AE

Client Name: LEW Environmental Services Account #: 201327

Address: 181 US HWY 46

City/State/Zip: Mine Hill NJ 07803 Phone: 908-654-8069

Email Address: labresults@lewenvironmental.com

Project Name/ Number: Marshall Elementary / 2320

Collection Address: 262 Grove Road City/State/Zip: South Orange NJ
(Required) (Required)

Approx. Age Of Property: _____ Collected By: Marvin Ayumbi

Water Source: (Check One) Public X or Well _____ Well Tag # (if applicable): _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	1	Room 120	12/15/24	AM / PM	✓	
2	2	Hall by 121		AM / PM	✓	
3	3	Room 121		AM / PM	✓	
4	3A	Room 121		AM / PM	✓	
5	4	Room 119		AM / PM	✓	
6	5	Room 122		AM / PM	✓	
7	6	Hall by 122		AM / PM	✓	
8	8	Room 125		AM / PM	✓	
9	9	Room 126		AM / PM	✓	
10	10A	Room 127		AM / PM	✓	
11	11	Room 128		AM / PM	✓	
12	12	Cafeteria		AM / PM	✓	
13	12A	Cafeteria		AM / PM	✓	
14	14	Hall by Bath Rms		AM / PM	✓	
15	15	Teachers' Lounge	12/15/24	AM / PM	✓	

Released by: Marvin Ayumbi Signature: [signature] Date/Time: 12/17/24

Received by: KTHARRIS Signature: [signature] Date/Time: 12.20.24 @ 12:27 pm

Client Name: _____ Account #_____ Page 2 of 2

Project Name: _____

Lab I.D. #: ____-____-4164

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
16	16	Nurse's Bath	12/15/24	AM / PM	✓	
17	17	Room 101		AM / PM	✓	
18	18	Room 107		AM / PM	✓	
19	19	Room 143		AM / PM	✓	
20	20	Hall by 203		AM / PM	✓	
21	21	Room 213		AM / PM	✓	
22	22	Room 209		AM / PM	✓	
23	23	Room 210		AM / PM	✓	
24	24	Room 211		AM / PM	✓	
25	25	Hall by Storage 167		AM / PM	✓	
26	26	Hall by Storage 167		AM / PM	✓	
27	27	Hall by Storage 167		AM / PM	✓	
28	28	Room 162		AM / PM	✓	
29	29	Room 164		AM / PM	✓	
30	30	Hall by Storage 231		AM / PM	✓	
31	31	Hall by Storage 231		AM / PM	✓	
32	32	Hall by Storage 231		AM / PM	✓	
33	33	Room 224		AM / PM	✓	
34	34	Room 226		AM / PM	✓	
35	35	Room SR	12/15/24	AM / PM	✓	
36				AM / PM		
37				AM / PM		
38				AM / PM		
39				AM / PM		
40				AM / PM		
41				AM / PM		
42				AM / PM		
43				AM / PM		
44				AM / PM		
45				AM / PM		
46				AM / PM		
47				AM / PM		
48				AM / PM		
49				AM / PM		
50				AM / PM		

Released by:	Signature:	Date/Time:
Received by: KT HARRIS	Signature: K Harris	Date/Time: 12·20·24 12:27 PM

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 25-01-05025

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 01/29/2025
Reported Date: 02/05/2025
Sampled By: Erick Ulloa
Tech Certification #:

Project/Test Address: 2320; 25 Harvard Ave; Maplewood, NJ 07040

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-01-05025-001	TE-WC-BFL-G16	01/27/2025	HALL BY G16 BUBBLER	<1.00	02/01/2025	
25-01-05025-002	TE-BF-BFL-G16	01/27/2025	HALL BY G16 BOTTLE FILLER	<1.00	02/01/2025	
25-01-05025-003	TE-WC-BFL-G24-1	01/27/2025	HALL BY G24 BUBBLER	<1.00	02/05/2025	
25-01-05025-004	TE-BF-BFL-G24-2	01/27/2025	HALL BY G24 BOTTLE FILLER	<1.00	02/05/2025	
25-01-05025-005	TE-WC-1FL-108	01/27/2025	HALL BY 108 BUBBLER	1.73	02/01/2025	
25-01-05025-006	TE-WC-1FL-132-1	01/27/2025	HALL BY 132 BUBBLER	<1.00	02/01/2025	
25-01-05025-007	TE-WC-1FL-117-1	01/27/2025	HALL BY 117 BUBBLER	<1.00	02/01/2025	
25-01-05025-008	TE-WC-1FL-117-2	01/27/2025	HALL BY 117 BUBBLER	<1.00	02/01/2025	
25-01-05025-009	TE-S-1FL-NO	01/27/2025	NURSE OFFICE SINK	2.66	02/01/2025	
25-01-05025-010	TE-WC-1FL-125-1	01/27/2025	HALL BY 125 BUBBLER	<1.00	02/01/2025	
25-01-05025-011	TE-WC-1FL-125-2	01/27/2025	HALL BY 125 BUBBLER	1.14	02/01/2025	
25-01-05025-012	TE-S-FL-1FL-120	01/27/2025	ROOM 120 SINK	2.60	02/01/2025	
25-01-05025-013	TE-S-1FL-122	01/27/2025	ROOM 122 SINK	4.33	02/01/2025	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 25-01-05025

Project/Test Address: 2320; 25 Harvard Ave; Maplewood, NJ 07040

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-01-05025-014	TE-DW-1FL-123	01/27/2025	ROOM 123 BUBBLER	<1.00	02/01/2025	
25-01-05025-015	TE-WC-2FL-202	01/27/2025	HALL BY 202 BUBBLER	1.60	02/01/2025	
25-01-05025-016	TE-SR	01/27/2025	SUNROOM	<1.00	02/01/2025	

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

25-01-05025

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

Due Date:
02/05/2025
(Wednesday)
AE

10+

Client Name: LEW CORP Account #: 201327

Address: 181 US HIGHWAY 46

City/State/Zip: MINE HILL, NJ 07803 Phone: 908-654-8068

Email Address: labresults@lewcorp.com

Project Name/ Number : 2320

Collection Address: 25 HARVARD AVE **City/State/Zip:** MAPLEWOOD, NJ 07040
(Required) (Required)

Approx. Age Of Property: _____ **Collected By:** ERICK ULLOA

Water Source: (Check One) **Public** X **or Well** _____ **Well Tag # (if applicable):** _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	TE-WC-BFL-G16	HALL BY G16, BUBBLER	01-27-2025	AM / PM	X	
2	TE-BF-BFL-G16	HALL BY G16, BOTTLE FILLER		AM / PM	X	
3	TE-WC-BFL-G24-1	HALL BY G24, BUBBLER		AM / PM	X	
4	TE-BF-BFL-G24-2	HALL BY G24, BOTTLE FILLER		AM / PM	X	
5	TE-WC-1FL-108	HALL BY 108, BUBBLER		AM / PM	X	
6	TE-WC-1FL-132-1	HALL BY 132, BUBBLER		AM / PM	X	
7	TE-WC-1FL-117-1	HALL BY 117, BUBBLER		AM / PM	X	
8	TE-WC-1FL-117-2	HALL BY 117, BUBBLER		AM / PM	X	
9	TE-S-1FL-NO	NURSE OFFICE, SINK		AM / PM	X	
10	TE-WC-1FL-125-1	HALL BY 125, BUBBLER		AM / PM	X	
11	TE-WC-1FL-125-2	HALL BY 125, BUBBLER		AM / PM	X	
12	TE-S-FL-1FL-120	ROOM 120, SINK		AM / PM	X	
13	TE-S-1FL-122	ROOM 122, SINK		AM / PM	X	
14	TE-DW-1FL-123	ROOM 123, BUBBLER		AM / PM	X	
15	TE-WC-2FL-202	HALL BY 202, BUBBLER		AM / PM	X	

Released by: ERICK ULLOA	Signature:	Date/Time: 01-27-2025
Received by: CHRISTMAS	Signature:	Date/Time: 1/29/25 11:31

Client Name: LEW CORP Account #201327 Page 2 of 2

Project Name: 2320

Lab I.D. #: 5025-___-___

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
51	TE-SR	SUNROOM	01-27-2025	AM / PM	X	
52				AM / PM	X	
53				AM / PM	X	
54				AM / PM	X	
55				AM / PM	X	
56				AM / PM	X	
57				AM / PM	X	
58				AM / PM	X	
59				AM / PM	X	
60				AM / PM	X	
61				AM / PM	X	
62				AM / PM	X	
63				AM / PM	X	
64				AM / PM	X	
65				AM / PM	X	
66				AM / PM	X	
67				AM / PM	X	
68				AM / PM	X	
69				AM / PM	X	
70				AM / PM	X	
71				AM / PM	X	
72				AM / PM	X	
73				AM / PM	X	
74				AM / PM	X	
75				AM / PM	X	
76				AM / PM	X	
77				AM / PM		
78				AM / PM		
79				AM / PM		
80				AM / PM		
81				AM / PM		
82				AM / PM		
83				AM / PM		
84				AM / PM		
85				AM / PM		

Released by: ERICK ULLOA	Signature:	Date/Time: 01-27-2025
Received by:	Signature:	Date/Time: 1/29/25 1131

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 25-01-05027

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 01/29/2025
Reported Date: 02/05/2025
Sampled By: Erick Ulloa
Tech Certification #:

Project/Test Address: 2320; 7 Burnet St; Maplewood, NJ 07040

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-01-05027-001	MM-WC-BFL-S02	01/27/2025	HALL BY S12 BUBBLER	<1.00	02/03/2025	
25-01-05027-002	MM-S-BFL-TL	01/27/2025	TEACHERS LOUNGE SINK	1.48	02/03/2025	
25-01-05027-003	MM-WC-1FL-138	01/27/2025	HALL BY 138 BUBBLER	<1.00	02/03/2025	
25-01-05027-004	MM-S-1FL-NO	01/27/2025	NURSE OFFICE SINK	1.09	02/03/2025	
25-01-05027-005	MM-S-1FL-NB	01/27/2025	NURSE BATHROOM SINK	3.11	02/03/2025	
25-01-05027-006	MM-WC-1FL-153	01/27/2025	HALL BY 153 BUBBLER	<1.00	02/03/2025	
25-01-05027-007	MM-BF-1FL-153	01/27/2025	HALL BY 153 BOTTLE FILLER	<1.00	02/03/2025	
25-01-05027-008	MM-WC-1FL-HGL	01/27/2025	HALL BY GIRLS LOCKER BUBBLER	<1.00	02/03/2025	
25-01-05027-009	MM-BF-1FL-HGL	01/27/2025	HALL BY GIRLS LOCKER BOTTLE FILLER	<1.00	02/03/2025	
25-01-05027-010	MM-DW-1FL-GL-1	01/27/2025	GIRLS LOCKER RM BUBBLER	<1.00	02/03/2025	
25-01-05027-011	MM-DW-1FL-HBL	01/27/2025	HALL BY BOYS LOCKER RM BUBBLER	7.46	02/03/2025	
25-01-05027-012	MM-DW-1FL-BL-1	01/27/2025	BOYS LOCKER RM BUBBLER	<1.00	02/03/2025	
25-01-05027-013	MM-FP-1FL-K-1	01/27/2025	KITCHEN STEAMER	10.0	02/03/2025	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 25-01-05027

Project/Test Address: 2320; 7 Burnet St; Maplewood, NJ 07040

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-01-05027-014	MM-FP-1FL-K-2	01/27/2025	KITCHEN SINK	2.06	02/03/2025	
25-01-05027-015	MM-FP-1FL-K-3	01/27/2025	KITCHEN ICE MACHINE	<1.00	02/05/2025	
25-01-05027-016	MM-WC-2FL-290	01/27/2025	HALL BY RM 290 BUBBLER	<1.00	02/03/2025	
25-01-05027-017	MM-WC-2FL-286	01/27/2025	HALL BY RM 286 BUBBLER	<1.00	02/03/2025	
25-01-05027-018	MM-DW-1FL-162	01/27/2025	HALL BY 162 BUBBLER	4.45	02/03/2025	
25-01-05027-019	MM-DW-2FL-S22	01/27/2025	HALL BY S22 BUBBLER	1.09	02/03/2025	
25-01-05027-020	MM-SR	01/27/2025	SUNROOM	<1.00	02/03/2025	

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

25-01-05027

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

Due Date:
02/05/2025
(Wednesday)
AE

Client Name: LEW CORP Account #: 201327

Address: 181 US HIGHWAY 46 107

City/State/Zip: MINE HILL, NJ 07803 Phone: 908-654-8068

Email Address: labresults@lewcorp.com

Project Name/ Number : 2320

Collection Address: 7 BURNET ST (Required) **City/State/Zip:** MAPLEWOOD, NJ 07040 (Required)

Approx. Age Of Property: _____ **Collected By:** ERICK ULLOA

Water Source: (Check One) **Public** X **or Well** _____ **Well Tag # (if applicable):** _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	MM-WC-BFL-S02	HALL BY S12, BUBBLER	01-27-2025	AM / PM	X	
2	MM-S-BFL-TL	TEACHERS LOUNGE, SINK		AM / PM	X	
3	MM-WC-1FL-138	HALL BY 138, BUBBLER		AM / PM	X	
4	MM-S-1FL-NO	NURSE OFFICE, SINK		AM / PM	X	
5	MM-S-1FL-NB	NURSE BATHROOM, SINK		AM / PM	X	
6	MM-WC-1FL-153	HALL BY 153, BUBBLER		AM / PM	X	
7	MM-BF-1FL-153	HALL BY 153, BOTTLE FILLER		AM / PM	X	
8	MM-WC-1FL-HGL	HALL BY GIRLS LOCKER, BUBBLER		AM / PM	X	
9	MM-BF-1FL-HGL	HALL BY GIRLS LOCKER, BOTTLE FILLER		AM / PM	X	
10	MM-DW-1FL-GL-1	GIRLS LOCKER RM, BUBBLER		AM / PM	X	
11	MM-DW-1FL-HBL	HALL BY BOYS LOCKER RM, BUBBLER		AM / PM	X	
12	MM-DW-1FL-BL-1	BOYS LOCKER RM, BUBBLER		AM / PM	X	
13	MM-FP-1FL-K-1	KITCHEN, STEAMER		AM / PM	X	
14	MM-FP-1FL-K-2	KITCHEN, SINK		AM / PM	X	
15	MM-FP-1FL-K-3	KITCHEN, ICE MACHINE		AM / PM	X	

Released by: ERICK ULLOA Signature: _____ Date/Time: 01-27-2025

Received by: EC CHRISTMAS Signature: _____ Date/Time: 1/29/25 1132am

Client Name: LEW CORP Account #201327 Page 2 of 2

Project Name: 2320

Lab I.D. #: 05027

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
51	MM-WC-2FL-290	HALL BY RM 290, BUBBLER	01-27-2025	AM / PM	X	
52	MM-WC-2FL-286	HALL BY RM 286, BUBBLER		AM / PM	X	
53	MM-DW-1FL-162	HALL BY 162, BUBBLER		AM / PM	X	
54	MM-DW-2FL-S22	HALL BY S22, BUBBLER		AM / PM	X	
55	MM-SR	SUNROOM		AM / PM	X	
56				AM / PM	X	
57				AM / PM	X	
58				AM / PM	X	
59				AM / PM	X	
60				AM / PM	X	
61				AM / PM	X	
62				AM / PM	X	
63				AM / PM	X	
64				AM / PM	X	
65				AM / PM	X	
66				AM / PM	X	
67				AM / PM	X	
68				AM / PM	X	
69				AM / PM	X	
70				AM / PM	X	
71				AM / PM	X	
72				AM / PM	X	
73				AM / PM	X	
74				AM / PM	X	
75				AM / PM	X	
76				AM / PM	X	
77				AM / PM		
78				AM / PM		
79				AM / PM		
80				AM / PM		
81				AM / PM		
82				AM / PM		
83				AM / PM		
84				AM / PM		
85				AM / PM		

Released by: ERICK ULLOA	Signature:	Date/Time: 01-27-2025
Received by: CHRISTMAS	Signature:	Date/Time: 1/29/25 1132AM

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 25-01-05030

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 01/29/2025
Reported Date: 02/05/2025
Sampled By: Erick Ulloa
Tech Certification #:

Project/Test Address: 2320; 17 Parker Ave; Maplewood, NJ 07040

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-01-05030-001	HS-S-1FL-NO	01/27/2025	NURSE OFFICE SINK	<1.00	02/03/2025	
25-01-05030-002	HS-S-1FL-NB	01/27/2025	NURSE BATHROOM SINK	1.38	02/03/2025	
25-01-05030-003	HS-S-1FL-SB	01/27/2025	STAFF BATHROOM C106 SINK	2.81	02/03/2025	
25-01-05030-004	HS-WC-1FL-109-1	01/27/2025	HALL BY C109 BUBBLER	1.59	02/03/2025	
25-01-05030-005	HS-WC-1FL-109-2	01/27/2025	HALL BY C109 BUBBLER	2.05	02/03/2025	
25-01-05030-006	HS-WC-1FL-134-1	01/27/2025	HALL BY B134 BUBBLER	<1.00	02/03/2025	
25-01-05030-007	HS-DW-1FL-114-1	01/27/2025	HALL BY B114 BUBBLER	8.97	02/03/2025	
25-01-05030-008	HS-DW-1FL-114-2	01/27/2025	HALL BY B114 BUBBLER	4.03	02/03/2025	
25-01-05030-009	HS-DW-1FL-105-1	01/27/2025	HALL BY D105 BUBBLER	<1.00	02/03/2025	
25-01-05030-010	HS-DW-1FL-105-2	01/27/2025	HALL BY D105 BOTTLE FILLER	<1.00	02/03/2025	
25-01-05030-011	HS-WC-1FL-129	01/27/2025	HALL BY A129 BUBBLER	<1.00	02/03/2025	
25-01-05030-012	HS-S-GFL-KIT-1	01/27/2025	KITCHEN SINK	<1.00	02/03/2025	
25-01-05030-013	HS-S-GFL-KIT-2	01/27/2025	KITCHEN KETTLE SINK	<1.00	02/03/2025	

Client Number: 201327 Report Number: 25-01-05030

Project/Test Address: 2320; 17 Parker Ave; Maplewood, NJ 07040

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-01-05030-014	HS-IM-GFL-KIT	01/27/2025	KITCHEN ICE MACHINE	<1.00	02/03/2025	
25-01-05030-015	HS-WC-GFL-CAF	01/27/2025	CAFETERIA WATER COOLER	<1.00	02/03/2025	
25-01-05030-016	HS-BF-GFL-CAF	01/27/2025	CAFETERIA BOTTLE FILLER	<1.00	02/03/2025	
25-01-05030-017	HS-WC-GFL-BB-1	01/27/2025	HALL BY BLACK BOX BUBBLER	1.88	02/03/2025	
25-01-05030-018	HS-WC-GFL-BB-2	01/27/2025	HALL BY BLACK BOX BUBBLER	2.58	02/03/2025	
25-01-05030-019	HW-DW-2FL-203-1	01/27/2025	HALL BY D203 BUBBLER	<1.00	02/03/2025	
25-01-05030-020	HS-BF-2FL-203-2	01/27/2025	HALL BY D203 BOTTLE FILLER	<1.00	02/03/2025	
25-01-05030-021	HS-WC-2FL-FL	01/27/2025	FACULTY LOUNGE BUBBLER	<1.00	02/03/2025	
25-01-05030-022	HS-S-2FL-FL	01/27/2025	FACULTY LOUNGE SINK	2.16	02/03/2025	
25-01-05030-023	HS-WC-2FL-207	01/27/2025	HALL BY B207 BUBBLER	<1.00	02/03/2025	
25-01-05030-024	HS-BF-2FL-207	01/27/2025	HALL BY B207 BOTTLE FILLER	<1.00	02/03/2025	
25-01-05030-025	HS-DW-2FL-230-1	01/27/2025	HALL BY B230 BUBBLER	<1.00	02/03/2025	
25-01-05030-026	HS-DW-2FL-230-2	01/27/2025	HALL BY B230 BOTTLE FILLER	<1.00	02/03/2025	
25-01-05030-027	HS-WC-2FL-207-1	01/27/2025	HALL BY C207 BUBBLER	<1.00	02/03/2025	
25-01-05030-028	HS-WC-2FL-207-2	01/27/2025	HALL BY C207 BUBBLER	<1.00	02/03/2025	
25-01-05030-029	HS-2FL-BF-207-2	01/27/2025	HALL BY C207 BOTTLE FILLER	<1.00	02/03/2025	
25-01-05030-030	HS-WC-2FL-229-1	01/27/2025	HALL BY C229 BUBBLER	<1.00	02/03/2025	
25-01-05030-031	HS-BF-2FL-229-2	01/27/2025	HALL BY C229 BOTTLE FILLER	<1.00	02/03/2025	
25-01-05030-032	HS-WC-3FL-BB	01/27/2025	HALL BY BOYS BATHROOM BUBBLER	<1.00	02/03/2025	
25-01-05030-033	HS-BF-3FL-BB	01/27/2025	HALL BY BOYS BATHROOM BOTTLE FILLER	<1.00	02/03/2025	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 25-01-05030

Project/Test Address: 2320; 17 Parker Ave; Maplewood, NJ 07040

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-01-05030-034	HS-DW-3FL-301-1	01/27/2025	HALL BY D301 BUBBLER	1.37	02/03/2025	
25-01-05030-035	HS-DW-3FL-301-2	01/27/2025	HALL BY D301 BUBBLER	7.65	02/03/2025	
25-01-05030-036	HS-DW-3FL-338-1	01/27/2025	HALL BY B338 BUBBLER	<1.00	02/03/2025	
25-01-05030-037	HS-DW-3FL-328-1	01/27/2025	HALL BY B328 BOTTLE FILLER	<1.00	02/03/2025	
25-01-05030-038	HS-DW-3FL-328-2	01/27/2025	HALL BY 328 BOTTLE FILLER	<1.00	02/03/2025	
25-01-05030-039	HS-DW-1FL-128-IM	01/27/2025	ROOM C128 ICE MACHINE	<1.00	02/05/2025	
25-01-05030-040	HS-DW-1FL-128	01/27/2025	ROO C128 SINK	1.60	02/03/2025	
25-01-05030-041	HS-SR	01/27/2025	SUNROOM	<1.00	02/03/2025	

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

25-01-05030

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Due Date:
02/05/2025
(Wednesday)
AE

Client Name: LEW CORP Account #: 201327

Address: 181 US HIGHWAY 46 10f

City/State/Zip: MINE HILL, NJ 07803 Phone: 908-654-8068

Email Address: labresults@lewcorp.com

Project Name/ Number : 2320

Collection Address: 17 PARKER AVE (Required) City/State/Zip: MAPLEWOOD, NJ 07040 (Required)

Approx. Age Of Property: _____ Collected By: ERICK ULLOA

Water Source: (Check One) Public X or Well _____ Well Tag # (if applicable): _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	HS-S-1FL-NO	NURSE OFFICE, SINK	01-27-2025	AM / PM	X	
2	HS-S-1FL-NB	NURSE BATHROOM, SINK		AM / PM	X	
3	HS-S-1FL-SB	STAFF BATHROOM C106, SINK		AM / PM	X	
4	HS-WC-1FL-109-1	HALL BY C109, BUBBLER		AM / PM	X	
5	HS-WC-1FL-109-2	HALL BY C109, BUBBLER		AM / PM	X	
6	HS-WC-1FL-134-1	HALL BY B134, BUBBLER		AM / PM	X	
7	HS-DW-1FL-114-1	HALL BY B114, BUBBLER		AM / PM	X	
8	HS-DW-1FL-114-2	HALL BY B114, BUBBLER		AM / PM	X	
9	HS-DW-1FL-105-1	HALL BY D105, BUBBLER		AM / PM	X	
10	HS-DW-1FL-105-2	HALL BY D105, BOTTLE FILLER		AM / PM	X	
11	HS-WC-1FL-129	HALL BY A129, BUBBLER		AM / PM	X	
12	HS-S-GFL-KIT-1	KITCHEN, SINK		AM / PM	X	
13	HS-S-GFL-KIT-2	KITCHEN KETTLE, SINK		AM / PM	X	
14	HS-IM-GFL-KIT	KITCHEN, ICE MACHINE		AM / PM	X	
15	HS-WC-GFL-CAF	CAFETERIA, WATER COOLER		AM / PM	X	

Released by: ERICK ULLOA	Signature:	Date/Time: 01-27-2025
Received by: ECHRISTMAS	Signature:	Date/Time: 1/29/25 1136am

Client Name: LEW CORP Account #201327 Page 2 of 2

Project Name: 2320

Lab I.D. #: 05030

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
51	HS-BF-GFL-CAF	CAFETERIA, BOTTLE FILLER		AM / PM	X	
52	HS-WC-GFL-BB-1	HALL BY BLACK BOX, BUBBLER		AM / PM	X	
53	HS-WC-GFL-BB-2	HALL BY BLACK BOX, BUBBLER		AM / PM	X	
54	HS-DW-2FL-203-1	HALL BY D203, BUBBLER		AM / PM	X	
55	HS-BF-2FL-203-2	HALL BY D203, BOTTLE FILLER		AM / PM	X	
56	HS-WC-2FL-FL	FACULTY LOUNGE, BUBBLER		AM / PM	X	
57	HS-S-2FL-FL	FACULTY LOUNGE, SINK		AM / PM	X	
58	HS-WC-2FL-207	HALL BY B207, BUBBLER		AM / PM	X	
59	HS-BF-2FL-207	HALL BY B207, BOTTLE FILLER		AM / PM	X	
60	HS-DW-2FL-230-1	HALL BY B230, BUBBLER		AM / PM	X	
61	HS-DW-2FL-230-2	HALL BY B230, BOTTLE FILELR		AM / PM	X	
62	HS-WC-2FL-207-1	HALL BY C207, BUBBLER		AM / PM	X	
63	HS-WC-2FL-207-2	HALL BY C207, BUBBLER		AM / PM	X	
64	HS-2FL-BF-207-2	HALL BY C207, BOTTLE FILLER		AM / PM	X	
65	HS-WC-2FL-229-1	HALL BY C229, BUBBLER		AM / PM	X	
66	HS-BF-2FL-229-2	HALL BY C229, BOTTLE FILLER		AM / PM	X	
67	HS-WC-3FL-BB	HALL BY BOYS BATHROOM, BUBBLER		AM / PM	X	
68	HS-BF-3FL-BB	HALL BY BOYS BATHROOM, BOTTLE FILELR		AM / PM	X	
69	HS-DW-3FL-301-1	HALL BY D301, BUBBLER		AM / PM	X	
70	HS-DW-3FL-301-2	HALL BY D301, BUBBLER		AM / PM	X	
71	HS-DW-3FL-338-1	HALL BY B338, BUBBLER		AM / PM	X	
72	HS-BF-3FL-328-1	HALL BY B328, Bottle Filler		AM / PM	X	
73	HS-DW-3FL-328-2	HALL BY 328, BOTTLE FILLER		AM / PM	X	
74	HS-DW-1FL-128-IM	ROOM C128, ICE MACHINE		AM / PM	X	
75	HS-DW-1FL-128	ROOM C128, SINK		AM / PM	X	
76	HS-SR	SUNROOM		AM / PM	X	
77				AM / PM		
78				AM / PM		
79				AM / PM		
80				AM / PM		
81				AM / PM		
82				AM / PM		
83				AM / PM		
84				AM / PM		
85				AM / PM		

Released by: ERICK ULLOA	Signature:	Date/Time: 01-27-2025
Received by: ERISTUARS	Signature:	Date/Time: 1/27/25 11:36am

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 25-01-05662

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 01/31/2025
Reported Date: 02/07/2025
Sampled By: Erick Ulloa
Tech Certification #:

Project/Test Address: 2320; 518 Ridgewood Road; Maplewood, NJ 07040

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-01-05662-001	JE-WC-GFL-B10	01/27/2025	HALL BY CUSTODIAL OFFICE BUBBLER	<1.00	02/06/2025	
25-01-05662-002	JE-DW-GFL-112	01/27/2025	HALL BY 112 BUBBLER	<1.00	02/06/2025	
25-01-05662-003	JE-DW-GFL-114	01/27/2025	ROOM A114 BUBBLER	4.33	02/06/2025	
25-01-05662-004	JE-DW-GFL-116	01/27/2025	ROOM A116 BUBBLER	6.82	02/06/2025	
25-01-05662-005	JE-DW-GFL-115-1	01/27/2025	ROOM A115 BUBBLER	7.50	02/06/2025	
25-01-05662-006	JE-DW-GFL-115-2	01/27/2025	ROOM A115 BUBBLER	12.4	02/06/2025	
25-01-05662-007	JE-DW-GFL-118	01/27/2025	ROOM A118 BUBBLER	1.45	02/06/2025	
25-01-05662-008	JE-DW-GFL-119	01/27/2025	ROOM A119 BUBBLER	6.08	02/06/2025	
25-01-05662-009	JE-S-GFL-NB	01/27/2025	NURSE BATHROOM SINK	<1.00	02/06/2025	
25-01-05662-010	JE-S-GFL-NO	01/27/2025	NURSE OFFICE SINK	3.57	02/06/2025	
25-01-05662-011	JE-WC-GFL-CAF-1	01/27/2025	HALL BY CAFETERIA BUBBLER	<1.00	02/06/2025	
25-01-05662-012	JE-BF-GFL-CAF	01/27/2025	HALL BY CAFETERIA BOTTLE FILLER	<1.00	02/06/2025	
25-01-05662-013	JE-WC-GFL-CAF-2	01/27/2025	HALL BY CAFETERIA BUBBLER	1.08	02/06/2025	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 25-01-05662

Project/Test Address: 2320; 518 Ridgewood Road; Maplewood, NJ 07040

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-01-05662-014	JE-WC-1FL-203-1	01/27/2025	HALL BY A203 BUBBLER	<1.00	02/06/2025	
25-01-05662-015	JE-WC-1FL-B201	01/27/2025	HALL BY B201 BUBBLER	<1.00	02/06/2025	
25-01-05662-016	JE-WC-1FL-B201	01/27/2025	HALL BY B201 BOTTLE FILLER	<1.00	02/06/2025	
25-01-05662-017	JE-S-1FL-L	01/27/2025	LIBRARY SINK	5.34	02/06/2025	
25-01-05662-018	JE-WC-2FL-TEC	01/27/2025	HALL BY B300A BUBBLER	<1.00	02/06/2025	
25-01-05662-019	JE-WC-2FL-304	01/27/2025	HALL BY A304 BUBBLER	<1.00	02/06/2025	
25-01-05662-020	JE-S-2FL-TL	01/27/2025	TEACHERS LOUNGE SINK	<1.00	02/06/2025	
25-01-05662-021	JE-SR	01/27/2025	SUNROOM	<1.00	02/06/2025	

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

25-01-05662

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Due Date:
02/07/2025
(Friday)
AE

104

Client Name: LEW CORP Account #: 201327

Address: 181 US HIGHWAY 46

City/State/Zip: MINE HILL, NJ 07803 Phone: 908-654-8068

Email Address: labresults@lewcorp.com

Project Name/ Number : 2320

Collection Address: 518 RIDGEWOOD ROAD (Required) **City/State/Zip:** MAPLEWOOD, NJ 07040 (Required)

Approx. Age Of Property: _____ **Collected By:** ERICK ULLOA

Water Source: (Check One) **Public** X **or Well** _____ **Well Tag # (if applicable):** _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	JE-WC-GFL-B110	HALL BY CUSTODIAL OFFICE, BUBBLER	01-27-2025	AM / PM	X	
2	JE-DW-GFL-112	HALL BY 112, BUBBLER		AM / PM	X	
3	JE-DW-GFL-114	ROOM A114, BUBBLER		AM / PM	X	
4	JE-DW-GFL-116	ROOM A116, BUBBLER		AM / PM	X	
5	JE-DW-GFL-115-1	ROOM A115, BUBBLER		AM / PM	X	
6	JE-DW-GFL-115-2	ROOM A115, BUBBLER		AM / PM	X	
7	JE-DW-GFL-118	ROOM A118, BUBBLER		AM / PM	X	
8	JE-DW-GFL-119	ROOM A119, BUBBLER		AM / PM	X	
9	JE-S-GFL-NB	NURSE BATHROOM, SINK		AM / PM	X	
10	JE-S-GFL-NO	NURSE OFFICE, SINK		AM / PM	X	
11	JE-WC-GFL-CAF-1	HALL BY CAFETERIA, BUBBLER		AM / PM	X	
12	JE-BF-GFL-CAF	HALL BY CAFETERIA, BOTTLE FILLER		AM / PM	X	
13	JE-WC-GFL-CAF-2	HALL BY CAFETERIA, BUBBLER		AM / PM	X	
14	JE-WC-1FL-203-1	HALL BY A203, BUBBLER		AM / PM	X	
15	JE-WC-1FL-B201	HALL BY B201, BUBBLER		AM / PM	X	

Released by: ERICK ULLOA	Signature:	Date/Time: 01-27-2025
Received by: CHRISTINA	Signature:	Date/Time: 1/31/25 1147

Client Name: LEW CORP Account #201327 Page 2 of 2

Project Name: 2320

Lab I.D. #: 05662

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
51	JE-BF-1FL-B201	HALL BY B201, BOTTLE FILLER	01-27-2025	AM / PM	X	
52	JE-S-1FL-L	LIBRARY, SINK		AM / PM	X	
53	JE-WC-2FL-TEC	HALL BY B300A, BUBBLER		AM / PM	X	
54	JE-WC-2FL-304	HALL BY A304, BUBBLER		AM / PM	X	
55	JE-S-2FL-TL	TEACHERS LOUNGE, SINK		AM / PM	X	
56	JE-SR	SUNROOM		AM / PM	X	
57				AM / PM	X	
58				AM / PM	X	
59				AM / PM	X	
60				AM / PM	X	
61				AM / PM	X	
62				AM / PM	X	
63				AM / PM	X	
64				AM / PM	X	
65				AM / PM	X	
66				AM / PM	X	
67				AM / PM	X	
68				AM / PM	X	
69				AM / PM	X	
70				AM / PM	X	
71				AM / PM	X	
72				AM / PM	X	
73				AM / PM	X	
74				AM / PM	X	
75				AM / PM	X	
76				AM / PM	X	
77				AM / PM		
78				AM / PM		
79				AM / PM		
80				AM / PM		
81				AM / PM		
82				AM / PM		
83				AM / PM		
84				AM / PM		
85				AM / PM		

Released by: ERICK ULLOA Signature: Date/Time: 01-27-2025

Received by: CHRISTIAN S Signature: Date/Time: 1/31/25 1147