181 US Hwy 46
Mine Hill, NJ 07803
(908) 654-8068
(800) 783-0567
Fax 908-654-8069

LEAD IN DRINKING WATER REPORT

Performed At:
Mount Olive Township School District

Performed For:
Mount Olive Township School District
227 US Highway 206, Sute 10, Flanders, NJ, 07836

Prepared By:
LEW Environmental Services, LLC.
181 US Hwy 46
Mine Hill, NJ 07803

Phone (908) 654-8068
Fax (908) 654-8069
Website http://www.LEWCorp.com

Inspection Date: 04/26/2025
Project Number: 1619

Table of Contents

Contact Information 3
Introduction 4
Sampling Methodology 4
Drinking Water Results 5
Recommendations 8
Additional Recommendations 8

Appendices

Appendix A Exceedances
Appendix B Recommendations
Appendix C All results
Appendix D Floor Plan(S)
Appendix E Water Outlet Inventory(ies)
Appendix F Laboratory Data

Contact Information

Education Agency

Client Contact:	John Maso3
Client Name:	Mount Olive Township School District3
Street Address	227 US Highway 206, Sute 10, Flanders, NJ, 07836
Phone Number:	973-691-4008 xt 8505

Sampler(s)

Site Assessor(s):	Erick Ulloa
Signature:	
Date:	May 4, 2025

Firm

Organization:	LEW Environmental Services, LLC.
Certification #:	NJDCA 00015 E
Street:	181 US Hwy 46
City, State & Zip:	Mine Hill, NJ 07803
Phone Number:	908-654-8068
Web Address:	http://www.lewcorp.com

Laboratory

Organization:	Environmental Hazard Services, LLC
Street:	7469 Whitepine Road
City, State & Zip:	Richmond, VA 23237
NJDEP Certification #	VA008
Phone Number:	800-347-4010

Introduction

LEW Environmental Services, LLC. was contracted by Mount Olive Township School District to test for the presence of lead in drinking water in six facilities in the district.

Sampling Methodology

LEW Environmental Services, LLC. followed NJAC 6A:26. Full details on sampling practices can be found in Districts Sampling Plan.

All samples were collected in 250mL wide mouth plastic containers that was prepackaged by the analytical laboratory. The sample containers may contain nitric acid, if expedited analysis is required. If not, nitric acid will be added to each sample upon arrival at the laboratory. At each sample location, the first draw sample was taken after it was determined that the water had been standing in the plumbing system for greater than eight hours but less than forty-eight hours. If second draw samples were collected, they were collecting following a flushing protocol outlined in the District's Sampling Plan.

Drinking Water Results

On April 26, 2025, LEW Environmental Services, LLC. collected the following number of water samples:

Sandshore School
- 34 first draw samples collected plus 1 QAQC blank sample
- 1 sample above the 15ppb action level

CMS Elementary
- 22 first draw samples collected plus 1 QAQC blank sample
- 2 samples above the 15ppb action level

TINC Road School
- 14 first draw samples collected plus 1 QAQC blank sample
- 1 sample above the 15ppb action level

Mt. View School
- 18 first draw samples collected plus 1 QAQC blank sample
- 1 sample above the 15ppb action level

Mt. Olive Middle School
- 69 first draw samples collected plus 1 QAQC blank sample
- 13 samples above the 15ppb action level

Mt. Olive High School
- 53 first draw samples collected plus 1 QAQC blank sample
- 1 sample above the 15ppb action level

The complete list of samples that exceeded the 15ppb limit can be found in Appendix A. The complete list of all sample results can be found in Appendix C. The laboratory results can be found in Appendix F.

Certain outlets could not or were not tested due to various reasons. The following table lists those locations and the reason why samples were not collected.

School	Sample Location	Reason for not testing.
Sandshore	SS-S4-K, Kitchen Back Rm Sink	Hand Wash Only
Sandshore	SS-S-NO, Nurse Exam Rm Sink	Hand Wash Only
Sandshore	SS-S-105, Rm 105 Sink	Not being tested
Sandshore	SS-S-106, Rm 106 Sink	Not being tested
Sandshore	SS-S-103, Rm 103 Sink	Not being tested

Sandshore	SS-SB-104, Rm 104 Bubbler	Not operating
Sandshore	SS-S-104, R, 104 Sink	Not being tested
Sandshore	SS-SB-101, Rm 101 Bubbler	Low Flow
Sandshore	SS-S-101, Rm 101 Sink	Not being tested
Sandshore	SS-S-102, Rm 102 Sink	Not being tested
Sandshore	SS-SB-99, Rm 99 Bubbler	Not operating
Sandshore	SS-S-99, Rm 99 Sink	Not being tested
Sandshore	SS-SB-100, Rm 100 Bubbler	Removed
Sandshore	SS-S-100, Rm 100 Sink	Not being tested
Sandshore	SS-S-LIB, Library Sink	Not being tested
Sandshore	SS-WC-155, Hall at 155 PE Girls Water Cooler	Removed
Sandshore	SS-SB-166, Rm 166 Bubbler	Removed
Sandshore	SS-S-166, Rm 166 Sink	Not being tested
Sandshore	SS-SB-172, Rm 172 Bubbler	Low Flow
Sandshore	SS-S-172, Rm 172 Sink	Not being tested
Sandshore	SS-S-179, Rm 179 Sink	Not being tested
Sandshore	SS-S-180, Rm 180 Sink	Not being tested
Sandshore	SS-S-181, Rm 181 Sink	Not being tested
Sandshore	SS-S-183, Rm 183 Sink	Not being tested
Sandshore	SS-S-184, Rm 184 Sink	Not being tested
Sandshore	SS-SB-189, Rm 189 Bubbler	Low Flow
Sandshore	SS-S-189, Rm 189 Sink	Not being tested
Sandshore	SS-S-190, Rm 190 Sink	Not being tested
Sandshore	SS-S-191, Rm 191 Sink	Not being tested
Sandshore	SS-S-192, Rm 192 Sink	Not being tested
Sandshore	SS-S-193, Rm 193 Sink	Not being tested
Sandshore	SS-S-194, Rm 194 Sink	Not being tested
Sandshore	SS-SB-195, RM 195 Bubbler	Low Flow
Sandshore	SS-S-195, Rm 195 Sink	Not being tested
Sandshore	SS-SB-196, RM 196 Bubbler	Not operating
Sandshore	SS-S-196, Rm 196 Sink	Not being tested
Sandshore	SS-S-197, Rm 197 Sink	Not being tested
Sandshore	SS-SB-198, Rm 198 Bubbler	Not operating
Sandshore	SS-S-198, Rm 198 Sink	Not being tested
CMS Elementary	CMS-WF-B40, RM B40 Water Fountain	Removed
CMS Elementary	CMS-WF-B39, RM B39 Water Fountain	Removed
CMS Elementary	CMS-BB-A25, Rm A25 Bubbler	Removed
CMS Elementary	CMS-BB-A16, Rm A15 Bubbler	Removed
CMS Elementary	CMS-BB-A24, Rm A24 Bubbler	Removed
CMS Elementary	CMS-BB-A16, Rm A16 Bubbler	Removed
CMS Elementary	CMS-BB-A17, Rm A17 Bubbler	Removed
Mt. View School	MV-S2-K, Kitchen Sink	Not operating

Mt. Olive High School	HS-S-B13, RM B13	HAND WASH ONLY
Mt. Olive High School	HS-S-B21, RM B21	REMOVED
Mt. Olive High School	HS-IM-B37SM, RM B37 SMALL RM	NOT OPERATING
Mt. Olive High School	HS-FO-B37SM, RM B37 SMALL RM	NOT OPERATING
Mt. Olive High School	HS-IM-B37LR, B37 LARGE RM	NOT OPERATING
Mt. Olive High School	HS-FO-B37LR, B37 LARGE RM	NOT OPERATING
Mt. Olive High School	HS-IM-B37LR, B37 LARGE RM	NOT LOCATED
Mt. Olive High School	HS-BF-MS, MAKER SPACE	NOT OPERATING
Mt. Olive High School	HS-S3-WS, KITCHEN WASH STATION	HAND WASH ONLY
Mt. Olive High School	HS-S5-WS, KITCHEN PRE-WASH	HAND WASH ONLY
Mt. Olive High School	HS-CM-CR, COFFEE RM	REMOVED
Mt. Olive High School	HS-S-SB, SNACK BAR RIGHT	NOT OPERATING
Mt. Olive High School	HS-S2-NO, NURSE EXAM RM	HAND WASH ONLY
Mt. Olive High School	HS-IM-NO, NURSE RM	NOT OPERATING
Mt. Olive High School	HS-SB1-G126, RM G126	NOT OPERATING
Mt. Olive High School	HS-S2-G126, RM G126	HAND WASH ONLY
Mt. Olive High School	HS-SB2-G126, RM G126	NOT OPERATING
Mt. Olive High School	HS-IM-B235, B235 FACUTLY	NOT OPERATING
Mt. Olive High School	HS-WC-LIB, LIBRARY	NOT LOCATED
Mt. Olive Middle School	MS-PF1-K, KITCHEN	NOT OPERATING
Mt. Olive Middle School	MS-WFL-GHB, GYM HALL BY BOYS LEFT	REMOVED
Mt. Olive Middle School	MS-S-148, RM 148	NOT OPERATING
Mt. Olive Middle School	MS-WFL-LIB, OUTSIDE LIBRARY	NOT LOCATED
Mt. Olive Middle School	MS-WCC-LIB, OUTSIDE LIBRARY	NOT LOCATED
Mt. Olive Middle School	MS-WCR-LIB, OUTSIDE LIBRARY	NOT LOCATED
Mt. Olive Middle School	MS-BF-LIB, OUTSIDE LIBRARY	NOT LOCATED
Mt. Olive Middle School	MS-S-D117, RM D117	NOT OPERATING

Mt. Olive Middle School	MS-WCR-F109, HALL BY F109 RIGHT	NOT OPERATING
Mt. Olive Middle School	MS-S-F113, RM F113	NOT OPERATING

Recommendations

On April 26, 2025, LEW Environmental Services, LLC. collected the first draw samples. We recommend the following actions.

Those outlets where the first draw sample tested below 15ppb are not considered to be elevated and no remediation is necessary.

For those outlets where the first draw sample exceeds 15ppb the following steps are recommended:

1) Immediately discontinue use of the outlets.
2) Conduct second draw (flush) samples on these outlets to further delineate source of contamination.

A complete list of recommendations per outlet can be found in Appendix B.

Additional Recommendations

1) Follow-up samples should be collected after any remediation efforts in order to determine the efficacy of the work.
2) Any of the inoperable/non-functioning outlets listed above that are brought back into service should be sampled.
3) Comply with all requirements set forth in NJAC 6A:26.

Appendix A Exceedances

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
Chester	4/26/2025	5/9/2025	CMS-S-NO	NURSE OFFICE SINK	19.3
Chester	4/26/2025	5/9/2025	CMS-S4-K	KITCHEN SINK	29.6
Mt. Olive High School	5/2/2025	6/13/2025	HS-S-SA	SNACK BAR LEFT SINK	49
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S3-HE	B142 SINK	20.2
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S4-HE	B142 SINK	26.5
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S1-WS	KITCHEN WASH STATION SINK	61.2
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S5-K	KITCHEN SINK	41.1
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S7-K	KITCHEN DISH WASH SINK	128
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S8-K	KITCHEN SERVICE AREA LEFT SINK	28.3
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S9-K	KITCHEN SERVICE AREA CENTER SINK	20.6
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S10-K	KITCHEN SERVICE AREA RIGHT SINK	63.4
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S11-K	KITCHEN SINK	258
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-SS	SNACK SHACK SINK	25.2
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-LIB	LIBRARY SINK	15.7
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-149	MAIN OFFICE 149 SINK	15.2
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-E134	E134 PREP SINK	76.6
Mt. View	4/26/2025	5/9/2025	MV-S3-NO	NURSE EXAM RM SINK	55.5
Sandshore	4/26/2025	5/8/2025	SS-S1-WS	KITCHEN SINK	43
Tinc	4/26/2025	5/7/2025	TR-S-TL	TEACHERS LOUNGE SINK	30.5

Appendix B Recommendations

Building	Location	Remediation Recommendation
Chester	NURSE OFFICE SINK	Discontinue use and perform second draw sampling
Chester	KITCHEN SINK	Discontinue use and perform second draw sampling
Mt. Olive High School	SNACK BAR LEFT SINK	Discontinue use and perform second draw sampling
Mt. Olive Middle School	B142 SINK	Discontinue use and perform second draw sampling
Mt. Olive Middle School	B142 SINK	Discontinue use and perform second draw sampling
Mt. Olive Middle School	KITCHEN WASH STATION SINK	Discontinue use and perform second draw sampling
Mt. Olive Middle School	KITCHEN SINK	Discontinue use and perform second draw sampling
Mt. Olive Middle School	KITCHEN DISH WASH SINK	Discontinue use and perform second draw sampling
Mt. Olive Middle School	KITCHEN SERVICE AREA LEFT SINK	Discontinue use and perform second draw sampling
Mt. Olive Middle School	KITCHEN SERVICE AREA CENTER SINK	Discontinue use and perform second draw sampling
Mt. Olive Middle School	KITCHEN SERVICE AREA RIGHT SINK	Discontinue use and perform second draw sampling
Mt. Olive Middle School	KITCHEN SINK	Discontinue use and perform second draw sampling
Mt. Olive Middle School	SNACK SHACK SINK	Discontinue use and perform second draw sampling
Mt. Olive Middle School	LIBRARY SINK	Discontinue use and perform second draw sampling
Mt. Olive Middle School	MAIN OFFICE 149 SINK	Discontinue use and perform second draw sampling
Mt. Olive Middle School	E134 PREP SINK	Discontinue use and perform second draw sampling
Mt. View	NURSE EXAM RM SINK	Discontinue use and perform second draw sampling
Sandshore	KITCHEN SINK	Discontinue use and perform second draw sampling
Tinc	TEACHERS LOUNGE SINK	Discontinue use and perform second draw sampling

Appendix C All Results

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
Sandshore	4/26/2025	5/8/2025	SS-S1-WS	KITCHEN SINK	43
Sandshore	4/26/2025	5/8/2025	SS-S2-WS	KITCHEN SINK	3.52
Sandshore	4/26/2025	5/8/2025	SS-S3-K	KITCHEN SINK	1.9
Sandshore	4/26/2025	5/8/2025	SS-WF-CAF	CAFETERIA WATER COOLER	<1.00
Sandshore	4/26/2025	5/8/2025	SS-BF-CAF	CAFETERIA BOTTLE FILLER	<1.00
Sandshore	4/26/2025	5/8/2025	SS-S2-NO	NURSE OFFICE SINK	2.11
Sandshore	4/26/2025	5/8/2025	SS-WC-NO	NURSE OFFICE WATER COOLER	<1.00
Sandshore	4/26/2025	5/8/2025	SS-WF-FAC	FACULTY HALLWAY WATTER COOLER	<1.00
Sandshore	4/26/2025	5/8/2025	SS-BF-FAC	FACULTY HALLWAY BOTTLE FILLER	<1.00
Sandshore	4/26/2025	5/8/2025	SS-S-FAC	FACULTY SINK	1.27
Sandshore	4/26/2025	5/8/2025	SS-WF-118	HALL AT 118 WATER COOLER	<1.00
Sandshore	4/26/2025	5/8/2025	SS-BF-118	HALL AT 118 BOTTLE FILLER	<1.00
Sandshore	4/26/2025	5/8/2025	SS-S-113	RM 113 SINK	13.3
Sandshore	4/26/2025	5/8/2025	SS-WF-123	HALL AT 123 WATER COOLER	<1.00
Sandshore	4/26/2025	5/8/2025	SS-BF-123	HALL AT 123 BOTTLE FILLER	<1.00
Sandshore	4/26/2025	5/9/2025	SS-SB-105	RM 105 BUBBLER	1.84
Sandshore	4/26/2025	5/9/2025	SS-SB-106	RM 106 BUBBLER	2.05
Sandshore	4/26/2025	5/9/2025	SS-SB-103	RM 103 BUBBLER	1.46
Sandshore	4/26/2025	5/8/2025	SS-SB-102	RM 102 BUBBLER	3.49
Sandshore	4/26/2025	5/8/2025	SS-SB-169	RM 169 BUBBLER	<1.00
Sandshore	4/26/2025	5/8/2025	SS-WF-169	HALL AT 169 WATER COOLER	<1.00
Sandshore	4/26/2025	5/8/2025	SS-BF-169	HALL AT 168 BOTTLE FILLER	<1.00
Sandshore	4/26/2025	5/8/2025	SS-SB-179	RM 179 BUBBLER	5.81
Sandshore	4/26/2025	5/8/2025	SS-S-182	RM 182 SINK	2.53
Sandshore	4/26/2025	5/8/2025	SS-SB-183	RM 183 BUBBLER	5.12
Sandshore	4/26/2025	5/8/2025	SS-SB-184	RM 184 BUBBLER	1.89
Sandshore	4/26/2025	5/8/2025	SS-WF-184	HALL AT 184 WATER COOLER	<1.00
Sandshore	4/26/2025	5/8/2025	SS-BF-184	HALL AT 184 BOTTLE FILLER	<1.00
Sandshore	4/26/2025	5/8/2025	SS-SB-190	RM 190 BUBBLER	6.12
Sandshore	4/26/2025	5/8/2025	SS-SB-191	RM 191 BUBBLER	3.18
Sandshore	4/26/2025	5/8/2025	SS-SB-192	RM 192 BUBBLER	7.86
Sandshore	4/26/2025	5/8/2025	SS-SB-193	RM 193 BUBBLER	13
Sandshore	4/26/2025	5/8/2025	SS-SB-194	RM 194 BUBBLER	4.42
Sandshore	4/26/2025	5/8/2025	SS-SB-197	RM 197 BUBBLER	7.46
Sandshore	4/26/2025	5/8/2025	SS-SR	SUNROOM	<1.00

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
Chester	4/26/2025	5/9/2025	CMS-WC-C59L	OUTSIDE C59 WATER COOLER	<1.00
Chester	4/26/2025	5/9/2025	CMS-BF-C59L	OUTSIDE C59 BOTTLE FILLER	<1.00
Chester	4/26/2025	5/9/2025	CMS-WF-C59R	OUTSIDE C59 WATER FOUNTAIN	<1.00
Chester	4/26/2025	5/9/2025	CMS-BF-B27	OUTSIDE B27 BOTTLE FILLER	<1.00
Chester	4/26/2025	5/9/2025	CMS-WF-B27	OUTSIDE B27 WATER FOUNTAIN	<1.00
Chester	4/26/2025	5/9/2025	CMS-BF-D62	OUTSIDE D62 BOTTLE FILLER	<1.00
Chester	4/26/2025	5/9/2025	CMS-WF-D62	OUTSIDE D62 WATER FOUNTAIN	<1.00
Chester	4/26/2025	5/9/2025	CMS-S-TL	TEACHERS LOUNGE SINK	12.5
Chester	4/26/2025	5/9/2025	CMS-WF-D65	OUTSIDE D65 WATER FOUNTAIN	<1.00
Chester	4/26/2025	5/9/2025	CMS-BF-D65	OUTSIDE D65 BOTTLE FILLER	<1.00
Chester	4/26/2025	5/9/2025	CMS-WF-A23	OUTSIDE A23 WATER FOUNTAIN	<1.00
Chester	4/26/2025	5/9/2025	CMS-BF-A23	OUTSIDE A23 BOTTLE FILLER	<1.00
Chester	4/26/2025	5/9/2025	CMS-S-OK	OFFICE KITCHEN SINK	9.94
Chester	4/26/2025	5/9/2025	CMS-S-NO	NURSE OFFICE SINK	19.3
Chester	4/26/2025	5/9/2025	CMS-WC-NO	NURSE OFFICE WATER COOLER	<1.00
Chester	4/26/2025	5/9/2025	CMS-WF-CAF	CAFETERIA WATER FOUNTAIN	<1.00
Chester	4/26/2025	5/9/2025	CMS-BF-CAF	CAFETERIA BOTTLE FILLER	<1.00
Chester	4/26/2025	5/9/2025	CMS-S1-K	KITCHEN SINK	1.8
Chester	4/26/2025	5/9/2025	CMS-S2-K	KITCHEN SINK	8.68
Chester	4/26/2025	5/9/2025	CMS-S3-K	KITCHEN SINK	11.1
Chester	4/26/2025	5/9/2025	CMS-S4-K	KITCHEN SINK	29.6
Chester	4/26/2025	5/9/2025	CMS-SR	SUNROOM	<1.00

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
Tinc	4/26/2025	5/7/2025	TR-S1-K	KITCHEN SINK	2.99
Tinc	4/26/2025	5/7/2025	TR-S2-K	KITCHEN SINK	4.12
Tinc	4/26/2025	5/7/2025	TR-WF-KH	KINDER HALL WATER FOUNTAIN	<1.00
Tinc	4/26/2025	5/7/2025	TR-BF-KH	KINDER HALL BOTTLE FILLER	<1.00
Tinc	4/26/2025	5/7/2025	TR-WF-ME	MAIN ENTRANCE WATER FOUNTAIN	<1.00
Tinc	4/26/2025	5/7/2025	TR-BF-ME	MAIN ENTRANCE BOTTLE FILLER	<1.00
Tinc	4/26/2025	5/7/2025	TR-S-TL	TEACHERS LOUNGE SINK	30.5
Tinc	4/26/2025	5/7/2025	TR-S-NO	NURSE OFFICE SINK	6.56
Tinc	4/26/2025	5/7/2025	TR-WF-126	ACROSS FROM 126 WATER FOUNTAIN	<1.00
Tinc	4/26/2025	5/7/2025	TR-BF-126	ACROSS FROM 126 BOTTLE FILLER	<1.00
Tinc	4/26/2025	5/7/2025	TR-WF-B5	BY DOOR B5 WATER FOUNTAIN	<1.00
Tinc	4/26/2025	5/7/2025	TR-BF-B5	BY DOOR B5 BOTTLE FILLER	<1.00
Tinc	4/26/2025	5/7/2025	TR-WF-149	BY RM 149 WATER FOUNTAIN	<1.00
Tinc	4/26/2025	5/7/2025	TR-BF-149	BY RM 149 BOTTLE FILLER	<1.00
Tinc	4/26/2025	5/7/2025	TR-SR	SUNROOM	<1.00


Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
Mt. View	4/26/2025	5/8/2025	MV-S1L-K	KITCHEN SINK	11.2
Mt. View	4/26/2025	5/8/2025	MV-S1R-K	KITCHEN SINK	7.39
Mt. View	4/26/2025	5/8/2025	MV-S-FR	FACULTY RM SINK	1.75
Mt. View	4/26/2025	5/8/2025	MV-WF-FR	OUTSIDE FACULTY RM WATER FOUNTAIN	<1.00
Mt. View	4/26/2025	5/8/2025	MV-BF-FR	OUTSIDE FACULTY RM BOTTLE FILLER	<1.00
Mt. View	4/26/2025	5/8/2025	MV-WF-AR	OUTSIDE ART RM WATER FOUNTAIN	<1.00
Mt. View	4/26/2025	5/8/2025	MV-BF-AR	OUTSIDE ART RM BOTTLE FILLER	<1.00
Mt. View	4/26/2025	5/8/2025	MV-WF-MR	BY DOOR 13 WATER FOUNTAIN	<1.00
Mt. View	4/26/2025	5/8/2025	MV-BF-MR	BY DOOR 13 BOTTLE FILLER	<1.00
Mt. View	4/26/2025	5/8/2025	MV-WF-RM112	OUTSIDE RM 112 WATER FOUNTAIN	<1.00
Mt. View	4/26/2025	5/8/2025	MV-BF-RM112	OUTSIDE RM 112 BOTTLE FILLER	<1.00
Mt. View	4/26/2025	5/8/2025	MV-WF-FO	FRONT OFFICE WATER FOUNTAIN	<1.00
Mt. View	4/26/2025	5/8/2025	MV-BF-FO	FRONT OFFICE BOTTLE FILLER	<1.00
Mt. View	4/26/2025	5/8/2025	MV-S1-NO	NURSE OFFICE SINK	2.63
Mt. View	4/26/2025	5/8/2025	MV-S2-NO	NURSE BATHROOM SINK	8.86
Mt. View	4/26/2025	5/9/2025	MV-S3-NO	NURSE EXAM RM SINK	55.5
Mt. View	4/26/2025	5/8/2025	MV-WF-LIB	LIBRARY WATER FOUNTAIN	<1.00
Mt. View	4/26/2025	5/8/2025	MV-BF-LIB	LIBRARY BOTTLE FILLER	<1.00
Mt. View	4/26/2025	5/9/2025	MV-SR	SUNROOM	<1.00

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S1-HE	B142 SINK	9.88
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S2-HE	B142 SINK	14.3
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S3-HE	B142 SINK	20.2
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-IM-HE	B142 ICE MACHINE	11.8
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S4-HE	B142 SINK	26.5
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S5-HE	B142 SINK	14.5
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WFL-BL	BOYS LOCKER RM LEFT WATER COOLER	4.18
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WFR-BL	BOYS LOCKER RM RIGHT WATER COOLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WFL-CAFE	HALL BY CAFE LEFT WATER COOLER	1.9
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-BFC-CAFE	HALL BY CAFE CENTER BOTTLE FILLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WFR-CAFE	HALL BY CAFE RIGHT WATER COOLER	1.4
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WFL-GL	GIRLS LOCKER RM LEFT WATER COOLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCR-GL	GIRLS LOCKER RM RIGHT WATER COOLER	1.05
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-TL	TEACHER LOUNGE SINK	7.47
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S1-WS	KITCHEN WASH STATION SINK	61.2
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S2-WS	KITCHEN WASH STATION SINK	7.3
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S3-LTR	KITCHEN LONG TABLE RIGHT SINK	12.8
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S4-LTL	KITCHEN LONG TABLE LEFT SINK	14
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-PF2-K	KITCHEN POT FILLER	10.5
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-IM-K	KITCHEN ICE MACHINE	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S5-K	KITCHEN SINK	41.1
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S6-K	KITCHEN SINK	5.47
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S7-K	KITCHEN DISH WASH SINK	128
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S8-K	KITCHEN SERVICE AREA LEFT SINK	28.3
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S9-K	KITCHEN SERVICE AREA CENTER SINK	20.6
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S10-K	KITCHEN SERVICE AREA RIGHT SINK	63.4
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S11-K	KITCHEN SINK	258
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-SS	SNACK SHACK SINK	25.2
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WFL-GHG	GYM HALL BY GIRLS LEFT WATER COOLER	2.54
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WFR-GHG	GYM HALL BY GIRLS RIGHT WATER COOLER	2.92
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-BFL-GHB	GYM HALL BY BOYS LEFT BOTTLE FILLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WFR-GHB	GYM HALL BY BOYS RIGHT WATER COOLER	11
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S1-NO	NURSE EXAM SINK	10.9
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-IM-NO	NURSE OFFICE ICE MACHINE	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S2-NO	NURSE OFFICE SINK	13.3
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-134	RM 134 SINK	3.75
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-LIB	LIBRARY SINK	15.7
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-145	MAIN OFFICE 145 SINK	6.67
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-149	MAIN OFFICE 149 SINK	15.2
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-151	RM 151 SINK	12.1
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCC-C133	HALL C133 WATER COOLER	1.05
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCR-C133	HALL C133 WATER COOLER	6.54
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCL-C133	HALL C133 WATER COOLER	2.4
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-C125	RM C125 SINK	4.87
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCR-D121	HALL BY D121 RIGHT WATER COOLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCC-D121	HALL BY D121 CENTER WATER COOLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCL-D121	HALL BY D121 LEFT WATER COOLER	5.63
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-133	RM 133 SINK	5.05
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCL-D108	HALL AT D108 LEFT WATER COOLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCC-D108	HALL AT D108 CENTER WATER COOLER	4.84
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCR-D108	HALL AT D108 RIGHT	1.35
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCL-C111	HALL BY C111 LEFT WATER COOLER	1.52
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCC-C111	HALL BY C111 CENTER WATER COOLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCR-C111	HALL BY C111 RIGHT WATER COOLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCL-E130	HALL BY E130 LEFT WATER COOLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCC-E130	HALL BY E130 CENTER WATER COOLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCR-E130	HALL BY E130 RIGHT WATER COOLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCL-E110	HALL BY E110 LEFT WATER COOLER	6.66
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCC-E110	HALL BY E110 CENTER WATER COOLER	1.15
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCR-E110	HALL BY E110 RIGHT WATER COOLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-E134	E134 PREP SINK	76.6
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCL-F121	HALL BY F121 LEFT WATER COOLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCC-F121	HALL BY F121 CENTER WATER COOLER	2.67
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCR-F121	HALL BY F121 RIGHT WATER COOLER	1.08
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-E120	RM E120 SINK	8.22
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-BF-E130	HALL BY E130 BOTTLE FILLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCL-F109	HALL BY F109 LEFT WATER COOLER	2
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-WCC-F109	HALL BY F109 CENTER WATER COOLER	<1.00
Mt. Olive Middle School	5/2/2025	6/13/2025	MS-S-F133	RM F133 SINK	11.5

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
Mt. Olive High School	5/2/2025	6/12/2025	HS-S-B07	RM B07 SINK	7.79
Mt. Olive High School	5/2/2025	6/12/2025	HS-WF-B29	HALL AT B29 WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-BF-B29	HALL AT B29 BOTTLE FILLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-S-B29	RM B29 SINK	5.64
Mt. Olive High School	5/2/2025	6/12/2025	HS-S-B34	RM B34 SINK	3.66
Mt. Olive High School	5/2/2025	6/12/2025	HS-S1-HE	B37 SINK	10.1
Mt. Olive High School	5/2/2025	6/12/2025	HS-S2-HE	B37 SINK	2.75
Mt. Olive High School	5/2/2025	6/12/2025	HS-S3-HE	B37 SINK	3.85
Mt. Olive High School	5/2/2025	6/12/2025	HS-S4-HE	B37 SINK	3.36
Mt. Olive High School	5/2/2025	6/12/2025	HS-S5-HE	B37 SINK	3.14
Mt. Olive High School	5/2/2025	6/12/2025	HS-S6-HE	B37 SINK	2.48
Mt. Olive High School	5/2/2025	6/12/2025	HS-S7-HE	B37 SINK	14.8
Mt. Olive High School	5/2/2025	6/12/2025	HS-WF-D17	HALL AT D17 WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-BF-D17	HALL AT D17 BOTTLE FILLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-WF-MS	MAKER SPACE WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-S1-MS	MAKER SPACE SINK	2.86
Mt. Olive High School	5/2/2025	6/12/2025	HS-S2-MS	MAKER SPACE SINK	5.46
Mt. Olive High School	5/2/2025	6/12/2025	HS-WF-C106	HALL AT C106 WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-BF-C106	HALL AT C106 BOTTLE FILLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-S1-SA	KITCHEN SERVING AREA SINK	6.43
Mt. Olive High School	5/2/2025	6/12/2025	HS-S2-FPR	KITCHEN FOOD PREP SINK	6.06
Mt. Olive High School	5/2/2025	6/12/2025	HS-S4-FPK	KITCHEN FOOD PREP SINK	10.8
Mt. Olive High School	5/2/2025	6/12/2025	HS-PF-K	KITCHEN POT FILLER	14.7
Mt. Olive High School	5/2/2025	6/12/2025	HS-IM-K	KITCHEN ICE MACHINE	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-S-CR	COFFEE ROOM SINK	6.99
Mt. Olive High School	5/2/2025	6/13/2025	HS-S-SA	SNACK BAR LEFT SINK	49
Mt. Olive High School	5/2/2025	6/12/2025	HS-WF-B115	HALL AT B115 WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-BF-B115	HALL AT B115 BOTTLE FILLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-S1-NO	NURSE OFFICE SINK	2.79
Mt. Olive High School	5/2/2025	6/12/2025	HS-WF-CA	HALL AT COM AREA WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-BF-CA	HALL AT COM AREA BOTTLE FILLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-WC-GEL	GYM ENTRANCE LOBBY WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-BF-GEL	GYM ENTRANCE BOTTLE FILLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-WF-G125	HALL BY G125 WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-BF-G125	HALL BY G125 BOTTLE FILLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-S1-G126	RM G126 SINK	8.5
Mt. Olive High School	5/2/2025	6/13/2025	HS-IM-G126	RM G126 ICE MACHINE	1.22
Mt. Olive High School	5/2/2025	6/12/2025	HS-WF-AB	AUX GYM BOYS BATH WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-BF-AB	AUX GYM BOYS BATH BOTTLE FILLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-WF-AG	AUX GYM GIRLS BATH WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-BF-AG	AUX GYM GIRLS BATH BOTTLE FILLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-WF-D115	HALL BY D115 WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-BF-D115	HALL BY D115 BOTTLE FILLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-WF-B209	B209 WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-BF-B209	B209 BOTTLE FILLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-S-B235	B235 FACULT SINK	6.75
Mt. Olive High School	5/2/2025	6/12/2025	HS-WF-B236	HALL BY B236 WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-BF-B236	HALL BY B236 BOTTLE FILLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-WF-D204	HALL BY D204 WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-BF-D204	HALL BY D204 BOTTLE FILLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-WF-B315	HALL BY B315 WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-BF-B315	HALL BY B315 BOTTLE FILLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-WC-NO	NURSE OFFICE WATER COOLER	<1.00
Mt. Olive High School	5/2/2025	6/12/2025	HS-SR		<1.00


Appendix D Floor Plan(s)

Sandshore Elementary School



Updated 8/16/21

2021-2022 SCHOOL YEAR




MOUNT OLIVE SCHOOL DISTRICT

"Ready for what comes next"

Chester M. Stephens Elementary

Tinc Road School Map 2021-2022



T4

97 Hopler 4th
96 Gentile 4th
SUPPLY ROOM

98 Whipple/Burrows 4th
99 Offending 4th

S3

130 Daly 3rd
129 Diefes/Ernst 3rd
128 DiMaggio 3rd
127 Damesto /Schoch 3rd
126 Lindsay 5th
125 Murphy/Hand 5th
124 Jurcsek SLP Hernandez-Spanish

131 Almeyda 2nd	132 Schneider/Krutisia 2nd	133 Iacampo 2nd	134 Polanco 2nd

B5

146 Kessler 1st	147 White 1st	148 Miller/Timpano 1st	149 Zagame 1st	161 & 164 Reber Bretzger PE

10+11 12+13

Beaulieu Media Center					
Sunshine Room	Library Office	Curr. Closet	Studio	Conference Room	Barba Guidance
CUS / MEN	WOMAN	Sullivan Health Office		O'Connell Inst. Sup.	Grilo Principal
		10 Waters/O'Brien OT/PT	Isolation Rooms	12 Rodriguez CST	COPY Main Office

8

Buzzelli Music	151 Baker/MAT ESL	156 Fernandez/Durland ART
	Instr. Music Spendley/Cardillo	
Cafeteria		Kitchen

5+6 1+2

Storage	CUST	ELEC
Lact Rm		
Women		
Cust.		
182		
185 Van Houten Kdg		
187 Glowinski Kdg		

9

3+4

P2


105 Carney Sp / 106 Carracino	104 Moschello/Tahmoosh 5th	103 Ferri CST	102 Fac Rm	STRGE

7


Foyer


STRGE	CUST	192 Enea Interv.	191 Capone Interv.	190 Smith/Sweeney Kdg


K7


#1 thru #4
#18 #19
#11 & #12
#7 & #8
#9 & #10
#15 #16 #17
#13 & #14
#5 & #6
Mt. View Elementary School
Exterior Door Numbers
speakers in all BR
LINWOOD DRIVE
HILL DRIVE
Cafeteria Multi Purpose Room
Kitchen
Store
Stage
Media center
Gymnasium
Music
Cafeteria
Faculty Room
Copy Rm.
Main Office
Strobe
Replace outside speaker
Ac-6 - crash
Ac-7 crash
Ac-1 crash
Ac-2 - double crash
Ac-4/5
Existing x2
x2-reader
x3- release buttons
MDF
IDF 2
IDF 3


06:05 5G 79
Floor plans-High School.pdf


Unexcavated
Elevator Room
CR
BR
CR D13
CR D14
CR D15
CR D16
CR D17
CR D18
Home Ec. B37
15 - 21
SCSE Life Skills B34
9
Elevator Room
SCSE B29
0
Courtyard
BR
CR
Earth Science 312
P
Earth Science 311
YOU ARE HERE
Chemistry 310
P
Chemistry 308
Science 307
P
Storage
Lab B113
CAD Lab B121
Wood Shop B111
BR
CR
Custodial B320
Metal Shop B109
Robotics B107
Elevator
Boiler Room
Basement
Choral Room
Band Room
EMERGENCY EVACUATION PLAN



64
65
X
2ND FL WING B
FIRE EVACUATION ROUTE
SOC STUDIES / ART /
ARCH


CR B249
CR B247
CR B245
CR B243
CR B241
CR B239
Faculty Room B235
Dark Room
Developing
Photo Lab B232
CR B211
CR B212
CR B213
CR B214
CR B215
CR B216
CR B244a
CR B244
CR B242
CR B240
YOU ARE HERE
Graphics B230
CR B210
Art Design Studio B226
Graphics B207
CR B225
CR B206
CR B221
IDF
CR B204
CR B217
CR B205
Secr
VP
2nd Floor
Prep B311
CR B310
CR B316
CR B315
CR B317
CR B308
CR B320
CR B306
CR B323
CR B303
CR B324
CR B325
CR B302

middle school



TEACHER ROOM ASSIGNMENTS



Appendix E Water Outlet Inventory(ies)

Attachment C - Water Outlet Inventory

(To be completed for each school)

Name of School: Sandshore ES Address: 498 Sandshore Road Budd Lake, NJ

Grade Levels: K-5 Year School Constructed: Renovations/Additions: N/A

Individual school project officer Name/Signature: _____ Date completed: 5/2/2022

#[1]	Type	Location	Code	Operating [2] (Y/N)	Corrosion [3] (Y/N)	Filter [4] (Y/N)	Brass Fittings, Faucets or valves? (Y/N)	Aerator/ Screen (Y/N)	Motion Activated (Y/N)	Chiller (Y/N)	Water Cooler		Comments
											Make	Model	
1	Sink	Kitchen Wask Station	SS-S1-WS	Y	N	N	N	N	N	N			
2	Sink	Kitchen Wask Station	SS-S2-WS	Y	N	N	N	N	N	N			
3	Sink	Kitchen Long Table	SS-S3-K	Y	N	N	N	N	N	N			
4	Sink	Kitchen Back Room	SS-S4-K	Y	N	N	N	N	N	N			
5	Water Cooler	Cafeteria	SS-WF-Caf	Y	N	N	N	N	N	N			Turned Off
6	Bottle Fill	Cafeteria	SS-BF-Caf	Y	N	Y	N	N	N	N			Turned Off
7	Sink	Nurse Exam Rm	SS-S-NO	Y	N	N	N	N	N	N			
8	Sink	Nurse Office	SS-S2-NO	Y	N	N	N	N	N	N			
9	Water Cooler	Hall at faculty	SS-WF-FAC	Y	N	N	N	N	N	N			Turned Off
10	Sink	Faculty	SS-S-FAC	Y	N	N	N	N	N	N			
11	Water Cooler	Hall at 118	SS-WF-118	Y	Y	N	Y	N	N	N			Turned Off
12	Water Cooler	Hall at Rm 118	SS-BF-123	Y	Y	Y	N	N	N	N			Turned Off

13	Sink	Room 113	SS-S-113	Y	Y	N	N	N	N	N			
14	Water Cooler	Hall at 123	SS-WF-123	Y	Y	N	N	N	N	N			Turned Off
15	Bottle Fill	Hall at 123	SS-BF-123	Y	Y	N	N	N	N	N			Turned Off
16	Sink Bubbler	Room 105	SS-SB-105	Y	Y	N	N	N	N	N			Not being tested
17	Sink	Room 105	SS-S-105	Y	Y	N	N	N	N	N			Not being tested
18	Sink Bubbler	Room 106	SS-SB-106	Y	Y	N	N	N	N	N			Not being tested
19	Sink	Room 106	SS-S-106	Y	Y	N	N	N	N	N			Not being tested
20	Sink Bubbler	Room 103	SS-S-103	Y	Y	N	N	N	N	N			Not being tested
21	Sink	Room 103	SS-S-103	Y	Y	N	N	N	N	N			Not being tested
22	Sink Bubbler	Room 104	SS-S-104	Y	Y	N	N	N	N	N			Not being tested
23	Sink	Room 104	SS-S-104	Y	Y	Y	N	N	N	N			Not Being Tested
24	Sink Bubbler	Room 101	SS-SB-101	Y	Y	Y	N	N	N	N			Not Being Tested
25	Sink	Room 101	SS-S-101	Y	Y	Y	N	N	N	N			Not Being Tested
26	Sink Bubbler	Room 102	SS-SB-102	Y	Y	Y	N	N	N	N			Not Being Tested
27	Sink	Room 102	SS-S-102	Y	Y	Y	N	N	N	N			Not Being Tested
28	Sink Bubbler	Room 99	SS-SB-99	Y	Y	N	N	N	N	N			Not Being Tested
29	Sink	Room 99	SS-S-99	Y	Y	N	N	N	N	N			Not Being Tested
30	Sink Bubbler	Room 100	SS-SB-100	Y	Y	N	N	N	N	N			Not Being Tested
31	Sink	Room 100	SS-S-100	Y	Y	N	N	N	N	N			Not Being Tested

32	Sink	Library	SS-S-Lib	Y	Y	N	N	N	N	N			
33	Water Cooler	Hall at 155 PE Girls	SS-WC-155	Y	Y	N	N	N	N	N			Turned Off
34	Sink Bubbler	Room 166	SS-SB-166	Y	Y	N	N	N	N	N			Not being tested
35	Sink	Room 166	SS-S-166	Y	Y	Y	N	N	N	N			Not Being Tested
36	Sink Bubbler	Room 169	SS-SB-169	Y	Y	Y	N	N	N	N			Not Being Tested
37	Water Cooler	Hall at 169	SS-WF-169	Y	Y	Y	N	N	N	N			Turned Off
38	Bottle Fill	Hall at 169	SS-BF-169	Y	Y	Y	N	N	N	N			Turned Off
39	Sink Bubbler	Room 172	SS-SB-172	Y	Y	Y	N	N	N	N			Not Being Tested
40	Sink	Room 172	SS-S-172	Y	Y	N	N	N	N	N			Not Being Tested
41	Sink Bubbler	Room 179	SS-SB-179	Y	Y	N	N	N	N	N			Not Being Tested
42	Sink	Room 179	SS-S-179	Y	Y	N	N	N	N	N			Not Being Tested
43	Sink	Room 180	SS-S-180	Y	Y	N	N	N	N	N			
44	Sink	Room 181	SS-S-181	Y	Y	N	N	N	N	N			
45	Sink	Room 182	SS-S-182	Y	Y	N	N	N	N	N			
46	Sink Bubbler	Room 183	SS-SB-183	Y	Y	N	N	N	N	N			Not being tested
47	Sink	Room 183	SS-S-183	Y	Y	Y	N	N	N	N			Not Being Tested
48	Sink Bubbler	Room 184	SS-SB-184	Y	Y	Y	N	N	N	N			Not Being Tested
49	Sink	Room 184	SS-S-184	Y	Y	Y	N	N	N	N			Not Being Tested
50	Water Cooler	Hall at 184	SS-WF-184	Y	Y	Y	N	N	N	N			Turned Off

51	Bottle Fill	Hall at 184	SS-BF-184	Y	Y	Y	N	N	N	N			Turned Off
52	Sink Bubbler	Room 189	SS-SB-189	Y	Y	N	N	N	N	N			Not Being Tested
53	Sink	Room 189	SS-S-189	Y	Y	N	N	N	N	N			Not Being Tested
54	Sink Bubbler	Room 190	SS-SB-190	Y	Y	N	N	N	N	N			Not Being Tested
55	Sink	Room 190	SS-S-190	Y	Y	N	N	N	N	N			Not Being Tested
56	Sink Bubbler	Room 191	SS-SB-191	Y	Y	N	N	N	N	N			Not Being Tested
57	Sink	Room 191	SS-S-191	Y	Y	N	N	N	N	N			Not Being Tested
58	Sink Bubbler	Room 192	SS-SB-192	Y	Y	N	N	N	N	N			Not being tested
59	Sink	Room 192	SS-S-192	Y	Y	Y	N	N	N	N			Not Being Tested
60	Sink Bubbler	Room 193	SS-SB-193	Y	Y	Y	N	N	N	N			Not Being Tested
61	Sink	Room 193	SS-S-193	Y	Y	Y	N	N	N	N			Not Being Tested
62	Sink Bubbler	Room 194	SS-SB-194	Y	Y	Y	N	N	N	N			Not Being Tested
63	Sink	Room 194	SS-S-194	Y	Y	Y	N	N	N	N			Not Being Tested
64	Sink Bubbler	Room 195	SS-SB-195	Y	Y	N	N	N	N	N			Not Being Tested
65	Sink	Room 195	SS-S-195	Y	Y	N	N	N	N	N			Not Being Tested
66	Sink Bubbler	Room 196	SS-SB-196	Y	Y	N	N	N	N	N			Not Being Tested
67	Sink	Room 196	SS-S-196	Y	Y	N	N	N	N	N			Not Being Tested
68	Sink Bubbler	Room 197	SS-SB-197	Y	Y	N	N	N	N	N			Not Being Tested
69	Sink	Room 197	SS-S-197	Y	Y	N	N	N	N	N			Not Being Tested

70	Sink Bubbler	Room 198	SS-SB-198	Y	Y	N	N	N	N	N			not being tested
71	Sink	Room 198	SS-S-198	Y	Y	Y	N	N	N	N			Not Being Tested
72	Water Cooler	Nurse Office	SS-WC-NO	Y	Y	Y	N	N	N	N			

Attachment C - Water Outlet Inventory

(To be completed for each school)

Name of School: Tinc Road School Address: 24 Tinc Road Flanders, NJ 07836

Grade Levels: K-5 Year School Constructed: Renovations/Additions: N/A

Individual school project officer Name/Signature: _____ Date completed: 5/2/2022

#[1]	Type	Location	Code	Operating [2] (Y/N)	Corrosion [3] (Y/N)	Filter [4] (Y/N)	Brass Fittings, Faucets or valves? (Y/N)	Aerator/ Screen (Y/N)	Motion Activated (Y/N)	Chiller (Y/N)	Water Cooler		Comments
											Make	Model	
1	Sink	Kitchen	TR-S1-K	Y	N	N	N	N	N	N			
2	Sink	Kitchen	TR-S2-K	Y	N	N	N	N	N	N			
3	Water Fountain	By Kinder Hall	TR-WF-KH	Y	N	N	N	N	N	N			
4	Bottle Fill	By Kinder Hall	TR-BF-KH	Y	N	N	N	N	N	N			
5	Water Fountain	Main Enterance	TR-WF-ME	Y	N	N	N	N	N	N			
6	Bottle Fill	Main Enterance	TR-BF-ME	Y	N	Y	N	N	N	N			
7	Sink	Teachers Lounge	TR-S-TL	Y	N	N	N	N	N	N			
8	Sink	Nurse Office	TR-S-NO	Y	N	N	N	N	N	N			
9	Water Fountain	Across From 126	TR-WF-126	Y	N	N	N	N	N	N			Not Working
10	Water Fountain	By Door B5	TR-WF-B5	Y	N	N	N	N	N	N			
11	Bottle Fill	By Door B5	TR-BF-B5	Y	Y	N	Y	N	N	N			
12	Water Fountain	By Room 149	TR-WF-149	Y	Y	Y	N	N	N	N			

13	Bottle Fill	By Room 149	TR-BF-149	Y	Y	N	N	N	N	N			

Attachment C - Water Outlet Inventory

(To be completed for each school)

Name of School: Chester M. Stephens E. S. Address: 99 Sunset Drive Budd Lake, NJ

Grade Levels: K-5 Year School Constructed: Renovations/Additions: N/A

Individual school project officer Name/Signature: _____ Date completed: 5/2/2022

#[1]	Type	Location	Code	Operating [2] (Y/N)	Corrosion [3] (Y/N)	Filter [4] (Y/N)	Brass Fittings, Faucets or valves? (Y/N)	Aerator/ Screen (Y/N)	Motion Activated (Y/N)	Chiller (Y/N)	Water Cooler		Comments
											Make	Model	
1	Water Cooler	Outside C59	CMS-WC-C59	Y	N	N	N	N	N	N			
2	Bottle Fill	Outside C59	CMS-BF-C59	Y	N	N	N	N	N	N			
3	Water Fountain	Outside C59	CMS-WF-C59	Y	N	N	N	N	N	N			
4	Bottle Fill	Outside B27	CMS-BF-B27	Y	N	N	N	N	N	N			
5	Water Fountain	Outside B27	CMS-WF-B27	Y	N	N	N	N	N	N			
6	Water Fountain	Room B40	CMS-WF-B40	Y	N	Y	N	N	N	N			
7	Water Fountain	Room B39	CMS-WF-B39	Y	N	N	N	N	N	N			
8	Bottle Fill	Outside D62	CMS-BF-D62	Y	N	N	N	N	N	N			
9	Water Fountain	Outside D62	CMS-WF-D62	Y	N	N	N	N	N	N			
10	Sink	Teachers Lounge	CMS-S-TL	Y	N	N	N	N	N	N			
11	Water Fountain	Outside D65	CMS-WF-D65	Y	Y	N	Y	N	N	N			
12	Bottle Fill	Outside D65	CMS-BF-D65	Y	Y	Y	N	N	N	N			

13	Sink Bubbler	Room A25	CMS-BB-A25	Y	Y	N	N	N	N	N			
14	Sink Bubbler	Room A15	CMS-BB-A16	Y	Y	N	N	N	N	N			
15	Sink Bubbler	Room A24	CMS-BB-A24	Y	Y	N	N	N	N	N			
16	Sink Bubbler	Room A16	CMS-BB-A16	Y	Y	N	N	N	N	N			
17	Sink Bubbler	Room A17	CMS-BB-A17	Y	Y	N	N	N	N	N			
18	Water Fountian	Outside A23	CMS-WF-A23	Y	Y	N	N	N	N	N			
19	Bottle Fill	Outside A23	CMS-BF-A23	Y	Y	N	N	N	N	N			
20	Sink	Office Kitchen	CMS-S-OK	Y	Y	N	N	N	N	N			
21	Sink	Nurse Office	CMS-S-NO	Y	Y	N	N	N	N	N			
22	Water Cooler	Nurse Office	CMS-WC-NO	Y	Y	N	N	N	N	N			
23	Water Fountian	Cafeteria	CMS-WF-CAF	Y	Y	Y	N	N	N	N			
24	Bottle Fill	Cafeteria	CMS-BF-CAF	Y	Y	Y	N	N	N	N			
25	Sink	Kitchen	CMS-S1-K	Y	Y	Y	N	N	N	N			
26	Sink	Kitchen	CMS-S2-K	Y	Y	Y	N	N	N	N			
27	Sink	Kitchen	CMS-S3-K	Y	Y	Y	N	N	N	N			
28	Sink	Kitchen	CMS-S4-K	Y	Y	N	N	N	N	N			

Attachment C - Water Outlet Inventory

(To be completed for each school)

Name of School: Mountain View E.S. Address: 118 Cloverhill Road Flanders, NJ 07836

Grade Levels: K-5 Year School Constructed: Renovations/Additions: N/A

Individual school project officer Name/Signature: _____ Date completed: 5/2/2022

#[1]	Type	Location	Code	Operating [2] (Y/N)	Corrosion [3] (Y/N)	Filter [4] (Y/N)	Brass Fittings, Faucets or valves? (Y/N)	Aerator/ Screen (Y/N)	Motion Activated (Y/N)	Chiller (Y/N)	Water Cooler		Comments
											Make	Model	
1	Sink	Kitchen	MV-S1L-K	Y	N	N	N	N	N	N			
2	Sink	Kitchen	MV-S1R-K	Y	N	N	N	N	N	N			
3	Sink	Kitchen	MV-S2-K	Y	N	N	N	N	N	N			
4	Sink	Faculty Room	MV-S-FR	Y	N	N	N	N	N	N			
5	Water Fountain	Outside Faculty Rm	MV-WF-FR	Y	N	N	N	N	N	N			
6	Bottle Fill	Outside Faculty Rm	MV-BF-FR	Y	N	Y	N	N	N	N			
7	Water Fountain	outside Art Room	MV-WF-AR	Y	N	N	N	N	N	N			
8	Bottle Fill	outside Art Room	MV-BF-AR	Y	N	N	N	N	N	N			
9	Water Fountain	Across From Music	MV-WF-MR	Y	N	N	N	N	N	N			Not Working
10	Bottle Fill	Across From Music	MV-BF-MR	Y	N	N	N	N	N	N			
11	Water Fountain	Outside Rm112	MV-WF-RM112	Y	Y	N	Y	N	N	N			
12	Bottle Fill	Across From RM 112	MV-BF-RM112	Y	Y	Y	N	N	N	N			

13	Water Fountian	Front Office	MV-WF-FO	Y	Y	N	N	N	N	N			
14	Bottle Fill	Front Office	MV-BF-FO	Y	Y	N	N	N	N	N			
15	Sink	Nurse Office	MV-S1-NO	Y	Y	N	N	N	N	N			
16	Sink	Nurse Bath	MV-S2-NO	Y	Y	N	N	N	N	N			
17	Sink	Nurse Exam	MV-S3-NO	Y	Y	N	N	N	N	N			
18	Water Fountian	Library	MV-WF-Lib	Y	Y	N	N	N	N	N			
19	Bottle Fill	Library	MV-BF-Lib	Y	Y	N	N	N	N	N			

Attachment C - Water Outlet Inventory

(To be completed for each school)

Name of School: Mount Olive High School Address: 18 Corey Road Flanders, NJ

Grade Levels: 9-12 Year School Constructed: Renovations/Additions: N/A

Individual school project officer Name/Signature: _____ Date completed: 5/2/2022

#[1]	Type	Location	Code	Operating [2] (Y/N)	Corrosion [3] (Y/N)	Filter [4] (Y/N)	Brass Fittings, Faucets or valves? (Y/N)	Aerator/ Screen (Y/N)	Motion Activated (Y/N)	Chiller (Y/N)	Water Cooler		Comments
											Make	Model	
~~1~~	~~Sink~~	~~B07~~	~~HS-S-B07~~	~~Y~~	~~N~~	~~N~~	~~N~~	~~N~~	~~N~~	~~N~~			~~Hand wash Only~~
2	Water Cooler	B11	HS-WF-B11	Y	N	N	N	N	N	N			
3	Bottle Fill	B11	HS-BF-B11	Y	N	N	N	N	N	N			
~~4~~	~~Sink~~	~~B13~~	~~HS-S-B13~~	~~Y~~	~~N~~	~~N~~	~~N~~	~~N~~	~~N~~	~~N~~			~~Hand wash only~~
~~5~~	~~Sink~~	~~B21~~	~~HS-S-B21~~	~~Y~~	~~N~~	~~N~~	~~N~~	~~N~~	~~N~~	~~N~~			~~Removed~~
6	Water Cooler	Hall at B29	HS-WF-B29	Y	N	Y	N	N	N	N			
7	Bottle Fill	Hall at B29	HS-BF-B29	Y	N	N	N	N	N	N			
~~8~~	~~Sink~~	~~B29~~	~~HS-S-B29~~	~~Y~~	~~N~~	~~N~~	~~N~~	~~N~~	~~N~~	~~N~~			~~Hand wash only~~
~~9~~	~~Sink~~	~~B34~~	~~HS-S-B34~~	~~Y~~	~~N~~	~~N~~	~~N~~	~~N~~	~~N~~	~~N~~			~~Hand wash only~~
10	Ice Machine	B37 Small Rm	HS-IM-B37SM	Y	N	N	N	N	N	N			
11	Frige Water Outlet	B37 Small Rm	HS-FO-B37SM	Y	Y	N	Y	N	N	N			
12	Ice Machine	B37 Large Room	HS-IM-B37LR	Y	Y	Y	N	N	N	N			

13	Frige Water Outlet	B37 Large Room	HS-FO-B37LR	Y	Y	N	N	N	N	N			
14	Ice Machine	B37 Large Room	HS-IM-B37LR	Y	Y	N	N	N	N	N			Not being tested
15	Sink	B37 Large Room	HS-S1-HE	Y	Y	N	N	N	N	N			
16	Sink	B37 Large Room	HS-S2-HE	Y	Y	N	N	N	N	N			
17	Sink	B37 Large Room	HS-S3-HE	Y	Y	N	N	N	N	N			
18	Sink	B37 Large Room	HS-S4-HE	Y	Y	N	N	N	N	N			
19	Sink	B37 Large Room	HS-S5-HE	Y	Y	N	N	N	N	N			
20	Sink	B37 Large Room	HS-S6-HE	Y	Y	N	N	N	N	N			
21	Sink	B37 Large Room	HS-S7-HE	Y	Y	N	N	N	N	N			
22	Water Cooler	Hall at D17	HS-WF-D17	Y	Y	N	N	N	N	N			
23	Bottle Fill	Hall at D17	HS-BF-D17	Y	Y	Y	N	N	N	N			
24	Water Cooler	Maker Space	HS-WF-MS	Y	Y	Y	N	N	N	N			
25	Bottle Fill	Maker Space	HS-BF-MS	Y	Y	Y	N	N	N	N			
26	Sink	Maker Space	HS-S1-MS	Y	Y	Y	N	N	N	N			
27	Sink	Maker Space	HS-S2-MS	Y	Y	Y	N	N	N	N			
28	Water Cooler	Hall at C106	HS-WF-C106	Y	Y	N	N	N	N	N			
29	Bottle Fill	Hall at C106	HS-BF-C106	Y	Y	N	N	N	N	N			
30	Sink	Kitchen Serving area	HS-S1-SA	Y	Y	N	N	N	N	N			In cornerby food prep
31	Sink	Kitchen Food Prep	HS-S2-FPR	Y	Y	N	N	N	N	N			

32	Sink	Kitchen Wash Station	HS-S3-WS	Y	Y	N	N	N	N	N			
33	Sink	Kitchen Food Prep	HS-S4-FPK	Y	Y	N	N	N	N	N			Food prep in Corner
34	Pot Filler	Kitchen	HS-PF-K	Y	Y	N	N	N	N	N			
35	Sink	Kitchen Pre Wash	HS-S5-WS	Y	Y	Y	N	N	N	N			
36	Ice Machine	Kitchen	HS-IM-K	Y	Y	Y	N	N	N	N			
37	Sink	Coffee Room	HS-S-CR	Y	Y	Y	N	N	N	N			
38	Coffee Maker	Coffee Room	HS-CM-CR	Y	Y	Y	N	N	N	N			
39	Sink	Serving Area	HS-S-SA	Y	Y	Y	N	N	N	N			Removed??
40	Sink	Snack Bar	HS-S-SB	Y	Y	N	N	N	N	N			
41	Water Cooler	Hall at B115	HS-WF-B115	Y	Y	N	N	N	N	N			
42	Bottle Fill	Hall at B115	HS-BF-B115	Y	Y	N	N	N	N	N			
43	Sink	Nurse Office	HS-S1-NO	Y	Y	N	N	N	N	N			
44	Sink	Nurse Exam Rm	HS-S2-NO	Y	Y	N	N	N	N	N			
45	Ice Machine	Nurse Room	HS-IM-NO	Y	Y	N	N	N	N	N			Not Working
46	Water Cooler	Hall at Com Area	HS-WF-CA	Y	Y	N	N	N	N	N			
47	Bottle Fill	Hall at Com Area	HS-BF-CA	Y	Y	Y	N	N	N	N			
48	Water Cooler	Hall at Girls Locker	HS-WF-GLR	Y	Y	Y	N	N	N	N			
49	Bottle Fill	Hall at Girls Locker	HS-BF-GLR	Y	Y	Y	N	N	N	N			
50	Water Cooler	Gym Entrance Lobby	HS-WC-GEL	Y	Y	Y	N	N	N	N			Not Working

51	Water Cooler	Hall by G125	HS-WF-G125	Y	Y	Y	N	N	N	N			
52	Bottle Fill	Hall by G125	HS-BF-G125	Y	Y	N	N	N	N	N			
53	Sink	Room G126	HS-S1-G126	Y	Y	N	N	N	N	N			
54	Sink Bubbler	Room G126	HS-SB1-G126	Y	Y	N	N	N	N	N			
55	Sink	Room G126	HS-S2-G126	Y	Y	N	N	N	N	N			
56	Sink Bubbler	Room G126	HS-SB2-G126	Y	Y	N	N	N	N	N			
57	Ice Machine	Room G126	HS-IM-G126	Y	Y	N	N	N	N	N			
58	Water Cooler	Aux Gym Boys bath	HS-WF-AB	Y	Y	N	N	N	N	N			
59	Bottle Fill	Aux Gym Boys Bathr	HS-BF-AB	Y	Y	Y	N	N	N	N			
60	Water Cooler	Aux Gym Girls Bath	HS-WF-AG	Y	Y	Y	N	N	N	N			Not Working
61	Bottle Fill	Aux Gym Girls Bath	HS-BF-AG	Y	Y	Y	N	N	N	N			
62	Water Cooler	Hall by D115	HS-WF-D115	Y	Y	Y	N	N	N	N			
63	Bottle Fill	Hall by D115	HS-BF-D115	Y	Y	Y	N	N	N	N			
64	Water Cooler	B209	HS-WF-B209	Y	Y	N	N	N	N	N			
65	Bottle Fill	B209	HS-BF-B209	Y	Y	N	N	N	N	N			
66	Sink	B235 Faculty	HS-S-B235	Y	Y	N	N	N	N	N			
67	Ice Machine	B235 Faculty	HS-IM-B235	Y	Y	N	N	N	N	N			Not Working
68	Water Cooler	Hall by B236	HS-WF-B236	Y	Y	N	N	N	N	N			
69	Bottle Fill	Hall by B236	HS-BF-B236	Y	Y	N	N	N	N	N			

70	Water Cooler	Hall by D204	HS-WF-D204	Y	Y	N	N	N	N	N			
71	Bottle Fill	Hall by D204	HS-BF-D204	Y	Y	Y	N	N	N	N			
72	Water Cooler	Hall by B315	HS-WF-B315	Y	Y	Y	N	N	N	N			
73	Bottle Fill	Hall by B315	HS-BF-B315	Y	Y	Y	N	N	N	N			
74	Water Cooler	Library	HS-WC-Lib	Y	Y	Y	N	N	N	N			
75	Water Cooler	Nurse Office	HS-WC-NO	Y	Y	Y	N	N	N	N			

Attachment C - Water Outlet Inventory

(To be completed for each school)

Name of School: Mount Olive Middle School Address: 160 Wolfe Road Budd Lake, NJ

Grade Levels: 7-8 Year School Constructed: Renovations/Additions: N/A

Individual school project officer Name/Signature: _____ Date completed: 5/2/2022

#[1]	Type	Location	Code	Operating [2] (Y/N)	Corrosion [3] (Y/N)	Filter [4] (Y/N)	Brass Fittings, Faucets or valves? (Y/N)	Aerator/ Screen (Y/N)	Motion Activated (Y/N)	Chiller (Y/N)	Water Cooler		Comments
											Make	Model	
1	Sink	B142	MS-S1-HE	Y	N	N	N	N	N	N			
2	Sink	B142	MS-S2-HE	Y	N	N	N	N	N	N			
3	Sink	B142	MS-S3-HE	Y	N	N	N	N	N	N			
4	Ice Machine	B142	MS-IM-HE	Y	N	N	N	N	N	N			not working
5	Sink	B142	MS-S4-HE	Y	N	N	N	N	N	N			
6	Sink	B142	MS-S5-HE	Y	N	Y	N	N	N	N			
7	Water Cooler	Boys Locker RM Left	MS-WFL-BL	Y	N	N	N	N	N	N			
8	Water Cooler	Boys Locker RM Right	MS-WFR-BL	Y	N	N	N	N	N	N			
9	Water Cooler	Hall by Café left	MS-WFL-Café	Y	N	N	N	N	N	N			
10	Water Cooler	Hall by Café Right	MS-WFR-Café	Y	N	N	N	N	N	N			
11	Water Cooler	Girls Locker Rm Left	MS-WFL-GL	Y	Y	N	Y	N	N	N			
12	Water Cooler	Girls Locker Room Right	MS-WCR-GL	Y	Y	Y	N	N	N	N			

13	Sink	teachers Lounge	MS-S-TL	Y	Y	N	N	N	N	N			
14	Sink	Kitchen wash station	MS-S1-WS	Y	Y	N	N	N	N	N			
15	Sink	Kitchen wash station	MS-S2-WS	Y	Y	N	N	N	N	N			
16	Sink	Kitchen Long Table Right	MS-S3-LTR	Y	Y	N	N	N	N	N			
17	Sink	Kitchen Long Table Left	MS-S4-LTL	Y	Y	N	N	N	N	N			
18	Pot Filler	Kitchen	MS-PF1-K	Y	Y	N	N	N	N	N			previously tested posi
19	Pot Filler	Kitchen	MS-PF2-K	Y	Y	N	N	N	N	N			
20	Ice Machine	Kitchen	MS-IM-K	Y	Y	N	N	N	N	N			
21	Sink	Kitchen	MS-S5-K	Y	Y	N	N	N	N	N			Back wall
22	Sink	Kitchen	MS-S6-K	Y	Y	N	N	N	N	N			By Office
23	Sink	kitchen Dish wash	MS-S7-K	Y	Y	Y	N	N	N	N			
24	Sink	Kitchen Service Area left	MS-S8-K	Y	Y	Y	N	N	N	N			
25	Sink	Kitchen Service Are Center	MS-S9-K	Y	Y	Y	N	N	N	N			
26	Sink	Kitchen Service Area Right	MS-S10-K	Y	Y	Y	N	N	N	N			
27	Sink	Kitchen	MS-S11-K	Y	Y	Y	N	N	N	N			Sprayer Not being used
28	Sink	Snack Shack	MS-S-SS	Y	Y	N	N	N	N	N			
29	Water Cooler	Gym Hall by Girls left	MS-WFL-GHG	Y	Y	N	N	N	N	N			
30	Water Cooler	Gym Hall by Girls right	MS-WFR-GHG	Y	Y	N	N	N	N	N			
31	Water Cooler	Gym Hall by Boys Left	MS-WFL-GHG	Y	Y	N	N	N	N	N			

32	Water Cooler	Gym Hall by Boys Right	MS-WFR-GHG	Y	Y	N	N	N	N	N			
33	Sink	Nurse Exam	MS-S1-NO	Y	Y	N	N	N	N	N			
34	Ice Machine	Nurse Office	MS-IM-NO	Y	Y	N	N	N	N	N			
35	Sink	Nurse Office	MS-S2-NO	Y	Y	Y	N	N	N	N			
36	Sink	Room 148	MS-S-148	Y	Y	Y	N	N	N	N			
37	Sink	Room 134	MS-S-134	Y	Y	Y	N	N	N	N			
38	Sink	Library	MS-S-Lib	Y	Y	Y	N	N	N	N			
39	Water Cooler	Outside Library	MS-WFL-Lib	Y	Y	Y	N	N	N	N			
40	Water Cooler	Outside Library	MS-WCC-Lib	Y	Y	N	N	N	N	N			
41	Water Cooler	Outside Library	MS-WCR-Lib	Y	Y	N	N	N	N	N			
42	Water Cooler	Outside Library	MS-BF-Lib	Y	Y	N	N	N	N	N			
43	Sink	Main Office 145	MS-S-145	Y	Y	N	N	N	N	N			
44	Sink	Main Office 149	MS-S -149	Y	Y	N	N	N	N	N			
45	Sink	Room 151	MS-S-151	Y	Y	N	N	N	N	N			
46	Water Cooler	Hall at C133	MS-WCC-C133	Y	Y	N	N	N	N	N			
47	Water Cooler	Hall at C133	MS-WCR-C133	Y	Y	Y	N	N	N	N			
48	Water Cooler	Hall at C133	MS-WCL-C133	Y	Y	Y	N	N	N	N			
49	Sink	Room C125	MS-S-C125	Y	Y	Y	N	N	N	N			
50	Water Cooler	Hall by D121 Right	MS-WCR-D121	Y	Y	Y	N	N	N	N			

51	Water Cooler	Hall by D121 center	MS-WCC-D121	Y	Y	Y	N	N	N	N			
52	Water Cooler	Hall by D121 Left	MS-WCL-D121	Y	Y	N	N	N	N	N			
53	Sink	Room 133	MS-S-133	Y	Y	N	N	N	N	N			
54	Ice Machine	Room D117	MS-S-D117	Y	Y	N	N	N	N	N			
55	Water Cooler	Hall at D108 left	MS-WCL-D108	Y	Y	N	N	N	N	N			
56	Water Cooler	Hall at D108 Center	MS-WCC-D108	Y	Y	N	N	N	N	N			
57	Water Cooler	Hall at D108 Right	MS-WCR-D108	Y	Y	N	N	N	N	N			
58	Water Cooler	Hall by C111 left	MS-WCL-C111	Y	Y	N	N	N	N	N			
59	Water Cooler	Hall by C111 Center	MS-WCC-C111	Y	Y	Y	N	N	N	N			
60	Water Cooler	Hall by C111 Right	MS-WCR-C111	Y	Y	Y	N	N	N	N			
61	Water Cooler	Hall by E130 Left	MS-WCL-E130	Y	Y	Y	N	N	N	N			
62	Water Cooler	Hall by E130 Center	MS-WCC-E130	Y	Y	Y	N	N	N	N			
63	Water Cooler	Hall by E130 Right	MS-WCR-E130	Y	Y	Y	N	N	N	N			
64	Water Cooler	Hall by E110 Left	MS-WCL-E110	Y	Y	N	N	N	N	N			
65	Water Cooler	Hall by E110 Center	MS-WCC-E110	Y	Y	N	N	N	N	N			
66	Water Cooler	Hall by E110 Right	MS-WCR-E110	Y	Y	N	N	N	N	N			
67	Sink	E134 Prep Rm	MS-S-E134	Y	Y	N	N	N	N	N			
68	Water Cooler	Hall by F121 Left	MS-WCL-F121	Y	Y	N	N	N	N	N			
69	Water Cooler	Hall by F121 Center	MS-WCC-F121	Y	Y	N	N	N	N	N			

70	Water Cooler	Hall by F121 Right	MS-WCR-F121	Y	Y	N	N	N	N	N			
71	Sink	Room E120	MS-S-E120	Y	Y	Y	N	N	N	N			
72	Bottle Fill	Hall by E130	MS-BF-E130	Y	Y	Y	N	N	N	N			
73	Water Cooler	Hall by F109 left	MS-WCL-F109	Y	Y	Y	N	N	N	N			
74	Water Cooler	Hall by F109 Center	MS-WCC-F109	Y	Y	Y	N	N	N	N			
75	Water Cooler	Hall by F109 Right	MS-WCR-F109	Y	Y	Y	N	N	N	N			
76	Sink	Room F133	MS-S-F133	Y	Y	Y	N	N	N	N			
77	Sink	Room F113	MS-S-F113	Y	Y	Y	N	N	N	N			

Appendix F Laboratory Data

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 25-05-00122

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 05/01/2025
Reported Date: 05/12/2025
Sampled By: Erick Ulloa
Tech Certification #:

Project/Test Address: 1619; Sandshore; 498 Sandshore Road; Budd Lake, NJ 07828

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-05-00122-001	SS-S1-WS	04/26/2025	KITCHEN SINK	43.0	05/08/2025	
25-05-00122-002	SS-S2-WS	04/26/2025	KITCHEN SINK	3.52	05/08/2025	
25-05-00122-003	SS-S3-K	04/26/2025	KITCHEN SINK	1.90	05/08/2025	
25-05-00122-004	SS-WF-CAF	04/26/2025	CAFETERIA WATER COOLER	<1.00	05/08/2025	
25-05-00122-005	SS-BF-CAF	04/26/2025	CAFETERIA BOTTLE FILLER	<1.00	05/08/2025	
25-05-00122-006	SS-S2-NO	04/26/2025	NURSE OFFICE SINK	2.11	05/08/2025	
25-05-00122-007	SS-WC-NO	04/26/2025	NURSE OFFICE WATER COOLER	<1.00	05/08/2025	
25-05-00122-008	SS-WF-FAC	04/26/2025	FACULTY HALLWAY WATTER COOLER	<1.00	05/08/2025	
25-05-00122-009	SS-BF-FAC	04/26/2025	FACULTY HALLWAY BOTTLE FILLER	<1.00	05/08/2025	
25-05-00122-010	SS-S-FAC	04/26/2025	FACULTY SINK	1.27	05/08/2025	
25-05-00122-011	SS-WF-118	04/26/2025	HALL AT 118 WATER COOLER	<1.00	05/08/2025	
25-05-00122-012	SS-BF-118	04/26/2025	HALL AT 118 BOTTLE FILLER	<1.00	05/08/2025	
25-05-00122-013	SS-S-113	04/26/2025	RM 113 SINK	13.3	05/08/2025	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 25-05-00122

Project/Test Address: 1619; Sandshore; 498 Sandshore Road; Budd Lake, NJ 07828

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-05-00122-014	SS-WF-123	04/26/2025	HALL AT 123 WATER COOLER	<1.00	05/08/2025	
25-05-00122-015	SS-BF-123	04/26/2025	HALL AT 123 BOTTLE FILLER	<1.00	05/08/2025	
25-05-00122-016	SS-SB-105	04/26/2025	RM 105 BUBBLER	1.84	05/09/2025	
25-05-00122-017	SS-SB-106	04/26/2025	RM 106 BUBBLER	2.05	05/09/2025	
25-05-00122-018	SS-SB-103	04/26/2025	RM 103 BUBBLER	1.46	05/09/2025	
25-05-00122-019	SS-SB-102	04/26/2025	RM 102 BUBBLER	3.49	05/08/2025	
25-05-00122-020	SS-SB-169	04/26/2025	RM 169 BUBBLER	<1.00	05/08/2025	
25-05-00122-021	SS-WF-169	04/26/2025	HALL AT 169 WATER COOLER	<1.00	05/08/2025	
25-05-00122-022	SS-BF-169	04/26/2025	HALL AT 168 BOTTLE FILLER	<1.00	05/08/2025	
25-05-00122-023	SS-SB-179	04/26/2025	RM 179 BUBBLER	5.81	05/08/2025	
25-05-00122-024	SS-S-182	04/26/2025	RM 182 SINK	2.53	05/08/2025	
25-05-00122-025	SS-SB-183	04/26/2025	RM 183 BUBBLER	5.12	05/08/2025	
25-05-00122-026	SS-SB-184	04/26/2025	RM 184 BUBBLER	1.89	05/08/2025	
25-05-00122-027	SS-WF-184	04/26/2025	HALL AT 184 WATER COOLER	<1.00	05/08/2025	
25-05-00122-028	SS-BF-184	04/26/2025	HALL AT 184 BOTTLE FILLER	<1.00	05/08/2025	
25-05-00122-029	SS-SB-190	04/26/2025	RM 190 BUBBLER	6.12	05/08/2025	
25-05-00122-030	SS-SB-191	04/26/2025	RM 191 BUBBLER	3.18	05/08/2025	
25-05-00122-031	SS-SB-192	04/26/2025	RM 192 BUBBLER	7.86	05/08/2025	
25-05-00122-032	SS-SB-193	04/26/2025	RM 193 BUBBLER	13.0	05/08/2025	
25-05-00122-033	SS-SB-194	04/26/2025	RM 194 BUBBLER	4.42	05/08/2025	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 25-05-00122

Project/Test Address: 1619; Sandshore; 498 Sandshore Road; Budd Lake, NJ 07828

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-05-00122-034	SS-SB-197	04/26/2025	RM 197 BUBBLER	7.46	05/08/2025	
25-05-00122-035	SS-SR	04/26/2025	SUNROOM	<1.00	05/08/2025	

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

25-05-00122

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

Due Date:
05/08/2025
(Thursday)
AE

Client Name: LEW CORP Account #: 201327

Address: 181 US HIGHWAY 46

City/State/Zip: MINE HILL, NJ 07803 Phone: 908-654-8068

Email Address: labresults@lewcorp.com

Project Name/ Number: 1619; SANDSHORE

Collection Address: 498 SANDSHORE ROAD (Required) City/State/Zip: BUDD LAKE, NJ 07828 (Required)

Approx. Age Of Property: _____ Collected By: ERICK ULLOA

Water Source: (Check One) Public X or Well _____ Well Tag # (if applicable): _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	SS-S1-WS	KITCHEN, SINK	04-26-2025	AM / PM	X	
2	SS-S2-WS	KITCHEN SINK		AM / PM	X	
3	SS-S3-K	KITCHEN SINK		AM / PM	X	
4	SS-WF-CAF	CAFETERIA WATER COOLER		AM / PM	X	
5	SS-BF-CAF	CAFETERIA BOTTLE FILLER		AM / PM	X	
6	SS-S2-NO	NURSE OFFICE SINK		AM / PM	X	
7	SS-WC-NO	NURSE OFFICE WATER COOLER		AM / PM	X	
8	SS-WF-FAC	FACULTY HALLWAY WATER COOLER		AM / PM	X	
9	SS-BF-FAC	FACULTY HALLWAY BOTTLE FILLER		AM / PM	X	
10	SS-S-FAC	FACULTY SINK		AM / PM	X	
11	SS-WF-118	HALL AT 118 WATER COOLER		AM / PM	X	
12	SS-BF-118	HALL AT 118 BOTTLE FILLER		AM / PM	X	
13	SS-S-113	RM 113 SINK		AM / PM	X	
14	SS-WF-123	HALL AT 123 WATER COOLER		AM / PM	X	
15	SS-BF-123	HALL AT 123 BOTTLE FILLER		AM / PM	X	

Released by: ERICK ULLOA Signature: [signature] Date/Time: 04-26-25

Received by: Johnathan McElroy Signature: Johnathan McElroy Date/Time: 5/1/25 12:15PM

Client Name: LEW CORP Account #201327 Page 2 of 2

Project Name: 1619

Lab I.D. #: ____-____-0012

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
16	SS-SB-105	RM 105 BUBBLER		AM / PM	X	
17	SS-SB-106	RM 106 BUBBLER		AM / PM	X	
18	SS-SB-103	RM 103 BUBBLER		AM / PM	X	
19	SS-SB-102	RM 102 BUBBLER		AM / PM	X	
20	SS-SB-169	RM 169 BUBBLER		AM / PM	X	
21	SS-WF-169	HALL AT 169 WATER COOLER		AM / PM	X	
22	SS-BF-169	HALL AT 169 BOTTLE FILLER		AM / PM	X	
23	SS-SB-179	RM 179 BUBBLER		AM / PM	X	
24	SS-S-182	RM 182 SINK		AM / PM	X	
25	SS-SB-183	RM 183 BUBBLER		AM / PM	X	
26	SS-SB-184	RM 184 BUBBLER		AM / PM	X	
27	SS-WF-184	HALL AT 184 WATER COOLER		AM / PM	X	
28	SS-BF-184	HALL AT 184 BOTTLE FILLER		AM / PM	X	
29	SS-SB-190	RM 190 BUBBLER		AM / PM	X	
30	SS-SB-191	RM 191 BUBBLER		AM / PM	X	
31	SS-SB-192	RM 192 BUBBLER		AM / PM	X	
32	SS-SB-193	RM 193 BUBBLER		AM / PM	X	
33	SS-SB-194	RM 194 BUBBLER		AM / PM	X	
34	SS-SB-197	RM 197 BUBBLER		AM / PM	X	
35	SS-SR	SUNROOM		AM / PM	X	
36				AM / PM	X	
37				AM / PM	X	
38				AM / PM	X	
39				AM / PM	X	
40				AM / PM	X	
41				AM / PM	X	
42				AM / PM		
43				AM / PM		
44				AM / PM		
45				AM / PM		
46				AM / PM		
47				AM / PM		
48				AM / PM		
49				AM / PM		
50				AM / PM		

Released by: ERICK ULLOA Signature: Date/Time: 04-28-25

Received by: Johnathon McElroy Signature: Johnathon McElroy Date/Time: 5/1/25 12:15 PM

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 25-05-00132

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 05/01/2025
Reported Date: 05/09/2025
Sampled By: Erick Ulloa
Tech Certification #:

Project/Test Address: 1619; Chester; 99 Sunset Drive; Budd Lake, NJ 07828

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-05-00132-001	CMS-WC-C59L	04/26/2025	OUTSIDE C59 WATER COOLER	<1.00	05/09/2025	
25-05-00132-002	CMS-BF-C59L	04/26/2025	OUTSIDE C59 BOTTLE FILLER	<1.00	05/09/2025	
25-05-00132-003	CMS-WF-C59R	04/26/2025	OUTSIDE C59 WATER FOUNTAIN	<1.00	05/09/2025	
25-05-00132-004	CMS-BF-B27	04/26/2025	OUTSIDE B27 BOTTLE FILLER	<1.00	05/09/2025	
25-05-00132-005	CMS-WF-B27	04/26/2025	OUTSIDE B27 WATER FOUNTAIN	<1.00	05/09/2025	
25-05-00132-006	CMS-BF-D62	04/26/2025	OUTSIDE D62 BOTTLE FILLER	<1.00	05/09/2025	
25-05-00132-007	CMS-WF-D62	04/26/2025	OUTSIDE D62 WATER FOUNTAIN	<1.00	05/09/2025	
25-05-00132-008	CMS-S-TL	04/26/2025	TEACHERS LOUNGE SINK	12.5	05/09/2025	
25-05-00132-009	CMS-WF-D65	04/26/2025	OUTSIDE D65 WATER FOUNTAIN	<1.00	05/09/2025	
25-05-00132-010	CMS-BF-D65	04/26/2025	OUTSIDE D65 BOTTLE FILLER	<1.00	05/09/2025	
25-05-00132-011	CMS-WF-A23	04/26/2025	OUTSIDE A23 WATER FOUNTAIN	<1.00	05/09/2025	
25-05-00132-012	CMS-BF-A23	04/26/2025	OUTSIDE A23 BOTTLE FILLER	<1.00	05/09/2025	
25-05-00132-013	CMS-S-OK	04/26/2025	OFFICE KITCHEN SINK	9.94	05/09/2025	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 25-05-00132

Project/Test Address: 1619; Chester; 99 Sunset Drive; Budd Lake, NJ 07828

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-05-00132-014	CMS-S-NO	04/26/2025	NURSE OFFICE SINK	19.3	05/09/2025	
25-05-00132-015	CMS-WC-NO	04/26/2025	NURSE OFFICE WATER COOLER	<1.00	05/09/2025	
25-05-00132-016	CMS-WF-CAF	04/26/2025	CAFETERIA WATER FOUNTAIN	<1.00	05/09/2025	
25-05-00132-017	CMS-BF-CAF	04/26/2025	CAFETERIA BOTTLE FILLER	<1.00	05/09/2025	
25-05-00132-018	CMS-S1-K	04/26/2025	KITCHEN SINK	1.80	05/09/2025	
25-05-00132-019	CMS-S2-K	04/26/2025	KITCHEN SINK	8.68	05/09/2025	
25-05-00132-020	CMS-S3-K	04/26/2025	KITCHEN SINK	11.1	05/09/2025	
25-05-00132-021	CMS-S4-K	04/26/2025	KITCHEN SINK	29.6	05/09/2025	
25-05-00132-022	CMS-SR	04/26/2025	SUNROOM	<1.00	05/09/2025	

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

25-05-00132

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Due Date:
05/08/2025
(Thursday)
AE

Client Name: LEW CORP Account #: 201327

Address: 181 US HIGHWAY 46

City/State/Zip: MINE HILL, NJ 07803 Phone: 908-654-8068

Email Address: labresults@lewcorp.com

Project Name/ Number : 1619 ; CHESTER

Collection Address: 99 SUNSET DRIVE (Required) City/State/Zip: BUDD LAKE, NJ 07828 (Required)

Approx. Age Of Property: _____ Collected By: ERICK ULLOA

Water Source: (Check One) Public X or Well _____ Well Tag # (if applicable): _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	CMS-WC-C59L	OUTSIDE C59 WATER COOLER	04-26-2025	AM / PM	X	
2	CMS-BF-C59L	OUTSIDE C59 BOTTLE FILLER		AM / PM	X	
3	CMS-WF-C59R	OUTSIDE C59 WATER FOUNTAIN		AM / PM	X	
4	CMS-BF-B27	OUTSIDE B27 BOTTLE FILLER		AM / PM	X	
5	CMS-WF-B27	OUTSIDE B27 WATER FOUNTAIN		AM / PM	X	
6	CMS-BF-D62	OUTSIDE D62 BOTTLE FILLER		AM / PM	X	
7	CMS-WF-D62	OUTSIDE D62 WATER FOUNTAIN		AM / PM	X	
8	CMS-S-TL	TEACHERS LOUNGE SINK		AM / PM	X	
9	CMS-WF-D65	OUTSIDE D65 WATER FOUNTAIN		AM / PM	X	
10	CMS-BF-D65	OUTSIDE D65 BOTTLE FILLER		AM / PM	X	
11	CMS-WF-A23	OUTSIDE A23 WATER FOUNTAIN		AM / PM	X	
12	CMS-BF-A23	OUTSIDE A23 BOTTLE FILLER		AM / PM	X	
13	CMS-S-OK	OFFICE KITCHEN SINK		AM / PM	X	
14	CMS-S-NO	NURSE OFFICE SINK		AM / PM	X	
15	CMS-WC-NO	NURSE OFFICE WATER COOLER		AM / PM	X	

Released by: ERICK ULLOA Signature: _____ Date/Time: 04-26-25

Received by: Johnathan McElroy Signature: _____ Date/Time: 5/1/25 12:27 PM

Client Name: LEW CORP Account #201327 Page 2 of 2

Project Name: 1619

Lab I.D. #: ____-____-00132

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
16	CMS-WF-CAF	CAFETERIA WATER FOUNTAIN		AM / PM	X	
17	CMS-BF-CAF	CAFETERIA BOTTLE FILLER		AM / PM	X	
18	CMS-S1-K	KITCHEN SINK		AM / PM	X	
19	CMS-S2-K	KITCHEN SINK		AM / PM	X	
20	CMS-S3-K	KITCHEN SINK		AM / PM	X	
21	CMS-S4-K	KITCHEN SINK		AM / PM	X	
22	CMS - S12	SUNROOM		AM / PM	X	
23				AM / PM	X	
24				AM / PM	X	
25				AM / PM	X	
26				AM / PM	X	
27				AM / PM	X	
28				AM / PM	X	
29				AM / PM	X	
30				AM / PM	X	
31				AM / PM	X	
32				AM / PM	X	
33				AM / PM	X	
34				AM / PM	X	
35				AM / PM	X	
36				AM / PM	X	
37				AM / PM	X	
38				AM / PM	X	
39				AM / PM	X	
40				AM / PM	X	
41				AM / PM	X	
42				AM / PM		
43				AM / PM		
44				AM / PM		
45				AM / PM		
46				AM / PM		
47				AM / PM		
48				AM / PM		
49				AM / PM		
50				AM / PM		

Released by: ERICK ULLOA	Signature:	Date/Time: 04-26-25
Received by: Johnathan McElroy	Signature:	Date/Time: 5/1/25 12:27 pm

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 25-05-00230

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 05/01/2025
Reported Date: 05/08/2025
Sampled By: Erick Ulloa
Tech Certification #:

Project/Test Address: 1619; Tinc; 24 Tinc Rd; Flanders, NJ 07836

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-05-00230-001	TR-S1-K	04/26/2025	KITCHEN SINK	2.99	05/07/2025	
25-05-00230-002	TR-S2-K	04/26/2025	KITCHEN SINK	4.12	05/07/2025	
25-05-00230-003	TR-WF-KH	04/26/2025	KINDER HALL WATER FOUNTAIN	<1.00	05/07/2025	
25-05-00230-004	TR-BF-KH	04/26/2025	KINDER HALL BOTTLE FILLER	<1.00	05/07/2025	
25-05-00230-005	TR-WF-ME	04/26/2025	MAIN ENTRANCE WATER FOUNTAIN	<1.00	05/07/2025	
25-05-00230-006	TR-BF-ME	04/26/2025	MAIN ENTRANCE BOTTLE FILLER	<1.00	05/07/2025	
25-05-00230-007	TR-S-TL	04/26/2025	TEACHERS LOUNGE SINK	30.5	05/07/2025	
25-05-00230-008	TR-S-NO	04/26/2025	NURSE OFFICE SINK	6.56	05/07/2025	
25-05-00230-009	TR-WF-126	04/26/2025	ACROSS FROM 126 WATER FOUNTAIN	<1.00	05/07/2025	
25-05-00230-010	TR-BF-126	04/26/2025	ACROSS FROM 126 BOTTLE FILLER	<1.00	05/07/2025	
25-05-00230-011	TR-WF-B5	04/26/2025	BY DOOR B5 WATER FOUNTAIN	<1.00	05/07/2025	
25-05-00230-012	TR-BF-B5	04/26/2025	BY DOOR B5 BOTTLE FILLER	<1.00	05/07/2025	
25-05-00230-013	TR-WF-149	04/26/2025	BY RM 149 WATER FOUNTAIN	<1.00	05/07/2025	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 25-05-00230

Project/Test Address: 1619; Tinc; 24 Tinc Rd; Flanders, NJ 07836

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-05-00230-014	TR-BF-149	04/26/2025	BY RM 149 BOTTLE FILLER	<1.00	05/07/2025	
25-05-00230-015	TR-SR	04/26/2025	SUNROOM	<1.00	05/07/2025	

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

25-05-00230

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Due Date:
05/08/2025
(Thursday)
AE

Client Name: LEW CORP Account #: 201327

Address: 181 US HIGHWAY 46

City/State/Zip: MINE HILL, NJ 07803 Phone: 908-654-8068

Email Address: labresults@lewcorp.com

Project Name/ Number : 1619; TINC

Collection Address: 24 TINC RD (Required) City/State/Zip: FLANDERS, NJ 07836 (Required)

Approx. Age Of Property: _____ Collected By: ERICK ULLOA

Water Source: (Check One) Public X or Well _____ Well Tag # (if applicable): _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	TR-S1-K	KITCHEN SINK	04-26-2025	AM / PM	X	
2	TR-S2-K	KITCHEN SINK		AM / PM	X	
3	TR-WF-KH	KINDER HALL WATER FOUNTAIN		AM / PM	X	
4	TR-BF-KH	KINDER HALL BOTTLE FILLER		AM / PM	X	
5	TR-WF-ME	MAIN ENTRANCE WATER FOUNTAIN		AM / PM	X	
6	TR-BF-ME	MAIN ENTRANCE BOTTLE FILLER		AM / PM	X	
7	TR-S-TL	TEACHERS LOUNGE SINK		AM / PM	X	
8	TR-S-NO	NURSE OFFICE SINK		AM / PM	X	
9	TR-WF-126	ACROSS FROM 126 WATER FOUNTAIN	Sample bottle labeled "TR-WF-149" (DB) 5/1	AM / PM	X	
10	TR-BF-126	ACROSS FROM 126 BOTTLE FILLER		AM / PM	X	
11	TR-WF-B5	BY DOOR B5 WATER FOUNTAIN		AM / PM	X	
12	TR-BF-B5	BY DOOR B5 BOTTLE FILLER		AM / PM	X	
13	TR-WF-149	BY RM 149 WATER FOUNTAIN		AM / PM	X	
14	TR-BF-149	BY RM 149 BOTTLE FILLER		AM / PM	X	
15	TR-SR	SUNROOM		AM / PM	X	

Released by: ERICK ULLOA Signature: [signature] Date/Time: 04-26-25

Received by: Johnathan McElroy Signature: Johnathan McElroy Date/Time: 05-1-25 3:05 PM

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 25-05-00233

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 05/01/2025
Reported Date: 05/12/2025
Sampled By: Erick Ulloa
Tech Certification #:

Project/Test Address: 1619; Mt View; 118 Cloverhill Road; Flanders, NJ 07836

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-05-00233-001	MV-S1L-K	04/26/2025	KITCHEN SINK	11.2	05/08/2025	
25-05-00233-002	MV-S1R-K	04/26/2025	KITCHEN SINK	7.39	05/08/2025	
25-05-00233-003	MV-S-FR	04/26/2025	FACULTY RM SINK	1.75	05/08/2025	
25-05-00233-004	MV-WF-FR	04/26/2025	OUTSIDE FACULTY RM WATER FOUNTAIN	<1.00	05/08/2025	
25-05-00233-005	MV-BF-FR	04/26/2025	OUTSIDE FACULTY RM BOTTLE FILLER	<1.00	05/08/2025	
25-05-00233-006	MV-WF-AR	04/26/2025	OUTSIDE ART RM WATER FOUNTAIN	<1.00	05/08/2025	
25-05-00233-007	MV-BF-AR	04/26/2025	OUTSIDE ART RM BOTTLE FILLER	<1.00	05/08/2025	
25-05-00233-008	MV-WF-MR	04/26/2025	BY DOOR 13 WATER FOUNTAIN	<1.00	05/08/2025	
25-05-00233-009	MV-BF-MR	04/26/2025	BY DOOR 13 BOTTLE FILLER	<1.00	05/08/2025	
25-05-00233-010	MV-WF-RM112	04/26/2025	OUTSIDE RM 112 WATER FOUNTAIN	<1.00	05/08/2025	
25-05-00233-011	MV-BF-RM112	04/26/2025	OUTSIDE RM 112 BOTTLE FILLER	<1.00	05/08/2025	
25-05-00233-012	MV-WF-FO	04/26/2025	FRONT OFFICE WATER FOUNTAIN	<1.00	05/08/2025	
25-05-00233-013	MV-BF-FO	04/26/2025	FRONT OFFICE BOTTLE FILLER	<1.00	05/08/2025	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 25-05-00233

Project/Test Address: 1619; Mt View; 118 Cloverhill Road; Flanders, NJ 07836

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-05-00233-014	MV-S1-NO	04/26/2025	NURSE OFFICE SINK	2.63	05/08/2025	
25-05-00233-015	MV-S2-NO	04/26/2025	NURSE BATHROOM SINK	8.86	05/08/2025	
25-05-00233-016	MV-S3-NO	04/26/2025	NURSE EXAM RM SINK	55.5	05/09/2025	
25-05-00233-017	MV-WF-LIB	04/26/2025	LIBRARY WATER FOUNTAIN	<1.00	05/08/2025	
25-05-00233-018	MV-BF-LIB	04/26/2025	LIBRARY BOTTLE FILLER	<1.00	05/08/2025	
25-05-00233-019	MV-SR	04/26/2025	SUNROOM	<1.00	05/09/2025	

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

25-05-00233

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Due Date:
05/08/2025
(Thursday)
AE

Client Name: LEW CORP Account #: 201327

Address: 181 US HIGHWAY 46

City/State/Zip: MINE HILL, NJ 07803 Phone: 908-654-8068

Email Address: labresults@lewcorp.com

Project Name/ Number : 1619; MT VIEW

Collection Address: 118 CLOVERHILL ROAD (Required) City/State/Zip: FLANDERS, NJ 07836 (Required)

Approx. Age Of Property: _____ Collected By: ERICK ULLOA

Water Source: (Check One) Public X or Well _____ Well Tag # (if applicable): _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	MV-S1L-K	KITCHEN SINK	04-26-2025	AM / PM	X	
2	MV-S1R-K	KITCHEN SINK		AM / PM	X	
3	MV-S-FR	FACULTY RM SINK		AM / PM	X	
4	MV-WF-FR	OUTSIDE FACULTY RM WATER FOUNTAIN		AM / PM	X	
5	MV-BF-FR	OUTSIDE FACULTY RM BOTTLE FILLER		AM / PM	X	
6	MV-WF-AR	OUTSIDE ART RM WATER FOUNTAIN		AM / PM	X	
7	MV-BF-AR	OUTSIDE ART RM BOTTLE FILLER		AM / PM	X	
8	MV-WF-MR	BY DOOR 13 WATER FOUNTAIN		AM / PM	X	
9	MV-BF-MR	BY DOOR 13 BOTTLE FILLER		AM / PM	X	
10	MV-WF-RM112	OUTSIDE RM 112 WATER FOUNTAIN		AM / PM	X	
11	MV-BF-RM112	OUTSIDE RM 112 BOTTLE FILLER		AM / PM	X	
12	MV-WF-FO	FRONT OFFICE WATER FOUNTAIN		AM / PM	X	
13	MV-BF-FO	FRONT OFFICE BOTTLE FILLER		AM / PM	X	
14	MV-S1-NO	NURSE OFFICE SINK		AM / PM	X	
15	MV-S2-NO	NURSE BATHROOM SINK		AM / PM	X	

Released by: ERICK ULLOA Signature: [signature] Date/Time: 04-26-25

Received by: Johnathan McElroy Signature: [signature] Date/Time: 05-1-25 3:10 PM

Client Name: LEW CORP Account #201327 Page 2 of 2

Project Name: 1619

Lab I.D. #: _____-_____-00233

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
16	MV-S3-NO	NURSE EXAM RM SINK		AM / PM	X	
17	MV-WF-LIB	LIBRARY WATER FOUNTAIN		AM / PM	X	
18	MV-BF-LIB	LIBRARY BOTTLE FILLER		AM / PM	X	
19	MV-SR	SUNROOM		AM / PM	X	
20				AM / PM	X	
21				AM / PM	X	
22				AM / PM	X	
23				AM / PM	X	
24				AM / PM	X	
25				AM / PM	X	
26				AM / PM	X	
27				AM / PM	X	
28				AM / PM	X	
29				AM / PM	X	
30				AM / PM	X	
31				AM / PM	X	
32				AM / PM	X	
33				AM / PM	X	
34				AM / PM	X	
35				AM / PM	X	
36				AM / PM	X	
37				AM / PM	X	
38				AM / PM	X	
39				AM / PM	X	
40				AM / PM	X	
41				AM / PM	X	
42				AM / PM		
43				AM / PM		
44				AM / PM		
45				AM / PM		
46				AM / PM		
47				AM / PM		
48				AM / PM		
49				AM / PM		
50				AM / PM		

Released by: ERICK ULLOA	Signature:	Date/Time: 04-26-25
Received by: Johnathan Mely	Signature:	Date/Time: 05-1-25 3:10 PM

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 25-06-01429

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 06/09/2025
Reported Date: 06/16/2025
Sampled By: Erick Ulloa
Tech Certification #:

Project/Test Address: 1619; Mount Olive High School; 18 Corey Rd; Flanders, NJ 07836

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-06-01429-001	HS-S-B07	05/02/2025	RM B07 SINK	7.79	06/12/2025	
25-06-01429-002	HS-WF-B29	05/02/2025	HALL AT B29 WATER COOLER	<1.00	06/12/2025	
25-06-01429-003	HS-BF-B29	05/02/2025	HALL AT B29 BOTTLE FILLER	<1.00	06/12/2025	
25-06-01429-004	HS-S-B29	05/02/2025	RM B29 SINK	5.64	06/12/2025	
25-06-01429-005	HS-S-B34	05/02/2025	RM B34 SINK	3.66	06/12/2025	
25-06-01429-006	HS-S1-HE	05/02/2025	B37 SINK	10.1	06/12/2025	
25-06-01429-007	HS-S2-HE	05/02/2025	B37 SINK	2.75	06/12/2025	
25-06-01429-008	HS-S3-HE	05/02/2025	B37 SINK	3.85	06/12/2025	
25-06-01429-009	HS-S4-HE	05/02/2025	B37 SINK	3.36	06/12/2025	
25-06-01429-010	HS-S5-HE	05/02/2025	B37 SINK	3.14	06/12/2025	
25-06-01429-011	HS-S6-HE	05/02/2025	B37 SINK	2.48	06/12/2025	
25-06-01429-012	HS-S7-HE	05/02/2025	B37 SINK	14.8	06/12/2025	
25-06-01429-013	HS-WF-D17	05/02/2025	HALL AT D17 WATER COOLER	<1.00	06/12/2025	

Client Number: 201327 Report Number: 25-06-01429

Project/Test Address: 1619; Mount Olive High School; 18 Corey Rd; Flanders, NJ 07836

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-06-01429-014	HS-BF-D17	05/02/2025	HALL AT D17 BOTTLE FILLER	<1.00	06/12/2025	
25-06-01429-015	HS-WF-MS	05/02/2025	MAKER SPACE WATER COOLER	<1.00	06/12/2025	
25-06-01429-016	HS-S1-MS	05/02/2025	MAKER SPACE SINK	2.86	06/12/2025	
25-06-01429-017	HS-S2-MS	05/02/2025	MAKER SPACE SINK	5.46	06/12/2025	
25-06-01429-018	HS-WF-C106	05/02/2025	HALL AT C106 WATER COOLER	<1.00	06/12/2025	
25-06-01429-019	HS-BF-C106	05/02/2025	HALL AT C106 BOTTLE FILLER	<1.00	06/12/2025	
25-06-01429-020	HS-S1-SA	05/02/2025	KITCHEN SERVING AREA SINK	6.43	06/12/2025	
25-06-01429-021	HS-S2-FPR	05/02/2025	KITCHEN FOOD PREP SINK	6.06	06/12/2025	
25-06-01429-022	HS-S4-FPK	05/02/2025	KITCHEN FOOD PREP SINK	10.8	06/12/2025	
25-06-01429-023	HS-PF-K	05/02/2025	KITCHEN POT FILLER	14.7	06/12/2025	
25-06-01429-024	HS-IM-K	05/02/2025	KITCHEN ICE MACHINE	<1.00	06/12/2025	
25-06-01429-025	HS-S-CR	05/02/2025	COFFEE ROOM SINK	6.99	06/12/2025	
25-06-01429-026	HS-S-SA	05/02/2025	SNACK BAR LEFT SINK	49.0	06/13/2025	
25-06-01429-027	HS-WF-B115	05/02/2025	HALL AT B115 WATER COOLER	<1.00	06/12/2025	
25-06-01429-028	HS-BF-B115	05/02/2025	HALL AT B115 BOTTLE FILLER	<1.00	06/12/2025	
25-06-01429-029	HS-S1-NO	05/02/2025	NURSE OFFICE SINK	2.79	06/12/2025	
25-06-01429-030	HS-WF-CA	05/02/2025	HALL AT COM AREA WATER COOLER	<1.00	06/12/2025	
25-06-01429-031	HS-BF-CA	05/02/2025	HALL AT COM AREA BOTTLE FILLER	<1.00	06/12/2025	
25-06-01429-032	HS-WC-GEL	05/02/2025	GYM ENTRANCE LOBBY WATER COOLER	<1.00	06/12/2025	
25-06-01429-033	HS-BF-GEL	05/02/2025	GYM ENTRANCE BOTTLE FILLER	<1.00	06/12/2025	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 25-06-01429

Project/Test Address: 1619; Mount Olive High School; 18 Corey Rd; Flanders, NJ 07836

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-06-01429-034	HS-WF-G125	05/02/2025	HALL BY G125 WATER COOLER	<1.00	06/12/2025	
25-06-01429-035	HS-BF-G125	05/02/2025	HALL BY G125 BOTTLE FILLER	<1.00	06/12/2025	
25-06-01429-036	HS-S1-G126	05/02/2025	RM G126 SINK	8.50	06/12/2025	
25-06-01429-037	HS-IM-G126	05/02/2025	RM G126 ICE MACHINE	1.22	06/13/2025	
25-06-01429-038	HS-WF-AB	05/02/2025	AUX GYM BOYS BATH WATER COOLER	<1.00	06/12/2025	
25-06-01429-039	HS-BF-AB	05/02/2025	AUX GYM BOYS BATH BOTTLE FILLER	<1.00	06/12/2025	
25-06-01429-040	HS-WF-AG	05/02/2025	AUX GYM GIRLS BATH WATER COOLER	<1.00	06/12/2025	
25-06-01429-041	HS-BF-AG	05/02/2025	AUX GYM GIRLS BATH BOTTLE FILLER	<1.00	06/12/2025	
25-06-01429-042	HS-WF-D115	05/02/2025	HALL BY D115 WATER COOLER	<1.00	06/12/2025	
25-06-01429-043	HS-BF-D115	05/02/2025	HALL BY D115 BOTTLE FILLER	<1.00	06/12/2025	
25-06-01429-044	HS-WF-B209	05/02/2025	B209 WATER COOLER	<1.00	06/12/2025	
25-06-01429-045	HS-BF-B209	05/02/2025	B209 BOTTLE FILLER	<1.00	06/12/2025	
25-06-01429-046	HS-S-B235	05/02/2025	B235 FACULT SINK	6.75	06/12/2025	
25-06-01429-047	HS-WF-B236	05/02/2025	HALL BY B236 WATER COOLER	<1.00	06/12/2025	
25-06-01429-048	HS-BF-B236	05/02/2025	HALL BY B236 BOTTLE FILLER	<1.00	06/12/2025	
25-06-01429-049	HS-WF-D204	05/02/2025	HALL BY D204 WATER COOLER	<1.00	06/12/2025	
25-06-01429-050	HS-BF-D204	05/02/2025	HALL BY D204 BOTTLE FILLER	<1.00	06/12/2025	
25-06-01429-051	HS-WF-B315	05/02/2025	HALL BY B315 WATER COOLER	<1.00	06/12/2025	
25-06-01429-052	HS-BF-B315	05/02/2025	HALL BY B315 BOTTLE FILLER	<1.00	06/12/2025	
25-06-01429-053	HS-WC-NO	05/02/2025	NURSE OFFICE WATER COOLER	<1.00	06/12/2025	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 25-06-01429

Project/Test Address: 1619; Mount Olive High School; 18 Corey Rd; Flanders, NJ 07836

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-06-01429-054	HS-SR	05/02/2025		<1.00	06/12/2025	

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

25-06-01429

Due Date:
06/16/2025
(Monday)
AE

10F

Client Name: LEW CORP Account #: 201327

Address: 181 US HIGHWAY 46

City/State/Zip: MINE HILL, NJ 07803 Phone: 908-654-8068

Email Address: labresults@lewcorp.com

Project Name/ Number : 1619; MOUNT OLIVE HIGH SCHOOL

Collection Address: 18 COREY RD (Required) City/State/Zip: FLANDERS, NJ 07836 (Required)

Approx. Age Of Property: _____ Collected By: ERICK ULLOA

Water Source: (Check One) Public X or Well _____ Well Tag # (if applicable): _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	HS-S-B07	RM B07 SINK	05-02-2025	AM / PM	X	
2	HS-WF-B29	HALL AT B29 WATER COOLER		AM / PM	X	
3	HS-BF-B29	HALL AT B29 BOTTLE FILLER		AM / PM	X	
4	HS-S-B29	RM B29 SINK		AM / PM	X	
5	HS-S-B34	RM B34 SINK		AM / PM	X	
6	HS-S1-HE	B37 SINK		AM / PM	X	
7	HS-S2-HE	B37 SINK		AM / PM	X	
8	HS-S3-HE	B37 SINK		AM / PM	X	
9	HS-S4-HE	B37 SINK		AM / PM	X	
10	HS-S5-HE	B37 SINK		AM / PM	X	
11	HS-S6-HE	B37 SINK		AM / PM	X	
12	HS-S7-HE	B37 SINK		AM / PM	X	
13	HS-WF-D17	HALL AT D17 WATER COOLER		AM / PM	X	
14	HS-BF-D17	HALL AT D17 BOTTLE FILLER		AM / PM	X	
15	HS-WF-MS	MAKER SPACE WATER COOLER		AM / PM	X	

Released by: ERICK ULLOA	Signature:	Date/Time: 05-02-25
Received by:	Signature:	Date/Time: 6/3/25 1350

Client Name: LEW CORP Account #201327 Page ____ of ____

Project Name: _____

Lab I.D. #: 01429

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
16	HS-S1-MS	MAKER SPACE SINK		AM / PM	X	
17	HS-S2-MS	MAKER SPACE SINK		AM / PM	X	
18	HS-WF-C106	HALL AT C106 WATER COOLER		AM / PM	X	
19	HS-BF-C106	HALL AT C106 BOTTLE FILLER		AM / PM	X	
20	HS-S1-SA	KITCHEN SERVING AREA SINK		AM / PM	X	
21	HS-S2-FPR	KITCHEN FOOD PREP SINK		AM / PM	X	
22	HS-S4-FPK	KITCHEN FOOD PREP SINK		AM / PM	X	
23	HS-PF-K	KITCHEN POT FILLER		AM / PM	X	
24	HS-IM-K	KITCHEN ICE MACHINE		AM / PM	X	
25	HS-S-CR	COFFE ROOM SINK		AM / PM	X	
26	HS-S-SA	SNACK BAR LEFT SINK		AM / PM	X	
27	HS-WF-B115	HALL AT B115 WATER COOLER		AM / PM	X	
28	HS-BF-B115	HALL AT B115 BOTTLE FILLER		AM / PM	X	
29	HS-S1-NO	NURSE OFFICE SINK		AM / PM	X	
30	HS-WF-CA	HALL AT COM AREA WATER COOLER		AM / PM	X	
31	HS-BF-CA	HALL AT COM AREA BOTTLE FILLER		AM / PM	X	
32	HS-WC-GEL	GYM ENTRANCE LOBBY WATER COOLER		AM / PM	X	
33	HS-BF-GEL	GYM ENTRANCE BOTTLE FILLER		AM / PM	X	
34	HS-WF-G125	HALL BY G125 WATER COOLER		AM / PM	X	
35	HS-BF-G125	HALL BY G125 BOTTLE FILLER		AM / PM	X	
36	HS-S1-G126	RM G126 SINK		AM / PM	X	
37	HS-IM-G126	RM G126 ICE MACHINE		AM / PM	X	
38	HS-WF-AB	AUX GYM BOYS BATH WATER COOLER		AM / PM	X	
39	HS-BF-AB	AUX GYM BOYS BATH BOTTLE FILLER		AM / PM	X	
40	HS-WF-AG	AUX GYM GIRLS BATH WATER COOLER		AM / PM	X	
41	HS-BF-AG	AUX GYM GIRLS BATH BOTTLE FILLER		AM / PM	X	
42	HS-WF-D115	HALL BY D115 WATER COOLER		AM / PM		
43	HS-BF-D115	HALL BY D115 BOTTLE FILLER		AM / PM		
44	HS-WF-B209	B209 WATER COOLER		AM / PM		
45	HS-BF-B209	B209 BOTTLE FILLER		AM / PM		
46	HS-S-B235	B235 FACULTY SINK		AM / PM		
47	HS-WF-B236	HALL BY B236 WATER COOLER		AM / PM		
48	HS-BF-B236	HALL BY B236 BOTTLE FILLER		AM / PM		
49	HS-WF-D204	HALL BY D204 WATER COOLER		AM / PM		
50	HS-BF-D204	HALL BY D204 BOTTLE FILLER		AM / PM		

Released by: ERICK ULLOA	Signature:	Date/Time: 05-02-25
Received by: CHRISTINAS	Signature:	Date/Time: 6/9/25 1:35pm

Client Name: LEW CORP Account #201327 Page 3 of 3

Project Name: 1619

Lab I.D. #: 01429

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
51	HS-WF-B315	HALL BY B315 WATER COOLER		AM / PM	X	
52	HS-BF-B315	HALL BY B315 BOTTLE FILLER		AM / PM	X	
53	HS-WC-NO	NURSE OFFICE WATER COOLER		AM / PM	X	
54	HS-SR			AM / PM	X	
55				AM / PM	X	
56				AM / PM	X	
57				AM / PM	X	
58				AM / PM	X	
59				AM / PM	X	
60				AM / PM	X	
61				AM / PM	X	
62				AM / PM	X	
63				AM / PM	X	
64				AM / PM	X	
65				AM / PM	X	
66				AM / PM	X	
67				AM / PM	X	
68				AM / PM	X	
69				AM / PM	X	
70				AM / PM	X	
71				AM / PM	X	
72				AM / PM	X	
73				AM / PM	X	
74				AM / PM	X	
75				AM / PM	X	
76				AM / PM	X	
77				AM / PM		
78				AM / PM		
79				AM / PM		
80				AM / PM		
81				AM / PM		
82				AM / PM		
83				AM / PM		
84				AM / PM		
85				AM / PM		

Released by: ERICK ULLOA	Signature:		Date/Time: 05-02-25
Received by: E CHRISTMAS	Signature:		Date/Time: 6/9/23 1350

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 25-06-01643

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 06/09/2025
Reported Date: 06/16/2025
Sampled By: Erick Ulloa
Tech Certification #:

Project/Test Address: 1619; Mount Olive Middle School; 1650 Wolfe Road; Budd Lake, NJ 07828

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-06-01643-001	MS-S1-HE	05/02/2025	B142 SINK	9.88	06/13/2025	
25-06-01643-002	MS-S2-HE	05/02/2025	B142 SINK	14.3	06/13/2025	
25-06-01643-003	MS-S3-HE	05/02/2025	B142 SINK	20.2	06/13/2025	
25-06-01643-004	MS-IM-HE	05/02/2025	B142 ICE MACHINE	11.8	06/13/2025	
25-06-01643-005	MS-S4-HE	05/02/2025	B142 SINK	26.5	06/13/2025	
25-06-01643-006	MS-S5-HE	05/02/2025	B142 SINK	14.5	06/13/2025	
25-06-01643-007	MS-WFL-BL	05/02/2025	BOYS LOCKER RM LEFT WATER COOLER	4.18	06/13/2025	
25-06-01643-008	MS-WFR-BL	05/02/2025	BOYS LOCKER RM RIGHT WATER COOLER	<1.00	06/13/2025	
25-06-01643-009	MS-WFL-CAFE	05/02/2025	HALL BY CAFE LEFT WATER COOLER	1.90	06/13/2025	
25-06-01643-010	MS-BFC-CAFE	05/02/2025	HALL BY CAFE CENTER BOTTLE FILLER	<1.00	06/13/2025	
25-06-01643-011	MS-WFR-CAFE	05/02/2025	HALL BY CAFE RIGHT WATER COOLER	1.40	06/13/2025	
25-06-01643-012	MS-WFL-GL	05/02/2025	GIRLS LOCKER RM LEFT WATER COOLER	<1.00	06/13/2025	
25-06-01643-013	MS-WCR-GL	05/02/2025	GIRLS LOCKER RM RIGHT WATER COOLER	1.05	06/13/2025	

Client Number: 201327 Report Number: 25-06-01643

Project/Test Address: 1619; Mount Olive Middle School; 1650 Wolfe Road; Budd Lake, NJ 07828

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-06-01643-014	MS-S-TL	05/02/2025	TEACHER LOUNGE SINK	7.47	06/13/2025	
25-06-01643-015	MS-S1-WS	05/02/2025	KITCHEN WASH STATION SINK	61.2	06/13/2025	
25-06-01643-016	MS-S2-WS	05/02/2025	KITCHEN WASH STATION SINK	7.30	06/13/2025	
25-06-01643-017	MS-S3-LTR	05/02/2025	KITCHEN LONG TABLE RIGHT SINK	12.8	06/13/2025	
25-06-01643-018	MS-S4-LTL	05/02/2025	KITCHEN LONG TABLE LEFT SINK	14.0	06/13/2025	
25-06-01643-019	MS-PF2-K	05/02/2025	KITCHEN POT FILLER	10.5	06/13/2025	
25-06-01643-020	MS-IM-K	05/02/2025	KITCHEN ICE MACHINE	<1.00	06/13/2025	
25-06-01643-021	MS-S5-K	05/02/2025	KITCHEN SINK	41.1	06/13/2025	
25-06-01643-022	MS-S6-K	05/02/2025	KITCHEN SINK	5.47	06/13/2025	
25-06-01643-023	MS-S7-K	05/02/2025	KITCHEN DISH WASH SINK	128	06/13/2025	
25-06-01643-024	MS-S8-K	05/02/2025	KITCHEN SERVICE AREA LEFT SINK	28.3	06/13/2025	
25-06-01643-025	MS-S9-K	05/02/2025	KITCHEN SERVICE AREA CENTER SINK	20.6	06/13/2025	
25-06-01643-026	MS-S10-K	05/02/2025	KITCHEN SERVICE AREA RIGHT SINK	63.4	06/13/2025	
25-06-01643-027	MS-S11-K	05/02/2025	KITCHEN SINK	258	06/13/2025	
25-06-01643-028	MS-S-SS	05/02/2025	SNACK SHACK SINK	25.2	06/13/2025	
25-06-01643-029	MS-WFL-GHG	05/02/2025	GYM HALL BY GIRLS LEFT WATER COOLER	2.54	06/13/2025	
25-06-01643-030	MS-WFR-GHG	05/02/2025	GYM HALL BY GIRLS RIGHT WATER COOLER	2.92	06/13/2025	
25-06-01643-031	MS-BFL-GHB	05/02/2025	GYM HALL BY BOYS LEFT BOTTLE FILLER	<1.00	06/13/2025	
25-06-01643-032	MS-WFR-GHB	05/02/2025	GYM HALL BY BOYS RIGHT WATER COOLER	11.0	06/13/2025	
25-06-01643-033	MS-S1-NO	05/02/2025	NURSE EXAM SINK	10.9	06/13/2025	

Client Number: 201327 Report Number: 25-06-01643

Project/Test Address: 1619; Mount Olive Middle School; 1650 Wolfe Road; Budd Lake, NJ 07828

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-06-01643-034	MS-IM-NO	05/02/2025	NURSE OFFICE ICE MACHINE	<1.00	06/13/2025	
25-06-01643-035	MS-S2-NO	05/02/2025	NURSE OFFICE SINK	13.3	06/13/2025	
25-06-01643-036	MS-S-134	05/02/2025	RM 134 SINK	3.75	06/13/2025	
25-06-01643-037	MS-S-LIB	05/02/2025	LIBRARY SINK	15.7	06/13/2025	
25-06-01643-038	MS-S-145	05/02/2025	MAIN OFFICE 145 SINK	6.67	06/13/2025	
25-06-01643-039	MS-S-149	05/02/2025	MAIN OFFICE 149 SINK	15.2	06/13/2025	
25-06-01643-040	MS-S-151	05/02/2025	RM 151 SINK	12.1	06/13/2025	
25-06-01643-041	MS-WCC-C133	05/02/2025	HALL C133 WATER COOLER	1.05	06/13/2025	
25-06-01643-042	MS-WCR-C133	05/02/2025	HALL C133 WATER COOLER	6.54	06/13/2025	
25-06-01643-043	MS-WCL-C133	05/02/2025	HALL C133 WATER COOLER	2.40	06/13/2025	
25-06-01643-044	MS-S-C125	05/02/2025	RM C125 SINK	4.87	06/13/2025	
25-06-01643-045	MS-WCR-D121	05/02/2025	HALL BY D121 RIGHT WATER COOLER	<1.00	06/13/2025	
25-06-01643-046	MS-WCC-D121	05/02/2025	HALL BY D121 CENTER WATER COOLER	<1.00	06/13/2025	
25-06-01643-047	MS-WCL-D121	05/02/2025	HALL BY D121 LEFT WATER COOLER	5.63	06/13/2025	
25-06-01643-048	MS-S-133	05/02/2025	RM 133 SINK	5.05	06/13/2025	
25-06-01643-049	MS-WCL-D108	05/02/2025	HALL AT D108 LEFT WATER COOLER	<1.00	06/13/2025	
25-06-01643-050	MS-WCC-D108	05/02/2025	HALL AT D108 CENTER WATER COOLER	4.84	06/13/2025	
25-06-01643-051	MS-WCR-D108	05/02/2025	HALL AT D108 RIGHT	1.35	06/13/2025	
25-06-01643-052	MS-WCL-C111	05/02/2025	HALL BY C111 LEFT WATER COOLER	1.52	06/13/2025	
25-06-01643-053	MS-WCC-C111	05/02/2025	HALL BY C111 CENTER WATER COOLER	<1.00	06/13/2025	

Client Number: 201327 Report Number: 25-06-01643

Project/Test Address: 1619; Mount Olive Middle School; 1650 Wolfe Road; Budd Lake, NJ 07828

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
25-06-01643-054	MS-WCR-C111	05/02/2025	HALL BY C111 RIGHT WATER COOLER	<1.00	06/13/2025	
25-06-01643-055	MS-WCL-E130	05/02/2025	HALL BY E130 LEFT WATER COOLER	<1.00	06/13/2025	
25-06-01643-056	MS-WCC-E130	05/02/2025	HALL BY E130 CENTER WATER COOLER	<1.00	06/13/2025	
25-06-01643-057	MS-WCR-E130	05/02/2025	HALL BY E130 RIGHT WATER COOLER	<1.00	06/13/2025	
25-06-01643-058	MS-WCL-E110	05/02/2025	HALL BY E110 LEFT WATER COOLER	6.66	06/13/2025	
25-06-01643-059	MS-WCC-E110	05/02/2025	HALL BY E110 CENTER WATER COOLER	1.15	06/13/2025	
25-06-01643-060	MS-WCR-E110	05/02/2025	HALL BY E110 RIGHT WATER COOLER	<1.00	06/13/2025	
25-06-01643-061	MS-S-E134	05/02/2025	E134 PREP SINK	76.6	06/13/2025	
25-06-01643-062	MS-WCL-F121	05/02/2025	HALL BY F121 LEFT WATER COOLER	<1.00	06/13/2025	
25-06-01643-063	MS-WCC-F121	05/02/2025	HALL BY F121 CENTER WATER COOLER	2.67	06/13/2025	
25-06-01643-064	MS-WCR-F121	05/02/2025	HALL BY F121 RIGHT WATER COOLER	1.08	06/13/2025	
25-06-01643-065	MS-S-E120	05/02/2025	RM E120 SINK	8.22	06/13/2025	
25-06-01643-066	MS-BF-E130	05/02/2025	HALL BY E130 BOTTLE FILLER	<1.00	06/13/2025	
25-06-01643-067	MS-WCL-F109	05/02/2025	HALL BY F109 LEFT WATER COOLER	2.00	06/13/2025	
25-06-01643-068	MS-WCC-F109	05/02/2025	HALL BY F109 CENTER WATER COOLER	<1.00	06/13/2025	
25-06-01643-069	MS-S-F133	05/02/2025	RM F133 SINK	11.5	06/13/2025	

Environmental Hazards Services, L.L.C

Client Number: 201327 Report Number: 25-06-01643

Project/Test Address: 1619; Mount Olive Middle School; 1650 Wolfe Road; Budd Lake, NJ 07828

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID

Method: EPA 200.8
Analyst: Nicole Holloway
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

ENVIRONMENTAL HAZARDS SERVICES, LLC

WaterSmart ® Lead Chain-of-Custody Form

Richmond, VA - Phone: (800) 347-4010 FAX: (804) 275-4907
www.leadlab.com

25-06-01643

Due Date:
06/16/2025
(Monday)
AE

104

Client Name: LEW CORP Account #: 201327

Address: 181 US HIGHWAY 46

City/State/Zip: MINE HILL, NJ 07803 Phone: 908-654-8068

Email Address: labresults@lewcorp.com

Project Name/ Number : 1619; MOUNT OLIVE MIDDLE SCHOOL

Collection Address: 160 WOLFE ROAD (Required) City/State/Zip: BUDD LAKE, NJ 07828 (Required)

Approx. Age Of Property: _____ Collected By: ERICK ULLOA

Water Source: (Check One) Public X or Well _____ Well Tag # (if applicable): _____

Turn-Around Time X 5 Days ____ 3 Days ____ 2 Days ____ 1 Day

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
1	MS-S1-HE	B142 SINK	05-02-2025	AM / PM	X	
2	MS-S2-HE	B142 SINK		AM / PM	X	
3	MS-S3-HE	B142 SINK		AM / PM	X	
4	MS-IM-HE	B142 ICE MACHINE		AM / PM	X	
5	MS-S4-HE	B142 SINK		AM / PM	X	
6	MS-S5-HE	B142 SINK		AM / PM	X	
7	MS-WFL-BL	BOYS LOCKER RM LEFT WATER COOLER		AM / PM	X	
8	MS-WFR-BL	BOYS LOCKER RM RIGHT WATER COOLER		AM / PM	X	
9	MS-WFL-CAFE	HALL BY CAFE LEFT WATER COOLER		AM / PM	X	
10	MS-BFC-CAFE	HALL BY CAFE CENTER BOTTLE FILLER		AM / PM	X	
11	MS-WFR-CAFE	HALL BY CAFE RIGHT WATER COOLER		AM / PM	X	
12	MS-WFL-GL	GIRLS LOCKER RM LEFT WATER COOLER		AM / PM	X	
13	MS-WCR-GL	GIRLS LOCKER RM RIGHT WATER COOLER		AM / PM	X	
14	MS-S-TL	TEACHER LOUNGE SINK		AM / PM	X	
15	MS-S1-WS	KITCHEN WASH STATION SINK		AM / PM	X	

Released by: ERICK ULLOA Signature: Date/Time: 05-02-25

Received by: ERICK STARR Signature: Date/Time: 6/10/25 1125AM

Client Name: LEW CORP Account #201327 Page 2 of 3

Project Name: 1619

Lab I.D. #: 01643

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
16	MS-S2-WS	KITCHEN WASH STATION SINK		AM / PM	X	
17	MS-S3-LTR	KITCHEN LONG TABLE RIGHT SINK		AM / PM	X	
18	MS-S4-LTL	KITCHEN LONG TABLE LEFT SINK		AM / PM	X	
19	MS-PF2-K	KITCHEN POT FILLER		AM / PM	X	
20	MS-IM-K	KITCHEN ICE MACHINE		AM / PM	X	
21	MS-S5-K	KITCHEN SINK		AM / PM	X	
22	MS-S6-K	KITCHEN SINK		AM / PM	X	
23	MS-S7-K	KITCHEN DISH WASH SINK		AM / PM	X	
24	MS-S8-K	KITCHEN SERVICE AREA LEFT SINK		AM / PM	X	
25	MS-S9-K	KITCHEN SERVICE AREA CENTER SINK		AM / PM	X	
26	MS-S10-K	KITCHEN SERVICE AREA RIGHT SINK		AM / PM	X	
27	MS-S11-K	KITCHEN SINK		AM / PM	X	
28	MS-S-SS	SNACK SHACK SINK		AM / PM	X	
29	MS-WFL-GHG	GYM HALL BY GIRLS LEFT WATER COOLER		AM / PM	X	
30	MS-WFR-GHG	GYM HALL BY GIRLS RIGHT WATER COOLER		AM / PM	X	
31	MS-BFL-GHB	GYM HALL BY BOYS LEFT BOTTLE FILLER		AM / PM	X	
32	MS-WFR-GHB	GYM HALL BY BOYS RIGHT WATER COOLER		AM / PM	X	
33	MS-S1-NO	NURSE EXAM SINK		AM / PM	X	
34	MS-IM-NO	NURSE OFFICE ICE MACHINE		AM / PM	X	
35	MS-S2-NO	NURSE OFFICE SINK		AM / PM	X	
36	MS-S-134	RM 134 SINK		AM / PM	X	
37	MS-S-LIB	LIBRARY SINK		AM / PM	X	
38	MS-S-145	MAIN OFFICE 145 SINK		AM / PM	X	
39	MS-S-149	MAIN OFFICE 149 SINK		AM / PM	X	
40	MS-S-151	RM 151 SINK		AM / PM	X	
41	MS-WCC-C133	HALL AT C133 WATER COOLER		AM / PM	X	
42	MS-WCR-C133	HALL AT C133 WATER COOLER		AM / PM		
43	MS-WCL-C133	HALL AT C133 WATER COOLER		AM / PM		
44	MS-S-C125	RM C125 SINK		AM / PM		
45	MS-WCR-D121	HALL BY D121 RIGHT WATER COOLER		AM / PM		
46	MS-WCC-D121	HALL BY D121 CENTER WATER COOLER		AM / PM		
47	MS-WCL-D121	HALL BY D121 LEFT WATER COOLER		AM / PM		
48	MS-S-133	RM 133 SINK		AM / PM		
49	MS-WCL-D108	HALL AT D108 LEFT WATER COOLER		AM / PM		
50	MS-WCC-D108	HALL AT D108 CENTER WATER COOLER		AM / PM		

Released by: ERICK ULLOA	Signature:	Date/Time: 05-02-25
Received by: ELHRISTIAS	Signature:	Date/Time: 6/10/25 1135

Client Name: LEW CORP Account #201327 Page 3 of 3

Project Name: 1619

Lab I.D. #: 01643

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analyte	
					Pb	Cu
51	MS-WCR-D108	HALL AT D108 RIGHT		AM / PM	X	
52	MS-WCL-C111	HALL BY C111 LEFT WATER COOLER		AM / PM	X	
53	MS-WCC-C111	HALL BY C111 CENTER WATER COOLER		AM / PM	X	
54	MS-WCR-C111	HALL BY C111 RIGHT WATER COOLER		AM / PM	X	
55	MS-WCL-E130	HALL BY E130 LEFT WATER COOLER		AM / PM	X	
56	MS-WCC-E130	HALL BY E130 CENTER WATER COOLER		AM / PM	X	
57	MS-WCR-E130	HALL BY E130 RIGHT WATER COOLER		AM / PM	X	
58	MS-WCL-E110	HALL BY E110 LEFT WATER COOLER		AM / PM	X	
59	MS-WCC-E110	HALL BY E110 CENTER WATER COOLER		AM / PM	X	
60	MS-WCR-E110	HALL BY E110 RIGHT WATER COOLER		AM / PM	X	
61	MS-S-E134	E134 PREP RM SINK		AM / PM	X	
62	MS-WCL-F121	HALL BY F121 LEFT WATER COOLER		AM / PM	X	
63	MS-WCC-F121	HALL BY F121 CENTER WATER COOLER		AM / PM	X	
64	MS-WCR-F121	HALL BY F121 RIGHT WATER COOLER		AM / PM	X	
65	MS-S-E120	RM E120 SINK		AM / PM	X	
66	MS-BF-E130	HALL BY E130 BOTTLE FILLER		AM / PM	X	
67	MS-WCL-F109	HALL BY F109 LEFT WATER COOLER		AM / PM	X	
68	MS-WCC-F109	HALL BY F109 CENTER WATER COOLER		AM / PM	X	
69	MS-S-F133	RM F133 SINK		AM / PM	X	
70				AM / PM	X	
71				AM / PM	X	
72				AM / PM	X	
73				AM / PM	X	
74				AM / PM	X	
75				AM / PM	X	
76				AM / PM	X	
77				AM / PM		
78				AM / PM		
79				AM / PM		
80				AM / PM		
81				AM / PM		
82				AM / PM		
83				AM / PM		
84				AM / PM		
85				AM / PM		

Released by: ERICK ULLOA Signature: Date/Time: 05-02-25

Received by: CHRISTMAS Signature: Date/Time: 6/10/25 1125AM