CONFIDENTIAL AND PRIVILEGED

LEAD SURVEY

For the Property located at:

15151 Columbia Ln
Huntington Beach, California 92647

Prepared for:

Westminster School District
14121 Cedarwood Ave
Westminster, CA 92683
Attn: Brad Seaver

Prepared by:

Ambient Environmental Inc.
8141 East Kaiser Blvd. Suite 110
Anaheim California 92808

Date: March 27, 2026

Ambient Environmental Inc. Project #26-0253

Reviewed By:



Justin Lavezzoli
California Certified
Sampling Technician #LRC-0009043

TABLE OF CONTENTS

1.0 EXECUTIVE SUMMARY

2.0 SURVEY PROCEDURES

3.0 LEAD ANALYTICAL METHODOLOGY

4.0 LEAD SAMPLE RESULTS AND LOCATIONS

5.0 DISCLAIMER

APPENDIX A LEAD LABORATORY ANALYSIS
APPENDIX B LEAD CHAIN OF CUSTODY AND BULK SAMPLE LOG
APPENDIX C SITE DRAWING WITH SAMPLE LOCATION
APPENDIX D CERTIFICATIONS

1.0 EXECUTIVE SUMMARY

Ambient Environmental Inc. was retained by Westminster School District to perform a lead survey for the property located at: 15151 Columbia Ln in Huntington Beach, California. The survey was performed on March 25, 2026 by Daniel Gonzales a California Department of Public Health (CDPH) a Certified Lead Sampling Technician (#LRC-00003833). The property consists of a single-story school property.

The purpose of the survey was to locate and identify interior and exterior painted/coated building surface/components per the client's limited scope of work for lead-based paint prior to any renovation, demolition or any other activity that will involve disturbance to materials. Once a visual inspection was performed, representative lead bulk samples were obtained from each building surface and component.

Once the lead visual inspection was performed, suspect painted/coated building surfaces and components were categorized into homogeneous areas. Homogeneous areas are defined as areas in which suspect painted building surface/components are uniform in color, texture, application date and general appearance. Building surface/components bulk samples were obtained from each homogeneous area. Bulk sample location and condition of painted surface/components was also documented during the survey. All relevant interior and exterior areas were visually inspected.

Lab results revealed detectable levels of lead greater than 0.06 mg/cm^2 or 600 parts per million (ppm) of lead in accordance with Title 8 CCR Section 1532.1 in the following building surface/components:

- **Blue Plaster Wall**

Locations and conditions of materials or components assessed and sampled can be found in the Material Inventory (Tables).

2.0 SURVEY PROCEDURES

The purpose of the limited lead survey was to locate and identify interior and exterior building surfaces and components for lead. All areas within the scope of work were surveyed for lead. Materials or components not identified in this report may be present within hidden or concealed areas of the building or outside the scope of work.

Painted/coated building surfaces and components were identified by entering each functional space and assessing all structural/mechanical building components and architectural finishes. The physical condition and damage of paint/coating were also assessed and documented. The following procedures were performed during the survey:

- A visual assessment to identify the location and type of materials and components.
- Obtain representative bulk samples from suspected surfaces and components for lead.
- Analyzed bulk samples by an independent accredited laboratory for the presence of asbestos by AIHA-LAP.
- Present all survey results in a written report including locations and laboratory results.

All findings and analytical data presented in this report are based on the information (assessment, sampling data) obtained by our inspector during the survey.

3.0 LEAD ANALYTICAL METHODOLOGY

The purpose of the limited lead-based paint inspection was in accordance with the EPA's Renovation Repair and Painting Rule (RRP) and U.S. Department of Housing and Urban Development (HUD) "Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing," 1997 Revision to Chapter 7: Lead Based Paint Inspections; to locate and identify interior surfaces and/or building components prior to the renovation activities or any other activity that will involve disturbance. Once a visual inspection was performed, representative bulk samples were obtained from each relevant building surface and component.

The California Division of Safety and Health (DOSH) or Cal/OSHA regulates all construction related work where an individual may be exposed to lead, regardless of the lead concentration in paint or other surface coatings. Objective data showing that a specific paint or coating contains less than 0.06 % lead by weight (equivalent to 600 parts per million [ppm]) constitutes a "negative initial determination" whereby that paint/coating may be "installed" or otherwise handled in an intact state by non-protected/trained personnel. However, any other activities such as cutting, sanding, scraping, manual demolition, etcetera, require compliance with Cal/OSHA Title 8 CCR Section 1532.1 irrespective of lead content. All lead laboratory testing was conducted in compliance with US EPA Method SW 846 3050B/7000B flame atomic absorption spectrometry analysis by the laboratory listed above. See attached analytical report for address and phone number as needed.

Lead-Based Paint (LBP): Paint or other surface coating that contains lead in excess of 1.0 milligrams per centimeter squared (mg/cm2) or 5,000 parts per million (0.7 or 600 parts per million for Los Angeles County). LBP removal and disposal must be performed in accordance with CDPH Regulations as well as California OSHA requirements. Lead-Containing Paint (LCP): Painted material or surfaces containing lead levels between 0.1 and 1.0 mg/cm2 or 90 to 5000 ppm of lead. LCP removal and disposal must be performed in accordance with California OSHA regulations and can be handled by a regular contractor who has prepared a California OSHA lead compliance plan/program for the protection of its workers. LCP is not a hazard to occupants per the EPA, HUD, and Cal/DPH and thus not regulated by those agencies.

4.0 LEAD SAMPLE RESULTS AND LOCATIONS

The samples were collected at these locations and yielded the following results:

Sample Number	Color	Location	Substrate	Component	Condition	Results (ppm)
L-1	White	Admin Copy Room	Plaster	Wall	Intact	5500
L-2	White	Mechanical Room/B-Storage	Plaster	Wall	Intact	29
L-3	White	Walkway	Plaster	Ceiling	Intact	100
L-4	White	A Restroom	Plaster	Wall	Intact	370
L-5	Blue	C Restroom	Plaster	Wall	Intact	110
L-6	White	A Restroom	Ceramic	Floor	Intact	94
L-7	White	C Restroom	Ceramic	Floor	Intact	<20

The table above indicates that samples contain lead below and above the limit of detection.

7.0 DISCLAIMER

Personnel should be made aware of the presence of lead containing building components and instruct them not to disturb and/or damage these materials identified in this report.

Every effort was made to sample every building surface/component within the scope of work. If any building components not identified in this report are discovered, all work should cease and these building components should be sampled prior to any r emoval activities.

Any professional opinions in this report are based solely on visual observations and analytical analyses, as described in this report. Also, if any changes to any regulation governing or lead occurred after the date of this report, Ambient cannot be responsible for these changes. Opinions or recommendations presented herein apply to site conditions existing at the time of our investigation and cannot necessarily apply to site changes of which this office is not aware of and/or has not had the opportunity to evaluate.

APPENDIX A

LABORATORY ANALYSIS

Final Report

Metals Analysis of Paints

(AIHA-LAP, LLC Accreditation, Lab ID #101629)

Ambient Environmental Inc.
Robert Valousky
8141 E. Kaiser Blvd.
Suite 110
Anaheim, CA 92808

Client ID: 5697
Report Number: M276969
Date Received: 03/26/26
Date Analyzed: 03/26/26
Date Printed: 03/26/26
First Reported: 03/26/26

Job ID / Site: 26-0253; 15151 Columbia Ln (HB)
Date(s) Collected: 3/25/26

SGSFL Job ID: 5697
Total Samples Submitted: 1
Total Samples Analyzed: 1

Sample Number	Lab Number	Analyte	Result	Result Units	Reporting Limit*	Method Reference
L-1	LM304539	Pb	5500	ppm	300	EPA 3050B/7000B

* The Reporting Limit represents the lowest amount of analyte that the laboratory can confidently detect in the sample, and is not a regulatory level. The Units for the Reporting Limit are the same as the Units for the Final Results.

Vincent To, Laboratory Supervisor, Carson Laboratory

Analytical results and reports are generated by SGS at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by SGS to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by SGS. The client is solely responsible for the use and interpretation of test results and reports requested from SGS. SGS is not able to assess the degree of hazard resulting from materials analyzed. SGS reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. Any modifications that have been made to referenced test methods are documented in SGS Standard Operating Procedures Manual. Sample results have not been blank corrected. Quality control and sample receipt condition were acceptable unless otherwise noted.
Note* Sampling data used in this report was provided by the client as noted on the associated chain of custody form.

20535 South Belshaw Avenue, Carson, CA 90746 | phone: 310.763.2374 / 800.813.9417 Fax: 310.763.4450 | https://www.sgs-ehsusa.com/

Metals Analysis of Bulks - TTLC

(AIHA-LAP, LLC Accreditation, Lab ID #101629)

Ambient Environmental Inc.
Robert Valousky
8141 E. Kaiser Blvd.
Suite 110
Anaheim, CA 92808

Client ID: 5697
Report Number: M276970
Date Received: 03/26/26
Date Analyzed: 03/26/26
Date Printed: 03/26/26
First Reported: 03/26/26

Job ID / Site: 26-0253; 15151 Columbia Ln (HB)
Date(s) Collected: 3/25/26

SGSFL Job ID: 5697
Total Samples Submitted: 6
Total Samples Analyzed: 6

Sample Number	Lab Number	Analyte	Result	Result Units	Reporting Limit*	Method Reference
L-2	LM304540	Pb	29	ppm	7	EPA 3050B/7000B
L-3	LM304541	Pb	100	ppm	6	EPA 3050B/7000B
L-4	LM304542	Pb	370	ppm	30	EPA 3050B/7000B
L-5	LM304543	Pb	110	ppm	6	EPA 3050B/7000B
L-6	LM304544	Pb	94	ppm	5	EPA 3050B/7000B
L-7	LM304545	Pb	< 20	ppm	20	EPA 3050B/7000B

* The Reporting Limit represents the lowest amount of analyte that the laboratory can confidently detect in the sample, and is not a regulatory level. The Units for the Reporting Limit are the same as the Units for the Final Results.

Vincent To, Laboratory Supervisor, Carson Laboratory

Analytical results and reports are generated by SGS at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by SGS to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by SGS. The client is solely responsible for the use and interpretation of test results and reports requested from SGS. SGS is not able to assess the degree of hazard resulting from materials analyzed. SGS reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. Any modifications that have been made to referenced test methods are documented in SGS Standard Operating Procedures Manual. Sample results have not been blank corrected. Quality control and sample receipt condition were acceptable unless otherwise noted.
Note* Sampling data used in this report was provided by the client as noted on the associated chain of custody form.

APPENDIX B

CHAIN OF CUSTODY
AND BULK SAMPLE LOG

AMBIENTENVIRONMENTAL, INC.
Consulting/ Engineering/Remediation

8141 E Kaiser Blvd., Suite 110
Anaheim, California 92808
Phone: (951) 272-4730

LEAD BULK SAMPLE LOG

Client Name: WESTMINSTER SCHOOL DISTRICT

Project Location: 15151 COLUMBIA LN (HB)

Date: 3/25/26 **Field Technician:** DANIEL GONZALES

Project Number: 26-0253 **Priority: 3 Hour**____ **24 HR** X **3 Days**____ **5 Days:** ____

Sample Number	Sample Description	Location/Surface	Condition/Area Wiped	Substrate
L-1	Color: BLUE (X) Paint Chip ( ) Ceramic Tile ( ) Soil ( ) Lead Wipe ( ) Waste Characterization	ADMIN-COPY RM/WALL	(X) Intact ( ) Fair ( ) Poor ( ) 1 SF Area	( ) Drywall (X) Plaster ( ) Wood
L-2	Color: WHITE (X) Paint Chip ( ) Ceramic Tile ( ) Soil ( ) Lead Wipe ( ) Waste Characterization	MECH RM/ B-STORAGE/ WALL	( ) Intact ( ) Fair ( ) Poor ( ) 1 SF Area	( ) Drywall ( ) Plaster ( ) Wood
L-3	Color: GRAY (X) Paint Chip ( ) Ceramic Tile ( ) Soil ( ) Lead Wipe ( ) Waste Characterization	WALKWAY/CEILING	(X) Intact ( ) Fair ( ) Poor ( ) 1 SF Area	( ) Drywall (X) Plaster ( ) Wood
L-4	Color: YELLOW ( ) Paint Chip (X) Ceramic Tile ( ) Soil ( ) Lead Wipe ( ) Waste Characterization	A-RESTROOM/ WALL	(X) Intact ( ) Fair ( ) Poor ( ) 1 SF Area	( ) Drywall (X) Plaster ( ) Wood
L-5	Color: YELLOW ( ) Paint Chip (X) Ceramic Tile ( ) Soil ( ) Lead Wipe ( ) Waste Characterization	C-	(X) Intact ( ) Fair ( ) Poor ( ) 1 SF Area	( ) Drywall (X) Plaster ( ) Wood
L-6	Color: GREEN ( ) Paint Chip (X) Ceramic Tile ( ) Soil ( ) Lead Wipe ( ) Waste Characterization	A- / FLOOR	(X) Intact ( ) Fair ( ) Poor ( ) 1 SF Area	( ) Drywall ( ) Plaster ( ) Wood CONCRETE
L-7		C- / FLOOR		

FLANGE

Chain of Custody **Analytical Method: PLM:** X **TEM:** _____ **Point Count:** _____
Samples Relinquished: **Hand Delivered:**_____ **Shipped:**_____ **Secured Lox Box:** _____

	Signature	Print	Date	Time
Sampled By	Daniel Gonzales	DANIEL GONZALES	3/25/26	1530
Relinquished By	Daniel Gonzales	DANIEL GONZALES	3/25/26	2000
Received By		Shirlysa Tieng	3/26/26	800 D/O
Relinquished By				
Received By				

APPENDIX C

SITE DRAWING WITH SAMPLE LOCATION

L-4, L-6
13, 14, 15

22

Schroeder Elementary School 2020-2021
Site Plan — Westminster School District

Schroeder Elementary School
15151 Columbia Lane
Huntington Beach, CA 92647
(714) 894-7268

3/25/26
WESTMINSTER SCHOOL DISTRICT
26-0253
DANIEL GONZALES



X FLOOR TILE UNDER CARPET

APPENDIX D

CERTIFICATION

Certificate Of Completion

Asbestos Contractor/Supervisor Refresher Course

DOSH #:CA-015-04

Daniel Gonzales

ASR0221250006N44243

Mauro Arias
Principal Instructor

Michael W. Horner
Training Director

Course Start Date	Course End Date	Exam Date	Expiration Date
2/21/2025	2/21/2025	2/21/2025	2/21/2026

This course satisfies the education requirements for Asbestos accreditation under the Toxic Substances Control Act, Title II. This course has been approved by the Department of Industrial Relations, Division of Occupational Safety and Health of the State of California

NATEC International, Inc.
National Association of Training and Environmental Consulting
1100 Technology Circle, Suite A, Anaheim, CA 92805 • www.natecintl.com • 800-969-3228

Important Industry Contacts
CAL-OSHA: PH# (916) 574-2993 (916) 483-0572 Fax Notification Web: www.dir.ca.gov or calosha.com
CDPH/CLPPB: PH# (510) 620-5600 Web: www.cdph.ca.gov/programs/CLPPB
SCAQMD: PH# (909) 396-3739 Fax#(909) 396-3342
BAAQMD: PH# (415) 749-4762

NATEC International, Inc.
National Association of Training and Environmental Consulting
Asbestos · Lead · Mold · HAZWOPER
PO Box 8657, Fountain Valley, CA 92728
(714) 678-2750, (800) 969-3228, Fax (714) 678-2757
www.natecintl.com

NATEC International, Inc.
National Association of Training and Environmental Consulting
This Card Acknowledges That Daniel Gonzales
Holds Training Certification For Asbestos Contractor/Supervisor Refresher Course
Expiration: 2/21/2026
Training Date: 2/21/2025 Michael W. Horner
Certificate No. ASR0221250006N44243 Training Director

Certificate Of Completion

Asbestos Building Inspector Refresher Course

DOSH #:CA-015-06

Daniel E. Gonzales III

ABIR0220250002N44311

Norm Kramer
Principal Instructor

Michael W. Horner
Training Director

Course Start Date	Course End Date	Exam Date	Expiration Date
2/20/2025	2/20/2025	2/20/2025	2/20/2026

This course satisfies the education requirements for Asbestos accreditation under the Toxic Substances Control Act, Title II. This course has been approved by the Department of Industrial Relations, Division of Occupational Safety and Health of the State of California

NATEC International, Inc.
National Association of Training and Environmental Consulting
1100 Technology Circle, Suite A, Anaheim, CA 92805 • www.natecintl.com • 800-969-3228

Important Industry Contacts
CAL-OSHA: PH# (916) 574-2993 (916) 483-0572 Fax Notification Web: www.dir.ca.gov or calosha.com
CDPH/CLPPB: PH# (510) 620-5600 Web: www.cdph.ca.gov/programs/CLPPB
SCAQMD: PH# (909) 396-3739 Fax#(909) 396-3342
BAAQMD: PH# (415) 749-4762

NATEC International, Inc.
National Association of Training and Environmental Consulting
Asbestos · Lead · Mold · HAZWOPER
PO Box 8657, Fountain Valley, CA 92728
(714) 678-2750, (800) 969-3228, Fax (714) 678-2757
www.natecintl.com

NATEC International, Inc.
National Association of Training and Environmental Consulting
This Card Acknowledges That Daniel E. Gonzales III
Holds Training Certification For Asbestos Building Inspector Refresher Course
Expiration: 2/20/2026
Training Date: 2/20/2025 Michael W. Horner
Certificate No. ABIR0220250002N44311 Training Director

Certificate of Attendance

CERTIFICATE NUMBER **46324**

This is to Certify that

DANIEL E. GONZALES III

Has Completed the Course of

AIR SAMPLING & ANALYSIS OF AIRBORNE ASBESTOS (NIOSH-582 EQUIVALENT)

For purposes of accreditation under section 206 of the Toxic Substances Control Act (TSCA) and compliance with AHAP in accordance with 40 FR 5226 effective April 1994

ARMANDO DUCOING
DIRECTOR

April 30, 2006	E042206NIOSH582	042206	
COMPLETION DATE	CLASS NUMBER / STARTING DATE		CERTIFICATE EXPIRES

Ecologics Training Institute

550 N. Parkcenter Drive, Suite 102 . Santa Ana. CA 92705 . Ph. (714) 480-0111 . Fax (714) 480-0222

STATE OF CALIFORNIA
DEPARTMENT OF INDUSTRIAL RELATIONS
Division of Occupational Safety and Health-Asbestos & Carcinogen Unit
1750 Howe Avenue, Suite 460
Sacramento, CA 95825
(916) 574-2993 Office http://www.dir.ca.gov/dosh/asbestos.html actu@dir.ca.gov

Gavin Newsom, Governor

611034103T

9/24/2025

Daniel Gonzales
5958 Berdie Drive
La Verne CA 91750

Dear Certified Asbestos Consultant or Technician:

Enclosed is your certification card. **To maintain your certification, you must abide by the rules printed on th back of the certification card.**

Your certification is valid for a period of one year. If you wish to renew your certification, you must apply for renewal at least 60 days before the expiration date shown on your card. [8 CCR 341.15(h)(1)].

Please hold and do not send copies of your required AHERA refresher renewal certificates to our office until you apply for renewal of your certification.

Certificates must be kept current if you are actively working as a CAC or CSST. The grace period is only for those who are not actively working as an asbestos consultant or site surveillance technician.

Please contact our office at the above address or email w any changes in your contact/mailing information within 15 days of the change.

Sincerely,

Dean Mochrie, CAC
Senior Safety Engineer

Attachment: Certification Card

cc: File

Renewal – Card Attached (08/24)

State of California
Division of Occupational Safety and Health
Certified Site Surveillance Technician
Daniel E Gonzales



Certification No. 06-4103
Expires on 11/15/2026

CDPH
California Department of Public Health

STATE OF CALIFORNIA
DEPARTMENT OF PUBLIC HEALTH

LEAD-RELATED CONSTRUCTION CERTIFICATE

INDIVIDUAL:	CERTIFICATE TYPE:	NUMBER:	EXPIRATION DATE:
	Lead Sampling Technician	LRC-00003833	2/12/2027

Daniel Gonzales

Disclaimer: This document alone should not be relied upon to confirm certification status. Compare the individual's photo and name to another valid form of government issued photo identification. Verify the individual's certification status by searching for Lead-Related Construction Professionals at www.cdph.ca.gov/programs/clppb or calling (800) 597-LEAD



Asbestos Training Program

This is to certify

Justin Lavezzoli
4633

Has successfully completed 4 hours of formal training required by section 206 of TSCA II entitled

Building Inspector
Refresher

Presented By
Environmental Compliance Training
PO BOX 16555
San Diego, CA 92176-6555
(858) 558-7465

Director:
Walter T. Amenta, CIH, Approval Number CA-029-06

Class Dates: 07-08-2025
Exam Date: n/a
Expiration Date: 07-08-2026
Certification Number: 0725ABCA192304

Asbestos Training Program

This is to certify

Justin Lavezzoli
4633

Has successfully completed 8 hours of formal training required by section 206 of TSCA II entitled

Project Designer
Refresher

Presented By
Environmental Compliance Training
PO BOX 16555
San Diego, CA 92176-6555
(858) 558-7465

Director:
Walter T. Amenta, CIH, Approval Number CA-029-10

Class Dates: 07-09-2025
Exam Date: n/a
Expiration Date: 07-09-2026
Certification Number: 0725ABCA192504

State of California
Division of Occupational Safety and Health
Certified Asbestos Consultant
Justin C Lavezzoli

Certification No. 24-7772
Expires on 10/18/2026

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq of the Business and Professions Code.

Asbestos Training Program

This is to certify

Justin Lavezzoli
4633

Has successfully completed 4 hours of formal training required by section 206 of TSCA II entitled

Management Planner
Refresher

Presented By
Environmental Compliance Training
PO BOX 16555
San Diego, CA 92176-6555
(858) 558-7465

Director:
Walter T. Amenta, CIH, Approval Number CA-029-08

Class Dates: 07-08-2025
Exam Date: n/a
Expiration Date: 07-08-2026
Certification Number: 0725ABCA192404

Asbestos Training Program

This is to certify

Justin Lavezzoli
4633

Has successfully completed 8 hours of formal training required by section 206 of TSCA II entitled

Contractor/Supervisor
Refresher

Presented By
Environmental Compliance Training
PO BOX 16555
San Diego, CA. 92176-6555
(858) 558-7465

Director:
Walter T. Amenta, CIH, Approval Number CA-029-04

Class Dates: 07-07-2025
Exam Date: n/a
Expiration Date: 07-07-2026
Certification Number: 0725ABCA192204

Asbestos Training Program

This is to certify

Justin Lavezzoli
4633

Has successfully completed 40 hours of formal training entitled

NIOSH 582
Equivalency

Presented By
Environmental Compliance Training
PO BOX 16555
San Diego, CA. 92176
(858) 558-7465

Director:
Walter T. Amenta, CIH

Class Dates: 04/18-22/2022
Expiration Date: N/A
Certification Number: 0422N582E-01

CDPH
California Department of Public Health

STATE OF CALIFORNIA
DEPARTMENT OF PUBLIC HEALTH

LEAD-RELATED CONSTRUCTION CERTIFICATE

INDIVIDUAL:	CERTIFICATE TYPE:	NUMBER:	EXPIRATION DATE:
	Lead Project Monitor	LRC-00013824	2/26/2027
	Lead Sampling Technician	LRC-00009043	7/27/2026

Justin Lavezzoli

Disclaimer: This document alone should not be relied upon to confirm certification status. Compare the individual's photo and name to another valid form of government issued photo identification. Verify the individual's certification status by searching for Lead-Related Construction Professionals at www.cdph.ca.gov/programs/clppb or calling (800) 597-LEAD