November 4, 2026

Leo Rodriguez
Risk Management
Portland Public Schools

Via email: lrodriguez@pps.net

Regarding: Electronic Radon Monitor Results
Vernon Elementary School
2044 NE Killingsworth Street
Portland, Oregon
Apex Project 25012092

Mr. Rodriguez:

In January and February 2025, Apex performed short-term radon monitoring at Vernon Elementary at the request of Portland Public Schools. Results of short-term testing identified elevated radon in the Basement Staff Room, Stage/Multipurpose Room, and Room 116. In response, in February 2025 Apex performed follow-up testing with electronic Continuous Radon Monitors (CRMs) in February 2025 to determine hour-by-hour radon concentrations and provide additional information on mitigation strategies. Those results indicated no elevated average radon concentrations. Now, Apex has conducted an additional round of CRM testing in the same locations in October 2026 to confirm those results.

METHODOLOGY

The Environmental Protection Agency (EPA) recommends, and the Oregon Health Authority (OHA) requires, that school buildings be tested for radon, and that any radon concentrations be maintained below 4.0 picocuries per liter (pCi/L) of air. Apex used Sun Nuclear 1028 CRMs to monitor in select areas and identify the dynamics of radon concentration over time.

Testing was conducted during the winter heating season and during the school week when building uses and operations were normal. Occupied hours were considered to be 6:00 AM to 6:00 PM and unoccupied hours were 6:00 PM to 6:00 AM.

RESULTS

The following table lists the results of radon concentrations at all tested locations.

Table 1: CRM Data Summary

Location	Test Dates	Overall Average Radon Level*	Average Radon Level During Occupied Hours*	Average Radon Level During Unoccupied Hours*
Basement Staff	10/26 – 10/30	3.0	2.6	3.3
Multipurpose Room	10/26 – 10/30	2.1	2.2	2.0
Room 116	10/26 – 10/30	0.7	0.6	0.7

* - units are pCi/L

Overall, the concentration of radon was below the regulatory limit of 4.0 pCi/L, in all tested locations, matching follow up test results from February 2025. See the attached CRM printout for additional information on each location.

LIMITATIONS OF SCOPE

This study was limited to the tests and locations as previously indicated. The site as a whole may have other environmental concerns that will not be characterized by this study. PBS is not able to represent conditions on the site or adjoining sites beyond those detected or observed by PBS.

Please feel free to contact me at 503.515.7489 or james.mastanduno@pbsusa.com with any questions or comments.

Sincerely,



James Mastanduno
Project Manager

Attachment: CRM Summary Report

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Radon Inspection Report

Test Location:
Vernon Elementary School

Test For:

Inspected By:
James Mastanduno, Apex Companies
YOUR ADDRESS1, YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Bldg. Type: Educational

Type: Follow Up



Test Result: Pass

Overall Average:
0.7 pCi/l

EPA Average:
0.7 pCi/l

Test Device Details:

SunRADON CRM:	1028XP
Serial Number:	238738020
Last Calibration:	11/05/2025
Next Calibration:	11/05/2026
Cal-Factors:	2.20
Motion Error:	Yes

Test Summary:

CRM Location:	Start	Stop	Interval	Duration
Room 116	10/26/2026 06:02 AM	10/30/2026 08:02 AM	1 hr	98 hr

Test Details:

*First 4 hrs of data excluded	Min	Max	Average	Units
Radon Concentration	0.0	2.7	0.7	pCi/l

Comments:

Lic/Cert Signature


Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

OneRADON™ Version 2.5.8

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Radon Inspection Chart



Test Result: Pass

Test Location: ,

Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Test Checklist

- ☑ The location of the detector was selected so the detector was not to be disturbed during testing.
- ☑ The monitor was not placed in an area of high humidity such as: Kitchen, laundry room, cellar, spa room, garage, crawl space or sump area.
- ☑ The detector was not located near drafts caused by HVAC vents, windows and doors.
- ☑ Whole house fans were turned off during the testing.
- ☑ The detector was not placed near areas of excessive heat, such as a fireplace or in direct sunlight.
- ☑ Portable window fans were removed or sealed in place prior to testing.
- ☑ The detector was placed within the breathing zone of at least 20 inches to 6 feet above the floor and at least 1 foot below the ceiling if suspended.
- ☑ The detector was not placed within 1 foot of outside walls of the home or within 3 feet of any windows or doors to the exterior of the home.

Test Result: Pass

Test Location: ,

Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Test Table

* Data from first 4 hours excluded from EPA calculations

Date/Time	Radon(pCi/l)	Flags
10/26/26 07:02 AM	0.9	M
10/26/26 08:02 AM	0.9	-
10/26/26 09:02 AM	1.8	-
10/26/26 10:02 AM	1.4	-
10/26/26 11:02 AM	2.7	-
10/26/26 12:02 PM	1.4	-
10/26/26 01:02 PM	0.0	-
10/26/26 02:02 PM	0.9	-
10/26/26 03:02 PM	1.8	-
10/26/26 04:02 PM	1.4	-
10/26/26 05:02 PM	0.0	-
10/26/26 06:02 PM	0.9	-
10/26/26 07:02 PM	1.4	-
10/26/26 08:02 PM	0.5	-
10/26/26 09:02 PM	0.0	-
10/26/26 10:02 PM	1.4	-
10/26/26 11:02 PM	0.9	-
10/27/26 12:02 AM	0.5	-
10/27/26 01:02 AM	0.5	-
10/27/26 02:02 AM	0.0	-
10/27/26 03:02 AM	2.7	-
10/27/26 04:02 AM	1.4	-
10/27/26 05:02 AM	1.4	-
10/27/26 06:02 AM	0.9	-
10/27/26 07:02 AM	1.4	-
10/27/26 08:02 AM	0.0	-
10/27/26 09:02 AM	0.0	-
10/27/26 10:02 AM	0.5	-
10/27/26 11:02 AM	0.0	-
10/27/26 12:02 PM	0.9	-
10/27/26 01:02 PM	0.5	-
10/27/26 02:02 PM	0.5	-
10/27/26 03:02 PM	1.4	-
10/27/26 04:02 PM	0.5	-
10/27/26 05:02 PM	1.4	-
10/27/26 06:02 PM	0.0	-
10/27/26 07:02 PM	0.5	-
10/27/26 08:02 PM	0.5	-
10/27/26 09:02 PM	0.9	-
10/27/26 10:02 PM	0.0	-
10/27/26 11:02 PM	0.0	-
10/28/26 12:02 AM	0.9	-
10/28/26 01:02 AM	0.9	-
10/28/26 02:02 AM	1.4	-
10/28/26 03:02 AM	0.5	-
10/28/26 04:02 AM	1.4	-
10/28/26 05:02 AM	0.0	-
10/28/26 06:02 AM	0.0	-

Test Result: Pass

Test Location: ,

Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Test Table

* Data from first 4 hours excluded from EPA calculations

Date/Time	Radon(pCi/l)	Flags
10/28/26 07:02 AM	0.5	-
10/28/26 08:02 AM	0.5	-
10/28/26 09:02 AM	0.9	-
10/28/26 10:02 AM	0.5	-
10/28/26 11:02 AM	0.5	-
10/28/26 12:02 PM	0.0	-
10/28/26 01:02 PM	0.5	-
10/28/26 02:02 PM	0.0	-
10/28/26 03:02 PM	0.0	-
10/28/26 04:02 PM	0.5	-
10/28/26 05:02 PM	0.5	-
10/28/26 06:02 PM	0.0	-
10/28/26 07:02 PM	1.4	-
10/28/26 08:02 PM	0.0	-
10/28/26 09:02 PM	0.5	-
10/28/26 10:02 PM	0.9	-
10/28/26 11:02 PM	0.9	-
10/29/26 12:02 AM	0.5	-
10/29/26 01:02 AM	0.5	-
10/29/26 02:02 AM	1.4	-
10/29/26 03:02 AM	0.0	-
10/29/26 04:02 AM	1.4	-
10/29/26 05:02 AM	0.0	-
10/29/26 06:02 AM	0.5	-
10/29/26 07:02 AM	0.0	-
10/29/26 08:02 AM	0.5	-
10/29/26 09:02 AM	1.4	-
10/29/26 10:02 AM	0.9	-
10/29/26 11:02 AM	0.9	-
10/29/26 12:02 PM	0.0	-
10/29/26 01:02 PM	0.0	-
10/29/26 02:02 PM	0.9	-
10/29/26 03:02 PM	0.9	-
10/29/26 04:02 PM	0.5	-
10/29/26 05:02 PM	0.0	-
10/29/26 06:02 PM	0.9	-
10/29/26 07:02 PM	2.3	-
10/29/26 08:02 PM	1.4	-
10/29/26 09:02 PM	0.5	-
10/29/26 10:02 PM	0.5	-
10/29/26 11:02 PM	0.5	-
10/30/26 12:02 AM	0.0	-
10/30/26 01:02 AM	0.9	-
10/30/26 02:02 AM	0.5	-
10/30/26 03:02 AM	1.4	-
10/30/26 04:02 AM	0.5	-
10/30/26 05:02 AM	1.4	-
10/30/26 06:02 AM	1.8	-

Test Result: Pass

Test Location: ,

Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Test Table

* Data from first 4 hours excluded from EPA calculations

Date/Time	Radon(pCi/l)	Flags
10/30/26 07:02 AM	0.5	-
10/30/26 08:02 AM	0.0	-

Test Result: Pass

Test Location: ,

Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Radon Inspection Report

Test Location:
Vernon Elementary School

Test For:

Inspected By:
James Mastanduno, Apex Companies
YOUR ADDRESS1, YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Bldg. Type: Educational

Type: Follow Up

Radon
Test.
Report.
Prevent.

Test Result: Pass

Overall Average:
3.0 pCi/l

EPA Average:
3.1 pCi/l

Test Device Details:

SunRADON CRM:	1028XP
Serial Number:	238348024
Last Calibration:	10/15/2025
Next Calibration:	10/15/2026
Cal-Factors:	2.47
Motion Error:	Yes

Test Summary:

CRM Location:	Start	Stop	Interval	Duration
Basement Staff Room Near Cafeteria	10/26/2026 06:19 AM	10/30/2026 08:19 AM	1 hr	98 hr

Test Details:

*First 4 hrs of data excluded	Min	Max	Average	Units
Radon Concentration	0.0	8.1	3.1	pCi/l

Comments:

Lic/Cert Signature


Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

OneRADON™ Version 2.5.8

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Radon Inspection Chart



Test Result: Pass

Test Location: ,

Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Test Checklist

- ☑ The location of the detector was selected so the detector was not to be disturbed during testing.
- ☑ The monitor was not placed in an area of high humidity such as: Kitchen, laundry room, cellar, spa room, garage, crawl space or sump area.
- ☑ The detector was not located near drafts caused by HVAC vents, windows and doors.
- ☑ Whole house fans were turned off during the testing.
- ☑ The detector was not placed near areas of excessive heat, such as a fireplace or in direct sunlight.
- ☑ Portable window fans were removed or sealed in place prior to testing.
- ☑ The detector was placed within the breathing zone of at least 20 inches to 6 feet above the floor and at least 1 foot below the ceiling if suspended.
- ☑ The detector was not placed within 1 foot of outside walls of the home or within 3 feet of any windows or doors to the exterior of the home.

Test Result: Pass

Test Location: ,

Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Test Table

* Data from first 4 hours excluded from EPA calculations

Date/Time	Radon(pCi/l)	Flags
10/26/26 07:19 AM	0.4	M
10/26/26 08:19 AM	1.2	-
10/26/26 09:19 AM	1.2	-
10/26/26 10:19 AM	2.8	-
10/26/26 11:19 AM	2.8	-
10/26/26 12:19 PM	2.4	-
10/26/26 01:19 PM	4.0	-
10/26/26 02:19 PM	2.8	-
10/26/26 03:19 PM	2.8	-
10/26/26 04:19 PM	1.6	-
10/26/26 05:19 PM	0.4	-
10/26/26 06:19 PM	2.8	-
10/26/26 07:19 PM	1.6	-
10/26/26 08:19 PM	3.6	-
10/26/26 09:19 PM	2.4	-
10/26/26 10:19 PM	4.0	-
10/26/26 11:19 PM	0.4	-
10/27/26 12:19 AM	3.6	-
10/27/26 01:19 AM	2.0	-
10/27/26 02:19 AM	2.4	-
10/27/26 03:19 AM	3.6	-
10/27/26 04:19 AM	1.6	-
10/27/26 05:19 AM	3.6	-
10/27/26 06:19 AM	4.0	-
10/27/26 07:19 AM	3.2	-
10/27/26 08:19 AM	8.1	-
10/27/26 09:19 AM	2.8	-
10/27/26 10:19 AM	1.6	-
10/27/26 11:19 AM	2.4	-
10/27/26 12:19 PM	0.8	-
10/27/26 01:19 PM	2.0	-
10/27/26 02:19 PM	3.2	M
10/27/26 03:19 PM	1.2	-
10/27/26 04:19 PM	2.4	-
10/27/26 05:19 PM	2.8	-
10/27/26 06:19 PM	5.7	-
10/27/26 07:19 PM	2.0	-
10/27/26 08:19 PM	5.7	-
10/27/26 09:19 PM	5.7	M
10/27/26 10:19 PM	1.6	-
10/27/26 11:19 PM	3.6	M
10/28/26 12:19 AM	2.8	-
10/28/26 01:19 AM	4.5	-
10/28/26 02:19 AM	3.2	-
10/28/26 03:19 AM	1.2	-
10/28/26 04:19 AM	2.8	-
10/28/26 05:19 AM	1.6	-
10/28/26 06:19 AM	0.4	-

Test Result: Pass

Test Location: ,

Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Test Table

* Data from first 4 hours excluded from EPA calculations

Date/Time	Radon(pCi/l)	Flags
10/28/26 07:19 AM	2.0	M
10/28/26 08:19 AM	2.0	-
10/28/26 09:19 AM	1.2	-
10/28/26 10:19 AM	1.6	-
10/28/26 11:19 AM	0.8	-
10/28/26 12:19 PM	1.2	-
10/28/26 01:19 PM	0.0	M
10/28/26 02:19 PM	0.8	-
10/28/26 03:19 PM	2.4	-
10/28/26 04:19 PM	1.6	-
10/28/26 05:19 PM	2.4	-
10/28/26 06:19 PM	1.2	-
10/28/26 07:19 PM	3.2	-
10/28/26 08:19 PM	3.6	-
10/28/26 09:19 PM	1.2	-
10/28/26 10:19 PM	1.6	-
10/28/26 11:19 PM	3.2	-
10/29/26 12:19 AM	3.2	-
10/29/26 01:19 AM	2.4	-
10/29/26 02:19 AM	3.6	-
10/29/26 03:19 AM	3.2	-
10/29/26 04:19 AM	2.0	-
10/29/26 05:19 AM	4.0	-
10/29/26 06:19 AM	4.5	-
10/29/26 07:19 AM	4.0	-
10/29/26 08:19 AM	4.9	-
10/29/26 09:19 AM	3.2	-
10/29/26 10:19 AM	2.4	-
10/29/26 11:19 AM	0.8	-
10/29/26 12:19 PM	2.4	-
10/29/26 01:19 PM	2.4	-
10/29/26 02:19 PM	2.4	-
10/29/26 03:19 PM	1.2	-
10/29/26 04:19 PM	2.8	-
10/29/26 05:19 PM	7.3	-
10/29/26 06:19 PM	5.7	-
10/29/26 07:19 PM	3.6	-
10/29/26 08:19 PM	7.3	-
10/29/26 09:19 PM	3.6	-
10/29/26 10:19 PM	7.7	-
10/29/26 11:19 PM	5.7	-
10/30/26 12:19 AM	4.5	-
10/30/26 01:19 AM	5.3	-
10/30/26 02:19 AM	5.3	-
10/30/26 03:19 AM	4.5	-
10/30/26 04:19 AM	6.5	-
10/30/26 05:19 AM	3.6	-
10/30/26 06:19 AM	4.9	-

Test Result: Pass

Test Location: ,

Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Test Table

* Data from first 4 hours excluded from EPA calculations

Date/Time	Radon(pCi/l)	Flags
10/30/26 07:19 AM	6.5	-
10/30/26 08:19 AM	3.2	-

Test Result: Pass

Test Location: ,

Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Radon Inspection Report

Test Location:
Vernon Elementary School

Test For:

Inspected By:
James Mastanduno, Apex Companies
YOUR ADDRESS1, YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Bldg. Type: Educational

Type: Follow Up



Test Result: Pass

Overall Average:
2.1 pCi/l

EPA Average:
2.1 pCi/l

Test Device Details:

SunRADON CRM:	1028XP
Serial Number:	238738033
Last Calibration:	11/05/2025
Next Calibration:	11/05/2026
Cal-Factors:	2.65
Motion Error:	Yes

Test Summary:

CRM Location:	Start	Stop	Interval	Duration
Multipurpose Room	10/26/2026 06:40 AM	10/30/2026 08:40 AM	1 hr	98 hr

Test Details:

*First 4 hrs of data excluded	Min	Max	Average	Units
Radon Concentration	0.0	5.7	2.1	pCi/l

Comments:

Lic/Cert Signature


Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

OneRADON™ Version 2.5.8

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Radon Inspection Chart



Test Result: Pass

Test Location: ,

Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Test Checklist

- ☑ The location of the detector was selected so the detector was not to be disturbed during testing.
- ☑ The monitor was not placed in an area of high humidity such as: Kitchen, laundry room, cellar, spa room, garage, crawl space or sump area.
- ☑ The detector was not located near drafts caused by HVAC vents, windows and doors.
- ☑ Whole house fans were turned off during the testing.
- ☑ The detector was not placed near areas of excessive heat, such as a fireplace or in direct sunlight.
- ☑ Portable window fans were removed or sealed in place prior to testing.
- ☑ The detector was placed within the breathing zone of at least 20 inches to 6 feet above the floor and at least 1 foot below the ceiling if suspended.
- ☑ The detector was not placed within 1 foot of outside walls of the home or within 3 feet of any windows or doors to the exterior of the home.

Test Result: Pass

Test Location: ,

Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Test Table

* Data from first 4 hours excluded from EPA calculations

Date/Time	Radon(pCi/l)	Flags
10/26/26 07:40 AM	1.5	M
10/26/26 08:40 AM	2.3	-
10/26/26 09:40 AM	4.9	-
10/26/26 10:40 AM	3.0	-
10/26/26 11:40 AM	3.0	-
10/26/26 12:40 PM	4.2	-
10/26/26 01:40 PM	3.4	-
10/26/26 02:40 PM	2.6	-
10/26/26 03:40 PM	1.9	-
10/26/26 04:40 PM	1.9	-
10/26/26 05:40 PM	2.6	-
10/26/26 06:40 PM	1.1	-
10/26/26 07:40 PM	2.3	-
10/26/26 08:40 PM	1.5	-
10/26/26 09:40 PM	2.3	-
10/26/26 10:40 PM	1.9	-
10/26/26 11:40 PM	1.5	-
10/27/26 12:40 AM	2.6	-
10/27/26 01:40 AM	1.5	-
10/27/26 02:40 AM	0.4	-
10/27/26 03:40 AM	2.3	-
10/27/26 04:40 AM	0.8	-
10/27/26 05:40 AM	0.8	-
10/27/26 06:40 AM	2.3	-
10/27/26 07:40 AM	1.5	-
10/27/26 08:40 AM	0.8	-
10/27/26 09:40 AM	2.3	-
10/27/26 10:40 AM	2.6	-
10/27/26 11:40 AM	1.5	-
10/27/26 12:40 PM	1.1	-
10/27/26 01:40 PM	0.0	-
10/27/26 02:40 PM	0.8	M
10/27/26 03:40 PM	1.1	-
10/27/26 04:40 PM	0.4	M
10/27/26 05:40 PM	0.8	M
10/27/26 06:40 PM	0.4	-
10/27/26 07:40 PM	1.1	-
10/27/26 08:40 PM	0.4	-
10/27/26 09:40 PM	0.0	-
10/27/26 10:40 PM	0.4	-
10/27/26 11:40 PM	0.8	-
10/28/26 12:40 AM	0.0	-
10/28/26 01:40 AM	1.9	-
10/28/26 02:40 AM	1.1	-
10/28/26 03:40 AM	1.9	-
10/28/26 04:40 AM	0.8	-
10/28/26 05:40 AM	1.1	-
10/28/26 06:40 AM	1.9	-

Test Result: Pass

Test Location: ,

Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Test Table

* Data from first 4 hours excluded from EPA calculations

Date/Time	Radon(pCi/l)	Flags
10/28/26 07:40 AM	3.0	-
10/28/26 08:40 AM	3.0	-
10/28/26 09:40 AM	1.1	-
10/28/26 10:40 AM	2.6	-
10/28/26 11:40 AM	1.9	-
10/28/26 12:40 PM	1.5	-
10/28/26 01:40 PM	1.5	-
10/28/26 02:40 PM	1.5	-
10/28/26 03:40 PM	0.4	-
10/28/26 04:40 PM	1.5	-
10/28/26 05:40 PM	1.5	M
10/28/26 06:40 PM	1.1	-
10/28/26 07:40 PM	1.5	-
10/28/26 08:40 PM	2.6	-
10/28/26 09:40 PM	1.5	-
10/28/26 10:40 PM	1.5	-
10/28/26 11:40 PM	0.4	-
10/29/26 12:40 AM	0.8	-
10/29/26 01:40 AM	0.4	-
10/29/26 02:40 AM	2.6	-
10/29/26 03:40 AM	0.8	-
10/29/26 04:40 AM	2.6	-
10/29/26 05:40 AM	1.5	-
10/29/26 06:40 AM	1.9	-
10/29/26 07:40 AM	1.5	-
10/29/26 08:40 AM	0.8	M
10/29/26 09:40 AM	1.9	-
10/29/26 10:40 AM	1.1	M
10/29/26 11:40 AM	2.3	-
10/29/26 12:40 PM	2.3	-
10/29/26 01:40 PM	3.0	-
10/29/26 02:40 PM	4.9	-
10/29/26 03:40 PM	2.3	M
10/29/26 04:40 PM	5.7	-
10/29/26 05:40 PM	4.9	-
10/29/26 06:40 PM	4.9	-
10/29/26 07:40 PM	3.4	-
10/29/26 08:40 PM	3.8	-
10/29/26 09:40 PM	5.3	-
10/29/26 10:40 PM	5.3	-
10/29/26 11:40 PM	3.4	-
10/30/26 12:40 AM	2.3	-
10/30/26 01:40 AM	4.2	-
10/30/26 02:40 AM	4.2	-
10/30/26 03:40 AM	3.8	-
10/30/26 04:40 AM	4.5	-
10/30/26 05:40 AM	4.9	-
10/30/26 06:40 AM	3.0	-

Test Result: Pass

Test Location: ,

Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC

Portland Public Schools
YOUR ADDRESS1 YOUR ADDRESS2
YOUR CITY, YOUR STATE YOUR ZIP
123-456-7890

Test Table

* Data from first 4 hours excluded from EPA calculations

Date/Time	Radon(pCi/l)	Flags
10/30/26 07:40 AM	3.0	-
10/30/26 08:40 AM	2.6	-

Test Result: Pass

Test Location: ,

Inspection Report Date: 11/02/2026

Test device manufactured by SunRADON, LLC