
William Floyd School District

CAPITAL PROJECT REVIEW #5



Capital Project Review





RECONSTRUCTION WORK

Wm Floyd SD - Capital Improvement Summary		
	20-Jul-17	
RECONSTRUCTION WORK		
William Floyd HS	\$3,770,000	
Fire Alarm System/Clrm UV's & Electrical Panels		
Paca MS	\$1,800,000	
Fire Alarm/Boiler Rm Floor & Electrical Panels		
Wm. Floyd MS	\$1,070,000	
Air Handling, Ventilation, Electrical Panels		
Wm. Floyd ES	\$3,080,000	
1992 Roof/Original Bld Windows/Water Piping/ Fire Alarm/ Clock System & Electrical Panels		
Woodhull ES	\$2,575,000	
Roof/Fire Alarm/ Clock System & Electrical Panels		
Hobart ES	\$725,000	
1992 Roof/Fire Alarm & Exhaust Sys		
Moriches ES	\$3,605,000	
Roof/Fire Alarm & Electrical Panels		
Tangier ES	\$875,000	
Roof/Fire Alarm & Electrical Panels		
Sub-Total	\$17,500,000	

ELEMENTARY AIR CONDITIONING



ELEMENTARY AIR CONDITIONING




ELEMENTARY AIR CONDITIONING

Wm Floyd SD - Capital Improvement Summary				
	20-Jul-17			
 AIR CONDITIONING WORK				
 Wm. Floyd ES	\$3,835,000			
Woodhull ES	\$2,125,000			
 Hobart ES	\$2,845,000			
Sub-Total	\$8,805,000			



AUDITORIUM UPGRADES



Upgrades to High School/PACA MS/WFMS - Auditorium lighting/sound systems and media systems -

COST ESTIMATE- \$2,625,000



Adaptive Playground – Site



Adaptive Playground – Site



Adaptive Playground Rendering























Cost Estimate - \$400,000



Main Sports Area



Main Sports Area



Main Sports Area Cost Est.

Main Sports Area	
 Reconstruction of Main Sports Area Multi-Sport Syn Turf/ New Track Concept 2	***************************************
New Pre-Fabricated Press Box 30' x 10'	\$265,000
Lighting upgrades Main Sports	\$450,000
 Sub-Total	\$4,630,000



Baseball/Softball Infield



Baseball/Softball Infield



Baseball/Softball Infield Cost Est.

Ballfields	
Baseball- Infield Syn Turf (@ 27,000 sqft)-includes logo, restorations of outfield, new backstop, foul poles, 6ft sideline and outfield chain link fence	\$825,000
Baseball- Infield Syn Turf (@ 13,000 sqft) -includes logo, restorations of outfield, new backstop, foul poles, 6ft sideline and outfield chain link fence	\$435,000
	\$1,260,000

TENNIS COURT WORK



TENNIS COURT WORK




TENNIS COURT WORK – COST EST.

	Tennis - Paca	
	2 new Tennis courts - includes netting, posts and chain link perimeter fence	*290.000
•••	Re-coat 8 existing courts- Two color system with new line striping. Assume minor repair to surface. No modifications to Exg posts, fencing or surrounding asphalt paths.	\$230,000
_		\$520,000



ORIGINAL SPORTS AREA



ORIGINAL SPORTS AREA



ORIGINAL SPORTS AREA

Original Sports Area	LARGER FLD NEW SYN TURF
Reconstruction of existing Fld into larger Fld (200 x 380) (no track)- Multi-Sport SynTurf Fld	\$1,830,000
New 6 lane rubberized track to fit on the larger (200 x 380) Fld (no field events)	\$1,720,000
New Scoreboard for Original Fld	\$80,000
Sub-Total	\$3,630,000



TOTAL COST ESTIMATES

AREA		COST ESTIMATE	
RECONSTRUCTION WORK DISTRICT WIDE	\$	17,500,000	
ELEMENTARY AIR CONDITIONING	\$	8,805,000	
MAIN SPORTS AREA	\$	4,630,000	
BASEBALL/SOFTBALL IN FIELDS	\$	1,260,000	
TENNIS COURTS	\$	520,000	
ORIGINAL SPORTS AREA	\$	3,630,000	
ADAPTIVE PLAYGROUND	\$	400,000	
HS GYMNASIUM PA SYSTEM	\$	100,000	
HS, WFMS, PACA MS - AUDITORIUM UPGRADES	\$	2,625,000	
	\$	39,470,000	



District Building Aid Ratio



For all approved Capital
Projects the district only
pays \$.1210 of each dollar
spent





