



WELDING TECHNICIAN - INTERMEDIATE

1. Understand and use welding safety and first aid.
2. Read and interpret welding blueprints.
3. Identify and apply intermediate welding symbols.
4. Use flux cored arc welding (FCAW) process.
5. Use gas tungsten arc welding (GTAW) process.
6. Use gas metal arc welding (GMAW) processes.
7. Use air carbon arc cutting (CAC-A) or gouging process.
8. Use plasma arc cutting process.
9. Understand the importance of career readiness skills as it relates to the workplace and outlined in the SkillsUSA Framework-Level 2.
10. CTE Skill Certificate Test.