

Lead in Water Testing Results

South Washington County Schools

District Program Center/Alternative High School

On September 12th, 2018 the District Program Center/Alternative High School's drinking water was tested for concentration of lead.

The following water sources tested less than 20 parts-per-billion.

No action was taken at this time.

LOCATION	SOURCE	RESULTS (in ug/L)
Room 125 (left)	SINK	8.1
Nurse's Office (DPC)	SINK	9.7
Room 125 (right)	SINK	11.8
Room 124	SINK	10.8
Lobby (left)	FOUNTAIN	.4
Lobby (right)	FOUNTAIN	.37
Senior Center	SINK	.35
Senior Kitchen	SPRAYER	.21
Senior Kitchen (right)	SINK	14.0
Senior Kitchen (left)	SINK	12.6
Hallway (south, right)	FOUNTAIN	0
Hallway (south, left)	FOUNTAIN	0
Hallway (south)	BOTTLE FILLER	0
Hallway (west, left)	FOUNTAIN	1.1
Hallway (west, right)	FOUNTAIN	.79
Room 103	SINK	12.6

LOCATION	SOURCE	RESULTS (in ug/L)
Nurse's Office (AHS, 1)	SINK	17.1
Nurse's Office (AHS 2)	SINK	1.6
Cafeteria	SINK	.49
Kitchen	SINK	18.6
Hallway (north)	FOUNTAIN	1.6
Room 123 (south)	SINK	10.4
Room 123 (north)	SINK	10.0
Storage Room/Staff (by lobby)	SINK	1.3
Room 130	SINK	12.8
Room 130 (porcelain)	SINK	3.1
Room 132	SINK	1.8
Room 132 (porcelain)	SINK	13.5
Lunchroom (middle west)	SINK	10.5
Lunchroom (middle east)	SINK	9.7
Special Services Workroom	SINK	1.4
Room 128 (east)	SINK	12.3
Room 128 (south)	SINK	8.0
Room 126 (right)	SINK	8.0
Room 126 (left)	SINK	9.5
Hallway (east, left)	SINK	1.5
Hallway (east, right)	SINK	.54

The following water sources tested with results of the concentration to be over 20 parts-per-billion. The fixtures of these water sources have been replaced and a re-test was administered. Results of the initial test and retest are below. No water sources re-tested over 20 parts-per-billion and no further action was taken at this time.

LOCATION	SOURCE	INITIAL RESULTS (in ug/L)	RE-TEST RESULTS
Kitchen (left)	SINK	40	10.9
Kitchen (right)	SINK	42.4	14.5
Kitchen (sprayer)	SPRAYER	23.9	13.5
Room 118	SINK	20.2	9.9
Room 118 (south)	SINK	20.2	11.6