

Lead in Water Testing Results

South Washington County Schools

Nuevas Fronteras Spanish Immersion School

On January 4th, 2019 Nuevas Fronteras SI School's drinking water was tested for concentration of lead.

All water sources tested less than 20 parts-per-billion.

No action was taken at this time.

LOCATION	SOURCE	RESULTS (in ug/L)
Room 116	SINK	1.2
Room 117	SINK	.56
Hallway (outside 117, left)	FOUNTAIN	0
Hallway (outside 117, right)	FOUNTAIN	0
Hallway (outside 117)	BOTTLE FILLER	0
Room 120	SINK	.89
Hallway (outside 120, left)	FOUNTAIN	0
Hallway (outside 120, right)	FOUNTAIN	0
Hallway (outside 120)	BOTTLE FILLER	0
Room 122	SINK	.81
Room 128 (1)	SINK	4.4
Room 128 (2)	SINK	2.4
Room 128 (3)	SINK	1.4
Room 128 (4)	SINK	2.6
Room 128 (5)	SINK	2.7
Hallway (outside 132)	FOUNTAIN	5.6
Hallway (outside 140)	FOUNTAIN	3.2

Hallway (outside 141, left)	FOUNTAIN	0
Hallway (outside 141, right)	FOUNTAIN	0
Hallway (outside 141)	BOTTLE FILLER	0
Gym (right)	FOUNTAIN	.64
Gym (left)	FOUNTAIN	.22
Cafeteria	FOUNTAIN	0
Cafeteria	BOTTLE FILLER	0
Kitchen	SINK	2.6
Kitchen	SPRAYER	4.9

*Please note that this building was under construction when the water testing took place. Not all fixtures could be tested at this time.