

2016-2017 Engine #3 Operator ReCertification Route

Leave Engine #3 Station turn left onto Pleasant Hill Rd. - **** NOTE * have Engine Brake on.**

Turn RIGHT onto US-1.

Turn LEFT onto Maine Turnpike Approach Road.

Turn RIGHT onto I 295 ramp.

**** CAUTION*** Enter I 295 staying in far right lane.

Turn RIGHT on to Broadway exit ramp. – **Have student observe speed w/ engine brake on.**

Turn LEFT on to Broadway.

Travel under overpass – Student needs to know Vehicle height.

Turn Left onto I 295 on ramp.

Merge onto US-1.

Turn LEFT Black Point Rd -**Turn off engine brake go downhill have student observe speed.**

Turn left onto Highland Ave.

Turn right onto Bornheimer Pl. **simulate RxR crossing.**

Turn left onto Fogg

Turn left onto Ironclad

Turn left onto Minuteman

Turn right onto Gunstock

Turn left onto Nutter way

Turn right onto Flintlock

Turn left onto Pleasant Hill

Ending parked inside Engine #3 Station – Using Backing Spotter- turn on engine brake