

# EHC ASSOCIATES

ENVIRONMENTAL CONSULTANTS & ABATEMENT CONTRACTORS

January 22, 2021

PA HIC #195

Mr. Glenn Davis  
c/o Lampeter-Strasburg School District  
1600 Book Road, P.O. Box 428  
Lampeter, PA 17537

Re: Lead in Water Testing Services  
Lampeter-Strasburg School District  
EHC Project No. 008735-006.1

Dear Mr. Davis:

Please review the enclosed analytical report in regard to the water samples collected from the Lampeter-Strasburg School District on January 7, 2021. The samples were analyzed for lead content by Suburban Test Laboratory using the EPA 200 Method. The following provides a summary of the results:

## LAMPETER-STRASBURG HIGH SCHOOL

<u>Sample Number/Sample Location</u>	<u>Results</u>
#1 Kitchen Sink	<0.001mg/L
#2 Men's Bathroom Sink at Auditorium	<0.001 mg/L
#3 Nurse's Office Sink	0.003 mg/L
#4 Men's Bathroom Sink – 3 <sup>rd</sup> Floor	<0.001 mg/L
#5 Men's Bathroom Sink at Room 232	<0.001 mg/L

## MARTIN MEYLIN MIDDLE SCHOOL

<u>Sample Number/Sample Location</u>	<u>Results</u>
#6 Kitchen Sink	0.005 mg/L
#7 Kitchen Bathroom Sink	<0.001 mg/L
#8 Sink – Room 52	0.003 mg/L
#9 Boy's Bathroom Sink – Room 42	<0.001 mg/L
#10 Girl's Bathroom Sink at Guidance	0.008 mg/L

2502 HORSESHOE ROAD, LANCASTER, PA 17601 ♦ 717-656-3008 ♦ FAX: 717-656-7134  
EMAIL: OFFICE@EHCASSOCIATES.COM ♦ WWW.EHCASSOCIATES.COM

Environmental Design • Consulting • Surveys • IAQ • Monitoring • Abatement & Demolition  
Specializing in the removal of Asbestos, Lead, Mold and other hazards in the built environment.

### HANS HERR ELEMENTARY SCHOOL

<u>Sample Number/Sample Location</u>	<u>Results</u>
#11 Room 55 Sink	0.001 mg/L
#12 Room 53 Sink	< 0.001 mg/L
#13 Room 50 Sink	< 0.001 mg/L
#14 Room 40 Sink	0.002 mg/L
#15 Room 42 Sink	< 0.001 mg/L

### LAMPETER ELEMENTARY SCHOOL

<u>Sample Number/Sample Location</u>	<u>Results</u>
#16 Kitchen Sink Foot Pedal	0.005 mg/L
#17 Kitchen Sink	0.003 mg/L
#18 Boy's Bathroom Sink at Café	< 0.001 mg/L
#19 Girl's Bathroom at Café	< 0.001 mg/L
#20 Room 110 Sink	< 0.001 mg/L

Laboratory analysis indicates **the water samples collected from all of the above locations are below the recommended action level of 0.015 mg/L.**

Please review the enclosed analytical report and contact our office with questions, or if further information is needed.

Sincerely,



Mark Andrechik  
Inspector

Encl.'s: Laboratory Analysis Report  
Invoice No.: 008735-006.1