IH In House

SIR WILLIAM PERKINS'S SCHOOL

FIRE RISK ASSESSMENT SUMMARY

A full review of Sir William Perkins's School Fire Risk Assessment was carried out in November 2021, of the main School and the Rowing Boathouse at Laleham, Middx. The assessment of fire risk was carried out under the requirements of the Regulatory Reform(Fire Safety) Order 2005.

During the review it was found that:

- The School has a High-level positive attitude towards Fire Safety;
- The School management throughout is a credit to the Senior Leadership Team for the acceptance of fire safety by staff, and to the Facilities team for the day-to-day management of fire safety;
- The Rowing Boathouse was separately reviewed by the Assessor;
- any significant issues identified in previous reviews had been appropriately actioned by school staff or had been discussed fully with the Governors as to the risk associated with the recommendation and the consequent actions required;
- ____Recommendations were given for additional staff training in certain areas. The school has actioned the
 —
 points raised by the assessor.
- All other assessment criteria reviewed were categorized as Good or-_/_Satisfactory. All other issues and
 recommendations identified were minor.
- The School also underwent a full 3 Day External H&S audit in April 2022 in which they were commended for their Fire Management procedures and plans

This risk assessment should be reviewed periodically, and a new review is recommended for the school within 2 years of the review date, subject to major changes to the structure and fabric of the building or major personnel changes occurring.

Formatted: List Paragraph, Left, Space Before: 0 pt, Bulleted + Level: 1 + Aligned at: 2.03 cm + Indent at: 2.62 cm, Tab stops: 2.62 cm, Left + 2.63 cm, Left



The support you need to reduce risk and protect people Registered in England no. 3293551