




PROPOSED IMPROVEMENTS GREELEY SCHOOL



- ✓ Address health/life safety upgrades
- ✓ Install new HVAC system to improve air quality, air flow and temperature control
- ✓ Improve secure entry vestibule
- ✓ Address ADA code issues
- ✓ Upgrade classroom electrical
- ✓ Update aging flooring, railings and hardware
- ✓ Upgrade classroom electrical

■ Renovation
■ Existing



Secure Entry Vestibule

A new secure entry vestibule would address best practices for safety and security, including access control.

